

7 Winchester Court Mauldin, SC 29662 864.404.3210 office 864.404.3213 fax

802 E. Martintown Rd N. Augusta, SC 29841 803.440.2790 office

www.apex-ehs.com

SERVICES

Indoor Air Quality

Mold Remediation

Asbestos & Lead

Industrial Hygiene

Worker Health & Safety

Mold Consulting

Moisture Management Plans

Safety Assessment

Environmental Site Assessments

Hazard Communication

Apex Project Number 0920-148

September 25, 2020

Mr. David Cook City of Spartanburg Fire Station 2 905 Union Street Spartanburg, South Carolina 29302

Reference: Limited Asbestos Assessment

City of Spartanburg Fire Station 2

905 Union Street

Spartanburg, South Carolina 29302

Dear Mr. Cook,

Apex Environmental Management, Inc. (Apex) has completed a limited asbestos assessment at the above-referenced property. The survey was limited to the areas on the roof of the building. Included in this report is a summary of our field activities and the results obtained. The objectives of the survey included the following:

- Identification of suspect asbestos-containing material (ACM) in readily observable locations on the roof. Limited demolition of building materials was conducted on the roof of the building during the assessment.
- Asbestos assessment with sample collection by a South Carolina Department of Health & Environmental Control accredited inspector.
- Suspect ACM analysis by polarized light microscopy (PLM) utilizing EMSL Analytical, Inc. (EMSL) as an NVLAP certified laboratory, their accreditation number is 200841-0.
- Transmission electron microscopy (TEM) analysis of non-friable organically bound materials suspected to contain asbestos and testing negatively by PLM analysis.
- Presenting the results in a report identifying confirmed ACMs.

Project Information

The survey was conducted on the roof of the City of Spartanburg Fire Station 2 located at 905 Union Street in Spartanburg, South Carolina. Due to a planned roof replacement activity, an asbestos assessment is required per SC DHEC Regulations.

Limited Asbestos Assessment Report City of Spartanburg Fire Station 2 Spartanburg, South Carolina September 25, 2020

Procedure/Methodology

Apex was requested to perform a limited asbestos assessment on the roof to identify asbestos-containing materials (ACM) which could be disturbed prior to or during scheduled renovation activities. The National Emission Standard for Hazardous Air Pollutants (NESHAP) requires the identification of friable ACM and non-friable ACM likely to become friable during demolition and/or renovation activities. NESHAP requires that the identified ACM be removed prior to initiating activities likely to disturb ACM.

- As per AHERA regulations, bulk asbestos samples were collected from random locations of each homogeneous area, with the material's number of samples based upon the following criteria:
- Thermal Insulation Materials (piping, breeching, boiler insulation, etc.) A minimum of three (3) samples are required. Only patch areas (less than 6 square or linear feet) may have one (1) sample collected.
- Surfacing Materials (plaster, fireproofing, sheetrock and joint compound, etc.) A minimum of seven (7) samples are to be taken for areas greater than 5,000 square feet; five (5) for areas greater than 1,000 square feet, but less than 5,000 square feet; three (3) for areas less than 1,000 square feet.
- Miscellaneous Materials (flooring, adhesives, roofing, floor tiles, etc.) A minimum of three (3) samples are required.
 - If samples of non-friable organically bound (NOB) materials were collected and reported by the laboratory to contain less than 1% asbestos by PLM, these materials were reanalyzed in accordance with SCDHEC requirements for NOB's by transmission electron microscopy (TEM).

The limited asbestos survey was performed by Mr. Tom Oliver (SC inspector license # BI-00680, exp. 01/15/2021) and Ms. Stephanie Hamby (SC inspector license # BI-01894, exp. 01/14/2021) on September 8, 2020. The survey consisted of observing the accessible areas of the roof of the structure that may potentially be disturbed during the scheduled roof replacement activities for the presence of suspect materials which may contain asbestos. The survey involved detecting both friable materials (materials which can be crumbled, pulverized or reduced to a powder by hand pressure when dry) and non-friable materials (materials which pose a hazard when sawn, sanded, drilled or pulverized). Homogeneous materials (based on material type, color, texture, etc.) were identified in various functional spaces during the survey.

In order to determine if the suspect materials observed during the visual survey contained asbestos, representative bulk samples were collected and placed in sealed packages. Eighteen (18) bulk samples were collected during the survey and submitted to EMSL in Charlotte, North Carolina for analysis using the EPA recommended method of Polarized Light Microscopy (PLM) coupled with dispersion staining (Method No. EPA 600/M4-82-020, Dec. 1982). EMSL participates in the National Voluntary Laboratory Accreditation Program (NVLAP). Their NVLAP accreditation number is 200841-0. Due to EPA regulations, samples are split into homogeneous layers and each layer is analyzed separately. Twenty-seven (27) samples were analyzed due to layering by PLM and positive stop methods. In accordance with South Carolina Regulation 61-86.1, non-friable organically bound materials that are reported to be non-asbestos containing by PLM analysis must also be analyzed by Transmission Electron Microscopy (TEM). Ten (10) samples were analyzed using TEM.

Limited Asbestos Assessment Report City of Spartanburg Fire Station 2 Spartanburg, South Carolina September 25, 2020

Results

The EPA defines an asbestos-containing material (ACM) as a material containing greater than 1% asbestos. OSHA defines ACM as a material containing detectable amounts of asbestos. Provided below is a general discussion of the asbestos containing materials identified on the roof of the building. A specific *Asbestos PLM and TEM Data Table* is included in Appendix II of this report and identifies positive materials and designates approximate quantities.

Suspect building materials identified to contain asbestos are:

Approximately 100 SF of roof flashing.

Recommendations and Discussion

If the above referenced asbestos materials are to be disturbed by renovations or demolition, the asbestos must be removed in accordance with EPA, State of South Carolina and OSHA asbestos regulations. The State of South Carolina, Department of Health and Environmental Control (DHEC) has specific regulations that must be adhered to during asbestos removal/abatement projects.

Apex recommends the following:

- 1. Abate the asbestos containing materials from the structure prior to roof replacement activities.
- 2. Follow applicable asbestos regulations during this project. You should be aware that stringent requirements are imposed upon anyone renovating or demolishing a structure in which ACM will be disturbed. This work must be performed in accordance with OSHA asbestos regulations, 29 CFR 1910 & 1926, and NESHAP asbestos regulations 40 CFR 61, subpart M. SCDHEC regulations require the accreditation of personnel who work in the asbestos field and notification and permitting fees for asbestos removal projects. Failure to take proper precautions and actions to protect human health and the environment can result in penalties, danger to personnel, and construction delays.
- 3. Follow SCDHEC regulations for disposal of asbestos containing materials.

Please note that this document is not a specification for asbestos removal. It does not contain means and methods for abatement. If you are planning an asbestos abatement project, please contact Apex to discuss the requirements. Use of this document without the express written consent of Apex is at the sole risk of the user and/or abatement contractor. **Quantities provided in this report are estimated**. **Contractors must verify material amounts prior to bidding or removal.** This report summarizes our evaluation of the conditions observed at the site.

The findings prepared by Apex are based upon testing performed in the building spaces. Additional ACM may exist (undetected) in other areas due to their inaccessibility or due to the limited nature of our testing. Our assessment procedures and recommendations are based on the guidelines presented in EPA, SCDHEC or OSHA asbestos regulations.

Limited Asbestos Assessment Report City of Spartanburg Fire Station 2 Spartanburg, South Carolina September 25, 2020

Apex appreciates the opportunity to provide you with our asbestos consulting services and looks forward to our continued association. If you have any questions about this report or any other industrial hygiene concerns please contact us at (864) 404-3210.

Tom Oliver

Vice President

Sincerely,

Apex Environmental Management, Inc.

Stephanie Hamby Project Manager

Appendix I PLM & TEM Asbestos Data Table

Appendix II Laboratory Analytical Results & Chain of Custody

Appendix III Photographic Log

Appendix IV SC DHEC Asbestos Inspector Licenses

APPENDIX I PLM & TEM ASBESTOS DATA TABLE

ASBESTOS SURVEY FIELD DATA SHEET PLM & TEM ANALYSIS

Project Name: City of Spartanburg Fire Station 2 Sampled By: Stephanie Hamby

Project Location: 905 Union Street, Spartanburg, SC 29302 Project Manager: Tom Oliver

Project Number: 0920-148 Date: 9/8/2020

Sample No.	Location	Sample Description	Analytical Results	Friable/Non Friable	Condition	Quantity
1		Duilt up roof avotom with	PLM - NAD			
2	Roof field	Built up roof system with gray patch/sealant	I LIVI - IVAD	Non Friable	Good	5,500 SF
3		gray patoriyoodidiit	TEM - NAD			
4			PLM - NAD			
5	Roof edges	Roof caulk	FLIVI - IVAD	Non Friable	Good	295 LF
6			TEM - NAD			
7		0	PLM - NAD			
8	HVAC	Gray sealant on metal HVAC duct	FLIVI - IVAD	Non Friable	Good	5 SF
9		TIVAO duot	TEM - NAD			
10		\\/\bits as alout on motal				
11	HVAC	White sealant on metal HVAC duct and unit	PLM - NAD	Friable	Good	10 SF
12		TIVAO duot and anit				
13			PLM - 5% Chrysotile (Tar), 50%			
14	Roof	Roof flashing	Chrysotile (Fibrous Layer); NAD (Top Roofing Layer & Felt)	Non Friable	Good	100 SF
15			TEM - 0.57% Chrysotile (Top roofing layer); NAD (felt)			
16	On top of Metal Roof		PLM - NAD			
17	Flashing	Gray caulk on flashing	I LIVI - IVAD	Non Friable	Good	80 LF
18	1 100111119		TEM - NAD			

NAD = No Asbestos Detected

LF = Linear Feet

EA = Each

Bold = Positive For Asbestos

SF = Square Feet

APPENDIX II LABORATORY ANALYTICAL RESULTS & CHAIN OF CUSTODY



EMSL Order: 412007633 **Customer ID:** AXEM25

Customer PO: Project ID:

Attention: Tom Oliver Phone: (864) 640-5274

Apex Environmental Management

7 Winchester Court Received Date: 09/09/2020 9:50 AM Mauldin, SC 29662 Analysis Date: 09/15/2020 - 09/16/2020

Collected Date: 09/08/2020

Fax:

Project: 0920-148 Fire Station #2 Limited Roof ACM

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-Asbes	stos	Asbestos
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type
1-Red Layer	Built Up Roof System with Gray	Red/Black Non-Fibrous	30% Cellulose	70% Non-fibrous (Other)	None Detected
412007633-0001	Patch/Sealant	Homogeneous			
1-Cellulose Layer	Built Up Roof System with Gray Patch/Sealant	Black Non-Fibrous Homogeneous	25% Cellulose	75% Non-fibrous (Other)	None Detected
1-Foam Insulation	Built Up Roof System with Gray	White/Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
412007633-0001B	Patch/Sealant	Homogeneous			
1-Tar Layer 412007633-0001C	Built Up Roof System with Gray Patch/Sealant	Black Non-Fibrous	5% Cellulose	95% Non-fibrous (Other)	None Detected
		Homogeneous Provin/Crov	90% Cellulose	5% Perlite	None Detected
1-Cellulose Insulation	Built Up Roof System with Gray Patch/Sealant	Brown/Gray Non-Fibrous Homogeneous	90% Cellulose	5% Non-fibrous (Other)	None Detected
2-Red Layer	Built Up Roof System	Red	30% Cellulose	70% Non-fibrous (Other)	None Detected
412007633-0002	with Gray Patch/Sealant	Non-Fibrous Homogeneous		,	
2-Cellulose Layer	Built Up Roof System with Gray	Black Non-Fibrous	20% Cellulose	80% Non-fibrous (Other)	None Detected
412007633-0002A	Patch/Sealant	Homogeneous			
2-Foam Insulation	Built Up Roof System with Gray	Yellow Non-Fibrous		100% Non-fibrous (Other)	None Detected
412007633-0002B	Patch/Sealant	Homogeneous			
2-Tar Layer 412007633-0002C	Built Up Roof System with Gray Patch/Sealant	Black Non-Fibrous	3% Cellulose	97% Non-fibrous (Other)	None Detected
		Homogeneous	000/ Callulana	5% Perlite	None Detected
2-Cellulose Insulation	Built Up Roof System with Gray Patch/Sealant	Gray/Black Non-Fibrous Homogeneous	90% Cellulose	5% Non-fibrous (Other)	None Detected
2-Tan Cellulose Layer	Built Up Roof System	Gray/Tan	65% Cellulose	15% Ca Carbonate	None Detected
·	with Gray	Fibrous		20% Non-fibrous (Other)	
412007633-0002E	Patch/Sealant	Homogeneous			
3-Foam Insulation	Built Up Roof System with Gray Patch/Sealant	White/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
3-Tan Cellulose Layer	Built Up Roof System	Tan/White	85% Cellulose	10% Ca Carbonate	None Detected
o Tan Ochalose Layer	with Gray	Non-Fibrous	CO / Collaioco	5% Non-fibrous (Other)	Tions Detected
412007633-0002G	Patch/Sealant	Homogeneous			
4	Roof Caulk on Roof Edges	Gray/Tan Non-Fibrous	5% Cellulose	20% Ca Carbonate 75% Non-fibrous (Other)	None Detected
412007633-0003		Homogeneous			
5 412007633-0004	Roof Caulk on Roof Edges	White Non-Fibrous		12% Ca Carbonate 88% Non-fibrous (Other)	None Detected
	Gray Sealant on	Homogeneous White		15% Ca Carbonate	None Detected
7-White Sealant	Metal HVAC Duct	Non-Fibrous Homogeneous		85% Non-fibrous (Other)	None Detected

Initial report from: 09/16/2020 11:14:28



EMSL Order: 412007633 Customer ID: AXEM25

Customer PO: Project ID:

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-Asbe	<u>stos</u>	<u>Asbestos</u>
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Туре
7-Grey Sealant	Gray Sealant on Metal HVAC Duct	Gray Non-Fibrous		100% Non-fibrous (Other)	None Detected
412007633-0005A		Homogeneous			
8-White Sealant	Gray Sealant on Metal HVAC Duct	White Non-Fibrous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
412007633-0006 No gray sealant present		Homogeneous			
10	White Sealant on Metal HVAC Duct &	Gray/Red Non-Fibrous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
412007633-0007	Unit	Homogeneous			
11 412007633-0008	White Sealant on Metal HVAC Duct & Unit	Gray/Red Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
13-Top Roofing Layer	Roof Flashing	Black Non-Fibrous Homogeneous	50% Cellulose 10% Glass	40% Non-fibrous (Other)	None Detected
13-Tar	Roof Flashing	Black Non-Fibrous		95% Non-fibrous (Other)	5% Chrysotile
412007633-0009A		Homogeneous			
13-Felt	Roof Flashing	Black Non-Fibrous	50% Glass	50% Non-fibrous (Other)	None Detected
412007633-0009B		Homogeneous			
13-Fibrous Layer	Roof Flashing	Black Non-Fibrous	3% Glass	47% Non-fibrous (Other)	50% Chrysotile
412007633-0009C		Homogeneous			
14-Tar	Roof Flashing				Positive Stop (Not Analyzed)
412007633-0010					
14-Felt	Roof Flashing	Brown/Black Fibrous	50% Glass	50% Non-fibrous (Other)	None Detected
412007633-0010A		Homogeneous			
14-Fibrous Layer	Roof Flashing				Positive Stop (Not Analyzed)
412007633-0010B					
16	Gray Caulk on Flashing	Gray Non-Fibrous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
412007633-0011		Homogeneous			
17	Gray Caulk on Flashing	Gray Non-Fibrous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
412007633-0012		Homogeneous			

Analyst(s)
Brant Alyea (17)
James Kincheloe (10)

Lee Plumley, Laboratory Manager or Other Approved Signatory

Evan L Plumber

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis . Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC NVLAP Lab Code 200841-0, VA 3333 00312

Initial report from: 09/16/2020 11:14:28



EMSL Order: 412007633 **Customer ID:** AXEM25

Fax:

Customer PO: Project ID:

Attention: Tom Oliver Phone: (864) 640-5274

Apex Environmental Management

7 Winchester Court Received Date: 09/09/2020 9:50 AM

Mauldin, SC 29662 Analysis Date: 09/17/2020 Collected Date: 09/08/2020

Project: 0920-148 Fire Station #2 Limited Roof ACM

Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID	Description	Appearance	% Matrix Material	% Non-Asbestos Fibers	Asbestos Types
3-Red Layer 412007633-0013	Built Up Roof System with Gray Patch/Sealant	Red Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
3-Cellulose Layer 412007633-0014	Built Up Roof System with Gray Patch/Sealant	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
3-Tar Layer 412007633-0015	Built Up Roof System with Gray Patch/Sealant	Black Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
6 412007633-0016	Roof Caulk on Roof Edges	White Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
9-White Sealant 412007633-0017	Gray Sealant on Metal HVAC Duct	White Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
9-Gray Sealant 412007633-0018	Gray Sealant on Metal HVAC Duct	Gray Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
12 412007633-0019	White Sealant on Metal HVAC Duct & Unit	Gray Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
15-Top Roofing Layer 412007633-0020	Roof Flashing	Black Non-Fibrous Homogeneous	99.43 Other	None	0.57% Chrysotile
15-Felt 412007633-0021	Roof Flashing	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
18 412007633-0022	Gray Caulk on Flashing	Gray Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. EMSL recommends that samples reported as none detected or <1% undergo additional analysis via PLM to avoid the possibility of false negatives.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC

Initial report from: 09/17/2020 12:59:39



7 Winchester Court

Mauldin, SC 29662

Attention: Tom Oliver

EMSL Order: 412007633 Customer ID: AXEM25

Customer PO: Project ID:

Phone: (864) 640-5274

Fax:

Received Date: 09/09/2020 9:50 AM

Analysis Date: 09/17/2020 **Collected Date:** 09/08/2020

Project: 0920-148 Fire Station #2 Limited Roof ACM

Apex Environmental Management

Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID Description Appearance % Matrix Material % Non-Asbestos Fibers Asbestos Types

Analyst(s)

Aaron Hartley (10)

Lee Plumley, Laboratory Manager or other approved signatory

Evan L Plumber

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. EMSL recommends that samples reported as none detected or <1% undergo additional analysis via PLM to avoid the possibility of false negatives.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC

Initial report from: 09/17/2020 12:59:39

OrderID: 412007633



Asbestos Bulk Building Material Chain of Custody

EMSL Order Number (lab use only):

EMSL Analytical, Inc.	
10801 Southern Loop Blvd	j

Pineville, NC 28134

Phone

(704) 525-2205 (704) 525-2382

412	.007633	Fax
	EMSL Customer ID:	

Company Name	e: Apex E	nvironmenta	l Management, Inc.	EMSL Customer ID:			
Street: 7 Wi	inchester C	ourt		City: Mauldin		State or Province: SC	
Zip/Postal Code	29662		Country: US	Telephone #: 864-40	04-3210	Fax #: 864-404-3213	
Report To (Nam	ıe): Tom	Oliver		Please Provide Results via: ☐ Fax ☐ Email			
email Address:	toliver@)apex-ehs.co	om	Purchase Order Number:			
Client Project II): 0920-14	18 Fire Station	#2 Limited Roof ACM	EMSL Project ID (inte	ernal use only	/):	
State or Province				CT only Commerc			
EMSL-Bill to:	Same 🗸	Different - if b		ons in comment. Third party (T) Options Please Chec		s written authorization from third party	
☐ 3 Hour	☐ 6 Hour	☐ 24 Hot		B Hour ☐ 72 Hour	☐ 96 Ho	ur 🔳 1 Week 🔲 2 Week	
'32 Hour TAT available for select tests only; samples must be submitted by 11:30am. Please call ahead for large projects and/or turnaround times 6 hours or less.							
	PLM - Bul	k (reporting l			<u>TEM</u>	<u>Bulk</u>	
PLM EPA 600)/R-93/116 (·	<1%)		■ TEM EPA NOB – EP.	A 600/R-93/1	16 Section 2.5.5.1	
PLM EPA NO	B (<1%)			NY ELAP Method 198	8.4 non-friabl	e - NY	
Point Count 🔲	400 (<0.25%	6) 🔲 1000 (<(0.1%)	☐ Chatfield Protocol (se	mi-quantitati	ve)	
Point Count w/Gi	ravimetric 🗌	400 (<0.25%) 🔲 1000 (<0.1%)	TEM % by Mass – EF	PA 600/R-93/	116 Section 2.5.5.2	
☐ NIOSH 9002	(<1%)			☐ TEM Qualitative via F	iltration Prep	Technique	
☐ NY ELAP Me		friable - NY		☐ TEM Qualitative via □			
☐ NY ELAP Me	thod 198.6 l	NOB- non-frial	ole - NY			ease specify)	
NY ELAP Me	thod 198.8-	Vermiculite Si	urfacing Material				
OSHA ID-19							
☐ EMSL Standa	ard Addition	Method	18 al 185			•	
Positive Stop - Clearly Identify Homogenous Areas (HA) Date Sampled: 9-8-2-20					-2020		
			Sampler's Signatu	re: //			
Sample #	HA#		Sample Location	on		Material Description	
i		Built	up roof system	with 1	PIM		
2		a Chu	Pote L/Seplant	.			
٠ کے		9.47	(41- 11- C4 (am)		TEA	1	
4		Roof	coult on roof	edges	PLM		
5		1-001	<u> </u>		1		
6				1_	TEM		
Client Sample #	Client Sample # (s): 1 -/8 Total # of Samples:						
Relinquished by		11	Date	$Q_{-1}() = 2 \circ 2$		Time: 1:30 Pm	
Received by (La	ıр): ДУ,		Date	املم		Time: 9:50AM EHSL TK	
Comments/Spec	cial Instruct			·	4,		
BitTo Apex Environmental M Attention: Tom Oliver Phone					<u>1</u> 9:	59 2729 2740	

Controlled Document - COC-01 Asbestos Bulk - R4 - 09/10/2019

EMSL Analytical, Inc.'s (DBA: LA Testing) Laboratory Terms and Conditions are incorporated into this chain of custody by reference in their entirety. Submission of samples to EMSL Analytical Inc. constitutes acceptance and acknowledgment of all terms and conditions.

OrderID: 412007633



Asbestos Bulk Building Material Chain of Custody

EMSL Order Number (lab use only):

-1	123		
١	633		

EMSL Analytical, Inc. 10801 Southern Loop Blvd

Pineville, NC 28134 Phone (704) 525-2205 Fax (704) 525-2382

Additional pages of the Chain of Custody are only necessary if needed for additional sample information

Sample #	HA#	Sample Location	Material Description
7		Gray Sealant on metal HUAC	PLM
8		Duct	
9			TEM
10		duct + unit	PLM
1		duct + unit	1
12	'		TEM
		Roof flushing	prm
14			
15		<u></u>	TEM
16		Gray coult on Flocking	PLM
_ 17	- <u>-</u> .		
18			TEM
	ts/Special Ir		

BillTo: Apex Environmental Management, Inc., 7 Winchester Court, Mauldin, SC, 29662, US

Attention: Tom Oliver Phone: 8644043210 Email: toliver@apex-ehs.com Purchase Order:

Page ____ of ___ pages

Controlled Document - COC-01 Asbestos Bulk - R4 - 09/10/2019

EMSL Analytical, Inc.'s (DBA: LA Testing) Laboratory Terms and Conditions are incorporated into this chain of custody by reference in their entirety. Submission of samples to EMSL Analytical Inc. constitutes acceptance and acknowledgment of all terms and conditions.

2

APPENDIX III PHOTOGRAPHIC LOG



Photo 1 – City of Spartanburg Fire Station 2 located in Spartanburg, SC.



Photo 2 – View of bottom roof field.



Photo 3 – View of upper roof field.



Photo 4 – Roof sample.



Photo 5 – Close up of the roof sample.



Photo 6 – Roof core sample.



Photo 7 - Roof caulk on roof edges.



Photo 8 – Gray sealant on HVAC duct.



Photo 9 - White sealant on HVAC duct.



Photo 10 – Roof flashing between roof transition.



Photo 11 – Roof flashing at chimney.



Photo 12 – Gray caulk on flashing.

Limited Roofing Asbestos Assessment Fire Station #2, 905 Union Street Spartanburg, South Carolina 29302



Photo 13 – Interior of roof flashing.

APPENDIX IV SC DHEC ASBESTOS INSPECTOR LICENSES

SCDHEC ISSUED

Asbestos ID Card

Thomas H Oliver



AIRSAMPLER AS-00202 CONSULTBI BI-00680 Expiration Date: 06/18/21 01/15/21

This card is nontransferable and provided invalid if loaned or given to another person for identification. This card will also be invalid if altered or defaced. This card is property of SCDHEC. It must be returned to the department if the holder's accreditation is revoked or if this card is invalidated. Any person performing regulated asbestos activities without current accreditation shall be subject to legal sanction. This card must be returned upon expiration and/or issuance of a new card.

YOU MUST HAVE THIS IDENTIFICATION CARD WITH YOU ON THE JOB.

For information of corrections contact: SCDHEC – Asbestos Section

SCDHEC – Asbestos Secti 2600 Bull Street Columbia, SC 29201 (803) 898-4289

SCDHEC ISSUED Asbestos ID Card

STEPHANIE HAMBY



AIRSAMPLER AS-000632 08/13/21 CONSULTBI BI-01894 01/15/21