



ADDENDA# 2

**RFQ NO. 3001-0-2019, ARCHITECTURAL/ENGINEERING DESIGN SERVICES
RFQ NO. 3002-0-2019, CONSTRUCTION MANAGEMENT AT RISK SERVICES
REPLACE MARTIN COUNTY SCHOOL DISTRICT'S JENSEN BEACH (JBES) &
PALM CITY ELEMENTARY (PCES) SCHOOLS**

DATE: 8/28/19

This addendum is a combination of Architects, Engineers, and Contractors represented at the joint mandatory pre-proposal meeting. Please find the following attachments requested at the mandatory Pre-proposal meeting on August 16, 2019 and the responses to the following questions:

- Attachment A JBES Asbestos, DOE, and Castaldi Reports
- Attachment B PCES Asbestos, DOE, and Castaldi Reports

1. **Question:** Question regarding Tab 9 Financial Capacity – confirm that the financial statement will be in a separate sealed envelope and not a part of Tab 9. Also confirm number of statements required to be submitted?

Answer: Submit two (2) copies of your financials in a sealed envelope within your submittal package.

2. **Question:** It is understood that the track to the east of Jensen Beach Elementary School is part of the school's property. Is this track going to be replaced as part of the scope? Or will it be left as is and in use?

Answer: The track is going to be replaced as part of the scope of work that only pertains to Jensen Beach Elementary School. This would apply to the A&E and CMR.

All other terms and conditions of this RFQ remain unchanged.

This Addendum shall be considered an integral part of the RFQ. Addendum must be signed and returned with your submittal on the designated time **on September 11, 2019.**

Lenora S. Darden, MCPP, CPPB, CPSM
Purchasing Supervisor

Acknowledgement is hereby made of Addenda# 2 to RFQ# 3001-0-2019 and 3002-0-2019.

Authorized Signature

Firm

Printed, Title

Date

Email Address



ADDENDA NO. 2

RFQ NO. 3001-0-2019/3002-0-2019


ATTACHMENT A

JENSEN BEACH ELEMENTARY SCHOOL (JBES)

**PURCHASING DEPARTMENT
2845 SE DIXIE HWY STUART, FL., 34997
TEL (772) 219-1255
EMAIL bids@martin.k12.fl.us**

2017 AHERA RE-INSPECTION
Jensen Beach Elementary
2525 NE Savannah Road
Jensen Beach, Florida
S&ME Project No. 4484-17-070-B

Assessment Performed by and Report Prepared by:



Nacole Caputo (Accreditation# BI-01317)

8/21/17

Date



Prepared for:
Martin County School District
1050 SE 10th Street
Stuart, FL 34994

Prepared by:
S&ME, Inc.
111 Kelsey Lane, Suite E
Tampa, FL 33619

August 21, 2017



August 21, 2017

Martin County School District
1050 SE 10th Street
Stuart, Florida 34994

Attention: Mr. Rob Phillips

Reference: **2017 AHERA Re-Inspection Report**
Jensen Beach Elementary
Jensen Beach, Florida
S&ME Project No. 4484-17-070-B

Dear Mr. Phillips:

S&ME, Inc. is pleased to submit the enclosed 2017 Asbestos Hazard Emergency Response Act (AHERA) Re-inspection Report for the referenced school located in Jensen Beach, Florida. This work was performed in general accordance with the S&ME Proposal No. 44-1700122, dated April 11, 2017.

The enclosed re-inspection report was conducted as outlined in the Environmental Protection Agency (EPA) Regulation 40 CFR 763.85 and was performed by an EPA accredited inspector and response actions determined by an accredited Management Planner. This report represents a summary of past re-inspection reports and must be used in conjunction with the original Asbestos Management Plan and subsequent three-year re-inspections to manage and track the asbestos containing building materials currently in the school. The regulation states that the Local Education Authority (LEA) shall:

- ◆ Select and implement, in a timely manner, the appropriate **response actions** for each known and assumed asbestos containing building material (ACBM). The LEA may select from response actions that protect human health and the environment and are the least burdensome methods.
- ◆ Ensure that workers and building occupants, or their legal guardians, are informed at least once each school year about inspections, response actions, and post response action activities, including periodic 3-year reinspection and surveillance activities that are planned or in progress. (40 CFR 763.84 (c)). Copies of **notifications** must be included with this report.
 - Annual notifications were not available for S&ME to review.
- ◆ Conduct **periodic surveillance**, at least once every six months, in each building that it leases, owns, or otherwise uses as a school building that contains ACBM or is assumed to contain ACBM." (40 CFR 763.92 (b))
 - Six-month surveillance documentation was not available for S&ME to review.
- ◆ Ensure, prior to implementation of the operations and maintenance provisions of the management plan, that members of its maintenance and custodial staff (custodians, electricians, heating/air conditioning technicians, plumbers, etc.) who may work in a building that contains ACBM receive **awareness training** of at least two hours, whether or not they are required to work

directly with ACBM. New custodial and maintenance employees are to be trained within 60 days after commencement of employment. (CFR 40 763.92 (a) (1))

- The 2-hour asbestos awareness training was observed for several employees over the last three years. The school board uses safeschools.com to provide training.
- ◆ Ensure that members of its maintenance and custodial staff who conduct operations and maintenance activities that will result in the disturbance of ACBM receive the **two hour asbestos awareness training and an additional 14 hours of training**. (40 CFR 763.92 (a) (2)). Training records must be made part of each building's 3-year reinspection/management planner report.
 - Documentation for the 14-hour O&M training was not available for S&ME to review.

Based on the findings of the initial inspection and subsequent re-inspections, S&ME confirmed the following asbestos containing building materials currently in the facility.

- ◆ Drywall and joint compound
- ◆ Heating, ventilation and air conditioning (HVAC) duct mastics
- ◆ Vinyl floor tiles and mastic
- ◆ Cove base mastics
- ◆ Carpet mastics
- ◆ Fire-rated doors
- ◆ Chalkboards
- ◆ Sink condensate barriers
- ◆ Plaster coatings
- ◆ Pipe wrap insulation
- ◆ Wall glues/mastics

The Scope of Service is based on historical sampling data and the 1988 (original) AHERA Asbestos Management Plan for the Jensen Beach Elementary. Suspect asbestos containing materials installed in the school since the original 1988 AHERA inspection and subsequent 3-year reinspections were not sampled or analyzed as a part of this scope of work. However, the client requested samples of damaged or significantly damaged assumed ACBMs be sampled. Damaged suspect ACBMs were not observed during our assessment.

This report does not comply with the EPA's National Emission Standards for Hazardous Air Pollutants (NESHAP) regulatory requirements for renovation or demolition activities impacting suspect asbestos containing materials. Compliance with NESHAP requirements for renovation or demolition projects will require additional bulk sampling and analysis of any suspect interior or exterior material not sampled and analyzed in this report.



We appreciate the opportunity to provide you with our industrial hygiene/environmental services. If you have any questions concerning this report, please call us at (813) 623-6646.

Sincerely,

S&ME, Inc.

Florida Asbestos Business Organization License #ZA0000094

Prepared by

A handwritten signature in black ink, appearing to read "Nacole Caputo".

Nacole Caputo, MBA, CIE
Project Manager
Management Planner

Reviewed by

A handwritten signature in black ink, appearing to read "Ken Warren".

Kenneth R. Warren, CIH
Senior Industrial Hygienist
Florida Licensed Asbestos Consultant #IA24

Attachments



AHERA RE-INSPECTION REPORT

LEA: Martin County School District

ADDRESS: 1050 SE 10th Street
Stuart, Florida 34994

TELEPHONE: (772) -223-3105

DATE: August 21, 2017

SCHOOL: Jensen Beach Elementary

SUBMIT TO LEA DESIGNEE

LIST OF DOCUMENTS ATTACHED:

- | | |
|--|--|
| <input checked="" type="checkbox"/> 1. List of School Buildings | <input type="checkbox"/> 6. Description of Each Sample Area & Assessment of Materials |
| <input checked="" type="checkbox"/> 2. Reassessment of Areas of ACBM or Suspect ACBM | <input type="checkbox"/> 7. Bulk Sample Analysis |
| <input type="checkbox"/> 3. Added Homogenous Areas of ACBM or Suspect ACBM | <input checked="" type="checkbox"/> 8. Response Actions Recommended, Response Actions Selected and Dates |
| <input checked="" type="checkbox"/> 4. Diagram of School Campus | <input checked="" type="checkbox"/> 9. Copy of Inspectors License |
| <input type="checkbox"/> 5. Description of Each New Homogenous Area and Determination of Sampling Location | <input checked="" type="checkbox"/> 10. Copy of Management Planners License |

No person or firm shall offer to perform, perform or be hired to perform as professionals in providing the services of inspection, preparation of management plans, designing of response actions, or supervising of response action except as properly accredited under the provisions of Public Law 99-519, EPA regulations 40 CFR Part 763 and SCDHEC Regulation 61-86 1. In addition these persons or firms performing as professionals shall be registered in South Carolina under the registration laws of the State. Such professionals shall be independent practitioners and shall have no financial or other interest in contractors, subcontractors, manufacturers, or jobbers under their jurisdiction where direct conflict of interest could occur, except as permitted as follows.

An employee of a public school, a private school association, a private school or an A/E may provide the services of inspection, and or preparation of management plans, provided the employee is properly accredited under the "AHERA" Laws and Regulations. Where an employee of the LEA provides these services, the LEA must request a Waiver of Professional Services.

LEA DESIGNEE: _____
 Name Telephone No. Signature & Date

HOURS TRAINING: _____ AGENCY: _____ DATE: _____


PRINCIPAL: _____
 Name Telephone No. Signature & Date

INSPECTOR: Jarett Epps _____
 Name & Signature

AHERA LICENSE NO. 170343-6205 Telephone No. (813) 623-6646

MANAGEMENT PLANNER: Nicole Caputo _____
 Name & Signature

AHERA LICENSE NO. 8301691 Telephone No. (813) 623-6646



AHERA RE-INSPECTION REPORT

LEA: Martin County School District

SCHOOL: Jensen Beach Elementary

ADDRESS: 2525 NE Savannah Road

Jensen Beach, Florida

DATE REINSPECTED: July 18, 2017

I - LIST OF BUILDINGS REINSPECTED

BUILDING NAME/NO.	ACBM		SUSPECT ACBM		NO ACBM
	FRIABLE	NONFRIABLE	FRIABLE	NONFRIABLE	
2			X	X	
3			X	X	
5			X	X	

COMMENTS: Access to Room 30 C in Building 2 was not available

2 - REASSESSMENT OF AREAS OF ACBM OR SUSPECT ACBM



LEA: Martin County School District

Condition Code Legend:

1. Damaged or significantly damaged thermal system insulation ACM
2. Damaged friable surfacing ACM
3. Significantly damaged friable surfacing ACM
4. Damaged or significantly damaged friable miscellaneous ACM
5. ACM with potential for damage
6. ACM with potential for significant damage
7. Any remaining ACBM or friable suspected ACBM

SCHOOL: Jensen Beach Elementary

ADDRESS: 2525 NE Savannah Road

Jensen Beach, Florida

DATE REINSPECTED: July 18, 2017

AHERA RE-INSPECTION REPORT

ROOM # AND FUNCTIONAL SPACE	2004 HA #	N e w	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
								YES	NO
101	9		Sink Condensate Barrier, Black	2 SF	MISC	7	Non-Friable		X
7, 130A, 130B, 130C, 130D, 131A, 131C, 131D, 132, 130(Cafeteria)	25		1' x 1' White with Light Green Specks VFT and Mastic	7,000 SF	MISC	5	Non-Friable		X
446, 130, 131A, 131D, Office, 130(Cafeteria)	27		Cove Base Mastic – Cove Base, Green	300 SF	MISC	5	Non-Friable	X – not found in 116 or Office!	
7, 130(Cafeteria)	28		Acoustical Wall Carpet, Green and Wall Mastic	4,000 SF	MISC	5	Non-Friable		X
Throughout	30		Drywall and Joint Compound	>10,000 SF	SUR	5	Friable		X
21C, 134, 135, Classrooms, Restrooms	31		Plaster Coating	12,000 SF	SUR	5	Friable		X
4A, 4B, 104, 106, 119C, 142A	32		1' x 1' White/Gray VFT and Mastic	2,000 SF	MISC	5	Non-Friable		X
4A, 19, 20, 21, 28, 29, 30, 101, 110, 118A, 142, 151, 152, 153, 155, 156, 157, 161, 162, 163, Classrooms	33		Cove Base Mastic – Cove Base, Blue	800 SF	MISC	5	Non-Friable		X
135, 159, 171	34		HVAC Duct Mastic, Gray	Unknown	MISC	7	Non-Friable		X
30C, 135, 139, 144, 145, 159, 160, 169, 171, Other interstitial ceiling space	35		Pipe Insulation Wrap	Unknown	TSI	7	Friable		X
20, 21	37		Carpet Mastic – Blue/Burgundy Carpet	800 SF	MISC	5	Non-Friable		X
104, 105, 106, 139, 144, 145, 146, 150, 158, 159, 160, 169, 171	39		Cove Base Mastic – Cove Base, Gray	400 SF	MISC	5	Non-Friable		X
143, 146, 150	40		1' x 1' White with Blue Specks VFT and Mastic	1,500 SF	MISC	5	Non-Friable		X
103, 107 – 116, 140A, 159	38		Carpet Mastic – Blue Carpet	4,000 SF	MISC	5	Non-Friable	X – not found in 159!	
19, 20, 21, 28, 29, 30, 140, 141, 155, 156	44		1' x 1' Blue VFT and Mastic	6,600 SF	MISC	5	Non-Friable		X

2 - REASSESSMENT OF AREAS OF ACBM OR SUSPECT ACBM

LEA: Martin County School District

Condition Code Legend:

1. Damaged or significantly damaged thermal system insulation ACM
2. Damaged friable surfacing ACM
3. Significantly damaged friable surfacing ACM
4. Damaged or significantly damaged friable miscellaneous ACM
5. Damaged or potential for damage to ACM with potential for significant damage
6. ACM with potential for significant damage
7. Any remaining ACBM or friable suspected ACBM

SCHOOL: Jensen Beach Elementary

ADDRESS: 2525 NE Savannah Road

Jensen Beach, Florida

DATE REINSPECTED: July 18, 2017

HERA RE-INSPECTION REPORT

Building 2:

ROOM # AND FUNCTIONAL SPACE	2004 HA #	N e w	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
								YES	NO
19 - 21, 28, 29, 170	45		Sink Condensate Barrier, Gray	16 SF	MISC	7	Non-Friable		X
100, 119D, 142, 162 - 164, 166, 168, 170, 170A, Halls of 100 Bldg.	46		1" x 1" White with Brown Specks VFT and Mastic	8,000 SF	MISC	5	Non-Friable		X
19	47		Green Chalkboard	50 SF	MISC	5	Non-Friable		X
Throughout	49		Plaster Coating, Textured	>10,000 SF	SUR	5	Friable		X
3, 3A	50		1" x 1" Tan with Brown Lines VFT and Mastic (over green RFT)	200 SF	MISC	5	Non-Friable		X
3, 3A, 3C	51		Cove Base Mastic - Cove Base, Black	80 SF	MISC	5	Non-Friable		X
104 - 106(Bathrooms), 130(Cafeteria), 132	14-01		Reinforced Vinyl Panel Glue	3,000 SF	MISC	7	Non-Friable		X
All Classrooms & Hallway	54		Fire-Rated Doors	40 EA	MISC	7	Non-Friable		X
19 - 21, 28, 29, 162, 170	14-02		Tan Mastic behind Blue Wall Panels	300 SF	MISC	7	Non-Friable		X

Building 3:

ROOM # AND FUNCTIONAL SPACE	2004 HA #	N e w	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
								YES	NO
22, 24	13		1" x 1" White with Black Specks VFT and Mastic	1,400 SF	MISC	5	Non-Friable		X
22, 24	14		Cove Base Mastic - Cove Base, Blue	60 SF	MISC	5	Non-Friable		X
22, 27	16		Sink Condensate Barrier, Black	4 SF	MISC	7	Non-Friable		X
Throughout	17		Drywall & Joint Compound	3,500 SF	SUR	5	Friable		X
22	18		Green Chalkboard	50 SF	MISC	5	Non-Friable		X
25	19		Cove Base Mastic - Cove Base, Black	15 SF	MISC	5	Non-Friable		X

2 - REASSESSMENT OF AREAS OF ACBM OR SUSPECT ACBM

LEA: Martin County School District

Condition Code Legend:

1. Damaged or significantly damaged thermal system insulation ACM
2. Damaged friable surfacing ACM
3. Significantly damaged friable surfacing ACM
4. Damaged or significantly damaged friable miscellaneous ACM
5. ACM with potential for damage
6. ACBM with potential for significant damage
7. Any remaining ACBM or friable suspected ACBM

SCHOOL: Jensen Beach Elementary

ADDRESS: 2525 NE Savannah Road

Jensen Beach, Florida

DATE REINSPECTED: July 18, 2017

AHERA RE-INSPECTION REPORT

Building 3:

ROOM # AND FUNCTIONAL SPACE	2004 HA #	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
							YES	NO
25	21	1' x 1' Tan/Olive VFT and Mastic	40 SF	MISC	5	Non-Friable		X
Mechanical Rooms	23	Pipe Insulation Wrap	Unknown	TSI	7	Friable		X
Mechanical Rooms	24	Cove Base Mastic – Cove Base, Gray	20 SF	MISC	Not Found ¹	Non-Friable	X	
Mechanical Rooms	25	Fire-Rated Doors	4 EA	MISC	7	Non-Friable		X
24	14-01	Sink Condensate Barrier, Gray	2 SF	MISC	7	Non-Friable		X

Building 5:

ROOM # AND FUNCTIONAL SPACE	2004 HA #	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
							YES	NO
40, 41, 41D, 41F, 41G	7	1' x 1' Blue VFT with Mastic	500 SF	MISC	5	Non-Friable		X
Throughout	9	Drywall and Joint Compound	1,800 SF	SUR	5	Friable		X
Throughout	10	Cove Base Mastic – Cove Base, Blue	210 SF	MISC	5	Non-Friable		X
41A	11	Carpet Mastic – Blue/Burgundy Carpet	360 SF	MISC	5	Non-Friable		X
Perimeter Walls	12	Plaster Coating	2,000 SF	MISC	5	Non-Friable		X
41B, 41C	13	Cove Base Mastic – Cove Base, Brown	30 SF	MISC	5	Non-Friable		X
41B, 41C	14	1' x 1' Tan/Olive VFT and Mastic	140 SF	MISC	5	Non-Friable		X
41H	15	Pipe Insulation Wrap	80 SF	TSI	7	Friable		X
41H	16	HVAC Duct Mastic, White	120 SF	MISC	7	Non-Friable		X

1 Asbestos NESHAP survey not observed during records review

2 - REASSESSMENT OF AREAS OF ACBM OR SUSPECT ACBM

Condition Code Legend:

1. Damaged or significantly damaged thermal system insulation ACM
2. Damaged friable surfacing ACM
3. Significantly damaged friable surfacing ACM
4. Damaged or significantly damaged friable miscellaneous ACM
5. ACBM with potential for damage
6. ACBM with potential for significant damage
7. Any remaining ACBM or Friable suspect ACBM

LEA Martin County School District

SCHOOL Jensen Beach Elementary

ADDRESS 2525 NE Savannah Road

Jensen Beach, Florida

DATE REINSPECTED July 18, 2017

AHERA RE-INSPECTION REPORT

Building S:

ROOM # AND FUNCTIONAL SPACE	2004 HA #	N e w	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES? YES NO
41H	17		HVAC Duct Mastic, Gray	20 SF	MISC	7	Non-Friable	X
41H	18		Fire-Rated Doors	2 EA	MISC	7	Non-Friable	X
41, 41A	10		Brown Mastic behind Blue Wall Panels	10 SF	MISC	7	Non-Friable	X

Jarrett Epps

July 18, 2017

LEA DESIGNER:

DATE OF RE-INSPECTION REVIEW:

AHERA LICENSE No.:

170343-6205

EXP. DATE:

01/25 2018

SIGNATURE:



SIGNATURE:

AHERA RE-INSPECTION REPORT

LEA: Martin County School District

SCHOOL: Jensen Beach Elementary

ADDRESS: 2525 NE Savannah Road

Jensen Beach, Florida

DATE REINSPECTED: July 18, 2017

4-DIAGRAM OF SCHOOL CAMPUS

(SEE FIGURE ON FOLLOWING PAGE)

宋

Song + Associates

Architecture • Planning • Interior Design
11115 Champlain Drive, North
Fort Lauderdale, FL 33308
Telephone: 561-455-1221
Fax: 561-455-1222
www.songad.com

Notes:
License # :
Consultants :

DATE: 12/14/2016
S.A. Project No.: 16056-A
Client: Project No.:
CREATED BY: SR
PERMITS: PERMIT DOCUMENTS
Sheet Title:




F.I.S.H. PLAN UPDATE
JENSEN BEACH
ELEMENTARY SCHOOL
200 S. PALM AVENUE
JENSEN BEACH, FL 33409

DATE: 12/14/2016
S.A. Project No.: 16056-A
Client: Project No.:
CREATED BY: SR
PERMITS: PERMIT DOCUMENTS
Sheet Title:

SITE PLAN

Sheet # :
A-201



SITE PLAN	01	1/2" = 1'-0"
-----------	----	--------------

宋

Song + Associates
A Multi-Service Professional Services Firm
1315 Chesapeake Drive, Suite 100
West Palm Beach, Florida 33411
Tel: 561-833-7122
Fax: 561-833-7123
AS - 10001965 ID - 10001969

Name: _____
License #: _____
Contributor #: _____

DATE: 08/14/2018
PROJECT: JENSEN BEACH ELEMENTARY SCHOOL
DRAWN BY: _____
CHECKED BY: _____
PERMIT DOCUMENTS




F.I.S.H. PLAN UPDATE
JENSEN BEACH ELEMENTARY SCHOOL
2525 NE BAYVIEW ROAD
JENSEN BEACH, FL 34957

DATE: 08/14/2018
S.I.A. Project No.: 1808245
Drawn Project No.: _____
Checked By: _____
Phase: PERMIT DOCUMENTS

Sheet Title: _____

BUILDINGS 2, 3,
AND 5

Sheet #: **A-221**



FIRST FLOOR PLAN - BUILDING 2

PARENT DROP OFF

MECHANICAL YARD

PORTABLE

BUILDING 5

GAZEBO

FIRST FLOOR PLAN - BUILDING 5

FIRST FLOOR PLAN - BUILDING 3

SEE SHEET A-222

SEE SHEET A-222

SEE SHEET A-222

BUILDINGS 2, 3, AND 5 ENLARGED PLANS

01

3/23/18-01

5

1

2

3

4

5

宋

Song + Associates

Architects & Planning & Interiors Group
1115 - Westpark Drive North
West Palm Beach, Florida 33411
Tel: 561-833-8888
Fax: 561-833-8889
www.songa.com

AA 000150 BB 000100
Sheet 1

Name: _____
License # : _____
Consultants : _____

DATE: 08/14/2018
DRAWN BY: _____
CHECKED BY: _____
PROJECT: _____
SHEET: _____



F.I.S.H. PLAN UPDATE
JENSEN BEACH
ELEMENTARY SCHOOL
3252 NE DANANIAH ROAD
JENSEN BEACH, FL 32057

DATE: 08/14/2018
SIA Project No.: 18005-A
Drawn By: _____
Checked By: _____
Project: PERMIT DOCUMENTS

Sheet Title :


BUILDING 9

Sheet # :

A-222

SEE SHEET A-221

SEE SHEET A-221



BUILDING 9

8 - ACTIONS RECOMMENDED AND RESPONSE ACTION
SELECTED & DATES

LEA: Martin County School District
 SCHOOL: Jensen Beach Elementary
 ADDRESS: 2525 NE Savannah Road
 Jensen Beach, Florida
 DATE REINSPECTED: July 18, 2017

AHERA RE-INSPECTION REPORT

HA # OR FS	RECOMMENDED RESPONSE ACTION	SELECTED RESPONSE ACTION	ORIGINAL DATE	SCHEDULED DATE	COMMENTS
Overall – HAs with condition codes 5-7	Restrict contact, periodically reinspect condition (minimum every six months) and maintain under Operations and Maintenance Plan or remove.				
Building 2: Rooms 116, Office and 159 Building 3: Mechanical Room	Obtain NESHAP Asbestos Survey report and store in Management Plan				

MANAGEMENT PLANNER: Nacole Caputo

LEA DESIGNEE:

DATE OF REPORT: August 21, 2017

DATE OF RE-INSPECTION REVIEW:

AHERA LICENSE NO.: 83071691

EXP. DATE: 08/30/2017

SIGNATURE:

SIGNATURE:



AHERA RE-INSPECTION REPORT

9- COPY OF INSPECTOR'S LICENSE

LEA: Martin County School District

SCHOOL: Jensen Beach Elementary

ADDRESS: 2525 NE Savannah Road

Jensen Beach, Florida

DATE REINSPECTED: July 18, 2017

ATTACH COPY OF INSPECTOR'S ACCREDITATION LICENSE

UF TREEO Center
UNIVERSITY of FLORIDA

Center for Training, Research and Education for Environmental Occupations

certifies

Jarett W Epps

S&MF, 933 Benninger Dr. Brandon, FL 33510

has successfully met certificate requirements for the

Asbestos: Inspector

Approval: FBPR Asbestos Licensing Unit: Provider #0000995; Course #FL49-0002859 (3 Days; 21 Contact Hours)
(Accreditation for Inspector Under TSCA Title II/AHERA)

Conducted

01/23/2017 to 01/25/2017

Certificate #: 170343-6205
CEUs: 2.1
EPA accreditation expires: 01/25/2018
Principal Instructor: Russell E. Stauffer, PE, LAC
FBPE PDI#: 0009087/Educational Institutions: 21.0

Carol Hinton
Carol Hinton, Associate Director

University of Florida TREEO Center • 3900 SW 63 Boulevard • Gainesville, FL 32608-3800 • 352-392-9570 • www.treeo.ufl.edu

10- COPY OF MANAGEMENT PLANNER'S LICENSE

LEA: Martin County School District

SCHOOL: Jensen Beach Elementary

ADDRESS: 2525 NE Savannah Road

Jensen Beach, Florida

DATE INSPECTED: July 18, 2017

ATTACH COPY OF MANAGEMENT PLANNER'S ACCREDITATION LICENSE





State Board of Education

Marva Johnson, *Chair*
Andy Tuck, *Vice Chair*
Members
Ben Gibson
Tom Grady
Michael Olenick
Joe York

Richard Corcoran
Commissioner of Education

June 27, 2019

Laurie Gaylord, Superintendent
Martin County School District
500 East Ocean Boulevard
Stuart, Florida 34994-2578

Dear Superintendent Gaylord:

The building replacement study dated January 2018, prepared by Song + Associates, Inc., and received by the Office of Educational Facilities (OEF) on June 25, 2018, has been reviewed. Based on the information provided to us by the Martin County School District (district), we concur with the recommendation that replacement of the buildings listed below is more economical than the rehabilitation of the existing buildings. Our recommendation does not result in these buildings being classified as unsatisfactory. Should you want to change the classification of these buildings, supporting documentation of unsatisfactory conditions must be provided.

Jensen Beach Elementary School			
Building # (s)	Building Use	Square Footage	Year of Construction/ Age
2	Administration/Classrooms/Kitchen/Dining	56,854	1970/48
3	Classrooms	3,141	1980/38
5	Music	2,217	1980/38
6	Covered Play	8,245	1993/25
9	Classrooms	19,802	1987/32

Our concurrence does not relieve the district of its responsibility for performing required

Superintendent Laurie Gaylord


June 27, 2019

Page Two

Should the district desire to raze these buildings, an approved survey recommendation must first be obtained from OEF.

Please let us know if we may be of further assistance.

Sincerely,

A handwritten signature in blue ink, appearing to read 'Mark A. Weigly', is written over a faint, illegible typed name.

Mark A. Weigly, Architect, LEED AP, FCP
Educational Facilities Construction Planning Manager
Office of Educational Facilities

MW/ss

cc: Mark Eggers, Assistant Deputy Commissioner
Violet Brown, Senior Educational Program Director
Don Whitehead, Safe and Efficient Facilities Design Manager



Martin County School District

Jensen Beach Elementary

Castaldi Analysis



2525 NE Savannah Road
Jensen Beach, Florida 34957
January, 2018



Table of Contents

Martin County School Board Members Executive Summary	Tab A
Jensen Beach Elementary Assessment Report & Recommendations	Tab B
Department of Education DOE OEF Form RCC-BRR-2008	Tab C
Castaldi Formula Analysis Jensen Beach Elementary	Tab D
Location Map	Tab E
Florida Inventory of School Houses FISH Plan Florida Inventory of School Houses Inventory Reports	Tab F
Florida DOE 2014 Cost of Construction Report	Tab G



Martin County School Board

District 1

Christia Li Roberts, Chair

District 2

Marsha Powers

District 3

Rebecca Negron

District 4

Tina McSoley

District 5

Michael DiTerlizzi, Vice Chair

Student Representative

Anna Ellis



Executive Summary

What follows is the Castaldi Analysis Report for the Martin County School District's (MCSD) Jensen Beach Elementary School (JBES).

The Castaldi analysis is based on information published by the Florida Department of Education (FLDOE) pertaining to school construction and project costs, data and a facilities assessment. The analysis presents the Castaldi Formula as accepted by FLDOE.

Jensen Beach Elementary School (JBES) began construction in 1970. It is located on 20 acres at 2525 Northeast Savanna Road, Jensen Beach, Martin County, Florida. All buildings are noted as satisfactory on FISH.

The buildings are:

Building 2, Administration, Classrooms, Offices, Cafeteria, Kitchen and Stage was built in 1970, some minor renovations have occurred that are not noted in the FISH Inventory and contains 65,747 sf.

Building 3, Primary Skills Lab, ESE Classrooms, Restrooms, Support Space and Office Space was built in 1980 and contains 3,141 sf. Currently only the Office space is being used.

Building 5, Music Classroom, Teacher's Planning, Storage, Staff Restrooms and Support Spaces was built in 1980 and contains 2,217 sf.

Building 6, Covered Play Area, PE Storage, Restrooms and Support Space was built in 1993 and contains 9,561 sf.

Building 9, Primary Classrooms, ESE Lockers and Showers, Student Restrooms, Student Storage and Support Spaces was built in 1987 and contains 19,802 sf.

Building 99, Two Units of Portable Classrooms, built in 2005 and contains 1,728 sf.

Building 9902, A Portable Classroom was built in 2004 and contains 764 sf.

The current FLDOE established costs per square foot for renovation, remodeling and new construction are based on the maximum allowed cost per student station for January 2013, Section 1013.64(6)(b)1, Florida Statutes and are as follows for an high school:

Cost of Renovation based on FDOE data is \$45/GSF

Cost of Remodeling based on FDOE data is \$68/GSF

Cost of Replacement based on FDOE data is \$136/GSF

In the Castaldi analysis, if the left side of the equation, cost of remodeling or renovating, shows a larger amount, the replacement of the facility is warranted and will be more cost effective than the renovation/remodeling of the existing building(s).

It would be beneficial to the MCSD to provide their educational programs in the most compact and efficient facility designed to function according to current Florida Department of Education (FLDOE) and

MCSD educational standards and design criteria, ADA requirements and the most current Florida Building Code Requirements. The buildings being considered for razing are beyond their useful life, are deficient



Executive Summary


with regard to current ADA and Florida Building Code requirements and are undersized for the programmatic needs and requirements. (See Castaldi Analysis). They both would require additional square footage to conform to the most current MCSD Educational Plant Survey Facilities List.

The review and analysis of the existing construction of the facility was tested against the Castaldi Formula and takes into consideration the educational, health, aesthetic, life safety and building improvements of educational facility design. Based on the information included in this report and the expressed needs of the Martin County School District, we recommend the following:

Buildings 2, 3 and 5 are recommended to be demolished and replaced with a new facility that would serve the current student capacity and same demographics as is reported in the 01 10 18 FISH Inventory Report.

From our review and analysis the best course of action is to modernize the facility by replacement of these buildings to meet the requirements and standards noted above. Our recommendation is to replace Buildings 2, 3 and 5 with a state of art new facilities. This path would be the most prudent and cost effective way to address the deficiencies with regard to Life Safety, Life Cycle Costs, Education Adequacy, and Health requirements. The recommended improvements would create a facility that provides the students, faculty, administration and staff with a state of the art modernized that would meet State Requirements for Educational Facilities (SREF), current FLDOE Guidelines, current Life Safety requirements, ADA requirements, Florida Building Code requirements and current Martin County School District Design Criteria and Standards.

Respectfully,


Mark Clary, Senior Project Manager
Song + Associates, Inc.
(561) 655-2423 Email: mclary@songandassociates.com

1.1 Campus Overview

Jensen Beach Elementary School (JBES) is one of 12 elementary schools that are part of the Martin County School District (MCSD). The JBES campus is located on 20 acres at 2525 Savanna Road, Jensen Beach, Florida. Its primary use is as an elementary high school serving Pre K through 5. As reported in the Facility Inventory Report (FISH), dated 09. 15. 16, its School Capacity is 722 students and its Year Round Capacity is 866 students. The Utilization Factor is 1.0% and all buildings are listed to be in satisfactory condition.



Aerial of JBES

Community Significance

JBES is located in Jensen Beach, Florida, a small community located on the east coast in a small town settled in the 19th century. It was named for John Laurence Jensen, originally from Denmark, arrived in 1881 and began a pineapple plantation. By 1895 Jensen Beach was known as the pineapple “Capital of the World”. The pineapple legacy is still celebrated during the Jensen Beach Pineapple Festival.

Jensen Beach is also known for their beaches and being a location for several species of turtles to nest.

2.0 Campus Design

The site of the campus is well maintained and is surrounded by suburban neighborhoods, a post office and a church.

Vehicles access the site heading north or south on NE Savanna Road, then turning right (east) into a single point entry. To the north is staff parking and to the south is visitor parking. A community playground is located to the east of the staff parking. East of the visitor parking are Buildings 2, 3 and 5, which are all under a single standing seam metal roof. Buildings 2, 3 and 5 are interconnected by exterior and interior corridors. As a result of the plan has many of the interior rooms do not have access to natural light. In many recent studies have demonstrated the need to increase natural light in classrooms. One study stated that one of the simplest ways to improve test scores is to increase natural light.



Building 2 includes Administration Offices, Offices, Conference Rooms, the Kitchen and Cafeteria with a Stage, various types of Classrooms, various types of Labs, Restrooms, Storage and Supports Spaces.

Building 3 includes Primary Skills Lab, ESE Classrooms, Restrooms, Support Space and Office Space.

Building 5 includes the Music Classroom, Teacher's Planning, Storage, Staff Restrooms and Support Spaces.

Building 6 is a Covered Play Area with PE Storage, Restrooms and Support Space.

Building 9 includes Primary Classrooms, ESE Lockers and Showers, Student Restrooms, Student Storage and Support Spaces.

Building 99 includes two units of Portable Classrooms.

Building 9902 is a Portable Classroom.

Site Recommendations:

1. Provide a new facility design were all rooms that are occupied have access to natural light.
2. New LED light fixtures for parking and exterior of buildings
3. Repair and replace underground storm sewer.
4. Landscaping for court yards to provide shaded areas for study.
5. Improve all covered walkways to provide ADA Compliance.

2.1 Buildings 2, 3 and 5

Building 2 houses Administration Offices, Offices, Conference Rooms, the Kitchen and Cafeteria with a Stage, various types of Classrooms, various types of Labs, Restrooms, Storage and Supports Spaces. Building 3 includes Primary Skills Lab, ESE Classrooms, Restrooms, Support Space and Office Space. Building 5 includes the Music Classroom, Teacher's Planning, Storage, Staff Restrooms and Support Spaces.

The existing structural system for these buildings is includes a steel roof deck mechanically fastened to steel joists and bearing on a concrete tie beam and steel angles. The joists are embedded and bear on the tie bear, which bears on the 8" concrete masonry units (CMU). All of the CMU walls bear on concrete footings with steel reinforcing. The foundation wall is CMU. All areas have a 4" concrete slab with woven wire mesh.

The buildings are one story with joist bearing on the exterior and some interior CMU walls is at approximately 11'-0" above the finish floor. The joist bearing for the corridors is approximately 8'-8" above the finished floor. The joists do not appear to be braced laterally and would not meet current codes. The existing wall construction included two types of wall partitions, exterior and interior 8" CMU and interior gypsum wall board (GWB) over 3 5/8" or 6" steel studs. The interior of the CMU has GWB mechanically fastened to 2x4 wood blocking mechanically fastened to the CMU. The exterior wall finish is stucco.

During the onsite review of the existing roof, which is a standing seam metal roof, the Head of Operations informed the site review team that this metal roof was "recently installed", but he was uncertain of the date of its installation. No as built for this roof replacement were available. The Director of Facilities provided additional information that clarified the at that time the roof wasn't replaced, but was coated with a Tremco product to prevent water infiltration. As built were available for one of the renovations where the original existing roof is noted and graphically represented as a built up roof over rigid insulation over metal roof deck. During this renovation, over a new addition, the roof construction consists of a built up roof over 4" of light weight concrete over a steel deck. These drawings were dated November, 1979. In another set

of as built, dated October 26, 1993, over an addition the roof is noted and graphically represented as a, "Butler CMR 24 Metal Roof Assembly." These drawings also contain notes that the metal roof over the addition is to match the existing Butler roof. So the metal roof was installed over the built up roof some time before 1993. The metal roof has a white finish that appears to be failing, the coating is turning to a powder like substance. The metal was installed over a modified roof creating an interstitial space that does not have fire protection sprinklers, which are required by current building code.

Only a few rooms have exposed ceilings where the metal deck could be reviewed without destructive investigation. In the rooms with exposed ceiling some minor corrosion and signs of water infiltration were observed. The steel joists also had signs of minor corrosion along the top cord.

Building 2, 3 and 5's roofing system does not meet current Energy Code requirements and current Florida Building Code (FBC), given its age. The existing steel deck would not meet the 2017 edition of the FBC. The lower roofs located at the perimeter of these buildings would also have to be replaced. The roofs do not meet current FBC wind load requirements.

The roofing system, as was noted earlier, for these buildings covers 3 buildings; Building 2, Building 3 and Building 5. All roof areas are sloped to the perimeter 1/2" per foot. All the roof areas have a roof ridge that divides each roof area down the middle and have the same slope on both sides. The storm drainage is handled by metal gutters and metal downspouts. Some, but not all of the downspouts are connected to an underground storm sewer system. Many of the downspouts drain directly on sidewalks and paved areas.



Aerial of JBES Roofs



Buildings 2, 3 & 5 Looking East



Buildings 2, 3 & 5 Looking West



Buildings 2, 3 & 5 Looking Northeast



Buildings 2, 3 & 5 Looking Southeast



Buildings 2, 3 & 5 Looking Northwest



Buildings 2, 3 & 5 Looking West



Buildings 2, 3 & 5 Finish Failing



Buildings 2, 3 & 5 Looking West



Buildings 2, 3 & 5 Slash Block at HVAC Unit



Buildings 2, 3 & 5 Top of Hood Missing

Asbestos may be present in the metal roofing system given that it was installed prior to Asbestos is probably present in the insulation and sealants, which is typical for roof construction at the time this campus was constructed and requires abatement. (Destructive testing on roofs to determine material content is not performed until the roof is removed for re-roofing or demolition.) Refer to Attachment 1 for Asbestos Report.

Entry to Administration



The exterior doors, door frames and windows show wear and corrosion. They do not meet current Energy Code requirements nor do they meet the current wind pressure requirements from the 2017 Florida Building Code.

The doors and windows should be replaced. None of the facility was constructed to current wind codes. Especially vulnerable are those parts of the buildings structure around fenestrations. The exterior should have subsurface investigation to determine if reinforcing is required to meet current wind load requirements. Although the exterior of the building do not meet current FBC requirements and must be "hardened".



Buildings 2, 3 & 5 Existing Window Does Not Meet FBC Pressure Requirements




Buildings 2, 3 & 5 Door and Hardware Not ADA Compliant

The door hardware for both exterior and interior doors is not ADA compliant and needs to be brought up to current requirements. This includes levers, hinges, strikes, closers, thresholds, panic hardware and weather proofing. The exterior and interior doors, door frames and interior view panels show wear and the finishes are worn and faded.



Buildings 2, 3 & 5 Door and Hardware Not ADA Compliant



Buildings 2, 3 & 5 Door and Hardware Not ADA Compliant and is Corroded

Storage is inadequate in all areas of Buildings 2, 3 and 5.

In general, the existing finishes are faded and decaying. The exterior wall finish is painted stucco over CMU and requires patching all most surfaces. All exterior walls require painting.

The interior wall construction includes 5/8" GWB on both sides of steel stud framing or CMU. All interior walls require painting.

The restrooms have ceramic tile finish on the walls and is faded and requires replacement.

4" resilient base is installed in most rooms, the kitchen has quarry tile base and restrooms have ceramic base. Where the rubber base is installed the adhesive has begun to fail and base has become separated from the wall surface. In the men's room, the rooms have a persistent background odor of urine, probably originating in the grout.

Three types of floor finishes are included in the buildings; quarry tile, ceramic tile, Vinyl Composition tile and concrete. All worn and faded and require replacement.

The concrete sidewalks connected with Buildings 2, 3 and 5 need some minor repair. In several place downspout drain directly on them.



Storm Drainage Not Tied in to the Underground Storm Sewer System

HVAC for Campus

HVAC system operates primarily on a chilled water loop. Chilled water is generated by two 170-ton air-cooled chillers manufactured by Trane. Chillers use refrigerant R-134A, which is still in wide use today and faces no significant legal sanctions. Years of chiller manufacture: 2005 and 2012. Centrifugal chillers are generally regarded as having a 25 year service life, leaving these chillers with 12 and 19 years of life respectively. Chiller operational noise is quite loud and affects instruction conducted on nearby exterior athletic area.



Degraded Insulation



Chilled water loop uses a primary / secondary pumping configuration. Chilled water pumps show surface age and corrosion but otherwise meet modern efficiency standards and likely still have ten years of service life remaining. Exterior chilled water insulation is severely degraded and must be replaced.

Building HVAC uses an antiquated pneumatic control system. System would need to be replaced with modern BACNet architecture as part of any upgrade. PC-based energy management software permits oversight of component status but provides limited to no ability to change set point or schedule operation.

Interior air conditioning is accomplished by modular chilled water air handling units in mechanical rooms and above-ceiling fan

coil units. Modular air handling units are at or near the end of their median 20-year service lifetimes. Above-ceiling fan coil units appear to be beyond their useful service lifetimes.

Air conditioning is supplemented in several areas by stand-alone direct-expansion equipment for areas such as the kitchen (both for occupants and commercial refrigeration). Systems are in good condition and serviceable but should be replaced with new (for commercial refrigeration) or chilled water (for occupant cooling) as part of any substantial facility renovation. The air-cooled chillers are in excellent shape and have substantial service life remaining. They could be saved and re-used as part of any potential facility HVAC upgrade, though an improved acoustical enclosure would likely be advised. Other system components such as pumps, chilled water insulation, control system, chilled water AC and direct-expansion AC are either severely degraded, at the end of their useful service lives, or otherwise would play no role in a modern, code-compliant AC system.

Items of note:

- Kitchen occupant cooling direct-expansion AC is new within the last two years and could be relocated to another facility owned by the Martin Co. School District.
- Kitchen exhaust fan for the dishwasher was damaged during Hurricane Irma and is currently out of service. This is likely forcing the direct-expansion AC to work harder than intended.
- Hurricane Irma destroyed the weather cover for air intake associated (it seems) with AHU-8.



Weather Cover Removed by Irma



Rainwater is likely flowing freely into the unit and draining out via the condensate drain. Unit mixing box access door would not open. Interior condition could not be assessed.

- Numerous exhaust fans are not currently working due to an electrical power problem. This is likely compromising indoor air quality.
- The classrooms in Building 5 were subdivided from what was originally a larger contiguous space. Occupants report air pressure problems, suggesting a proper return air pathway was not maintained.
- Occupants report condensation on interior walls during some parts of the season.

Fire Suppression System:

The campus has a partial fire suppression system in the auditorium stage area, the kitchen hood and one piece of cooking equipment located within the footprint of the hood.

- Per the Florida Building Code (2017) the campus falls under Educational Group E.
 - 3. Group E - An *automatic sprinkler system* shall be provided for Group E occupancies as follows:
 - Throughout all Group E *fire areas* greater than 12,000 square feet (1115 m²) in area.
 - Throughout every portion of educational buildings below the lowest *level of exit discharge* serving that portion of the building.
Exception: An *automatic sprinkler system* is not required in existing educational buildings unless 50 percent of the aggregate area of the building is being remodeled.
- NFPA 13 (2013) categorizes Education as Light Hazard, defined as occupancies or portions of other occupancies where combustibility is low, quantity of combustibles is moderate, stockpiles of combustibles do not exceed 8 ft., and fires with moderate rates of heat release are expected.
- Protective cover on sprinkler head needs to be re-installed and avoid high storage.



Domestic Service Water Heating System:

The campus is served by series of electric water heaters located throughout the campus for service to the associated area. The Median Service Life of an electric water heater is approximately 13 years.

- The age of the water heater(s) varies, one made in 2005 (13 years old), one made in 2012 (6 years old), another about the same time. As water heaters age, their efficiency decreases.
- The majority of the visible hot water piping was not insulated, which is a loss of energy and does not meet the current Florida Energy requirements.

- The water heaters are not piped according to the current plumbing code requirements (see 2017 FPC, sections 502, 503, 504 and, section 607).
- Hot water recirculating system piping does not exist and therefore does not meet the plumbing code requirements, where applicable. (See 2017 FPC section 607.2).



Photo 3
 Electric water heater in room 148.



Photo 6 - Electric water heater in room 3

Plumbing system:

The visible plumbing systems reflects the age of the building and are in need of replacement or remodel. Areas that have been impacted are the sanitary system and the storm system.

- Plumbing fixtures are older and not up to current water efficiency standards, per FPC 604.4 “The maximum water consumption flow rates and quantities for all plumbing fixtures and fixture fittings shall be in accordance with Table 604.4.”

TABLE 604.4
 MAXIMUM FLOW RATES AND CONSUMPTION FOR
 PLUMBING FIXTURES AND FIXTURE FITTINGS

PLUMBING FIXTURE OR FIXTURE FITTING	MAXIMUM FLOW RATE OR QUANTITY ^a
Lavatory, private	2.2 gpm at 60 psi
Lavatory, public (metering)	0.25 gallon per metering cycle
Lavatory, public (other than metering)	0.5 gpm at 60 psi
Shower head ^a	2.5 gpm at 80 psi
Sink faucet	2.2 gpm at 60 psi
Urinal	1.0 gallon per flushing cycle
Water closet	1.6 gallons per flushing cycle

- Kitchen – Some of the sanitary connection points are not up to code standards. See State of Florida Department of Health Chapter 64E-11 Food Hygiene.
- Grease interceptor – The grease interceptor could not be located and is a required item. It must be installed per the State of Florida Department of Health Chapter 64E-6 Standards for Onsite Sewage Treatment and Disposal System.

Electrical for Campus

Interior lighting - 2' by 4' fluorescent lighting mainly. Look in good shape. Stage had incandescent high hats and track lighting. Bulbs could be changed out for energy savings. This will require lighting to be brought up to current code. Daylight harvesting, 50% receptacle controls in all offices, open offices and computer classrooms. This will require new light fixture that are capable of dimming.



Exterior Lighting Needed

hazard. Broken pipe with exposed wiring was observed from the roof. Recommend updating to led lighting in the parking lot for energy cost saving and ease of maintenance.

Emergency generator 40KW Winco generator. Looks to be at end of life. Recommend replacement. **Fire Alarm for Campus**

Fire Alarm Panel appears to have been replaced in last 2 years. Device appear to be mixed with older

Exterior lighting – Site lights in parking lot and over the cover playground area with Metal halide or High pressure sodium, recommend replacement site lighting looked dated with LED. Exterior wall mounted lights on building face are low hung. Building Engineer reported this is issue for vandals. One exterior corridor has no lighting and this creates a safety



Exterior Lighting Accessible to Vandals



and newer devices (mainly newer looking). Recommend replacement of older fire alarm devices.

Power Distribution - Panels mixed between Eaton, Culter Hammer, Westinghouse, Federal Pacific, Gould, and Square D. Panels are in rough shape, with rust, latches not latching. Recommend new electrical grid replacement with one vendor for ease of maintenance. All panels look to be fair to poor shape and at end of life. Exposed power distribution wiring was observed above the ceiling.



Exposed Wiring above Ceiling



Furniture, Fixtures and Equipment

The furniture and the equipment in most areas need to be brought up to current MCSD Furniture standards. In most areas the furniture is ad hoc and damaged.

ADA Compliance

ADA Requirements for Buildings 2, 3 and 5:

1. Provide ADA compliant restrooms and drinking fountains as required.
2. Provide ADA compliant accessible loading zones and routes with from parking.
3. Provide ADA compliant doors and hardware.

The design and construction of this project shall comply with the following codes and standards.

1. FBC (Florida Building Code), 2017 Edition 6, Including:
 - a. FBC (Florida Existing Construction Building Code)
 - b. FBC Energy Conservation
 - c. FBC Mechanical
 - d. FBC Plumbing
 - e. FBC Fuel Gas
 - f. NEC (National Electric Code) 2002; FBC Charter 27
 - g. FBC Florida Accessibility Code for Building Construction
 - h. FBC References, Chapter 35
 - i. Florida Fire Prevention Code, FAC 69A-60, including:
 - ii. NFPA 1-2004 with adopted revisions
 - iii. NFPA 101-2004 with adopted revisions
 - iv. NFPA Codes listed in FAC 69A-.005
 - v. NFPA 45-00: Instructional Laboratories
 - vi. NFPA 88B-97: Repair Garages, (Auto Lab)
 - vii. Fire Safety in Existing Educational Facilities, FAC 69A-58
 - i. State Requirements for Educational Facilities (SREF)
 - j. ASCE 7-98: American Society of Civil Engineers
 - k. UL Fire Resistance Directory

Recommendations:

We recommend that Buildings 2, 3 and 5 be demolished and replaced. Application of the Castaldi Formula for Modernization supports this recommendation. The items below are the specifics that would define the scope that should would need to be included if the building was to be renovated or remodeled.

- a. Remove and replace the exterior lighting installed in the covered walkway and the lighting on the exterior building to meet current Energy Code requirements
- b. Perform an asbestos abatement.
- c. Remove lead paint.
- d. Upgrade the building so that it is in compliant with the Florida Building Code and Fire Prevention requirements. Installation of Fire Protection Sprinklers is recommended.
- e. Remove and replace all existing exterior and interior doors, door hardware and windows.
- f. Harden all fenestrations to receive the load from the wind resistant windows.
- g. Bring all required fixtures and Restrooms into compliance with ADA requirements.
- h. All room finishes need to be refreshed.
- i. Remove and Replace the air handling unit with equipment that meets current codes.
- j. Remove and replace all plumbing fixtures.
- k. Provide a fire protection system integrated with the fire alarm system that will be installed in the near future.
- l. Provide and install an Energy Management System. It would improve efficiency and increase cost savings.

- m. Provide and install new power systems, such as electric panels.
- n. Provide and install new exterior LED lighting for the building and covered walkway.
- o. Provide and install new interior LED lighting where required.
- p. Upgrade the existing IT system. Upgrade the existing telephone system.
- q. Provide and install a new public address system.

2.2 Building 6 Covered Play Area

Included in this building is a covered play area. PE storage, mechanical room and male and female restrooms are located to the southwest. As noted in the 09 15 16 FISH Report, it was built in 1993, is one story and contains approximately 9,561 sf.



The existing structural system for this building is made of a steel roof deck mechanically fastened to steel trusses and bearing on steel beams and steel angles. Which bear on concrete columns. The columns bear on concrete footing. All areas have a 4" painted concrete slab with woven wire mesh.

It is uncertain what the uplift loads are for this building as no as built drawings were available

The buildings are one story with


Buildings 6 Looking East Damaged from Hurricane

joist bearing at approximately 15'-0" above the finished floor. The trusses do not appear to be braced laterally and would not meet current codes. There are no walls exterior walls and the concrete columns are painted.

During the onsite review of the existing roof, is a mansard roof with a barrel vault is in extremely poor condition. No as built for this roof replacement were available, but the FISH report note it's date of construction to 1993. The roof in all areas appears to be failing.



Buildings 6 Looking East and North Damaged from Hurricane



Buildings 6 Looking West and South Damaged from Hurricane

Building 6's roofing system does not meet current Energy Code requirements and current Florida Building Code (FBC), given its age. The existing deck would not meet the 2017 edition of the FBC. The roof would also not meet FBC current wind load requirements.

The roofing system for all roof areas are sloped to the perimeter. The storm water sheet drains around the perimeter and are not connected to an underground storm sewer system.

This roof would not meet current wind pressure and current code requirements.

Furniture, Fixtures and Equipment

1. The equipment in the cover play area requires to be brought up to current MCSD Furniture standards.

ADA Compliance

ADA Requirements for Building 6:

1. Provide ADA compliant Restrooms and Drinking Fountains.
2. Provide ADA compliant accessible loading zones and routes with from parking.
3. Provide ADA compliant doors and hardware.

The design and construction of this project shall comply with the following codes and standards.

2. FBC (Florida Building Code), 2017 Edition 6, Including:
 - I. FBC (Florida Existing Construction Building Code)
 - m. FBC Energy Conservation
 - n. FBC Mechanical
 - o. FBC Plumbing
 - p. FBC Fuel Gas
 - q. NEC (National Electric Code) 2002; FBC Charter 27
 - r. FBC Florida Accessibility Code for Building Construction
 - s. FBC References, Chapter 35
 - viii. Florida Fire Prevention Code, FAC 69A-60, including:
 - ix. NFPA 1-2004 with adopted revisions
 - x. NFPA 101-2004 with adopted revisions
 - xi. NFPA Codes listed in FAC 69A-.005
 - xii. NFPA 45-00: Instructional Laboratories



- xiii. NFPA 88B-97: Repair Garages, (Auto Lab)
- xiv. Fire Safety in Existing Educational Facilities, FAC 69A-58
- t. State Requirements for Educational Facilities (SREF)
- u. ASCE 7-98: American Society of Civil Engineers
- v. UL Fire Resistance Directory

Recommendations:

We recommend that Building 6, the Cover Play Area be demolished and replaced. The application of the Castaldi Formula for Modernization does not work for building with minimal construction like Building 6. The items below are the specifics that would define the scope that should would need to be included if the building was to be renovated or remodeled.

- a. Field test roofing for asbestos, moisture, structural integrity to determine if a re-roof or removal and replacement of existing roofing system is required. Also to determine if the roof deck is required to be removed and replaced. Reroof as required.
- b. Remove and replace the exterior and lighting under the covered area with lighting that meets current Energy Code requirements
- c. Perform an asbestos testing and abate if required.
- d. Upgrade the building so that it is in compliant with the Florida Building Code and Fire Prevention requirements
- e. Remove and replace all existing exterior and interior doors, door hardware and windows. Harden all fenestrations to receive the load from the wind resistant windows.
- f. Bring all required fixtures and Restrooms into compliance with ADA requirements.
- g. All finishes need to be refreshed.
- h. Remove and replace all plumbing fixtures.
- i. Provide a fire protection system integrated with the fire alarm system that will be installed in the near future.
- j. Provide and install an Energy Management System. It would improve efficiency and increase cost savings for enclosed areas.
- k. Provide and install new power systems, such as electric panels.
- l. Provide and install new exterior LED lighting for the building and covered walkway.
- m. Provide and install new interior LED lighting where required.
- n. Upgrade the existing IT system. Upgrade the existing telephone system.
- o. Provide and install a new public address system.

2.3 Buildings 9

Building 9 houses Primary Classrooms, ESE Lockers and Showers, Student Restrooms, Student Storage and Support Spaces was built in 1987 and contains 19,802 sf.

The existing structural system for this building consists of a steel roof deck mechanically fastened to steel joists and bearing on a concrete tie beam and steel angles. The joists are embedded and bear on the tie bear, which bears on the 8" concrete masonry units (CMU). All of the CMU wall bear on concrete footings with steel reinforcing. There is no foundation wall. All areas have a 4" concrete slab with woven wire mesh.

The building is one story with joist bearing on the exterior walls and some interior CMU walls is at approximately 11'-0" above the finish floor. The joists do not appear to be braced laterally and would not meet current codes. The existing wall construction included two types of wall partitions, exterior and interior 8" CMU and interior gypsum wall board (GWB) over 3 5/8" or 6" steel studs. The interior of the CMU has GWB mechanically fastened to 2x4 wood blocking mechanically fastened to the CMU. The walls exterior wall finish is stucco.

No as built for this roofing system were available, but from observation the existing roof appears to be a built up roof and under that it is very likely that the construction is similar to the original

roofs under the metal roof over Buildings 2, 3 and 5. Which is built up roof over rigid insulation over metal roof deck. The roof on Building 6 has never been replaced or recovered.

In rooms with exposed ceilings, where the metal deck could reviewed without destructive investigation. Some minor corrosion and signs of water infiltration were observed. The steel joists also had signs of minor corrosion along the top cord.

Building 9's roofing system does not meet current Energy Code requirements and current Florida Building Code (FBC). The existing steel deck would not meet the 2017 edition of the FBC. The roof would also not meet FBC current wind load requirements.



Aerial of JBES Roofs

All roof areas are sloped to the perimeter 1/4" per foot. The roof has a ridge that divides each roof area down the middle running east to west with hip like construction on the east and west ends. The storm drainage is handled by metal gutters and metal downspouts. The downspouts are connected to an underground storm sewer system.



Building 9 Looking East



Building 9 Looking South



Building 9 Looking South



Building 9 Looking Southwest

Asbestos testing on roofs is recommended in order to determine material content of the roofing system. Refer to Attachment 1 for Asbestos Report.

The doors and windows should be replaced. None of the facility was constructed to current wind codes. Especially vulnerable are those parts of the buildings structure around fenestrations. The exterior should have subsurface investigation to determine if reinforcing is required to meet current wind load requirements. Although the exterior of the building finishes refreshing and they would not meet the current FBC requirements and must be “hardened”.



Building 9 Windows & Doors Does Not Meet Current FBC and ADA Requirements

The door hardware for both exterior and interior doors is not ADA compliant and needs to be brought up to current requirements. This includes levers, hinges, strikes, closers, thresholds, panic hardware and weather proofing.

The exterior and interior doors, door frames and interior view panels show wear and the finishes are worn and faded.

Storage is inadequate in all areas of Building 6.

In general, the existing finishes are faded and decaying.

The exterior wall finish is painted stucco over CMU and requires patching all most surfaces. All exterior walls require painting.

The interior wall construction includes 5/8" GWB on both sides of steel stud framing or CMU. All interior walls require painting.

The restrooms have ceramic tile finish on the walls and is faded and requires replacement.

4" resilient base is installed in most rooms, the kitchen has quarry tile base and restrooms have ceramic base. Where the rubber base is installed the adhesive has begun to fail and base has become separated from the wall surface. In the men's room, the rooms have a persistent background odor of urine, probably originating in the grout.

Three types of floor finishes are included in the buildings; quarry tile, ceramic tile, Vinyl Composition tile and concrete. All worn and faded and require replacement.

The concrete sidewalks connected with Buildings 2, 3 and 5 need some minor repair. In several place downspout drain directly on them.

**4. Buildings 99 and 9902 Portable Classrooms
Recommendations:**

1. The portable classrooms appear to need to be removed from campus and replaced with new classrooms in a new facility.



Buildings 99 and 9902 Do Not Meet Current FBC Wind Pressure and ADA Requirements and are in an Extreme Disrepair

5. Lightning Protection

The campus currently does not have lightning protection.

Recommendations:

1. We recommend that the UL Master Label lightning protection system be provided and installed on the campus that is compliant with NFPA 780.
1. **Proposed Use, Student Population and Scope of Replacement /Renovation**
 1. The proposed use or program would remain the same as is currently designated. The demographics indicate growth in several of the neighborhoods that the school serves.
1. **Funding**
To be determined
2. **Equipment Costs**
To be determined



**Office of Educational Facilities
Florida Department of
Education**

**Room Condition Change
Building Replacement/Raze**

District: Martin County School District
Contact Person: Garrett Grabowski

Phone: 772-223-3105 ext. 130

Facility/Campus Name: Jensen Beach ES
Facility Number (school districts only): 14-A

Building Number(s): 2, 3, 5, 6 and 9

Parcel/Site Number(s): 15

This Proposed Project will:

- Change the condition of permanent rooms from satisfactory to unsatisfactory (if yes, go to Section I and complete certification in Section III). (Not applicable to community colleges)
- Change the condition of permanent rooms from unsatisfactory to satisfactory (if yes, go to Section I and complete certification in Section III). (Not applicable to community colleges)
- Raze permanent building(s) (if yes, go to Section II and complete certification in Section III).
- Replace permanent building(s) (if yes, go to Section II and complete certification in Section III).
Major Capital Outlay Funding Source(s) – Original Building
Major Capital Outlay Funding Source(s) – Replacement Building

This form is not required for razing a single, freestanding structure that is less than 750 NSF and is debt free, or multiple small structures on a single campus whose total area is less than 750 NSF and are debt free. This form must be completed for any structure 750 NSF or greater and any structure, regardless of size, that is not debt free.

A. DISTRICT/COMMUNITY COLLEGE CERTIFICATION

The district/community college must submit this certification document, completed and signed by the appropriate school officials, along with all required or necessary supporting documentation pertaining to the proposed project.

The Palm Beach County District School Board hereby certifies that:

I. CONDITION CHANGE: (Not applicable to community colleges)

1. All room condition changes are consistent with State Requirements for Educational Facilities (SREF) standards and the Florida Fire Prevention Code (FFPC) requirements for the condition of space.

II. RAZE/REPLACE PERMANENT BUILDING(S):

1. All fund sources have been researched and no current indebtedness or outstanding debt exists for the building(s) that will be razed and/or replaced.
2. Funding Source(s):
 - a. Original Building: Unknown

- b. If Replaced: To Be Determined
- 3. Voters of the district have approved local bonding for the project: Yes/No
 - a. Date of voter approval: _____
- 4. Imminent danger exists for the building(s) that will be razed and/or replaced.

III. CERTIFICATION SIGNATURES:

 Garrett Grabowski
 Facilities Director

 Date

 Laurie G. Gaylord
 Superintendent

 Date

 Christia Li Roberts
 Board Chair

 Date

NOTE: Certification is required by the Superintendent and Director of Facilities Planning for room condition changes. Certification is required by the Superintendent/President and Board Chair to raze or replace permanent buildings.

Submit signed form and supporting documents to:
Office of Educational Facilities, Room 1054
Florida Department of Education
325 West Gaines Street
Tallahassee, Florida 32399-0400

Procedures and Processes Instructions:

B. CONDITION CHANGE (Not applicable to community colleges)

1. **RATIONALE** (provide the following information, as appropriate, to justify changing the condition of spaces):
 - i. In order to change the space condition from satisfactory to unsatisfactory the district must certify that the space is no longer physically safe or suitable for occupancy:
 1. Unsatisfactory space is typically designated as such due to compromising effects on the structural integrity, safety, or excessive physical deterioration of a building.
 2. Typically, space condition should be the same, either satisfactory or unsatisfactory, for all rooms in a permanent building.
 3. Space that has been determined to be unsatisfactory should not be occupied.
 4. Application of a facility replacement formula, such as the Castaldi generalized formula for modernization or other similar facilities study, does not necessarily mean that the condition of the identified spaces is unsatisfactory. The condition code cannot be changed simply due to the results of a planned replacement unless the integrity of the space meets the criteria identified to classify the space as unsatisfactory.
 - ii. In order to change the space condition from unsatisfactory to satisfactory the district must certify that the space has been successfully reconditioned to meet all applicable regulations regarding occupancy requirements.
1. **OEF Review:**
 - i. Site visit by OEF staff, when necessary.
 - ii. Concur with district rationale, data, and analyses:
 1. Building(s) approved as unsatisfactory; OEF will make the room condition code changes in FISH.
 2. Building(s) approved as satisfactory; OEF will make the room condition code changes in FISH.
 - iii. Disagree with district rationale, data, and analyses:
 1. Building(s) not approved as unsatisfactory.
 2. Building(s) not approved as satisfactory.
1. **OEF Notify District of Findings and Decision:**
 - i. OEF staff will analyze the district's data along with all supporting documentation, coordinate any further reviews with the district, make a final decision regarding the proposed room condition changes, and provide a timely response either approving or disapproving the proposed room condition changes.

C. RAZE/REPLACE PERMANENT BUILDING(S)

1. **RATIONALE** (provide the following information, as appropriate, to justify razing/replacing permanent buildings):
 - i. Detailed explanation of need for the proposed project and the expected benefit to the district/community college.
 - ii. General scope of the proposed project.
 - iii. Building age and year of construction.
 - iv. Existing capacity of building(s), include the number of student stations, classrooms, and other instructional spaces.
 - v. Current number of students housed and the projected number of students to be housed in the affected building(s).
 - vi. Current educational plant survey recommendations and capacity.
 - vii. What alternatives have been considered besides razing/replacement and why are the alternatives not feasible?
 - viii. School board/community college board approval of the concept of razing/replacing permanent buildings.
 - ix. Building condition/engineer study (optional).
 - x. Impact if the proposed project is not approved.

- xi. Other relevant data; identify any major systems (include date, if applicable) that have been replaced or upgraded, e.g., electrical, HVAC, fire alarm, roof, plumbing, drainage, etc. Provide a general scope of work for any previous remodeling, renovation, and addition, and year completed.
2. COST ANALYSIS (Building by Building):
- i. Castaldi Analysis (or other cost analysis formula to support the proposed project).
 - ii. The following five questions must be addressed:
 - 1. How many years will modernization extend the useful life of the modernized building(s)?
 - 2. Does the existing building(s) lend itself to improvement, alteration, remodeling, and expansion? If no, explain why not.
 - 3. Explain how a modernized and a replacement building(s) fits into a well-conceived long-range plan of the district/community college?
 - 4. What is the percentage derived by dividing the cost for modernization by the cost for a replacement building?
 - 5. A committee of district officials and independent citizens from outside the school attendance zone has determined that the replacement of the building(s) is financially justified and no other alternative is feasible? (Not applicable to community colleges)
 - i. Detailed scope of work for modernization of the existing building(s).
 - ii. FISH building plan and/or schematic drawings of the existing building with FISH room numbers.
2. OEF Review:
- i. Site visit by OEF staff, when necessary.
 - ii. Educational adequacy review.
 - iii. Concur with district/community college rationale, data, and analyses:
 - 3. Recommend replacement of building(s).
 - 4. Recommend razing building(s).
 - ii. Disagree with district/community college rationale, data, and analyses:
 - 4. Building(s) not approved to be replaced.
 - 5. Building(s) not approved to be razed.
4. OEF Notify District/Community College of Findings and Decision:
- i. OEF staff will analyze the district's/community college's data along with all supporting documentation, coordinate any further reviews with the district, make a final decision regarding the disposition of the proposed project, and provide a timely response either approving or disapproving the proposed request.

Jensen Beach Elementary School
Castaldi Analysis

Building 2

	Jensen Beach Elementary School	Castaldi Formula		Building 2
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1970		
	Year of Modernization	2020		
	Building Age	50 Years		
	Useful Life	15 Year		
	Building Area	65,747 SF		
	Additional Area	5,000		
	Renovation Area	65,747		
	Remodeling Area	65,747 SF		
	Total Area	70,747 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		<u>(CE+CH+CS) x 1.2</u>	VS	<u>R</u>
		LM x IA		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	70,747 sf x \$68 = \$4,470,796		
	Useful Life of Modernized Building	15		
	Educational Adequacy Index	0.75		
	Replacement Cost	70,747 sf x \$136/sf = \$9,621,592, + Demolish 65,747 sf x \$8.50 = \$558,850 Total = \$10,180,442		
	Estimated Life of New Building	65 Years		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		<u>\$4,470,796 x 1.2 = \$5,364,955</u>	VS	<u>\$10,180,442</u>
		15 x .75 = 11		65
	Results	\$357,664		\$146,161
	Percentage of Modernization to Replacement	40.86544913661980%	41%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			

Jensen Beach Elementary School
Castaldi Analysis

Building 3

	Jensen Beach Elementary School	Castaldi Formula		Building 3
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1980		
	Year of Modernization	2020		
	Building Age	40 Years		
	Useful Life	25 Year		
	Building Area	3,141 SF		
	Additional Area	0		
	Renovation Area	3,141		
	Remodeling Area	3,141 SF		
	Total Area	3,141 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		<u>(CE+CH+CS) x 1.2</u>	VS	<u>R</u>
		LM x IA		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	3,141 sf x \$68 = \$213,588		
	Useful Life of Modernized Building	25		
	Educational Adequacy Index	0.75		
	Replacement Cost	3,141 sf x \$136/sf = \$427,176 + Demolish 3,141 sf x \$8.50 = \$26,699 Total = \$453,875		
	Estimated Life of New Building	65 Years		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		<u>\$213,588 x 1.2 = \$256,306</u>	VS	<u>\$453,875</u>
		25 x .75 = 19		65
	Results	\$10,252		\$6,983
	Percentage of Modernization to Replacement	68.11353882169330%	68%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			

Jensen Beach Elementary School
Castaldi Analysis

Building 5

	Jensen Beach Elementary School	Castaldi Formula		Building 5
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1980		
	Year of Modernization	2020		
	Building Age	40 Years		
	Useful Life	25 Year		
	Building Area	2,217 SF		
	Additional Area	0		
	Renovation Area	2,217		
	Remodeling Area	2,217 SF		
	Total Area	2,217 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		$(CE+CH+CS) \times 1.2$	VS	R
		$LM \times IA$		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	$2,217 \text{ sf} \times \$68 = \$150,756$		
	Useful Life of Modernized Building	25		
	Educational Adequacy Index	0.75		
	Replacement Cost	$2,217 \text{ sf} \times \$136/\text{sf} = \$301,512 + \text{Demolish } 2,217 \text{ sf} \times \$8.50 = \$18,845 \text{ Total} = \$320,357$		
	Estimated Life of New Building	65 Years		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		$\$150,556 \times 1.2 = \$180,918$	VS	$\$320,356$
		$25 \times .75 = 19$		65
	Results	\$9,522		\$4,929
	Percentage of Modernization to Replacement	51.76433522369250%	68%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			

Jensen Beach Elementary School
Castaldi Analysis

Building 9

	Jensen Beach Elementary School	Castaldi Formula		Building 9
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	187		
	Year of Modernization	2020		
	Building Age	33 Years		
	Useful Life	32 Year		
	Building Area	19,802 SF		
	Additional Area	5,000		
	Renovation Area	19,802		
	Remodeling Area	19,802 SF		
	Total Area	24,802 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		<u>(CE+CH+CS) x 1.2</u>	VS	<u>R</u>
		LM x IA		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	24,802 sf x \$68 = \$1,686,536		
	Useful Life of Modernized Building	32		
	Educational Adequacy Index	0.75		
	Replacement Cost	24,802 sf x \$136/sf = \$3,373,072 + Demolish 24,802 sf x \$8.50 = \$210,817 Total = \$3,583,889		
	Estimated Life of New Building	65 Years		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		<u>\$1,686,536 x 1.2 = \$2,023,843</u>	VS	<u>\$3,583,889</u>
		32 x .75 = 24		65
	Results	\$84,327		\$55,137
	Percentage of Modernization to Replacement	65.38475221459320%	68%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			



Jensen Beach ES Facility Location



2525 NE Savannah Road
Jensen Beach, Florida 34957



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

ORGANIZATION: 43-MARTIN COUNTY SCHOOL DISTRICT
 FACILITY: JENSEN BEACH ELEMENTARY
 FACILITY USE: ALL

DISTRICT: 43 MARTIN COUNTY SCHOOL DISTRICT

FACILITY: 14-A JENSEN BEACH ELEMENTARY

Primary Use: ELEMENTARY Grades Housed: PK - 05 DOE Validation Date: Capital Outlay Classification: SCHOOL RECOMMENDED FOR CONTINUED USE

MASTER SCHOOL ID

MSID	Name	Status
211	JENSEN BEACH ELEMENTARY SCHOOL	Default

CAPITAL OUTLAY FTE

Year: 2015 / 2016							
PK:6.83	01:112.00	03:105.50	05:110.42	07:0.00	09:0.00	11:0.00	PK-12:633.23
KG:91.00	02:112.50	04:94.98	06:0.00	08:0.00	10:0.00	12:0.00	Adult:0.00
							Total:633.23

SCHOOL CAPACITY

SCHOOL CAPACITY	YEAR ROUND CAPACITY	UTILIZATION FACTOR	PRIMARY USE
722	866	1.00	ELEMENTARY



**FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT**

PARCEL: 15
2525 NE SAVANNA ROAD
JENSEN BEACH, FL 34957

Parking: DEVELOPED	Owner: SCHOOLBOARD	Fire: 7
Athletic: INCLUDED WITHSITE	Water: PUBLIC	Police: COUNTY
Sewage: PUBLIC	Plan: COMPACT	Drainage: ADEQUATE
Landscape: PARTIALLY DEVELOPED	Playground: INCLUDED WITHSITE	Acreage: 20.00
Date Acquired: 1/1/1967		Lease Expiration Date:

DISTRICT: 43 MARTIN COUNTY SCHOOL DISTRICT

FACILITY: 14-A JENSEN BEACH ELEMENTARY

BUILDING: 2 - Building Number 00002

Owner: SCHOOLBOARD	Light: ADEQUATE	Cooling: LOCALZONE
Use: ESEZONE	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1970	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: ZONE HOTAIR
Year Modified:	Educational TV: COMMERCIAL ANTENNA	Heat Capacity: ADEQUATE
Average Age NSF: 1985	Intercom: TWO WAY COMPLETE	Walls: STUCCO
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: DOUBLE INSIDE

ROOM	NET SQ FT	DESIG N COD E	DESCRIPTION	S T U S T A	FL R L O C	FLOORCOVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	560	334	CUSTODIAL EQUIPMENT STORAGE	0	01	CONCRETE	2010	SATISFACTORY	2	15	14
002	225	702	MECHANICAL ROOM	0	01	CONCRETE	1970	SATISFACTORY	2	15	14
003	236	332	CUSTODIAL WORK AREA	0	01	COMPOSITION TILE	1970	SATISFACTORY	2	15	14



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

003A	102	332	CUSTODIAL WORKAREA	0	01	COMPOSITIONTILE	1970	SATISFACTORY	2	15	14
003B	42	821	STAFF RESTROOM (BOTHSEXES)	0	01	QUARRYTILE	1970	SATISFACTORY	2	15	14
003C	95	332	CUSTODIAL WORKAREA	0	01	COMPOSITIONTILE	1981	SATISFACTORY	2	15	14
004	1242	346	KITCHEN FOODPREPARATION	0	01	QUARRYTILE	1970	SATISFACTORY	2	15	14
004A	48	821	STAFF RESTROOM (BOTHSEXES)	0	01	QUARRYTILE	1970	SATISFACTORY	2	15	14
004B	15	350	OTHER FOODSERVICE	0	01	QUARRYTILE	1970	SATISFACTORY	2	15	14
004C	294	342	KITCHEN DRYSTORAGE	0	01	QUARRYTILE	1970	SATISFACTORY	2	15	14
004D	22	331	CUSTODIAL SERVICECLOSET	0	01	CONCRETE	1970	SATISFACTORY	2	15	14
004E	120	350	OTHER FOODSERVICE	0	01	OTHER	1970	SATISFACTORY	2	15	14
004F	74	700	INSIDECIRCULATION	0	01	COMPOSITIONTILE	1970	SATISFACTORY	2	15	14
004G	134	343	KITCHENOFFICE	0	01	COMPOSITIONTILE	1970	SATISFACTORY	2	15	14
004H	94	350	OTHER FOODSERVICE	0	01	OTHER	2010	SATISFACTORY	2	15	14
004J	80	350	OTHER FOODSERVICE	0	01	OTHER	2010	SATISFACTORY	2	15	14
005	70	703	ELECTRICALROOM	0	01	CONCRETE	1970	SATISFACTORY	2	15	14
006	70	703	ELECTRICALROOM	0	01	CONCRETE	1970	SATISFACTORY	2	15	14
007	2700	340	DININGAREA	0	01	COMPOSITIONTILE	1970	SATISFACTORY	2	15	14
015A	164	815	STUDENT RESTROOM(MALE)	0	01	CERAMICTILE	1970	SATISFACTORY	2	15	14
015B	195	816	STUDENT RESTROOM(FEMALE)	0	01	CERAMICTILE	1970	SATISFACTORY	2	15	14
016A	166	815	STUDENT RESTROOM(MALE)	0	01	CERAMICTILE	2010	SATISFACTORY	2	15	14
016B	193	816	STUDENT RESTROOM(FEMALE)	0	01	CERAMICTILE	2010	SATISFACTORY	2	15	14
017	190	823	PUBLIC USE RESTROOM(FEMALE)	0	01	QUARRYTILE	1970	SATISFACTORY	2	15	14
017A	190	822	PUBLIC USE RESTROOM(MALE)	0	01	QUARRYTILE	1970	SATISFACTORY	2	15	14
018	88	703	ELECTRICALROOM	0	01	CONCRETE	1970	SATISFACTORY	2	15	14
019	1043	1	PRIMARY CLASSROOM(K-3)	18	01	CARPET	1970	SATISFACTORY	2	15	14



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

019A	80	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1970	SATISFACTORY	2	15	14
019B	20	813	STUDENT STORAGE	0	01	COMPOSITION TILE	1970	SATISFACTORY	2	15	14
019C	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	QUARRY TILE	1970	SATISFACTORY	2	15	14
020	1022	1	PRIMARY CLASSROOM(K-3)	18	01	CARPET	1970	SATISFACTORY	2	15	14
020A	75	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1970	SATISFACTORY	2	15	14
020B	20	813	STUDENT STORAGE	0	01	COMPOSITION TILE	1970	SATISFACTORY	2	15	14
020C	23	814	STUDENT RESTROOM (BOTHSEXES)	0	01	QUARRY TILE	1970	SATISFACTORY	2	15	14
021	1044	1	PRIMARY CLASSROOM(K-3)	18	01	CARPET	1970	SATISFACTORY	2	15	14
021A	77	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1970	SATISFACTORY	2	15	14
021B	20	813	STUDENT STORAGE	0	01	COMPOSITION TILE	1970	SATISFACTORY	2	15	14
021C	23	814	STUDENT RESTROOM (BOTHSEXES)	0	01	QUARRY TILE	1970	SATISFACTORY	2	15	14
028	1072	60	E S EPRE-K	5	01	COMPOSITION TILE	1970	SATISFACTORY	2	15	14
028A	50	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1970	SATISFACTORY	2	15	14
028B	23	814	STUDENT RESTROOM (BOTHSEXES)	0	01	QUARRY TILE	1970	SATISFACTORY	2	15	14
029	338	315	TEACHER PLANNING OFFICE	0	01	COMPOSITION TILE	1970	SATISFACTORY	2	15	14
030	372	316	TEACHER LOUNGE/DINING	0	01	COMPOSITION TILE	1970	SATISFACTORY	2	15	14
030A	46	700	INSIDE CIRCULATION	0	01	COMPOSITION TILE	1970	SATISFACTORY	2	15	14
030B	37	821	STAFF RESTROOM (BOTHSEXES)	0	01	QUARRY TILE	1970	SATISFACTORY	2	15	14
030C	240	702	MECHANICAL ROOM	0	01	CONCRETE	1970	SATISFACTORY	2	15	14
100	436	304	RECEPTION AREA	0	01	COMPOSITION TILE	1993	SATISFACTORY	2	15	14
100A	641	700	INSIDE CIRCULATION	0	01	CARPET	2010	SATISFACTORY	2	15	14
101	280	305	PRODUCTION WORKROOM	0	01	COMPOSITION TILE	1993	SATISFACTORY	2	15	14
102	211	303	SECRETARIAL SPACE	0	01	CARPET	1993	SATISFACTORY	2	15	14
103	103	309	VAULT/STUDENT RECORDS	0	01	CARPET	1993	SATISFACTORY	2	15	14



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

104	65	820	STAFF RESTROOM(FEMALE)	0	01	COMPOSITIONTILE	1993	SATISFACTORY	2	15	14
105	34	819	STAFF RESTROOM(MALE)	0	01	COMPOSITIONTILE	1993	SATISFACTORY	2	15	14
106	254	307	CLINIC	0	01	COMPOSITIONTILE	1993	SATISFACTORY	2	15	14
106A	33	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1996	SATISFACTORY	2	15	14
106B	33	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1996	SATISFACTORY	2	15	14
107	132	303	SECRETARIALSPACE	0	01	CARPET	1993	SATISFACTORY	2	15	14
108	230	303	SECRETARIALSPACE	0	01	CARPET	1993	SATISFACTORY	2	15	14
109	225	300	PRINCIPAL/DIRECTOROFFICE	0	01	CARPET	1993	SATISFACTORY	2	15	14
110	255	308	GENERAL SCHOOLSTORAGE	0	01	CARPET	1993	SATISFACTORY	2	15	14
111	252	306	CONFERENCEROOM	0	01	CARPET	1993	SATISFACTORY	2	15	14
112	143	314	ITINERANTOFFICE	0	01	CARPET	1993	SATISFACTORY	2	15	14
113	75	317	GENERAL SCHOOLSPACE	0	01	CARPET	1993	SATISFACTORY	2	15	14
114	110	314	ITINERANTOFFICE	0	01	CARPET	1993	SATISFACTORY	2	15	14
115	176	306	CONFERENCEROOM	0	01	CARPET	1993	SATISFACTORY	2	15	14
116	150	303	SECRETARIALSPACE	0	01	COMPOSITIONTILE	1993	SATISFACTORY	2	15	14
117	2612	380	LIBRARY (READINGROOM/STACKS)	0	01	CARPET	1993	SATISFACTORY	2	15	14
117A	248	700	INSIDECIRCULATION	0	01	CARPET	2010	SATISFACTORY	2	15	14
118	252	385	CLOSED CIRCUIT TVLAB	0	01	CARPET	1993	SATISFACTORY	2	15	14
118A	180	703	ELECTRICALROOM	0	01	COMPOSITIONTILE	1993	SATISFACTORY	2	15	14
118B	174	700	INSIDECIRCULATION	0	01	COMPOSITIONTILE	2010	SATISFACTORY	2	15	14
118C	5	707	TELEPHONEEQUIPMENT/COMMUNICATION CLOSET	0	01	COMPOSITIONTILE	2010	SATISFACTORY	2	15	14
119	660	390	MEDIA GROUPPROJECTS/INSTRUCTION	0	01	CARPET	1993	SATISFACTORY	2	15	14
119A	256	301	ASSISTANT PRINCIPAL/OTHEROFFICE	0	01	CARPET	1993	SATISFACTORY	2	15	14



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

119B	402	387	MEDIA PRODUCTIONLAB	0	01	COMPOSITIONTILE	1993	SATISFACTORY	2	15	14
119C	236	383	AUDIO VISUALSTORAGE	0	01	COMPOSITIONTILE	1993	SATISFACTORY	2	15	14
120	498	315	TEACHER PLANNINGOFFICE	0	01	CARPET	1993	SATISFACTORY	2	15	14
130	2897	361	MULTIPURPOSE ROOM(DINING)	0	01	COMPOSITIONTILE	1994	SATISFACTORY	2	15	14
130A	245	362	MULTIPURPOSE ROOM CHAIRSTORAGE	0	01	COMPOSITIONTILE	1993	SATISFACTORY	2	15	14
130B	107	362	MULTIPURPOSE ROOM CHAIRSTORAGE	0	01	COMPOSITIONTILE	1994	SATISFACTORY	2	15	14
130C	26	703	ELECTRICALROOM	0	01	COMPOSITIONTILE	1994	SATISFACTORY	2	15	14
130D	29	700	INSIDECIRCULATION	0	01	COMPOSITIONTILE	2010	SATISFACTORY	2	15	14
130E	110	700	INSIDECIRCULATION	0	01	COMPOSITIONTILE	2010	SATISFACTORY	2	15	14
131	953	363	STAGE	0	01	WOOD	1994	SATISFACTORY	2	15	14
131A	315	364	STAGESTORAGE	0	01	COMPOSITIONTILE	1994	SATISFACTORY	2	15	14
131B	186	365	STAGE DRESSING ROOM(MALE)	0	01	COMPOSITIONTILE	1994	SATISFACTORY	2	15	14
131C	152	366	STAGE DRESSING ROOM(FEMALE)	0	01	COMPOSITIONTILE	1994	SATISFACTORY	2	15	14
131D	110	700	INSIDECIRCULATION	0	01	COMPOSITIONTILE	1994	SATISFACTORY	2	15	14
132	418	315	TEACHER PLANNINGOFFICE	0	01	COMPOSITIONTILE	1994	SATISFACTORY	2	15	14
132A	53	821	STAFF RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1994	SATISFACTORY	2	15	14
133	203	815	STUDENT RESTROOM(MALE)	0	01	COMPOSITIONTILE	1994	SATISFACTORY	2	15	14
134	29	331	CUSTODIAL SERVICECLOSET	0	01	CERAMICTILE	1994	SATISFACTORY	2	15	14
135	255	702	MECHANICALROOM	0	01	CONCRETE	1994	SATISFACTORY	2	15	14
136	236	816	STUDENT RESTROOM(FEMALE)	0	01	COMPOSITIONTILE	1994	SATISFACTORY	2	15	14
139	115	702	MECHANICALROOM	0	01	CONCRETE	1998	SATISFACTORY	2	15	14
140	975	2	INTERMEDIATE/MIDDLE CLASSROOM(4-8)	22	01	CARPET	1998	SATISFACTORY	2	15	14
140A	242	315	TEACHER PLANNINGOFFICE	0	01	CARPET	1998	SATISFACTORY	2	15	14
141	970	2	INTERMEDIATE/MIDDLE CLASSROOM(4-8)	22	01	CARPET	1998	SATISFACTORY	2	15	14



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

141A	242	315	TEACHER PLANNING OFFICE	0	01	CARPET	1998	SATISFACTORY	2	15	14
142	972	2	INTERMEDIATE/MIDDLE CLASSROOM(4-8)	22	01	COMPOSITION TILE	1998	SATISFACTORY	2	15	14
142A	240	315	TEACHER PLANNING OFFICE	0	01	CARPET	1998	SATISFACTORY	2	15	14
143	56	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1998	SATISFACTORY	2	15	14
144	128	702	MECHANICAL ROOM	0	01	CONCRETE	1998	SATISFACTORY	2	15	14
145	128	702	MECHANICAL ROOM	0	01	CONCRETE	1998	SATISFACTORY	2	15	14
146	56	331	CUSTODIAL SERVICE CLOSET	0	01	CARPET	1998	SATISFACTORY	2	15	14
147	988	2	INTERMEDIATE/MIDDLE CLASSROOM(4-8)	22	01	CARPET	1998	SATISFACTORY	2	15	14
148	980	2	INTERMEDIATE/MIDDLE CLASSROOM(4-8)	22	01	CARPET	1998	SATISFACTORY	2	15	14
149	988	10	PRIMARY SKILLS LAB(K-3)	18	01	CARPET	1998	SATISFACTORY	2	15	14
150	56	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1998	SATISFACTORY	2	15	14
151	988	2	INTERMEDIATE/MIDDLE CLASSROOM(4-8)	22	01	CARPET	1998	SATISFACTORY	2	15	14
152	980	2	INTERMEDIATE/MIDDLE CLASSROOM(4-8)	22	01	CARPET	1998	SATISFACTORY	2	15	14
153	988	2	INTERMEDIATE/MIDDLE CLASSROOM(4-8)	22	01	CARPET	1998	SATISFACTORY	2	15	14
154	115	702	MECHANICAL ROOM	0	01	CONCRETE	1998	SATISFACTORY	2	15	14
155	980	2	INTERMEDIATE/MIDDLE CLASSROOM(4-8)	22	01	CARPET	1998	SATISFACTORY	2	15	14
155A	242	315	TEACHER PLANNING OFFICE	0	01	CARPET	1998	SATISFACTORY	2	15	14
156	980	2	INTERMEDIATE/MIDDLE CLASSROOM(4-8)	22	01	CARPET	1998	SATISFACTORY	2	15	14
156A	242	315	TEACHER PLANNING OFFICE	0	01	CARPET	1998	SATISFACTORY	2	15	14
157	988	1	PRIMARY CLASSROOM(K-3)	18	01	CARPET	1997	SATISFACTORY	2	15	14
157A	223	315	TEACHER PLANNING OFFICE	0	01	CARPET	1998	SATISFACTORY	2	15	14
158	56	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1998	SATISFACTORY	2	15	14
159	120	702	MECHANICAL ROOM	0	01	CONCRETE	1998	SATISFACTORY	2	15	14
160	120	702	MECHANICAL ROOM	0	01	CONCRETE	1998	SATISFACTORY	2	15	14



**FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT**

161	47	808	MATERIAL STORAGE	0	01	COMPOSITIONTILE	1998	SATISFACTORY	2	15	14
162	731	1	PRIMARY CLASSROOM(K-3)	18	01	CARPET	1998	SATISFACTORY	2	15	14
163	727	61	E S EPART-TIME	15	01	CARPET	1998	SATISFACTORY	2	15	14
164	731	1	PRIMARY CLASSROOM(K-3)	18	01	CARPET	1998	SATISFACTORY	2	15	14
165	115	702	MECHANICALROOM	0	01	CONCRETE	1998	SATISFACTORY	2	15	14
166	964	64	E S E PT/OTLAB	0	01	COMPOSITIONTILE	1998	SATISFACTORY	2	15	14
167	933	61	E S EPART-TIME	15	01	CARPET	1998	SATISFACTORY	2	15	14
168	738	62	E S EFULL-TIME	10	01	CARPET	1998	SATISFACTORY	2	15	14
169	120	702	MECHANICALROOM	0	01	CONCRETE	1998	SATISFACTORY	2	15	14
170	1995	50	ART -ELEMENTARY	0	01	COMPOSITIONTILE	1998	SATISFACTORY	2	15	14
170A	56	805	KILN	0	01	COMPOSITIONTILE	1998	SATISFACTORY	2	15	14
171	125	702	MECHANICALROOM	0	01	CONCRETE	1970	SATISFACTORY	2	15	14
701	8893	701	COVEREDWALKWAY	0	01	CONCRETE	1970	SATISFACTORY	2	15	14
801	6670	700	INSIDECIRCULATION	0	01	COMPOSITIONTILE	1970	SATISFACTORY	2	15	14

	Satisfactory		Unsatisfactory		FailedStandards		Scheduled ForReplacement	
	SquareFeet	StudentStations	SquareFeet	StudentStations	SquareFeet	StudentStations	SquareFeet	StudentStations
Permanent	65,747	391	0	0				
TOTAL	65,747	391	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 43 MARTIN COUNTY SCHOOL DISTRICT

FACILITY: 14-A JENSEN BEACH ELEMENTARY

BUILDING: 3 - Building Number 00003

Owner: SCHOOLBOARD	Light: ADEQUATE	Cooling: CENTRAL
Use: EXCEPTIONAL STUDENT	Mech Vent: NONE	Heat Source: ELECTRIC
Year Constructed: 1980	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOT AIR
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 1980	Intercom: TWO WAY COMPLETE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: NONE	Struct Comp: CONCRETE
Stories: 1		Corridor: SINGLE OUTSIDE

ROOM	NET SQ FT	DESIG N COD E	DESCRIPTION	S T U S T A	FL R L O C	FLOORCOVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
022	1054	10	PRIMARY SKILLS LAB (K-3)	0	01	COMPOSITION TILE	1980	SATISFACTORY	3	15	14
022A	25	814	STUDENT RESTROOM (BOTH SEXES)	0	01	QUARRY TILE	1980	SATISFACTORY	3	15	14
022B	25	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1980	SATISFACTORY	3	15	14
023	48	702	MECHANICAL ROOM	0	01	CONCRETE	1980	SATISFACTORY	3	15	14
024	813	62	E S E FULL-TIME	10	01	COMPOSITION TILE	1980	SATISFACTORY	3	15	14
024A	50	817	STUDENT RESTROOM & BATH	0	01	QUARRY TILE	1980	SATISFACTORY	3	15	14
024B	95	808	MATERIAL STORAGE	0	01	COMPOSITION TILE	1980	SATISFACTORY	3	15	14
025	27	331	CUSTODIAL SERVICE CLOSET	0	01	COMPOSITION TILE	1980	SATISFACTORY	3	15	14
026	48	702	MECHANICAL ROOM	0	01	CONCRETE	1980	SATISFACTORY	3	15	14
027	931	61	E S E PART-TIME	15	01	COMPOSITION TILE	1980	SATISFACTORY	3	15	14



**FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT**

027A	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	QUARRY TILE	1980	SATISFACTORY	3	15	14
		Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement			
		Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations		
Permanent		3,141	25	0	0						
TOTAL		3,141	25	0	0	0	0	0	0	0	



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 43 MARTIN COUNTY SCHOOL DISTRICT

FACILITY: 14-A JENSEN BEACH ELEMENTARY

BUILDING: 5 - Building Number 00005

Owner: SCHOOLBOARD	Light: ADEQUATE	Cooling: LOCALZONE
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: ELECTRIC
Year Constructed: 1980	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: CENTRAL HOTAIR
Year Modified:	Educational TV: NONE	Heat Capacity: ADEQUATE
Average Age NSF: 1991	Intercom: TWO WAY COMPLETE	Walls: HOLLOWBLOCK
Relocatable Units: 0	Telephone: NONE	Struct Comp: CONCRETE
Stories: 1		Corridor: NONE

ROOM	NETS SQ FT	DESIG N COD E	DESCRIPTION	S T U S T A	FL R L O C	FLOORCOVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
041	960	55	MUSIC -ELEMENTARY	0	01	CARPET	1980	SATISFACTORY	5	15	14
041A	475	40	RESOURCEROOM	0	01	CARPET	2001	SATISFACTORY	5	15	14
041B	38	83	MUSIC RELATEDSPACE	0	01	COMPOSITIONTILE	1980	SATISFACTORY	5	15	14
041C	38	83	MUSIC RELATEDSPACE	0	01	COMPOSITIONTILE	1980	SATISFACTORY	5	15	14
041D	196	808	MATERIALSTORAGE	0	01	COMPOSITIONTILE	2001	SATISFACTORY	5	15	14
041E	32	821	STAFF RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	2001	SATISFACTORY	5	15	14
041F	109	315	TEACHER PLANNINGOFFICE	0	01	COMPOSITIONTILE	2001	SATISFACTORY	5	15	14
041G	66	808	MATERIALSTORAGE	0	01	COMPOSITIONTILE	2001	SATISFACTORY	5	15	14
041H	188	702	MECHANICALROOM	0	01	CONCRETE	2002	SATISFACTORY	5	15	14
041J	35	700	INSIDECIRCULATION	0	01	CARPET	2001	SATISFACTORY	5	15	14



**FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT**

041K	80	700	INSIDE CIRCULATION	0	01	CARPET	2001	SATISFACTORY	5	15	14
	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement				
	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations			
Permanent	2,217	0	0	0							
TOTAL	2,217	0	0	0	0	0	0	0			0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 43 MARTIN COUNTY SCHOOL DISTRICT

FACILITY: 14-A JENSEN BEACH ELEMENTARY

BUILDING: 6 - Building Number 00006

Owner: SCHOOLBOARD	Light: ADEQUATE	Cooling: NONE
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: NONE
Year Constructed: 1993	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: NO HEAT PROVIDED
Year Modified:	Educational TV: NONE	Heat Capacity: NONE
Average Age NSF: 1993	Intercom: NONE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: NONE	Struct Comp: COMBINATION OF 1-3
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIG N COD E	DESCRIPTION	S T U D S T A	FL R L O C	FLOORCOVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
001	378	701	COVERED WALKWAY	0	01	CONCRETE	1993	SATISFACTORY	6	15	14
002	1526	14	ELEMENTARY COVERED PLAY AREA	0	01	CONCRETE	1993	SATISFACTORY	6	15	14
003	407	701	COVERED WALKWAY	0	01	COMPOSITION TILE	1993	SATISFACTORY	6	15	14
090	209	13	ELEMENTARY P ESTORAGE	0	01	CONCRETE	1993	SATISFACTORY	6	15	14
091	46	702	MECHANICAL ROOM	0	01	CONCRETE	1993	SATISFACTORY	6	15	14
092	94	815	STUDENT RESTROOM (MALE)	0	01	CONCRETE	1993	SATISFACTORY	6	15	14
093	94	816	STUDENT RESTROOM (FEMALE)	0	01	CONCRETE	1993	SATISFACTORY	6	15	14
094	88	701	COVERED WALKWAY	0	01	CONCRETE	2010	SATISFACTORY	6	15	14



**FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT**

100	6719	14	ELEMENTARY COVERED PLAYAREA	0	01	CONCRETE	1993	SATISFACTORY	6	15	14
		Satisfactory		Unsatisfactory		FailedStandards		Scheduled ForReplacement			
		SquareFeet	StudentStations	SquareFeet	StudentStations	SquareFeet	StudentStations	SquareFeet	StudentStations		
Permanent	9,561	0	0	0	0						
TOTAL	9,561	0	0	0	0	0	0	0	0	0	



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 43 MARTIN COUNTY SCHOOL DISTRICT

FACILITY: 14-A JENSEN BEACH ELEMENTARY

BUILDING: 9 - Building Number 00009

Owner: SCHOOLBOARD	Light: ADEQUATE	Cooling: LOCALZONE
Use: ELEMENTARY	Mech Vent: ADEQUATE	Heat Source: ELECTRIC
Year Constructed: 1987	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: ZONERADIANT
Year Modified:	Educational TV: CLOSED CIRCUIT	Heat Capacity: ADEQUATE
Average Age NSF: 1987	Intercom: TWO WAY COMPLETE	Walls: HOLLOW BLOCK
Relocatable Units: 0	Telephone: PARTIAL SYSTEM	Struct Comp: CONCRETE
Stories: 1		Corridor: DOUBLE INSIDE

ROOM	NET SQ FT	DESIG N COD E	DESCRIPTION	S T U S T A	FL R L O C	FLOORCOVER	YEAR CONST	CONDITION	BLDG	PAR	FAC
009A	140	702	MECHANICAL ROOM	0	01	CONCRETE	1987	SATISFACTORY	9	15	14
009B	140	702	MECHANICAL ROOM	0	01	CONCRETE	1987	SATISFACTORY	9	15	14
009C	140	702	MECHANICAL ROOM	0	01	CONCRETE	1987	SATISFACTORY	9	15	14
009D	140	702	MECHANICAL ROOM	0	01	CONCRETE	1987	SATISFACTORY	9	15	14
051	982	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1987	SATISFACTORY	9	15	14
051A	30	813	STUDENT STORAGE	0	01	COMPOSITION TILE	1987	SATISFACTORY	9	15	14
051B	78	818	LOCKERS/RESTROOM/SHOWER (ESE/VOCED)	0	01	COMPOSITION TILE	1987	SATISFACTORY	9	15	14
051C	25	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1987	SATISFACTORY	9	15	14
052	982	1	PRIMARY CLASSROOM (K-3)	18	01	COMPOSITION TILE	1987	SATISFACTORY	9	15	14
052A	30	813	STUDENT STORAGE	0	01	COMPOSITION TILE	1987	SATISFACTORY	9	15	14
052B	78	818	LOCKERS/RESTROOM/SHOWER (ESE/VOCED)	0	01	COMPOSITION TILE	1987	SATISFACTORY	9	15	14
052C	25	814	STUDENT RESTROOM (BOTH SEXES)	0	01	CERAMIC TILE	1987	SATISFACTORY	9	15	14



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

053	982	1	PRIMARY CLASSROOM(K-3)	18	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
053A	30	813	STUDENT STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
053B	78	808	MATERIAL STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
053C	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
054	982	1	PRIMARY CLASSROOM(K-3)	18	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
054A	30	813	STUDENT STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
054B	78	808	MATERIAL STORAGE	0	01	CARPET	1987	SATISFACTORY	9	15	14
054C	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
055	982	1	PRIMARY CLASSROOM(K-3)	18	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
055A	30	813	STUDENT STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
055B	78	808	MATERIAL STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
055C	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
056	982	1	PRIMARY CLASSROOM(K-3)	18	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
056A	30	813	STUDENT STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
056B	78	808	MATERIAL STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
056C	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
057	68	703	ELECTRICAL ROOM	0	01	CONCRETE	1987	SATISFACTORY	9	15	14
058	48	331	CUSTODIAL SERVICE CLOSET	0	01	OTHER	1987	SATISFACTORY	9	15	14
058A	52	702	MECHANICAL ROOM	0	01	OTHER	2010	SATISFACTORY	9	15	14
059	91	823	PUBLIC USE RESTROOM(FEMALE)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
060	91	822	PUBLIC USE RESTROOM(MALE)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
061	770	10	PRIMARY SKILLS LAB(K-3)	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
062	982	1	PRIMARY CLASSROOM(K-3)	18	01	CARPET	1987	SATISFACTORY	9	15	14
062A	30	813	STUDENT STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

062B	78	808	MATERIAL STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
062C	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
063	982	1	PRIMARY CLASSROOM(K-3)	18	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
063A	30	813	STUDENT STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
063B	78	808	MATERIAL STORAGE	0	01	CARPET	1987	SATISFACTORY	9	15	14
063C	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
064	982	1	PRIMARY CLASSROOM(K-3)	18	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
064A	30	813	STUDENT STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
064B	78	808	MATERIAL STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
064C	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
065	982	1	PRIMARY CLASSROOM(K-3)	18	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
065A	30	813	STUDENT STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
065B	78	808	MATERIAL STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
065C	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
066	982	1	PRIMARY CLASSROOM(K-3)	18	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
066A	30	813	STUDENT STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
066B	78	808	MATERIAL STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
066C	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
067	982	1	PRIMARY CLASSROOM(K-3)	18	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
067A	30	813	STUDENT STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
067B	78	808	MATERIAL STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
067C	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
068	982	1	PRIMARY CLASSROOM(K-3)	18	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
068A	30	813	STUDENT STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

068B	78	808	MATERIAL STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
068C	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
069	982	1	PRIMARY CLASSROOM(K-3)	18	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
069A	30	813	STUDENT STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
069B	78	808	MATERIAL STORAGE	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
069C	25	814	STUDENT RESTROOM (BOTHSEXES)	0	01	CERAMICTILE	1987	SATISFACTORY	9	15	14
070	20	702	MECHANICALROOM	0	01	CONCRETE	1987	SATISFACTORY	9	15	14
071	20	702	MECHANICALROOM	0	01	CONCRETE	1987	SATISFACTORY	9	15	14
076	20	702	MECHANICALROOM	0	01	CONCRETE	1987	SATISFACTORY	9	15	14
077	20	702	MECHANICALROOM	0	01	CONCRETE	1987	SATISFACTORY	9	15	14
078	20	702	MECHANICALROOM	0	01	CONCRETE	1987	SATISFACTORY	9	15	14
083	20	702	MECHANICALROOM	0	01	CONCRETE	1987	SATISFACTORY	9	15	14
084	20	702	MECHANICALROOM	0	01	CONCRETE	1987	SATISFACTORY	9	15	14
085	20	703	ELECTRICALROOM	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
805	272	700	INSIDECIRCULATION	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14
806	2080	700	INSIDECIRCULATION	0	01	COMPOSITIONTILE	1987	SATISFACTORY	9	15	14

	Satisfactory		Unsatisfactory		Failed Standards		Scheduled For Replacement	
	SquareFeet	StudentStations	SquareFeet	StudentStations	SquareFeet	StudentStations	SquareFeet	StudentStations
Permanent	19,802	252	0	0				
TOTAL	19,802	252	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

DISTRICT: 43 MARTIN COUNTY SCHOOL DISTRICT

FACILITY: 14-A JENSEN BEACH ELEMENTARY

BUILDING: 99 - Classroom Portables

Owner: SCHOOLBOARD	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: ELECTRIC
Year Constructed: 2005	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: INDIVIDUAL UNIT REVERSE CYCLE
Year Modified:	Educational TV: CLOSED CIRCUIT	Heat Capacity: ADEQUATE
Average Age NSF: 2005	Intercom: TWO WAY PARTIAL	Walls: RELOCATABLE
Relocatable Units: 2	Telephone: PARTIAL SYSTEM	Struct Comp: RELOCATABLE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	S T U S T	FL R L O C	FLOORCOVER	YEAR CONST	CONDITION		BLDG	PAR	FAC
								SATISFACTORY	UNSATISFACTORY			
008	864	1	PRIMARY CLASSROOM (K-3)	18	01	CARPET	2005	SATISFACTORY	SCHEDULED FOR REPLACEMENT	99	15	14
				Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	
Relocatable	864	1	PRIMARY CLASSROOM (K-3)	0	01	COMPOSITION TILE	2005	SATISFACTORY	SCHEDULED FOR REPLACEMENT	0	99	15
TOTAL	1,728			0	0			0		0		0



**FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT**

DISTRICT: 43 MARTIN COUNTY SCHOOL DISTRICT

FACILITY: 14-A JENSEN BEACH ELEMENTARY

BUILDING: 9902 - Classroom Portable

Owner: LEASERENT	Light: ADEQUATE	Cooling: INDIVIDUAL UNITS
Use: ELEMENTARY	Mech Vent: NONE	Heat Source: ELECTRIC
Year Constructed: 2004	Artificial Lighting: SHIELDED FLORESCENT	Heat Distribution: INDIVIDUAL UNIT REVERSE CYCLE
Year Modified:	Educational TV: CLOSED CIRCUIT	Heat Capacity: ADEQUATE
Average Age NSF: 2004	Intercom: TWO WAY PARTIAL	Walls: RELOCATABLE
Relocatable Units: 1	Telephone: PARTIAL SYSTEM	Struct Comp: RELOCATABLE
Stories: 1		Corridor: NONE

ROOM	NET SQ FT	DESIGN CODE	DESCRIPTION	S T U S	FL R L O C	FLOORCOVER	YEAR CONST	CONDITION				BLDG	PAR	FAC
								Satisfactory	Unsatisfactory	Failed Standards	Scheduled For Replacement			
		Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations	Square Feet	Student Stations					
Relocatable	1	764	PRIMARY CLASSROOM (3)	0	18	0	2004	SATISFACTORY	0	9902	2	15	18	
TOTAL		764	18	0	18	0		0	0	0	2	15	18	



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

STUDENT STATIONS BY DESIGN CODE FOR:

FACILITY: JENSEN BEACH ELEMENTARY

Design Code	Design Code Description	Satis StuSta			Unsat StuSta			Sat	Unsat	SatisRooms			UnsatRooms			FailStd StuSta	Repl StuSta	FailStd Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo	Tot	Tot	Perm	Mod	Relo	Perm	Mod	Relo	Relo	Relo	Relo	Relo
00001	PRIMARY CLASSROOM(K-3)	360	0	54	0	0	0	414	0	20	0	3	0	0	0	0	0	0	0
00002	INTERMEDIATE/MIDDLE CLASSROOM(4-8)	220	0	0	0	0	0	220	0	10	0	0	0	0	0	0	0	0	0
00010	PRIMARY SKILLS LAB(K-3)	18	0	0	0	0	0	18	0	3	0	0	0	0	0	0	0	0	0
00013	ELEMENTARY P E STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00014	ELEMENTARY COVERED PLAYAREA	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00040	RESOURCEROOM	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00050	ART -ELEMENTARY	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00055	MUSIC -ELEMENTARY	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00060	E S EPRE-K	5	0	0	0	0	0	5	0	1	0	0	0	0	0	0	0	0	0
00061	E S EPART-TIME	45	0	0	0	0	0	45	0	3	0	0	0	0	0	0	0	0	0
00062	E S EFULL-TIME	20	0	0	0	0	0	20	0	2	0	0	0	0	0	0	0	0	0
00064	E S E PT/OTLAB	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00083	MUSIC RELATEDSPACE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00300	PRINCIPAL/DIRECTOROFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00301	ASSISTANT PRINCIPAL/OTHEROFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00303	SECRETARIALSPACE	0	0	0	0	0	0	0	0	4	0	0	0	0	0	0	0	0	0
00304	RECEPTIONAREA	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00305	PRODUCTIONWORKROOM	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00306	CONFERENCE ROOM	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00307	CLINIC	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00308	GENERAL SCHOOLSTORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00309	VAULT/STUDENTRECORDS	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00314	ITINERANT OFFICE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00315	TEACHER PLANNINGOFFICE	0	0	0	0	0	0	0	0	10	0	0	0	0	0	0	0	0	0



**FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)
FACILITY INVENTORY REPORT**

Design Code	Design Code Description	Satis StuSta			Unsat StuSta			Sat	Unsat	SatisRooms			UnsatRooms			FailStd	Repl	FailStd	Repl
		Perm	Mod	Relo	Perm	Mod	Relo	Tot	Tot	Perm	Mod	Relo	Perm	Mod	Relo	Relo	Relo	Relo	Relo
00316	TEACHERLOUNGE/DINING	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00317	GENERAL SCHOOLSPACE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00331	CUSTODIAL SERVICECLOSET	0	0	0	0	0	0	0	0	5	0	0	0	0	0	0	0	0	0
00332	CUSTODIAL WORKAREA	0	0	0	0	0	0	0	0	3	0	0	0	0	0	0	0	0	0
00334	CUSTODIAL EQUIPMENT STORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00340	DININGAREA	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00342	KITCHEN DRYSTORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00343	KITCHENOFFICE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00346	KITCHEN FOODPREPARATION	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00350	OTHER FOODSERVICE	0	0	0	0	0	0	0	0	4	0	0	0	0	0	0	0	0	0
00361	MULTIPURPOSE ROOM(DINING)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00362	MULTIPURPOSE ROOM CHAIRSTORAGE	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00363	STAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00364	STAGESTORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00365	STAGE DRESSING ROOM(MALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00366	STAGE DRESSING ROOM(FEMALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00380	LIBRARY (READINGROOM/STACKS)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00383	AUDIO VISUALSTORAGE	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00385	CLOSED CIRCUIT TVLAB	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00387	MEDIA PRODUCTIONLAB	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00390	MEDIA GROUPPROJECTS/INSTRUCTION	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00700	INSIDECIRCULATION	0	0	0	0	0	0	0	0	13	0	0	0	0	0	0	0	0	0
00701	COVEREDWALKWAY	0	0	0	0	0	0	0	0	4	0	0	0	0	0	0	0	0	0
00702	MECHANICALROOM	0	0	0	0	0	0	0	0	28	0	0	0	0	0	0	0	0	0
00703	ELECTRICALROOM	0	0	0	0	0	0	0	0	7	0	0	0	0	0	0	0	0	0
00707	TELEPHONEEQUIPMENT/COMMUNICATION CLOSET	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0



FLORIDA INVENTORY OF SCHOOL HOUSES (FISH)

FACILITY INVENTORY REPORT

Design Code	Design Code Description	Satis StuSta			Unsat StuSta			Sat	Unsat	SatisRooms			UnsatisRooms			FailStd StuSta	Repl StuSta	FailStd Rooms	Repl Rooms
		Perm	Mod	Relo	Perm	Mod	Relo	Tot	Tot	Perm	Mod	Relo	Perm	Mod	Relo	Relo	Relo	Relo	Relo
00805	KILN	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00808	MATERIAL STORAGE	0	0	0	0	0	0	0	0	24	0	0	0	0	0	0	0	0	0
00813	STUDENT STORAGE	0	0	0	0	0	0	0	0	17	0	0	0	0	0	0	0	0	0
00814	STUDENT RESTROOM (BOTHSEXES)	0	0	0	0	0	0	0	0	22	0	0	0	0	0	0	0	0	0
00815	STUDENT RESTROOM(MALE)	0	0	0	0	0	0	0	0	4	0	0	0	0	0	0	0	0	0
00816	STUDENT RESTROOM(FEMALE)	0	0	0	0	0	0	0	0	4	0	0	0	0	0	0	0	0	0
00817	STUDENT RESTROOM & BATH	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00818	LOCKERS/RESTROOM/SHOWER (ESE/VOCED)	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00819	STAFF RESTROOM(MALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00820	STAFF RESTROOM(FEMALE)	0	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0	0	0
00821	STAFF RESTROOM (BOTHSEXES)	0	0	0	0	0	0	0	0	5	0	0	0	0	0	0	0	0	0
00822	PUBLIC USE RESTROOM(MALE)	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
00823	PUBLIC USE RESTROOM(FEMALE)	0	0	0	0	0	0	0	0	2	0	0	0	0	0	0	0	0	0
Totals:		668	0	54	0	0	0	722	0	243	0	3	0	0	0	0	0	0	0



ADDENDA NO. 2

RFQ NO. 3001-0-2019/3002-0-2019

ATTACHMENT B



PALM CITY ELEMENTARY SCHOOL (PCES)

**PURCHASING DEPARTMENT
2845 SE DIXIE HWY STUART, FL., 34997
TEL (772) 219-1255
EMAIL bids@martin.k12.fl.us**



**2017 AHERA Re-inspection
Palm City Elementary
Palm City, Florida
S&ME Project No. 4484-17-070G**

Assessment Performed by and Report Prepared by:

 
Nacole Caputo (Accreditation# ME2A31728ED625463) Date

PREPARED FOR:
Martin County School Board
1050 SE 10th Street
Stuart, Florida 34994

PREPARED BY:
S&ME, Inc.
111 Kelsey Lane, Suite E
Tampa, FL 33619
September 7, 2017



September 7, 2017

Martin County School District
1050 SE 10th Street
Stuart, Florida 34994

Attention: Mr. Rob Phillips

Reference: **2017 AHERA Re-Inspection Report**
Palm City Elementary School
Palm City, Florida
S&ME Project No. 4484-17-070-G
Florida Asbestos Business Organization License #ZA0000094

Dear Mr. Phillips:

S&ME, Inc. is pleased to submit the enclosed 2017 Asbestos Hazard Emergency Response Act (AHERA) Re-inspection Report for the referenced school located in Palm City, Florida. This work was performed in general accordance with the S&ME Proposal No. 44-1700122, dated April 11, 2017.

The enclosed re-inspection report was conducted as outlined in the Environmental Protection Agency (EPA) Regulation 40 CFR 763.85 and was performed by an EPA accredited inspector and response actions determined by an accredited Management Planner. This report represents a summary of past re-inspection reports and must be used in conjunction with the original Asbestos Management Plan and subsequent three-year re-inspections to manage and track the asbestos containing building materials currently in the school. The regulation states that the Local Education Authority (LEA) shall:

- Select and implement, in a timely manner, the appropriate **response actions** for each known and assumed asbestos containing building material (ACBM). The LEA may select from response actions that protect human health and the environment and are the least burdensome methods.
- Ensure that workers and building occupants, or their legal guardians, are informed at least once each school year about inspections, response actions, and post response action activities, including periodic 3-year re-inspection and surveillance activities that are planned or in progress. (40 CFR 763.84 (c)). Copies of **notifications** must be included with this report.
 - Annual notifications were not available for S&ME to review.
- Conduct **periodic surveillance**, at least once every six months, in each building that it leases, owns, or otherwise uses as a school building that contains ACBM or is assumed to contain ACBM." (40 CFR 763.92 (b))
 - Six-month surveillance documentation was not available for S&ME to review.
- Ensure, prior to implementation of the operations and maintenance provisions of the management plan, that members of its maintenance and custodial staff (custodians, electricians, heating/air conditioning technicians, plumbers, etc.) who may work in a building that contains ACBM receive **awareness training** of at least two hours, whether or not they are



required to work directly with ACBM. New custodial and maintenance employees are to be trained within 60 days after commencement of employment. (CFR 40 763.92 (a) (1))

- The 2-hour asbestos awareness training was observed for several employees over the last three years. The school board uses safeschools.com to provide training.
- Ensure that members of its maintenance and custodial staff who conduct operations and maintenance activities that will result in the disturbance of ACBM receive the **two hour asbestos awareness training and an additional 14 hours of training**. (40 CFR 763.92 (a) (2)). Training records must be made part of each building's 3-year reinspection/management planner report.
- Documentation for the 14-hour O&M training was not available for S&ME to review.

Based on the findings of the initial inspection and subsequent re-inspections, S&ME confirmed the following asbestos containing building materials currently in the facility.

- Drywall and joint compound
- Heating, ventilation and air conditioning (HVAC) duct mastics
- Vinyl floor tiles and mastic
- Cove base mastics
- Carpet mastics
- Fire-rated doors
- Chalkboards
- Sink condensate barriers
- Plaster coatings
- Pipe wrap insulation
- Wall glues/mastics
- Gypsum Ceiling Panels
- Resilient Sheet Flooring
- Mirror Mastics
- Metal Doors
- Stage Curtains

The Scope of Service is based on historical sampling data and the 1988 (original) AHERA Asbestos Management Plan for the Palm City Elementary School. Suspect asbestos containing materials installed in the school since the original 1988 AHERA inspection and subsequent 3-year reinspections were not sampled or analyzed as a part of this scope of work. However, the client requested samples of damaged or significantly damaged assumed ACBMs be sampled. Damaged suspect ACBMs was observed in floor tiles during our assessment.

This report does not comply with the EPA's National Emission Standards for Hazardous Air Pollutants (NESHAP) regulatory requirements for renovation or demolition activities impacting suspect asbestos containing materials. Compliance with NESHAP requirements for renovation or demolition projects will require additional bulk sampling and analysis of any suspect interior or exterior material not sampled and analyzed in this report.



We appreciate the opportunity to provide you with our industrial hygiene/environmental services. If you have any questions concerning this report, please call us at (813) 623-6646.

Sincerely,

S&ME, Inc.

Prepared by

A handwritten signature in black ink, appearing to read 'Nacole Caputo'.

Nacole Caputo, MBA, CIE
Project Manager
Management Planner

Reviewed by

A handwritten signature in black ink, appearing to read 'Ken Warren'.

Kenneth R. Warren, CIH
Senior Industrial Hygienist
Florida Licensed Asbestos Consultant #IA24

Attachments



AHERA RE-INSPECTION REPORT

LEA: Martin County School District
ADDRESS: 1050 SE 10th Street, Stuart, Florida 34994
TELEPHONE: (772)-223-3105
DATE: September 7, 2017
SCHOOL: Palm City Elementary School

SUBMIT TO LEA DESIGNEE

LIST OF DOCUMENTS ATTACHED:

- List of School Buildings, Reassessment of Areas of ACBM or Suspect ACBM, Added Homogenous Areas of ACBM or Suspect ACBM, Diagram of School Campus, Description of Each New Homogenous Area and Determination of Sampling Location, Description of Each Sample Area & Assessment of Materials, Bulk Sample Analysis, Response Actions Recommended, Response Actions Selected and Dates, Copy of Inspectors License, Copy of Management Planners License

No person or firm shall offer to perform, perform or be hired to perform as professionals in providing the services of inspection, preparation of management plans, designing of response actions, or supervising of response action except as properly accredited under the provisions of Public Law 99-519, EPA regulations 40 CFR Part 763 and SCDHEC Regulation 61-86.1. In addition these persons or firms performing as professionals shall be registered in South Carolina under the registration laws of the State. Such professionals shall be Independent practitioners and shall have no financial or other interest in contractors, subcontractors, manufacturers, or jobbers under their jurisdiction where direct conflict of interest could occur, except as permitted as follows.

An employee of a public school, a private school association, a private school or an A/E may provide the services of inspection, and or preparation of management plans, provided the employee is properly accredited under the "AHERA" Laws and Regulations. Where an employee of the LEA provides these services, the LEA must request a Waiver of Professional Services.

LEA DESIGNEE: Name, Telephone No., Signature, &, Date

HOURS TRAINING: AGENCY: DATE:


PRINCIPAL: Name, Telephone No., Signature, &, Date

INSPECTOR: Name & Signature (with signature)

AHERA LICENSE NO. MEA1D667C15FAF426 Telephone No. (813) 623-6646

MANAGEMENT PLANNER: Name & Signature (with signature)

AHERA LICENSE NO. 8301691 Telephone No. (813) 623-6646



AHERA RE-INSPECTION REPORT

LEA: Martin County School District

I - LIST OF BUILDINGS REINSPECTED

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE REINSPECTED: July 19, 2017

BUILDING NAME/NO.	ACBM		SUSPECT ACBM		NO ACBM
	FRIABLE	NONFRIABLE	FRIABLE	NONFRIABLE	
1			X	X	
2			X	X	
3		X	X	X	
4			X	X	
9			X	X	
10			X	X	
11			X	X	
12			X	X	
16			X	X	
99-056			X	X	

COMMENTS: Access to Room 30 C in Building 2 was not available

It appears renovations occurred in Building 3 that affected green floor tile, green cove base, acoustical wall carpet and stage curtains. Damaged wallboard and vinyl paneling was observed in the food storage area (7D) from possible mold contamination.

It appears renovations occurred in Building 12 that affected some rooms with green floor tile, green carpet, green cove base and black cove base. NESHAP survey reports and air monitoring reports were not available for review.



2 - REASSESSMENT OF AREAS OF ACBM OR SUSPECT ACBM

Condition Code Legend:

1. Damaged or significantly damaged thermal system insulation ACM
2. Damaged friable surfacing ACM
3. Significantly damaged friable surfacing ACM
4. Damaged or significantly damaged friable miscellaneous ACM
5. ACBM with potential for damage
6. ACBM with potential for significant damage
7. Any remaining ACBM or friable suspected ACBM

IEA: Martin County School District

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE REINSPECTED: July 19, 2017

AHERA RE-INSPECTION REPORT

ROOM # AND FUNCTIONAL SPACE	HA #	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
							YES	NO
Hall/Corridor	3	1'x1' VFT Tan with Streaks & Mastic	900 SF	MISC	5	Non-Friable		X
1,2,26-28	5	Cove Base Mastic, Blue Cove Base	160 SF	MISC	5	Non-Friable		X
Hall/Corridor	6	Cove Base Mastic - Black Cove Base	100 SF	MISC	7	Non-Friable		X
Rooms 1,2,26-28	7	Sink Barrier, Grey	20 SF	MISC	7	Non-Friable		X
Throughout	8	Drywall and Joint Compound w/ skimcoat	5,000 SF	MISC	5	Friable		X
Throughout	9	Plaster Coating	1,000 SF	SUR	5	Friable		X
Rooms 1,2,26-28	10	Green Chalkboard	300 SF	MISC	7	Non-Friable		X
A01,A02	11	Pipe Insulation Wrap, foamglass	unknown	TSI	5	Friable		X
A01,A02	12	HVAC Mastic, White	unknown	MISC	5	Non-Friable		X
A01,A02, 1, 2	13	Fire-rated Doors	4 EA	MISC	7	Non-Friable		X

ROOM # AND FUNCTIONAL SPACE	HA #	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
							YES	NO
6Y,6K, corridor	3	1'x1' Tan With Streaks VFT and Mastic	240 SF	MISC	5	Non-Friable		X
6Y,6K	4	Cove Base Mastic - Cove Base Black	40 SF	MISC	7	Non-Friable		X
Throughout	7	Drywall & Joint Compound	22,000 SF	MISC	5	Non-Friable		X
Throughout	8	Plaster Coating	20,000 SF	SUR	5	Friable		X

2 - REASSESSMENT OF AREAS OF ACBM OR SUSPECT ACBM

LEA: Martin County School District

Condition Code Legend:

1. Damaged or significantly damaged thermal system insulation ACM
2. Damaged friable surfacing ACM
3. Significantly damaged friable surfacing ACM
4. Damaged or significantly damaged friable miscellaneous ACM
5. ACBM with potential for damage
6. ACBM with potential for significant damage
7. Any remaining ACBM or friable suspected ACBM

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE REINSPECTED: July 19, 2017

AHERA RE-INSPECTION REPORT

ROOM # AND FUNCTIONAL SPACE	HA #	N e w	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON- FRIABLE	CHANGES?	
								YES	NO
5, 6, 6H, 83, 84, 85, 86, 87	9		Sink Condensate Barrier, Grey	18 SF	MISC	7	Non-Friable		X
5, 6, 6E, 83, 84, 85, 86, 87	10		Green Chalkboard	100 SF	MISC	7	Non-Friable		X
61, 63	12		Pipe Insulation Wrap, White	Unknown	TSI	5	Friable		X
3, 6, 6D	11		Sink Condensate Barrier, Black	8 SF	MISC	7	Non-Friable		X
61, 63	13		HVAC Mastic/White	Unknown	MISC	7	Non-Friable		X
6Y, 6K, 6I (painted)	15		9'x9' Green VFT and Mastic	60 SF	MISC	5	Non-Friable		X
6J, 5, 6	17		Fire-rated Doors	4 EA	MISC	7	Non-Friable		X
Above Drop Ceiling Throughout	45		1' x 1' Ceiling Tiles	Unknown	MISC	7	Friable		X

Building 3:

ROOM # AND FUNCTIONAL SPACE	HA #	N e w	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON- FRIABLE	CHANGES?	
								YES	NO
52D7C, Kitchen	1		Plaster Coating	7,000 SF	SUR	5	Friable		X
Throughout	2		Drywall and Joint Compound	11,000 SF	MISC	5	Friable		X
20, 20C	4		1"X1' VFT Green & Mastic	630 SF	MISC	5	Non-Friable	X - Not Found!	
20, 20C	5		Cove Base Mastic, Green Cove Base	50 SF	MISC	7	Non-Friable	X - Not Found!	
7, 15A, 22A, 23A	7		2'x4' Ceiling Tile, Cloth Textured	700 SF	MISC	5	Non-Friable		X

¹ Asbestos NESHAP survey not observed during records review

2 - REASSESSMENT OF AREAS OF ACBM OR SUSPECT ACBM

LEA: Martin County School District

Condition Code Legend:

1. Damaged or significantly damaged thermal system insulation ACM
2. Damaged friable surfacing ACM
3. Significantly damaged friable surfacing ACM
4. Damaged or significantly damaged friable miscellaneous ACM
5. ACBM with potential for damage
6. ACBM with potential for significant damage
7. Any remaining ACBM or friable suspected ACBM

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE REINSPECTED: July 19, 2017

AHERA RE-INSPECTION REPORT

Building 3:

ROOM # AND FUNCTIONAL SPACE	HA #	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
							YES	NO
14A, 14B, 16, stage, 15A, 15C, 15E, Stage Corridors	8	1"x1" VFT Blue & Mastic	2,200 SF	MISC	5	Non-Friable		X
14A, 14B, 15A, 15C, 15E, 16, Stage	9	Cove Base Mastic, Blue Cove Base	200 SF	MISC	5	Non-Friable		X
Cafeteria	10	Acoustical Wall Carpet and Mastic	3,000 SF	MISC	5	Non-Friable	X - Not Found ²	
Stage	12	Burgundy Stage Curtains	2,000 SF	MISC	5	Non-Friable	X - Not Found ²	
15E, 20, Kitchen Entrances	13	Fire-rated Doors	8 EA	MISC	7	Non-Friable		X
8, 14, 7D, 23, 22A	14-01	Reinforced Vinyl Panel & Glue	350 SF	MISC	7	Non-Friable	X - damaged (7D)	
19 (Outside Laundry)	14-02	12"x12" Tan with Brown Specks VFT - Mastic is 3% Chrysotile	180 SF	MISC	6	Non-Friable	X - damaged	
17 (Mechanical Room)	14-03	HVAC Grey Mastic	100 SF	MISC	7	Non-Friable		X
17 (Mechanical Room)	14-04	HVAC White Mastic	300 SF	MISC	7	Non-Friable		X
17 (Mechanical Room)	14-05	Pipe Insulation Wrap, foaming glass	300 LF	TSI	5	Friable		X

² Asbestos NESHAP survey not observed during records review

2 - REASSESSMENT OF AREAS OF ACBM OR SUSPECT ACBM

LEA: Martin County School District

Condition Code Legend:

1. Damaged or significantly damaged thermal system insulation ACM
2. Damaged friable surfacing ACM
3. Significantly damaged friable surfacing ACM
4. Damaged or significantly damaged friable miscellaneous ACM
5. ACM with potential for damage
6. ACBM with potential for significant damage
7. Any remaining ACBM or friable suspected ACBM

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE REINSPECTED: July 19, 2017

AHERA RE-INSPECTION REPORT

Building 4 (Former Main Office):

ROOM # AND FUNCTIONAL SPACE	HA #	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
							YES	NO
Throughout	5	Drywall and Joint Compound w/ skimcoat	3,200 SF	MISC	5	Friable		X
13	7	Sink Condensate Barrier, White	3 SF	MISC	7	Non-Friable		X
PCE.4.A01 (Mechanical Room)	8	Pipe Insulation Wrap, White, foamglass	Unknown	TSI	7	Friable		X
Not Labeled	10	Fire-rated Doors	unknown	MISC	7	Non-Friable		X
9,13	14-11	Green Chalkboard	18 SF	MISC	7	Non-Friable		X

Building 9:

ROOM # AND FUNCTIONAL SPACE	HA #	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
							YES	NO
29,33,34, 35	7	Sink Condensate Barrier, Grey	8 SF	MISC	7	Non-Friable		X
Throughout	8	Drywall and Joint Compound	10,500 SF	MISC	5	Non-Friable		X
Throughout	9	Plaster Coating as skimcoat	10,000 SF	SUR	5	Non-Friable		X
30, 33	10	Green Chalkboard	50 SF	MISC	7	Non-Friable		X
31 (PCE.9.01)	11	Pipe Insulation Wrap, White, foamglass	Unknown	TSI	5	Friable		X
Not Labeled	13	Fire-rated Doors	n/a	MISC	7	Non-Friable		X
31 (PCE.9.01)	12	HVAC White Mastic	Unknown	MISC	7	Non-Friable		X
Hall	3	12"x12" Tan with Brown Streaks RFT	2,000 SF	MISC	5	Non-Friable		X
31, 32B, Hall	6	Black Cove Base	120 SF	MISC	5	Non-Friable		X
30	14-14	Black Sink Condensate	3 SF	MISC	7	Non-Friable		X

2 - REASSESSMENT OF AREAS OF ACBM OR SUSPECT ACBM

LEA: Martin County School District

Condition Code Legend:

1. Damaged or significantly damaged thermal system insulation ACM
2. Damaged friable surfacing ACM
3. Significantly damaged friable surfacing ACM
4. Damaged or significantly damaged friable miscellaneous ACM
5. ACM with potential for damage
6. ACBM with potential for significant damage
7. Any remaining ACBM or friable suspected ACBM

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE REINSPECTED: July 19, 2017

AHERA RE-INSPECTION REPORT

ROOM # AND FUNCTIONAL SPACE	HA #	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
							YES	NO
Hall	2	1'x1' Tan with Brown Lines VFT and Mastic	900 SF	MISC	5	Non-Friable		X
Hall	3	Cove Base Mastic - Black Cove Base	140 SF	MISC	5	Non-Friable		X
41, 42	5	Green Chalkboard	75 SF	MISC	7	Non-Friable		X
Throughout	7	Plaster Coating, skimcoat	10,000 SF	SUR	5	Friable		X
Throughout	8	Drywall & Joint Compound	10,500 SF	MISC	5	Friable		X
36,37, 38, 39,40	10	Sink Condensate Barrier, Black	10 SF	MISC	7	Non-Friable		X
43	11	1'x1' Grey with Red/Brown VFT and Mastic	640 SF	MISC	5	Non-Friable		X
43,43C	12	Cove Base Mastic, Brown Cove Base	40 SF	MISC	5	Non-Friable		X
Hall, 43, 43C, 43D	14	Fire-rated Doors	Unknown	MISC	7	Non-Friable		X
43D	45	Pipe Wrap Foamglass	Unknown	MISC	7	Non-Friable		X
43D	46	HVAC Mastic, white	Unknown	MISC	7	Non-Friable		X

ROOM # AND FUNCTIONAL SPACE	HA #	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
							YES	NO
Throughout	8	Drywall and Joint Compound	14,000 SF	MISC	5	Non-Friable		X
44, 48,49,50,51	9	Green Chalkboard	100 SF	MISC	7	Non-Friable		X
Throughout	10	Plaster Coating, skimcoat	12,000 SF	MISC	5	Non-Friable		X
53	11	Pipe Insulation Wrap, White	Unknown	TSI	5	Friable		X
PCE.11.A01	12	Fire-rated Doors	n/a	MISC	7	Non-Friable		X

2 - REASSESSMENT OF AREAS OF ACBM OR SUSPECT ACBM

LEA: Martin County School District

Condition Code Legend:

1. Damaged or significantly damaged thermal system insulation ACM
2. Damaged friable surfacing ACM
3. Significantly damaged friable surfacing ACM
4. Damaged or significantly damaged friable miscellaneous ACM
5. ACM with potential for damage
6. ACBM with potential for significant damage
7. Any remaining ACBM or friable suspected ACBM

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE REINSPECTED: July 19, 2017

AHERA RE-INSPECTION REPORT

ROOM # AND FUNCTIONAL SPACE	HA #	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
							YES	NO
47A,53	14-13	HVAC White Mastic	Unknown	MISC	7	Non-Friable		X
Throughout	14-14	Cove Base Mastic, Light Blue	2,200 SF	MISC	5	Non-Friable		X

Building 12:

ROOM # AND FUNCTIONAL SPACE	HA #	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON-FRIABLE	CHANGES?	
							YES	NO
59,60,62, 67A, 78A,80 Reception Desk	1	1'x1' Green VFT and Mastic	500 SF	MISC	5	Non-Friable		X
64-68, 70	2	Carpet Mastic – Green Carpet	700 SF	MISC	7	Non-Friable		X
56, 63, 73, 74, 78, 78A	3	Cove Base Mastic, Light Green	100 SF	MISC	5	Non-Friable		X
Throughout	4	Drywall and Joint Compound	8,000 SF	MISC	5	Friable		X
58	7	Cove Base Mastic, Light Black	40 SF	MISC	5	Non-Friable	X – Not Found ³	
60, 62, 73	11	Sink Condensate Barrier, Black	5 SF	MISC	7	Non-Friable		X
61, 62,75A	12	Pipe Insulation Wrap, White, foaming	Unknown	TSI	5	Non-Friable		X
Throughout	13	HVAC Yellow Mastic	Unknown	MISC	5	Non-Friable		X
Throughout	14	Fire-rated Doors	Unknown	MISC	7	Non-Friable		X
61	14-15	HVAC White	Unknown	MISC	7	Non-Friable		X

³ Asbestos NESHAP survey not observed during records review

2 - REASSESSMENT OF AREAS OF ACBM OR SUSPECT ACBM

LEA: Martin County School District

Condition Code Legend:

1. Damaged or significantly damaged thermal system insulation ACM
2. Damaged friable surfacing ACM
3. Significantly damaged friable surfacing ACM
4. Damaged or significantly damaged friable miscellaneous ACM
5. ACBM with potential for damage
6. ACBM with potential for significant damage
7. Any remaining ACBM or friable suspected ACBM

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE REINSPECTED: July 19, 2017

AHERA RE-INSPECTION REPORT

ROOM # AND FUNCTIONAL SPACE	HA #	N e w	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON- FRIABLE	CHANGES?	
								YES	NO
PCE.16.A02	1		Pipe Insulation Wrap, White	Unknown	TSI	5	Friable		X
Throughout	2		Plaster Coating	30,000 SF	SUR	5	Friable		X
101A	4		Cove Base Mastic, Black Cove Base	60 SF	MISC	5	Non-Friable		X
101, 101A, 102, 103, 103B, 104, 105, 109,111,112,106B,105B,107B,107E, 115, 1113, 107	5		Drywall and Joint Compound	35,000 SF	MISC	5	Friable		X
Throughout	7		Carpet Mastic, Grey w/ blue Carpet	12,000 SF	MISC	7	Non-Friable		X
102,103,105,107, 109 110-115	9		Sink Condensate Barrier, White	40 SF	MISC	7	Non-Friable		X
107,110, 113, 114,115	10		Black Chalkboard	70 SF	MISC	7	Non-Friable		X
Throughout, except 103	11		Cove Base Mastic, Blue Cove Base	400 SF	MISC	5	Non-Friable		X
PCE.16.A02, A01	13		HVAC White Mastic	Unknown	MISC	7	Non-Friable		X
101,101A, 102B, A01	15		Fire-rated Doors	2 EA	MISC	7	Non-Friable		X

Building Portable 99-056:

ROOM # AND FUNCTIONAL SPACE	HA #	N e w	DESCRIPTION OF ACBM	QUANTITY	TYPE	CONDITION CODE	FRIABLE/ NON- FRIABLE	CHANGES?	
								YES	NO
Portable 99-056	14-01		Reinforced Vinyl Panel	120 SF	MISC	7	Non-Friable		X
Portable 99-056	14-02		2'x2' Ceiling Tile, Fissured	1,100SF	MISC	7	Friable		X
Portable 99-056	14-03		Drywall & Joint Compound	2,000 SF	MISC	5	Friable		X

2 - REASSESSMENT OF AREAS OF ACBM OR SUSPECT ACBM

Condition Code Legend:

- 1. Damaged or significantly damaged thermal system insulation ACM
- 2. Damaged friable surfacing ACM
- 3. Significantly damaged friable surfacing ACM
- 4. Damaged or significantly damaged friable miscellaneous ACM
- 5. Areas with potential for damage
- 6. ACBM with potential for significant damage
- 7. Any remaining ACBM or friable suspected ACBM

LEA: Martin County School District
 SCHOOL: Palm City Elementary School
 ADDRESS: 1951 SW 34th Street
 Palm City, Florida
 DATE REINSPECTED: July 19, 2017

AHERA RE-INSPECTION REPORT

INSPECTOR: Nacole Caputo LEA DESIGNEE: _____
 DATE OF INSPECTION: July 19, 2017 DATE OF RE-INSPECTION REVIEW: _____
 AHERA LICENSE No.: MEA1D667C15FA EXP. DATE: 08/10/2018
 SIGNATURE:  SIGNATURE: _____

AHERA RE-INSPECTION REPORT

LEA: Martin County School District

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE REINSPECTED: July 19, 2017

4-DIAGRAM OF SCHOOL CAMPUS

(SEE FIGURE ON FOLLOWING PAGE)



ARCHITECTS, ENGINEERS, CONSTRUCTORS
 2700 UNIVERSITY BLVD. SUITE 1000
 PALM BEACH, FLORIDA 33480
 PHONE: 561-832-1000
 FAX: 561-832-1001
 WWW.B7PH.COM

PROFESSIONAL ENGINEER
 BOARD OF PROFESSIONAL ENGINEERS
 STATE OF FLORIDA
 LICENSE NO. 12458
 EXPIRES 12/31/2018


PROFESSIONAL ARCHITECT
 BOARD OF ARCHITECTS
 STATE OF FLORIDA
 LICENSE NO. 12458
 EXPIRES 12/31/2018

PROFESSIONAL CONSTRUCTOR
 BOARD OF PROFESSIONAL CONSTRUCTORS
 STATE OF FLORIDA
 LICENSE NO. 12458
 EXPIRES 12/31/2018

PALM CITY ELEMENTARY SCHOOL
 PALM CITY, FLORIDA
 MARTIN COUNTY SCHOOL DISTRICT

DATE: 08/07/2010
 DRAWN BY: HENNES
 CHECKED BY: PAPANTIE
 PROJECT NO.: 10-00000000
 SHEET NO.: 10-00000000-01

BLDG 2 3 11 12
 AND 13 FLOOR
 PLANS
 X2.1



E

D

C

B

A

1

2

3

4

5

6

6 - ASSESSMENT OF MATERIAL AND DESCRIPTION OF EACH SAMPLE

LEA: Martin County School District
 SCHOOL: Palm City Elementary School
 ADDRESS: 1951 SW 34th Street
 Palm City, Florida

DATE REINSPECTED: July 19, 2017

SAMPLE NUMBER	LOCATION OF SAMPLE	Homogeneous Area			ASBESTOS TYPE AND PERCENT	ASSESSMENT	TYPE OF MATERIAL
		HA	Sq Ft	Ln Ft			
19-01	Building 3, Room 19	14-02			Tile - None Detected	Damaged	12" x 12" Tan w/ brown streaks floor tile w/ black mastic
19-02					Mastic -- 3% Chrysotile		
19-03					Tile - None Detected		
					Tile - None Detected		
					Mastic -- 3% Chrysotile		

SPECIAL COMMENTS: n/a

INSPECTOR: Nacole Caputo

LEA DESIGNEE:

DATE OF INSPECTION: July 19, 2017

DATE OF REINSPECTION REVIEW:

AHERA LICENSE No.: MEAID667C15FAF426 EXP. DATE: 08/10/2018

SIGNATURE:  SIGNATURE:

AHERA RE-INSPECTION REPORT

LEA: Martin County School District

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE REINSPECTED: July 19, 2017

7-BULK SAMPLE ANALYSIS

(SEE LABORATORY REPORT ON FOLLOWING PAGE)



Bulk Asbestos Analysis

By Polarized Light Microscopy
EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: S&ME
111 Kelsey Lane
Tampa, FL 33619

Attn: Nacole Caputo

Lab Order ID: 1715746
Analysis ID: 1715746_PLM
Date Received: 7/24/2017
Date Reported: 7/27/2017

Project: 4484-17-070G PCE

Sample ID	Description	Asbestos	Fibrous Components	Non-Fibrous Components	Attributes
Lab Sample ID	Lab Notes				Treatment
19-01 - A	12x12 Tan w/brown streaks VFT w/black mastic	None Detected		100% Other	Tan Non Fibrous Homogeneous
1715746PLM_1	tile				Crushed, Dissolved
19-01 - B	12x12 Tan w/brown streaks VFT w/black mastic	3% Chrysotile		97% Other	Black Non Fibrous Homogeneous
1715746PLM_4	mastic				Dissolved
19-02	12x12 Tan w/brown streaks VFT w/black mastic	None Detected		100% Other	Tan Non Fibrous Homogeneous
1715746PLM_2	tile only				Crushed, Dissolved
19-03 - A	12x12 Tan w/brown streaks VFT w/black mastic	None Detected		100% Other	Tan Non Fibrous Homogeneous
1715746PLM_3	tile				Crushed, Dissolved
19-03 - B	12x12 Tan w/brown streaks VFT w/black mastic	3% Chrysotile		97% Other	Black Non Fibrous Homogeneous
1715746PLM_5	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Heather Davide (5)

Analyst

Approved Signatory

8 - ACTIONS RECOMMENDED AND RESPONSE ACTION
SELECTED & DATES

LEA: Martin County School District

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE REINSPECTED: July 18, 2017

AHERA RE-INSPECTION REPORT

HA # OR FS	RECOMMENDED RESPONSE ACTION	SELECTED RESPONSE ACTION	ORIGINAL DATE	SCHEDULED DATE	COMMENTS
Overall – HAs with condition codes 5-7	Restrict contact, periodically re-inspect condition (minimum every six months) and maintain under Operations and Maintenance Plan or remove.				
Building 3: Green Floor tile and cove base, acoustical wall carpet and mastic and burgundy stage curtains Building 12: Green Floor tile, Green Carpet, Green Cove base, and Black cove base	Obtain NESHAP Asbestos Survey report and store in Management Plan				

8 - ACTIONS RECOMMENDED AND RESPONSE ACTION
SELECTED & DATES

LEA: Martin County School District

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE REINSPECTED: July 18, 2017

AHERA RE-INSPECTION REPORT

HA # OR FS	RECOMMENDED RESPONSE ACTION	SELECTED RESPONSE ACTION	ORIGINAL DATE	SCHEDULED DATE	COMMENTS
Building 3: Damaged Reinforced vinyl paneling in Room 7D and 12" x 12" Tan floor tile in Room 19	Restrict access. Isolate until material can be abated. Reduce potential for disturbance. Repair localized damage after work hours or hire an abatement contractor to perform removal. Ensure maintenance workers conducting repair have 14 hour training. Be aware of the potential for mold contamination and evaluate as necessary. Repairing or removing asbestos-containing materials requires compliance with several complex governmental regulations. Non-compliance with these regulations can expose the building owner to citations and fines.				

MANAGEMENT PLANNER: Nacole Caputo

LEA DESIGNNEE:

DATE OF REPORT: September 7, 2017

DATE OF RE-INSPECTION REVIEW:

AHERA LICENSE NO.: 8301691

EXP. DATE: 08/30/2017

SIGNATURE:

SIGNATURE:

AHERA RE-INSPECTION REPORT

9- COPY OF INSPECTOR'S LICENSE

LEA: Martin County School District

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE REINSPECTED: July 19, 2017

ATTACH COPY OF INSPECTOR'S ACCREDITATION LICENSE

UF TREEO Center
UNIVERSITY of FLORIDA

Center for Training, Research and Education for Environmental Occupations

certifies

Jarett W Epps

S&ME, 933 Benninger Dr. Brandon, FL 33510

has successfully met certificate requirements for the

Asbestos: Inspector

Approval: FBPR Asbestos Licensing Unit: Provider #0000995; Course #FL49-0002859 (3 Days; 21 Contact Hours)
(Accreditation for Inspector Under TSCA Title II/AHERA)

Conducted

01/23/2017 to 01/25/2017

Certificate #: 170343-6205
CEUs: 2.1
EPA accreditation expires: 01/25/2018
Principal Instructor: Russell E. Stauffer, PE, LAC
FBPE PDHs: 0009087/Educational Institutions: 21.0

Carol Hinton
Carol Hinton, Associate Director

University of Florida TREEO Center • 3900 SW 63 Boulevard • Gainesville, FL 32608-3800 • 352-392-9570 • www.treeo.ufl.edu

10- COPY OF MANAGEMENT PLANNER'S LICENSE

LEA: Martin County School District

SCHOOL: Palm City Elementary School

ADDRESS: 1951 SW 34th Street

Palm City, Florida

DATE INSPECTED: July 19, 2017

ATTACH COPY OF MANAGEMENT PLANNER'S ACCREDITATION LICENSE





Marva Johnson, *Chair*
Andy Tuck, *Vice Chair*
Members
Ben Gibson
Tom Grady
Michael Olenick
Joe York

June 27, 2019

Ms. Laurie Gaylord, Superintendent
Martin County School District
500 East Ocean Boulevard
Stuart, Florida 34994-2578

Dear Superintendent Gaylord:

The building replacement study dated April 2018, prepared by Song + Associates, Inc., and received by the Office of Educational Facilities (OEF) on June 25, 2018, has been reviewed. Based on the information provided to us by the Martin County School District (district), we concur with the recommendation that replacement of the buildings listed below is more economical than the rehabilitation of the existing buildings. Our recommendation does not result in these buildings being classified as unsatisfactory. Should you want to change the classification of these buildings, supporting documentation of unsatisfactory conditions must be provided.

Palm City Elementary School			
Building # <i>(s)</i>	Building Use	Square Footage	Year of Construction/ Age
1	Classrooms	6,401	1979/39
2	Classrooms	10,981	1958/60
3	Cafetorium/Kitchen	11,257	1958/60
4	Music	3,325	1967/51
8	Mechanical	1,422	1978/40
9	Classrooms	7,573	1979/39
10	Classrooms	7,658	1979/39
16	Classrooms	12,221	1989/29

Our concurrence does not relieve the district of its responsibility for performing required maintenance, minor renovation or minor remodeling of the buildings identified to maintain their present use.

Should the district desire to raze these buildings, an approved survey recommendation must first be obtained from the OEF.

Suzanne Pridgeon
Deputy Commissioner, Finance and Operations

Superintendent Laurie Gaylord
June 27, 2019
Page Two

Please let us know if we may be of further assistance.

Sincerely,

A handwritten signature in black ink, appearing to read 'm. weigly', with a long horizontal flourish extending to the right.

Mark A. Weigly, Architect, LEED AP, FCP
Educational Facilities Construction Planning Manager
Office of Educational Facilities

MW/ss

cc: Garret Grabowski, Facilities Planner, Martin County School District
Mark Eggers, Assistant Deputy Commissioner
Violet Brown, Senior Educational Program Director
Don Whitehead, Safe and Efficient Facilities Design Manager



Andy Tuck, *Chair*
Marva Johnson, *Vice Chair*
Members
Ben Gibson
Tom Grady
Michael Olenick
Joe York

August 12, 2019

Ms. Laurie Gaylord, Superintendent
Martin County School District
500 East Ocean Boulevard
Stuart, Florida 34994-2578

Dear Superintendent Gaylord:

The building replacement study dated April 2018, prepared by Song + Associates, Inc., and received by the Office of Educational Facilities (OEF) on June 25, 2018, has been reviewed. Based on the information provided to us by the Martin County School District (district), we concur with the recommendation that replacement of the buildings listed below is more economical than the rehabilitation of the existing buildings. Our recommendation does not result in these buildings being classified as unsatisfactory. Should you want to change the classification of these buildings, supporting documentation of unsatisfactory conditions must be provided.

Palm City Elementary School			
Building #(s)	Building Use	Square Footage	Year of Construction/ Age
11	Classrooms/ESE	11,612	1980/39
12	Administration	10,074	1984/35
Comments: Building 20 – Restrooms and PE Storage. The district has requested that future consideration be given to raze the building. As Building 20 is less than 750 square feet, a Castaldi is not required for the district to raze the building.			

Our concurrence does not relieve the district of its responsibility for performing required maintenance, minor renovation or minor remodeling of the buildings identified to maintain their present use.


Should the district desire to raze these buildings, an approved survey recommendation must first be obtained from the OEF.

Suzanne Pridgeon
Deputy Commissioner, Finance and Operations

Superintendent Laurie Gaylord
August 12, 2019
Page Two

Please let us know if we may be of further assistance.

Sincerely,

A handwritten signature in black ink, appearing to read 'm a w e i g l y', with a long horizontal flourish extending to the right.

Mark A. Weigly, Architect, LEED AP, FCP
Educational Facilities Construction Planning Manager
Office of Educational Facilities

MW/ss

cc: Garret Grabowski, Martin County School District
Mark Eggers, Assistant Deputy Commissioner
Violet Brown, Senior Educational Program Director
Don Whitehead, Safe and Efficient Facilities Design Manager



Martin County School District

Palm City Elementary

Castaldi Analysis



1951 SW 34th Street
Palm City, Florida 34990
April, 2018



Table of Contents

Martin County School Board Members Executive Summary	Tab A
Palm City Elementary Assessment Report & Recommendations	Tab B
Department of Education DOE OEF Form RCC-BRR-2008	Tab C
Castaldi Formula Analysis	Tab D
Palm City Elementary Location Map	Tab E
Florida Inventory of School Houses FISH Plans	Tab F
Florida Inventory of School Houses Inventory Reports	Tab G
Florida DOE 2014 Cost of Construction Report	Tab H



Martin County School Board

District 1

Christia Li Roberts, Chair

District 2

Marsha Powers

District 3

Rebecca Negrón

District 4

Tina McSoley

District 5

Michael DiTerlizzi, Vice Chair

Student Representative

Anna Ellis



Executive Summary

What follows is the Castaldi Analysis Report for the Martin County School District's (MCSD) Palm City Elementary School (PCES).

The Castaldi analysis is based on information published by the Florida Department of Education (FLDOE) pertaining to school construction and project costs, data and a facilities assessment. The analysis presents the Castaldi Formula as accepted by FLDOE.

Palm City School (PCES) began construction in 1958. It is located on 13 acres at 1951 SW 34th Street, Palm City, Martin County, Florida. Modifications occurred in 1967, 1979, 1980, 1990 and 1991. All buildings are noted as satisfactory on FISH.

The buildings are:

Building 1, is one story and houses classrooms, offices, restrooms, storage and support spaces was built in 1979, some minor renovations have occurred that are not noted in the FISH Inventory and contains 22,359 sf.

Building 2, is one story and houses classrooms, restrooms, storage and support spaces was built in 1958, no modifications this building are noted in the FISH Inventory and contains 10,981 sf.

Building 3, is one story and houses kitchen, dining, teacher's dining, multipurpose rooms, stage, dressing rooms, restrooms, storage and support spaces was built in 1958, no modifications this building are noted in the FISH Inventory and contains 11,257 sf.

Building 4, is one story and houses music, classrooms, offices, storage and support spaces was built in 1967, no modifications this building are noted in the FISH Inventory and contains 3,325 sf.

Building 6, Storage Equipment Storage is one story was built in 1958, no modifications this building are noted in the FISH Inventory and contains 99 sf. Because this building is less than 750 sf, it does not require FLDOE permission to be demolished.

Building 8, is one story and houses mechanical rooms, electrical room and support spaces was built in 1978, no modifications this building are noted in the FISH Inventory and contains 1,422 sf.

Building 9, is one story and houses classrooms, restrooms, storage and support spaces was built in 1979, no modifications this building are noted in the FISH Inventory and contains 7,573 sf.

Building 10, is one story and houses classrooms, restrooms, storage and support spaces was built in 1979, no modifications this building are noted in the FISH Inventory and contains 7,658 sf.

Building 11, is one story and houses classrooms, offices, restrooms, storage and support spaces was built in 1980, no modifications this building are noted in the FISH Inventory and contains 11,612 sf.

Building 12, is one story and houses administration, media center, TV lab, restrooms, storage and support spaces was built in 1980, no modifications this building are noted in the FISH Inventory and contains 10,074 sf.

Building 16, is one story and houses classrooms, covered outdoor play area, art lab, restrooms, storage and support spaces was built in 1990, no modifications this building are noted in the FISH Inventory and contains 15,305 sf.

Building 20, is one story and houses restrooms, storage and support spaces was built in 1991, no modifications this building are noted in the FISH Inventory and contains 873 sf.



Executive Summary

Building 99 are two modular classrooms that are one story. No modifications this building are noted in the FISH Inventory and contains 1,780 sf. We recommend they be relocated.

The current FLDOE established costs per square foot for renovation, remodeling and new construction are based on the maximum allowed cost per student station for January 2013, Section 1013.64(6)(b)1, Florida Statutes and are as follows for an high school:

Cost of Renovation based on FDOE data is \$45/GSF

Cost of Remodeling based on FDOE data is \$68/GSF

Cost of Replacement based on FDOE data is \$136/GSF

In the Castaldi analysis, if the left side of the equation, cost of remodeling or renovating, shows a larger amount, the replacement of the facility is warranted and will be more cost effective than the renovation/remodeling of the existing building(s).

It would be beneficial to the MCSD to provide their educational programs in the most compact and efficient facility designed to function according to current Florida Department of Education (FLDOE) and MCSD educational standards and design criteria, ADA requirements and the most current Florida Building Code Requirements. The buildings being considered for razing are beyond their useful life, are deficient with regard to current ADA and Florida Building Code requirements and are undersized for the programmatic needs and requirements. (See Castaldi Analysis). They both would require additional square footage to conform to the most current MCSD Educational Plant Survey Facilities List.

The review and analysis of the existing construction of the facility was tested against the Castaldi Formula and takes into consideration the educational, health, aesthetic, life safety and building improvements of educational facility design. Based on the information included in this report and the expressed needs of the Martin County School District, we recommend the following:

Buildings 1, 2, 3, 4, 6, 8, 9, 10 and 16 are recommended to be demolished and replaced with a new buildings that would serve the current student capacity and same demographics are is reported in the 01 10 18 FISH Inventory Report.

Buildings 11, 12, and 20 are recommended to be remodeled to meet the standards noted above. The Castaldi Analysis of the difference in cost do not justify razing the building for replacement. FLDOE would most likely require that they be remodeled.

Building 22 the modular classrooms are recommended to be relocated and replaced with classrooms in a new facility.

From our review and analysis the best course of action is to modernize the facility by replacement of these buildings to meet the requirements and standards noted above. Our recommendation is to replace Buildings 1, 2, 3, 4 6, 8 and 10 and remodel Buildings 11, 12 and 16 so that they become state of art new facilities. This path would be the most prudent and cost effective way to address the deficiencies with regard to Life Safety, Life Cycle Costs, Education Adequacy, and Health requirements. The recommended improvements would create a facility that provides the students, faculty, administration and staff with a state



Executive Summary

of the art modernized that would meet State Requirements for Educational Facilities (SREF), current FLDOE Guidelines, current Life Safety requirements, ADA requirements, Florida Building Code requirements and current Martin County School District Design Criteria and Standards.

Respectfully,

A handwritten signature in red ink, appearing to read "Mark Clary", is written over the word "Respectfully,".

Mark Clary, Senior Project Manager
Song + Associates, Inc.
(561) 655-2423 Email: mclary@songandassociates.com

1.1 Campus Overview

Palm City Elementary School (PCES) began construction in 1958. It is located on 13 acres at 1951 SW 34th Street, Palm City, Florida. The Center was a vocational technical school, but was taken out of service in 2001. Its primary use is as an elementary high school serving Pre K through 5. As reported in the Facility Inventory Report (FISH), dated 01. 10. 18, its School Capacity is 714 students and its Year Round Capacity is 857 students. The Utilization Factor is 1.0% and all buildings are listed to be in satisfactory condition.



Aerial of PCES

Community Significance

The Palm Beach Chamber of Commerce web site provides the following brief history of Palm City.

“In 1912, Charles C. Chillingworth and his Palm Beach County Land Company (at the time the area was part of Palm Beach County) bought property from George Beckwith, who had acquired the land in 1889, and advertised the land throughout the United States, Canada and Europe. Pineapples, oranges and grapefruit were grown at a “Demonstration Farm” on present-day Martin Highway to show farmers what they could expect if they settled in the newly named Palm City. Chillingworth provided boats, mule-teams and covered wagons (later replaced by a Model T Ford) to take the prospective clients around the undeveloped countryside. An advertisement in the Palm Beach County newspaper boasted “Free dinner on New Year’s Day for progressive buyers. A 10 acre tract for \$50 per acre (to be raised to \$60 the next day) with a free town lot in Palm City to every purchaser and 85 cents for a round trip train ticket from West Palm Beach to Stuart.”

PCES is located west of St. Lucie River and north of SW Martin Highway.

2.0 Architectural



1. Campus Design

In general, the site is well maintained, but, security is an issue. The campus can be accessed from several points around the perimeter. The campus security would be greatly improved if a single point of entry was designed for the facility.

The concept for the facility is a series of pods laid out in a grid with interior and exterior circulation interconnecting the various buildings

Recommendations:

1. Provide new perimeter fencing with a single point of entry and additional security systems to increase campus security.
2. New paving for parking and staging.
3. New LED light fixtures for parking and exterior of buildings
4. Landscaping for court yards to provide shaded areas for study.
5. Update all covered walkways so they are ADA Compliant.

2.2 Buildings 1, 2, 3, 4, 8, 9, 10, 11, 12, 16 and 20

Buildings 1, 2, 3, 4, 8, 10, 11, 12, 16 and 20 have essentially the same construction and will be accessed together.

Building 1, has program space for Classrooms, Restrooms, Storage and Supports Spaces. It was built in 1979. It one story and contains 22,359 sf.

Building 2, is one story and houses classrooms, restrooms, storage and support spaces was built in 1958, no modifications this building are noted in the FISH Inventory and contains 10,981 sf.

Building 3, is one story and houses kitchen, dining, teacher's dining, multipurpose rooms, stage, dressing rooms, restrooms, storage and support spaces was built in 1967, no modifications this building are noted in the FISH Inventory and contains 11,257 sf.

Building 4, is one story and houses music, classrooms, offices, storage and support spaces was built in 1958, no modifications this building are noted in the FISH Inventory and contains 3,325 sf.

Building 8, is one story and houses mechanical rooms, electrical room and support spaces was built in 1978, no modifications this building are noted in the FISH Inventory and contains 1,422 sf.

Building 9, is one story and houses classrooms, restrooms, storage and support spaces was built in 1979, no modifications this building are noted in the FISH Inventory and contains 7,573 sf.

Building 10, is one story and houses classrooms, restrooms, storage and support spaces was built in 1979, no modifications this building are noted in the FISH Inventory and contains 7,658 sf.

Building 11, is one story and houses classrooms, offices, restrooms, storage and support spaces was built in 1980, no modifications this building are noted in the FISH Inventory and contains 11,612sf.

Building 12, is one story and houses administration, media center, TV lab, restrooms, storage and support spaces was built in 1980, no modifications this building are noted in the FISH Inventory and contains 10,074 sf.

Building 16, is one story and houses classrooms, outdoor play area, art lab, restrooms, storage and support spaces was built in 1990, no modifications this building are noted in the FISH Inventory and contains 15,305 sf.



Building 20, is one story and houses restrooms, storage and support spaces was built in 1991, no modifications this building are noted in the FISH Inventory and contains 873 sf.

The existing structural system for these buildings is a 1 ½" 22 gauge metal roof deck mechanically fastened to steel joists bearing on a concrete tie beam and column frame. The frame has a concrete masonry infill. The bar joist throughout the facility would have to be reinforced to meet current codes. The CMU walls bear on concrete footings. The drawings do not show vertical rebar, therefore, they offer only limited resistance to lateral loads. Since the single ply roofing membrane is long past its life, and therefore likely laden with moisture (as evidenced by ceiling tile stains), stripping the roof to the deck will then require structural enhancement to meet current codes.

The buildings on campus are connected by covered walkways. The walkway's structural system includes concrete roof deck mechanically bearing on concrete beams bearing on concrete columns.

The metal decks in the labs have various degrees of corrosion and signs of water infiltration. Where visible, the steel joists also had signs of corrosion along the top cord and where the joist seat is bearing on the tie beam. This indicates corrosion of the bearing seat.

The facility's roofing system does not meet current Energy Code requirements nor current Florida Building Code requirements and needs replacement. The roof is original and was installed in 1979 and is 38 years old. The roof and roof structure are not designed to meet current code. The construction of the roof, including the roof over the covered walkways are a single ply roofing system over metal deck over steel bar joists. The covered walkways roof is also single ply bonded to a concrete deck. Some areas where the deck is exposed signs of corrosion due to water infiltration and the caustic nature of the South Florida environment. The roof and roof structure are not designed to meet current wind load requirements.

Asbestos is probably present in the insulation and sealants, which is typical for roof construction at the time this campus was constructed and requires abatement. (Destructive testing on roofs to determine material content is not performed until the roof is removed for re-roofing or demolition.) Refer to Attachment 1 for Asbestos Report.

The roof is sloped ½" per foot and storm water drains to the perimeter to metal gutter and PVC downspouts. There is no underground drainage system, so the downspouts discharge to soil, sidewalks or paving. An underground storm sewer system is recommended.

Given the age and condition of the roof coping, flashing, wood blocking assembly also requires replacement.

Primary and secondary existing exterior wall construction types exist for Building 1. The primary wall type is unreinforced 8" concrete masonry units (CMU) with a 4" fluted concrete masonry veneer. No weeps or vents were observed on the exterior face of any of the buildings nor were they noted on an as built wall section. Without weeps and vents being provided in exterior walls moisture will be trapped within the airspace of the building envelope. As there is not vertical reinforcement in the exterior CMU wall, resistance to lateral wind loads or loads imparted by windows and doors is minimal.

The secondary wall type is wall type is 8" unreinforced concrete masonry units (CMU) with a stucco finish. Also no weeps or vents were observed on the exterior face of any of the buildings nor were they noted on an as built wall section. Without weeps and vents being provided in exterior walls moisture will be trapped within the airspace of the building envelope. As there is not vertical reinforcement in the exterior CMU wall, resistance to lateral wind loads or loads imparted by windows and doors is minimal.



Primary and Secondary Exterior Wall Types

Evidence of water infiltration and the resulting black mold was present on the exterior of this building and most of the buildings. Additional information confirming that water infiltration is occurring in this building's exterior wall is that the steel angle supporting the ribbed CMU veneer located at the base of the wall was extremely corroded and requires replacement. Given the degree of decay of this structural support it is uncertain how long the veneer will remain intact and certainly does not meet the Florida Building Code wind load requirements. The Facility's Maintenance Service Manager showed the Castaldi team a video of an exterior wall being repaired that while filming failed completely and collapsed leaving the interior space of the wall exposed.



Water Infiltration in Exterior Wall and Corrosion of Fluted CMU Masonry Ledge

The exterior doors, door frames and windows show extreme wear and corrosion. They do not meet current Energy Code requirements nor do they meet the current wind pressure requirements from the 2014 Florida Building Code. Some of the windows have hardware that is inoperable.

Per the Facility's Service Manager pests, such as insects and rodents have infiltrated many of the buildings due to openings created by corrosion and win too many of the doors and windows. The doors and windows should be replaced.

The fascia at the roof edge is failing and has numerous gaps allowing water infiltration.



Fascia Allowing Water Infiltration



Non-Compliant ADA Hardware



Windows Do Not Meet Current
FBC Pressure Requirements

None of the facility building envelope assemblies and or systems were constructed to current wind codes. Especially vulnerable are those parts of the buildings structure around fenestrations. The exterior CMU should be exposed at every opening, and sufficient reinforcing added along with infill of the CMU cells with concrete.



Building 8, Fluted CMU Showing
Mold, Corrosion Occurring to
Louvers and Door & Non-
Compliant ADA Hardware



Non-Compliant ADA Drinking
Fountain



Non-Compliant ADA Handrails and Faded and Damaged Finishes

The interior doors, door frames and interior view panels show wear and the finishes are worn and faded.

The door hardware for both exterior and interior doors is not ADA compliant and needs to be brought up to current requirements. This includes levers, hinges, strikes, closers, thresholds, panic hardware and weather proofing.

In general, the existing finishes are faded and decaying.

The interior wall construction includes 5/8" GWB on both sides of 3 5/8" steel framing and 8" CMU. All interior walls require painting.

The interior ceilings show water infiltration and are sagging. They need to be replaced with mold resistant non sag acoustical tile ceilings.

The restrooms are both painted CMU and ceramic tile on the floors and some walls. All require a refresh or replacement due to damage by water infiltration and the presence of mold.

4" rubber base is installed in most rooms and restrooms have ceramic base. Where the rubber base is installed the adhesive has begun to fail and base has become separated from the wall surface.


The exterior corridors and covered walkways do not meet current code requirements for light and need to be for safety reasons and vandalism.



Exterior Corridors and Covered Walkways Lighting Do Not Meet Current FBC Requirements,

2.3 HVAC

HVAC system operates primarily on a chilled water loop. Chilled water is generated by two 170-ton air-cooled chillers manufactured by Trane. Chillers use refrigerant R-134A, which is still in wide use today and faces no significant legal sanctions. Years of chiller manufacture: 2011 and 2014. Centrifugal chillers are generally regarded as having a 25 year service life, leaving these chillers with 18 and 21 years of life respectively.



Chilled water loop uses a primary / secondary pumping configuration. Exterior chilled water pumps show significant surface age and corrosion and do not meet modern efficiency standards. These likely still have five to ten years of service life remaining. Interior (secondary) pumps are in excellent condition and likely still have 10 to 15 years of service life remaining. Exterior chilled water insulation needs to be replaced at the pump volutes but is otherwise in good condition. Building HVAC uses an antiquated pneumatic control system. System would need to be replaced with modern BACNet architecture as part of any upgrade. No

PC-based energy management software installed. A dedicated central plant controller manages operation of air-cooled chillers and pumps. Controller provides ability to schedule operation, trend data and run reports.

Interior air conditioning is accomplished by modular chilled water air handling units in mechanical rooms. Air handling units appear to be in good condition and likely have 5+ years of useful service life remaining.

Air conditioning is supplemented in several areas by stand-alone direct-expansion equipment for areas such as the kitchen (both for occupants and commercial refrigeration) and portable classrooms. Systems are in good condition and serviceable but should be replaced with new (for commercial refrigeration) or chilled water (for occupant cooling) as part of any substantial facility renovation.

The air-cooled chillers and interior secondary pumps are in excellent shape and have substantial service life remaining. They could be saved and re-used as part of any potential facility HVAC upgrade. Other system components such as exterior primary pumps, chilled water insulation, control system (building-wide), chilled water AC and direct-expansion AC are either severely

degraded, at the end of their useful service lives, or otherwise would play no role in a modern, code-compliant AC system.

Items of note:

- Chillers appear to be running 24/7, likely elevating current energy consumption.
- Modular chilled water AHU's appear to be well maintained, particularly with respect to filter change-outs.
- Maintenance staff experiences frequent problem with AHU variable frequency drives. The VFD's shut themselves down and must be manually reset. Staff suspects the problem can be traced to low-quality incoming power.
- A portable spot-cooler has been placed in the kitchen in an attempt to improve thermal comfort. This arrangement is likely both poor-performing and expensive. HVAC in this area should be improved as quickly as possible. A wall-mounted PTAC (such as those used on the portable classrooms) would be a better solution.



Spot Cooler used in Kitchen

2.4 Fire Suppression System

The campus does not have a fire

suppression system except for the kitchen hood and one piece of cooking equipment located within the footprint.

- Per the Florida Building Code (2017) the campus falls under Educational Group E.
 - 3. Group E - An *automatic sprinkler system* shall be provided for Group E occupancies as follows:
 - Throughout all Group E *fire areas* greater than 12,000 square feet (1115 m²) in area.
 - Throughout every portion of educational buildings below the lowest *level of exit discharge* serving that portion of the building.
 - Exception:** An *automatic sprinkler system* is not required in existing educational buildings unless 50 percent of the aggregate area of the building is being remodeled.
- NFPA 13 (2013) categorizes Education as Light Hazard, defined as occupancies or portions of other occupancies where combustibility is low, quantity of combustibles is moderate, stockpiles of combustibles do not exceed 8 ft., and fires with moderate rates of heat release are expected.




Photo 1
Fire Suppression release points at the kitchen exhaust hood




Photo 2
Ansul System box on wall adjacent to the exhaust hood.

5. Domestic Service Water Heating System:

The campus is served by series of electric water heaters located throughout the campus for service to the associated area. The Median Service Life of an electric water heater is approximately 13 years.

- The age of the water heater(s) varies, one made in 2005 (13 years old), one made in 2012 (6 years old), another about the same time. As water heaters age, their efficiency decreases.
- The majority of the visible hot water piping was not insulated, which is a loss of energy and does not meet the current Florida Energy requirements.
- The water heaters are not piped according to the current plumbing code requirements (see 2017 FPC, sections 502, 503, 504 and, section 607).
- Hot water recirculating system piping does not exist and therefore does not meet the plumbing code requirements, where applicable. (See 2017 FPC section 607.2).



2.6 Plumbing System



The visible plumbing systems reflect the age of the building and are in need of replacement or remodel. Areas that have been impacted are the sanitary system and the storm system.

- o Plumbing fixtures are older and not up to current water efficiency standards, per FPC 604.4 “The maximum water consumption flow rates and quantities for all plumbing fixtures and fixture fittings shall be in accordance with Table 604.4.”

TABLE 604.4
 MAXIMUM FLOW RATES AND CONSUMPTION FOR
 PLUMBING FIXTURES AND FIXTURE FITTINGS

PLUMBING FIXTURE OR FIXTURE FITTING	MAXIMUM FLOW RATE OR QUANTITY ^b
Lavatory, private	2.2 gpm at 60 psi
Lavatory, public (metering)	0.25 gallon per metering cycle
Lavatory, public (other than metering)	0.5 gpm at 60 psi
Shower head ^a	2.5 gpm at 80 psi
Sink faucet	2.2 gpm at 60 psi
Urinal	1.0 gallon per flushing cycle
Water closet	1.6 gallons per flushing cycle

- o Kitchen – Some of the sanitary connection points are not up to code standards. See State of Florida Department of Health Chapter 64E-11 Food Hygiene.
- o Grease interceptor – The grease interceptor outside of the kitchen area needs to be regularly service. Staff has indicated that it backs up.
- o Emergency generator fuel storage tank: The transfer piping was leaking and is currently being repaired.



Photo 6
 Diesel fuel storage tank





- Make up water to the mechanical system will have to be replaced.



2.7 Electrical



Mix of Manufacturers

Interior lighting – 2' by 4' fluorescent lighting mainly. Look in good shape. Lighting will have to be brought up to current code. This would require daylight harvesting, 50% receptacle controls in all office, open office and Computer classrooms. This will require new light fixture that are capable of dimming.

Exterior lighting – Few building mounted lights for site lighting, not controlled properly. No Parking lot lighting, comments were made that teachers do not feel safe at night walking to car. Lighting outdoor pathways need to be recruited to light only the enclosed area

not open covered walkway. Broken pipes with exposed wire observed at portable

building and from the roof. Recommend adding site lighting for safety to both front drop off and bus drop off. Recommend rewiring exterior lighting controls for better control and energy savings. Will require additional lighting in spaces to meet minimum foot candle levels.



Insufficient Exterior Corridor Lighting

Emergency generator – Onco 100KW Generator. Is currently being repaired. Recommend replacing generator.

Fire alarm – Fire Alarm Panel appears to have been replaced in last 2 years. Devices appear to be mixed with older and newer devices (mainly newer looking). Outdoor Strobes waterproof covers have yellowed. Recommend replacing exterior yellow devices.

Power Distribution – Panels are all Square D. Panels are in rough shape, with Rust, latches not latching. Panel on site in fenced in enclosure is missing Panel cover and open to elements. Kitchen area only place where Gould Panels and Disconnects was observed in use. These are at end of life recommend replacement. Outlet in kitchen observed within 6' of water basin and not on GFI outlet/circuit. Outlet observed to have caught fire in on the mechanical rooms. Electrical rooms being used as storage space. Recommend replacing electrical in the kitchen area and update panels in this space to Square to match rest of campus for ease of maintenance. Recommend new storage spaces for school equipment as to avoid storage in electrical rooms.

Photovoltaic panels – Bracket holding the panels looks to be rusted through. Panels look to be in bad shape but still functional. Recommend replace the bracket holding the photovoltaic cell. Clean the Cell themselves.



No Safety Lighting Installed





3.1 Lightning Protection

1. The campus currently does not have lightning protection.

Recommendations:

1. We recommend that the UL Master Label lightning protection system be provided and installed on the campus that is compliant with NFPA 780.

3.2 Proposed Use, Student Population and Scope of Replacement/Remodel

1. The proposed use or program would remain the same as is currently designated. The demographics indicate growth in several of the neighborhoods that the school serves.

3. ADA Compliance

ADA Requirements for All Buildings:

1. Provide ADA compliant restrooms and drinking fountains as required.
2. Provide ADA compliant accessible loading zones and routes with from parking.
3. Provide ADA compliant doors and hardware.

The design and construction of this project shall comply with the following codes and standards.

1. FBC (Florida Building Code), 2017 Edition 6, Including:
 - a. FBC (Florida Existing Construction Building Code)
 - b. FBC Energy Conservation
 - c. FBC Mechanical
 - d. FBC Plumbing
 - e. FBC Fuel Gas
 - f. NEC (National Electric Code) 2002; FBC Charter 27
 - g. FBC Florida Accessibility Code for Building Construction
 - h. FBC References, Chapter 35
 - i. Florida Fire Prevention Code, FAC 69A-60, including:
 - ii. NFPA 1-2004 with adopted revisions
 - iii. NFPA 101-2004 with adopted revisions
 - iv. NFPA Codes listed in FAC 69A-.005
 - v. NFPA 45-00: Instructional Laboratories
 - vi. NFPA 88B-97: Repair Garages, (Auto Lab)
 - vii. Fire Safety in Existing Educational Facilities, FAC 69A-58
 - i. State Requirements for Educational Facilities (SREF)
 - j. ASCE 7-98: American Society of Civil Engineers
 - k. UL Fire Resistance Directory

Recommendations:

We recommend that Buildings 1, 2, 3, 4, 8, 9, 10 and 16 be demolished and replaced and that Buildings 11,12 and 20 be remodeled. Application of the Castaldi Formula for Modernization supports this recommendation. The items below are the specifics that would define the scope that should would need to be included if the building was to be renovated or remodeled.

- a. Remove and replace the exterior lighting installed in the covered walkway and the lighting on the exterior building to meet current Energy Code requirements
- b. Perform an asbestos abatement.
- c. Remove lead paint.
- d. Upgrade the building so that it is in compliant with the Florida Building Code and Fire Prevention requirements. Installation of Fire Protection Sprinklers is recommended.
- e. Remove and replace all existing exterior and interior doors, door hardware and windows.
- f. Harden all fenestrations to receive the load from the wind resistant windows.
- g. Bring all required fixtures and Restrooms into compliance with ADA requirements.



- h. All room finishes need to be refreshed.
- i. Remove and Replace the air handling unit with equipment that meets current codes.
- j. Remove and replace all plumbing fixtures.
- k. Provide a fire protection system integrated with the fire alarm system that will be installed in the near future.
- l. Provide and install an Energy Management System. It would improve efficiency and increase cost savings.
- m. Provide and install new power systems, such as electric panels.
- n. Provide and install new exterior LED lighting for the building and covered walkway.
- o. Provide and install new interior LED lighting where required.
- p. Upgrade the existing IT system. Upgrade the existing telephone system.
- q. Provide and install a new public address system.

1. Funding

- 1. To be Determined

2. Equipment Costs

- 2. To be Determined



**Office of Educational Facilities
Florida Department of
Education**

**Room Condition Change
Building Replacement/Raze**

District: Martin County School District
Contact Person: Garrett Grabowski

Phone: 772-223-3105 ext. 130

Facility/Campus Name: Palm City Elementary School
Facility Number (school districts only): 16-A

Building Number(s): 1, 2, 3, 4, 8, 9, 10 and 16 Parcel/Site Number(s): 5

This Proposed Project will:

- Change the condition of permanent rooms from satisfactory to unsatisfactory (if yes, go to Section I and complete certification in Section III). (Not applicable to community colleges)
 - Change the condition of permanent rooms from unsatisfactory to satisfactory (if yes, go to Section I and complete certification in Section III). (Not applicable to community colleges)
 - Raze permanent building(s) (if yes, go to Section II and complete certification in Section III).
 - Replace permanent building(s) (if yes, go to Section II and complete certification in Section III).
- Major Capital Outlay Funding Source(s) – Original Building
Major Capital Outlay Funding Source(s) – Replacement Building

This form is not required for razing a single, freestanding structure that is less than 750 NSF and is debt free, or multiple small structures on a single campus whose total area is less than 750 NSF and are debt free. This form must be completed for any structure 750 NSF or greater and any structure, regardless of size, that is not debt free.

A. DISTRICT/COMMUNITY COLLEGE CERTIFICATION

The district/community college must submit this certification document, completed and signed by the appropriate school officials, along with all required or necessary supporting documentation pertaining to the proposed project.

The Palm Beach County District School Board hereby certifies that:

- I. CONDITION CHANGE:** (Not applicable to community colleges)
 - 1. All room condition changes are consistent with State Requirements for Educational Facilities (SREF) standards and the Florida Fire Prevention Code (FFPC) requirements for the condition of space.
- II. RAZE/REPLACE PERMANENT BUILDING(S):**
 - 1. All fund sources have been researched and no current indebtedness or outstanding debt exists for the building(s) that will be razed and/or replaced.
 - 2. Funding Source(s):
 - a. Original Building: Unknown
 - b. If Replaced: To Be Determined

3. Voters of the district have approved local bonding for the project: Yes/No
 - a. Date of voter approval: _____
4. Imminent danger exists for the building(s) that will be razed and/or replaced.

III. CERTIFICATION SIGNATURES:

Garrett Grabowski
Facilities Director

Date

Laurie G. Gaylord
Superintendent

Date

Christia Li Roberts
Board Chair

Date

NOTE: Certification is required by the Superintendent and Director of Facilities Planning for room condition changes. Certification is required by the Superintendent/President and Board Chair to raze or replace permanent buildings.

OEF Form RCC-
BRR – March 2008

Submit signed form and supporting documents to:
Office of Educational Facilities, Room 1054
Florida Department of Education
325 West Gaines Street
Tallahassee, Florida 32399-0400

OEF Form RCC-
BRR – March 2008

- rooms in a permanent building.
 - 3. Space that has been determined to be unsatisfactory should not be occupied.
 - 4. Application of a facility replacement formula, such as the Castaldi generalized formula for modernization or other similar facilities study, does not necessarily mean that the condition of the identified spaces is unsatisfactory. The condition code cannot be changed simply due to the results of a planned replacement unless the integrity of the space meets the criteria identified to classify the space as unsatisfactory.
 - i. In order to change the space condition from unsatisfactory to satisfactory the district must certify that the space has been successfully reconditioned to meet all applicable regulations regarding occupancy requirements.
1. OEF Review:

- i. Site visit by OEF staff, when necessary.
 - ii. Concur with district rationale, data, and analyses:
 - 1. Building(s) approved as unsatisfactory; OEF will make the room condition code changes in FISH.
 - 2. Building(s) approved as satisfactory; OEF will make the room condition code changes in FISH.
 - iii. Disagree with district rationale, data, and analyses:
 - 1. Building(s) not approved as unsatisfactory.
 - 2. Building(s) not approved as satisfactory.
1. OEF Notify District of Findings and Decision:
- i. OEF staff will analyze the district's data along with all supporting documentation, coordinate any further reviews with the district, make a final decision regarding the proposed room condition changes, and provide a timely response either approving or disapproving the proposed room condition changes.

C. RAZE/REPLACE PERMANENT BUILDING(S)

1. RATIONALE (provide the following information, as appropriate, to justify razing/replacing permanent buildings):
- i. Detailed explanation of need for the proposed project and the expected benefit to the district/community college.
 - ii. General scope of the proposed project.
 - iii. Building age and year of construction.
 - iv. Existing capacity of building(s), include the number of student stations, classrooms, and other instructional spaces.
 - v. Current number of students housed and the projected number of students to be housed in the affected building(s).
 - vi. Current educational plant survey recommendations and capacity.
 - vii. What alternatives have been considered besides razing/replacement and why are the alternatives not feasible?
 - viii. School board/community college board approval of the concept of razing/replacing permanent buildings.
 - ix. Building condition/engineer study (optional).
 - x. Impact if the proposed project is not approved.

- xi. Other relevant data; identify any major systems (include date, if applicable) that have been replaced or upgraded, e.g., electrical, HVAC, fire alarm, roof, plumbing, drainage, etc. Provide a general scope of work for any previous remodeling, renovation, and addition, and year completed.
2. COST ANALYSIS (Building by Building):
- i. Castaldi Analysis (or other cost analysis formula to support the proposed project).
 - ii. The following five questions must be addressed:
 - 1. How many years will modernization extend the useful life of the modernized building(s)?
 - 2. Does the existing building(s) lend itself to improvement, alteration, remodeling, and expansion? If no, explain why not.
 - 3. Explain how a modernized and a replacement building(s) fits into a well-conceived long-range plan of the district/community college?
 - 4. What is the percentage derived by dividing the cost for modernization by the cost for a replacement building?
 - 5. A committee of district officials and independent citizens from outside the school attendance zone has determined that the replacement of the building(s) is financially justified and no other alternative is feasible? (Not applicable to community colleges)
 - i. Detailed scope of work for modernization of the existing building(s).
 - ii. FISH building plan and/or schematic drawings of the existing building with FISH room numbers.
2. OEF Review:
- i. Site visit by OEF staff, when necessary.
 - ii. Educational adequacy review.
 - iii. Concur with district/community college rationale, data, and analyses:
 - 3. Recommend replacement of building(s).
 - 4. Recommend razing building(s).
 - ii. Disagree with district/community college rationale, data, and analyses:
 - 4. Building(s) not approved to be replaced.
 - 5. Building(s) not approved to be razed.
4. OEF Notify District/Community College of Findings and Decision:
- i. OEF staff will analyze the district's/community college's data along with all supporting documentation, coordinate any further reviews with the district, make a final decision regarding the disposition of the proposed project, and provide a timely response either approving or disapproving the proposed request.

Palm City Elementary School
Castaldi Analysis

Building 1

	Palm City Elementary School	Castaldi Formula		Building 1
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1979		
	Year of Modernization	2020		
	Building Age	39 Years		
	Useful Life	24 Year		
	Building Area	22,359 SF		
	Additional Area	5,000		
	Renovation Area	22,359		
	Remodeling Area	22,359 SF		
	Total Area	27,359 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		$(CE+CH+CS) \times 1.2$	VS	R
		$LM \times IA$		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	27,359 sf x \$68 = \$1,860,412		
	Useful Life of Modernized Building	18		
	Educational Adequacy Index	0.75		
	Replacement Cost	27,359 sf x \$136/sf = \$3,720,824 + Demolish 22,359 sf x \$8.50 = \$190,052 Total = \$3,910,856		
	Estimated Life of New Building	65 Years		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		$\$1,860,412 \times 1.2 = \$2,232,495$	VS	$\$3,910,856$
		$24 \times .75 = 18$		65
	Results	\$93,021		\$60,167
	Percentage of Modernization to Replacement	64.68109351651780%	65%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			

Palm City Elementary School
Castaldi Analysis

Building 2

	Palm City Elementary School	Castaldi Formula		Building 2
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1958		
	Year of Modernization	2020		
	Building Age	60 Years		
	Useful Life	3 Year		
	Building Area	10,981 SF		
	Additional Area	0		
	Renovation Area	10,981		
	Remodeling Area	10,981 SF		
	Total Area	10,981 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		$(CE+CH+CS) \times 1.2$	VS	R
		$LM \times IA$		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	10,981 sf x \$68 = \$746,708		
	Useful Life of Modernized Building	2		
	Educational Adequacy Index	0.75		
	Replacement Cost	10,981 sf x \$136/sf = \$1,493,416 + Demolish 10,981 sf x \$8.50 = \$93,338 Total = \$1,586,755		
	Estimated Life of New Building	65 Years		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		$\underline{\$746,708 \times 1.2 = \$896,050}$	VS	$\underline{\$1,586,755}$
		$3 \times .75 = 2.25$		65
	Results	\$298,683		\$24,412
	Percentage of Modernization to Replacement	8.17321374165922%	8%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			

Palm City Elementary School
Castaldi Analysis

Building 3

	Palm City Elementary School	Castaldi Formula		Building 3
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1958		
	Year of Modernization	2020		
	Building Age	60 Years		
	Useful Life	5 Year		
	Building Area	11,257 SF		
	Additional Area	0		
	Renovation Area	11,257		
	Remodeling Area	11,257 SF		
	Total Area	11,257 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		<u>(CE+CH+CS) x 1.2</u>	VS	<u>R</u>
		LM x IA		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	11,257 sf x \$68 = \$765,476		
	Useful Life of Modernized Building	2		
	Educational Adequacy Index	0.75		
	Replacement Cost	11,257 sf x \$136/sf = \$1,530,952 + Demolish 11,257 sf x \$8.50 = \$95,685 Total = \$1,626,637		
	Estimated Life of New Building	65 Years		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		<u>\$765,476 x 1.2 = \$918,571</u>	VS	<u>\$1,626,637</u>
		3 x .75 = 2.25		65
	Results	\$408,254		\$25,025
	Percentage of Modernization to Replacement	6.12976235382874%	6%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			

Palm City Elementary School
Castaldi Analysis

Building 4

	Palm City Elementary School	Castaldi Formula		Building 4
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1967		
	Year of Modernization	2020		
	Building Age	51 Years		
	Useful Life	14 Year		
	Building Area	3,325 SF		
	Additional Area	0		
	Renovation Area	3,325		
	Remodeling Area	3,325 SF		
	Total Area	3,325 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		$(CE+CH+CS) \times 1.2$	VS	R
		$LM \times IA$		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	3,325 sf x \$68 = \$226,100		
	Useful Life of Modernized Building	2.25		
	Educational Adequacy Index	0.75		
	Replacement Cost	11,257 sf x \$136/sf = \$1,530,952 + Demolish 11,257 sf x \$8.50 = \$95,685 Total = \$1,626,637		
	Estimated Life of New Building	65 Years		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		$\underline{\$226,100 \times 1.2 = \$271,320}$	VS	$\underline{\$480,463}$
		$14 \times .75 = 11$		65
	Results	\$17,505		\$7,392
	Percentage of Modernization to Replacement	42.22793487574980%	42%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			

	Palm City Elementary School	Castaldi Formula		Building 8
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1979		
	Year of Modernization	2020		
	Building Age	39 Years		
	Useful Life	24 Year		
	Building Area	1,422 SF		
	Additional Area	0		
	Renovation Area	1,422		
	Remodeling Area	1,422 SF		
	Total Area	1,422 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		$(CE+CH+CS) \times 1.2$	VS	R
		$LM \times IA$		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	1,422 sf x \$68 = \$96,696		
	Useful Life of Modernized Building	24		
	Educational Adequacy Index	0.75		
	Replacement Cost	1,422 sf x \$136/sf = \$193,392 + Demolish 1,422 sf x \$8.50 = \$64,371 Total = \$205,479		
	Estimated Life of New Building	65		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		$\$514,964 \times 1.2 = \$617,957$	VS	$\$205,479$
		$24 \times .75 = 18$		65
	Results	\$10,274		\$3,161
	Percentage of Modernization to Replacement	30.76698462137430%	30%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			

Palm City Elementary School
Castaldi Analysis

Building 9

	Palm City Elementary School	Castaldi Formula		Building 9
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1979		
	Year of Modernization	2020		
	Building Age	39 Years		
	Useful Life	24 Year		
	Building Area	7,573 SF		
	Additional Area	0		
	Renovation Area	7,573		
	Remodeling Area	7,573 SF		
	Total Area	7,573 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		<u>(CE+CH+CS) x 1.2</u>	VS	<u>R</u>
		LM x IA		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	7,573 sf x \$68 = \$514,964		
	Useful Life of Modernized Building	24		
	Educational Adequacy Index	0.75		
	Replacement Cost	7,573 sf x \$136/sf = \$1,029,928 + Demolish 7,573 sf x \$8.50 = \$64,371 Total = \$1,094,299		
	Estimated Life of New Building	65		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		<u>\$514,964 x 1.2 = \$617,957</u>	VS	<u>\$1,094,299</u>
		24 x .75 = 18		65
	Results	\$34,331		\$16,835
	Percentage of Modernization to Replacement	49.03731321546120%	49%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			

Palm City Elementary School
Castaldi Analysis

Building 10

	Palm City Elementary School	Castaldi Formula		Building 10
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1979		
	Year of Modernization	2020		
	Building Age	39 Years		
	Useful Life	24 Year		
	Building Area	7,658 SF		
	Additional Area	0		
	Renovation Area	7,658		
	Remodeling Area	7,658 SF		
	Total Area	7,658 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		$(CE+CH+CS) \times 1.2$	VS	R
		$LM \times IA$		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	7,658 sf x \$68 = \$520,744		
	Useful Life of Modernized Building	24		
	Educational Adequacy Index	0.75		
	Replacement Cost	7,573 sf x \$136/sf = \$1,041,488 + Demolish 7,658 sf x \$8.50 = \$65,093 Total = \$1,106,581		
	Estimated Life of New Building	65		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		$\$520,744 \times 1.2 = \$624,893$	VS	$\$1,106,581$
		$24 \times .75 = 18$		65
	Results	\$26,037		\$17,024
	Percentage of Modernization to Replacement	65.38387679072090%	65%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			

Palm City Elementary School
Castaldi Analysis

Building 11

	Palm City Elementary School	Castaldi Formula		Building 11
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1980		
	Year of Modernization	2020		
	Building Age	40 Years		
	Useful Life	25 Year		
	Building Area	11,612 SF		
	Additional Area	0		
	Renovation Area	11,612		
	Remodeling Area	11,612 SF		
	Total Area	11,612 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		$(CE+CH+CS) \times 1.2$	VS	R
		$LM \times IA$		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	11,612 sf x \$68 = \$789,616		
	Useful Life of Modernized Building	25		
	Educational Adequacy Index	0.75		
	Replacement Cost	11,612 sf x \$136/sf = \$1,579,232 + Demolish 11,612 sf x \$8.50 = \$98,702 Total = \$1,677,934		
	Estimated Life of New Building	65		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		$\$789,616 \times 1.2 = \$947,540$	VS	$\$1,677,934$
		$25 \times .75 = 19$		65
	Results	\$49,870		\$37,902
	Percentage of Modernization to Replacement	76.00160417084420%	76%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			

Palm City Elementary School
Castaldi Analysis

Building 12

	Palm City Elementary School	Castaldi Formula		Building 12
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1980		
	Year of Modernization	2020		
	Building Age	40 Years		
	Useful Life	25 Year		
	Building Area	10,074 SF		
	Additional Area	0		
	Renovation Area	10,074		
	Remodeling Area	10,074 SF		
	Total Area	10,074 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		$(CE+CH+CS) \times 1.2$	VS	R
		LM x IA		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	10,074 sf x \$68 = \$685,032		
	Useful Life of Modernized Building	25		
	Educational Adequacy Index	0.75		
	Replacement Cost	10,074 sf x \$136/sf = \$1,370,064 + Demolish 10,074 sf x \$8.50 = \$85,629 Total = \$1,455,693		
	Estimated Life of New Building	65		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		$\$685,032 \times 1.2 = \$822,038$	VS	$\$11,455,693$
		$25 \times .75 = 19$		65
	Results	\$43,265		\$37,902
	Percentage of Modernization to Replacement	87.60429908702180%	87%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			

Palm City Elementary School
Castaldi Analysis

Building 16

	Palm City Elementary School	Castaldi Formula		Building 16
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1990		
	Year of Modernization	2020		
	Building Age	30 Years		
	Useful Life	35 Year		
	Building Area	15,305 SF		
	Additional Area	0		
	Renovation Area	15,305		
	Remodeling Area	15,305 SF		
	Total Area	15,305 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		$(CE+CH+CS) \times 1.2$	VS	R
		$LM \times IA$		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	15,305 sf x \$68 = \$1,040,740		
	Useful Life of Modernized Building	65		
	Educational Adequacy Index	0.75		
	Replacement Cost	15,305 sf x \$136/sf = \$2,081,480 + Demolish 15,305 sf x \$8.50 = \$130,093 Total = \$2,211,573		
	Estimated Life of New Building	25		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		$\$1,040,740 \times 1.2 = \$1,248,888$	VS	$\$2,211,573$
		$35 \times .75 = 26.25$		65
	Results	\$48,034		\$34,024
	Percentage of Modernization to Replacement	70.83315984510970%	70%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			


Palm City Elementary School
Castaldi Analysis

Building 20

	Palm City Elementary School	Castaldi Formula		Building 20
CE =	Cost of Educational Improvements			
CH =	Cost of Health and Aesthetic Improvements			
CS =	Cost of Building and Safety Improvements			
IA =	Estimated Index of Educational Adequacy	0.75		
LM =	Estimated Useful Life of Modernized Bldg.	(65 years - current age)		
R =	Cost of Replacement Bldg.	\$136/sf (2013 DOE)		
LR =	Estimated Life of New Bldg.	65 Years		
	<u>Building Information</u>			
	Year Built	1991		
	Year of Modernization	2020		
	Building Age	27 Years		
	Useful Life	36 Year		
	Building Area	873 SF		
	Additional Area	0		
	Renovation Area	873		
	Remodeling Area	873 SF		
	Total Area	873 SF		
	Castaldi Formula	Remodel	VS	Replacement Cost
		$(CE+CH+CS) \times 1.2$	VS	R
		LM x IA		LR
	Based on Cost per square foot			
	Renovation Cost	33.30% \$45/sf		(2013 DOE)
	Remodel Cost	50% \$68/sf		
	Replacement Cost	100% \$136/sf		
	Demolition Cost	7% \$8.50/sf		
	Cost of Educational Improvements	873 sf x \$68 = \$59,364		
	Useful Life of Modernized Building	25		
	Educational Adequacy Index	0.75		
	Replacement Cost	873 sf x \$136/sf = \$118,728 + Demolish 873 sf x \$8.50 = \$7,421 Total = \$126,149		
	Estimated Life of New Building	65		
	Castaldi Formula	Remodel Cost	VS	Replacement Cost
		$\underline{\$59,364 \times 1.2 = \$71,237}$	VS	$\underline{\$126,149}$
		$36 \times .75 = 27$		65
	Results	\$1,979		\$1,941
	Percentage of Modernization to Replacement	98.07983830217280%	98%	
	Preliminary results indicate the costs to renovate the facility appear to be higher than the valued cost for replace over the anticipated life of the building.			




Palm City Elementary School Facility Location



1951 SW 34th Street
Palm City, Florida 34990

FISH Site Plan, See EFIS for Inventory





Refer to Attachment 2 for Palm City Elementary School FISH
Inventory Reports



Florida DOE 2014 Report of Cost of Construction

FLORIDA DEPARTMENT OF EDUCATION PUBLIC SCHOOL DISTRICTS

DESIGN BUILD=YELLOW

ALL CONSTRUCTION
ALL SCHOOLS

CALENDAR YEAR 2014

Construction Contract Completed Between 1/1/2014 and 12/31/2014

January 2014 Cost per student station increases

Site 25.164
Site 22.666
High 25.728

TYPE	DISTRICT	NAME	FACILITY NAME	STATION STATIONS	TEACHERS	NO OF CLSRMS	NO OF CLSRMS	NO OF CLSRMS	NET SQUARE FEET	GROSS SQUARE FEET	LEGAL ADM.	ARCHITECT ENGR	SITE	CONTRACT	FURNITURE AND EQUIPMENT	TOTAL FACILITY COST	TOTAL STATION COST	HURRICANE SHELTER	SITE COST	PUBLIC UTILITIES COST	DRAINAGE AND/OR ROAD ACCESS COST	RETENTION AREA COST	ENVIROM. COST	TOTAL PLANT COST	CONST. COST PER STATION	PLANT COST PER STATION	PER SQUARE FOOT	REVENUE CODES		
																													STATION STATIONS	TEACHERS
1	DeSoto	DeSoto High School	DeSoto High School	1072	48	0	0	0	123,559	197,978	762,966	2,162,275	34,473,975	462,187	35,615,381	46,223	1,174,475	119,968	0	0	0	0	0	0	32,360	35,256	162	6,147.17	16.19	
1	Indian River	Palmetto Elementary	Palmetto Elementary	0	6	0	0	0	8,513	10,094	0	280,337	574,193	1,423,974	299,360	2,547,824	0	0	0	0	0	0	0	2,580,259	0	0	256	18.18		
1	Indian River	Palmetto Elementary	Palmetto Elementary	274	15	0	0	0	22,469	31,092	0	386,194	873,834	4,233,390	107,500	5,620,718	20,580	0	0	0	0	0	0	5,843,152	15,523	20,866	192	16.18		
1	Indian River	Treasure Coast Elementary	Treasure Coast Elementary	220	10	0	0	0	12,533	18,498	0	208,356	269,000	3,342,273	126,650	3,841,879	17,917	0	0	0	0	0	0	3,843,343	15,192	11,824	213	16.18		
2	Lake	Mc Dora MS	Mc Dora MS	252	16	0	0	0	20,705	28,292	0	382,719	14,898	9,115,430	341,741	9,849,743	16,617	0	0	0	0	0	0	3,932,443	14,516	16,526	250	16.18		
3	Law	Quaker High School	Quaker High School	1,655	109	0	0	29	239,000	294,000	3,009	1,037,000	56,000	23,421,627	3,200,000	27,715,627	15,186	0	0	0	0	0	0	27,715,627	12,834	15,166	107	16.18		
3	Madison	Lee Elementary	Lee Elementary	0	0	0	0	0	745	758	0	2,972	22,242	0	25,214	0	0	0	0	0	0	0	0	25,214	0	0	95	16.18		
1	Orange	Dr. Philip ES	Dr. Philip ES	960	45	0	0	0	69,297	72,617	0	827,933	1,956,671	8,150,993	830,824	11,670,561	17,640	0	0	0	0	0	0	178,373	303,800	13,844,818	12,380	21,528	191	16.18
1	Orange	John Young ES	John Young ES	832	54	0	0	0	70,068	84,111	0	644,445	1,438,471	8,916,724	1,037,820	11,991,500	14,341	0	0	0	0	0	0	25,215	12,646,647	10,590	14,842	147	16.18	
1	Orange	Little River ES	Little River ES	500	34	0	0	0	81,570	91,780	0	1,212,782	1,742,327	8,202,194	705,810	11,263,093	22,328	0	0	0	0	0	0	1,233,000	284,873	16,464	25,817	207	16.18	
1	Orange	Osceola ES	Osceola ES	930	53	0	0	0	82,147	93,220	0	860,662	1,470,389	9,288,070	1,039,087	12,666,105	15,519	0	0	0	0	0	0	96,917	12,640,772	11,189	15,220	143	16.18	
1	Orange	Phoebe ES	Phoebe ES	830	53	0	0	0	82,147	93,220	0	822,289	1,426,793	9,343,280	1,048,877	12,433,759	14,969	0	0	0	0	0	0	8,196	12,479,472	11,287	15,254	140	16.18	
1	Orange	Shingle Creek ES	Shingle Creek ES	1,330	83	0	0	0	79,008	84,111	0	638,833	1,948,410	8,933,494	1,228,740	11,609,067	14,045	0	0	0	0	0	0	1,814,833	19,339	10,577	15,325	162	16.18	
1	Orange	Spring Lake ES	Spring Lake ES	627	40	0	0	0	70,096	72,794	0	648,903	1,276,100	9,748,510	874,049	12,566,568	20,941	0	0	0	0	0	0	27,515	12,633,282	15,380	20,149	174	16.18	
1	Orange	Waukegan Shores ES	Waukegan Shores ES	884	49	0	0	0	77,892	82,949	0	591,791	1,096,661	10,068,098	664,356	11,970,419	19,938	0	0	0	0	0	0	54,301	13,888,242	14,720	19,136	167	16.18	
1	Orange	Wheatley ES	Wheatley ES	660	36	0	0	0	77,207	79,521	0	740,795	1,083,517	9,153,893	803,731	11,781,321	21,679	0	0	0	0	0	0	30,943	13,896,698	16,346	21,173	148	16.18	
1	Ocala	Central Avenue Elementary School	Central Avenue Elementary School	308	14	0	0	0	98,333	109,825	8,190	144,377	271,882	2,822,828	233,544	3,482,881	11,959	0	0	0	0	0	0	0	3,492,881	9,165	11,368	178	16.18	
3	Ocala	Calhoun High School	Calhoun High School	500	30	0	0	17	23,300	35,938	26,106	799,695	383,343	4,992,091	425,114	6,198,939	12,334	0	0	0	0	0	0	0	6,198,939	9,964	12,334	172	16.18	
1	Ocala	History Tree Elementary School	History Tree Elementary School	309	14	0	0	0	13,664	16,330	7,790	170,631	231,376	2,267,998	270,628	3,078,973	9,594	0	0	0	0	0	0	0	3,078,973	7,786	9,964	166	16.18	
1	Palm Beach	The Conservatory School of North Palm	The Conservatory School of North Palm	753	52	0	0	0	89,261	117,600	0	1,570,733	3,970,758	17,577,796	734,515	21,633,933	30,396	443,318	0	0	0	0	0	0	22,077,152	23,344	29,717	190	16.18	
1	Pasco	Schreier Elementary	Schreier Elementary	498	27	0	0	0	75,626	84,980	0	741,224	1,217,162	10,620,662	79,852	13,600,680	25,523	0	0	0	0	0	0	177,270	13,725,091	21,327	27,561	162	16.18	
4	Pineles	Pineles Elementary School	Pineles Elementary School	0	0	0	0	0	0	0	1,548	45,322	27,865	587,280	0	661,993	0	0	0	0	0	0	0	0	661,993	0	0	270	16.18	
4	Santa Rosa	Chumuckla Elementary	Chumuckla Elementary	0	0	0	0	0	13,841	13,838	0	194,670	213,300	1,840,937	378,429	2,629,336	0	0	0	0	0	0	0	86,000	2,723,300	0	0	172	16.18	
4	Santa Rosa	Queen Intermedial	Queen Intermedial	0	0	0	0	0	3,830	4,133	0	94,094	93,058	648,119	288,190	1,084,343	0	0	0	0	0	0	0	1,084,343	0	0	284	16.18		
4	Santa Rosa	Tall Branch High	Tall Branch High	0	0	0	0	0	8,098	9,146	0	189,628	40,495	1,423,419	32,587	1,601,809	0	0	0	0	0	0	0	4,790	82,992	0	0	236	16.18	
3	Santa Rosa	Jay High	Jay High	81	2	0	0	2	5,327	7,037	0	11,048	88,367	808,817	97,219	994,842	18,311	0	0	0	0	0	0	0	1,019,158	13,284	16,707	143	16.17	
3	Santa Rosa	Jay High	Jay High	0	0	0	0	0	12,285	14,286	0	184,645	138,982	1,841,935	346,470	2,391,242	0	0	0	0	0	0	0	49,064	3,346,300	0	0	164	16.17	
3	Santa Rosa	Milton High	Milton High	150	8	0	0	6	11,189	12,147	0	156,107	81,004	1,868,189	83,408	1,987,806	13,252	11,862	0	0	0	0	0	23,446	17,900	2,940,807	11,112	13,664	168	16.18
4	Sarasota	Sarasota High School	Sarasota High School	0	0	0	0	0	296,090	0	20,000	4,600,000	7,400,000	42,200,000	3,200,000	54,800,000	0	1,004,422	0	0	0	0	0	1,350,000	35,800	57,209,422	0	0	16,17.16.18	
1	Suwannee	Suwannee Primary School	Suwannee Primary School	54	3	0	0	0	2,513	0	0	27,979	0	287,884	23,811	309,433	5,730	0	0	0	0	0	0	0	309,433	4,776	5,730	0	16.17.16.18	
3	Volusia	Volusia High School	Volusia High School	20	1	0	0	1	1,001	0	0	28,897	0	429,495	8,441	460,516	20,697	0	0	0	0	0	0	0	460,516	27,426	23,371	139	16.17	
Total				534	34	28	0	0	93,392	89,696	5,435	687,611	1,085,873	7,492,187	654,617	9,765,122	17,538	26,678	289,914	26,426	15,716	11,551	46,318	16,114,235	13,680	18,164	162			
17	Elem Average			352	16	8	16	0	28,255	28,282	0	388,718	18,859	5,116,430	341,141	5,849,143	18,917	0	0	0	0	0	0	3,452,443	14,518	16,628	289			
6	High Average			465	30	8	0	17	87,187	84,063	122,846	897,385	97,289	16,443,691	775,531	12,156,579	18,899	1,377	192,412	34,849	4,844	100,192	65,463	12,911,288	16,324	19,416	152			
8	Other Average			6	0	0	0	0	42,321	6,711	2,697	168,338	3,921,027	6,195,198	314,489	8,176,324	8	128,444	0	4,778	27,920	160,756	4,278	6,848,997	0	0	181			
24	State Average			487	27	16	5	8	47,465	54,654	42,760	567,877	371,071	7,684,728	690,487	9,216,946	17,631	9,362	136,776	17,482	8,653	37,348	38,054	8,916,681	14,414	18,943	173			