



## **Asbestos & Lead Based Paint Assessment**

City of Spartanburg  
342 Ridgewood Avenue  
Spartanburg, South Carolina 29306

***Prepared for:***

The City of Spartanburg  
440 South Church St., Suite B  
Spartanburg, South Carolina 29306

***Prepared by:***

Apex Environmental Management, Inc.  
7 Winchester Court  
Mauldin, South Carolina 29662

Project Number: 0119-09

May 20, 2019





Apex Project Number 0119-09

May 20, 2019

Mr. Jeff Tillerson  
City of Spartanburg  
440 South Church Street, Suite B  
Spartanburg, SC 29306

Reference: Asbestos and Lead-Based Paint Assessment Services  
342 Ridgewood Avenue  
Spartanburg, South Carolina 29306

Dear Mr. Tillerson:

Apex Environmental Management, Inc. (Apex) is pleased to provide the results of our assessment services for the referenced property.

This report and the associated attachments summarize our evaluation of the conditions observed at the project site. The findings presented by Apex are based upon sampling performed in the subject building. There is a chance that undetected ACM may exist in the building between walls or in other areas that would only be exposed during demolition or structural renovations. Should material be discovered that could potentially contain asbestos during the demolition process, additional samples of the material should be collected by a licensed asbestos inspector and submitted to an accredited laboratory for analytical interpretation. Our recommendations are based on the guidelines presented in EPA and/or OSHA regulations.

Please note that this document is not a specification for asbestos removal. It does not contain means and methods for abatement. Quantities are estimates and contractors must verify amounts prior to bidding or removal. If you are planning an abatement project, please contact Apex to discuss the requirements. Use of this document without the express written consent of Apex is at the sole risk of the user and or/abatement contractor.

The conclusions and/or recommendations contained in this report are based on our understanding of the applicable standards at the time this report was prepared. No warranty, expressed or implied, is made. If you have any questions please feel free to contact us at (864) 404-3210.

Respectfully submitted,  
**APEX ENVIRONMENTAL MANAGEMENT, INC.**

A handwritten signature in blue ink, appearing to read 'Tom Oliver', is written over a horizontal line.

Tom Oliver  
Director of Operations

Appendices

7 Winchester Court  
Mauldin, SC 29662  
864.404.3210 office  
864.404.3213 fax

802 E. Martintown Rd  
N. Augusta, SC 29841  
803.440-2790 office

[www.apex-ehs.com](http://www.apex-ehs.com)

## SERVICES

Indoor Air Quality

Mold Remediation

Asbestos & Lead

Industrial Hygiene

Worker Health &  
Safety

Mold Consulting

Moisture  
Management  
Plans

Safety  
Assessment

Environmental Site  
Assessments

Hazard  
Communication

**ASBESTOS AND LEAD BASED PAINT ASSESSMENT**

**CITY OF SPARTANBURG  
342 RIDGEWOOD AVENUE  
SPARTANBURG, SOUTH CAROLINA 29306**

**APEX PROJECT NO. 0119-09**

**TABLE OF CONTENTS**

**SECTION**

- I Asbestos & Lead Evaluation Report
- II Asbestos & LBP Data Tables
- III Laboratory Analytical Results & Chain of Custody
- IV Photographic Log
- V SC DHEC Asbestos Inspector License

**SECTION I**

**Asbestos & Lead Evaluation Report**

**ASBESTOS EVALUATION REPORT**  
**APEX PROJECT NUMBER: 0119-09**

|                        |  |                             |                        |
|------------------------|--|-----------------------------|------------------------|
| Date:                  | 5/20/2019  | Page Number:                | 1 of 5                 |
| Client:                | City of Spartanburg  | Client Contact:             | Mr. Jeff Tillerson     |
| Client Address:        | 440 South Church Street<br>Suite B<br>Spartanburg, SC 29306              | Client Phone Number:        | (864) 596-2911         |
| Project:               | Asbestos Evaluation and Lead Based Paint Assessment                      |                             |                        |
| Property Address:      | 342 Ridgewood Avenue<br>Spartanburg, SC 29306                            |                             |                        |
| Assessor:              | Tom Oliver   | Date of Assessment:         | 5/3/2019               |
| Company:               | Apex Environmental Management<br>7 Winchester Court<br>Mauldin, SC 29662 | Phone Number:               | (864) 404-3210         |
| Purpose of Assessment: | Demolition   | Age of Structure:           | Approximately 90 years |
| Building Type:         | Residential  | Number of Stories:          | 1                      |
| Foundation:            | Partial Finished Basement & Partial Crawlspace                           | Approximate Square Footage: | 2,140 SF               |

**EXTERIOR BUILDING MATERIALS**

- Flat wooden roof with shingles, tar & felt on the front porch.
- Pitched wooden roof with tar & no felt on the main house.
- Tar on 1 chimney & on brick wall on left side of house on previous roof location.
- Brick siding/walls over felt & wooden shake shingle siding over wood.
- Wooden windows with glazing on the brick/wooden casings & on glass panes.
- Wooden doors with caulk on the brick/wooden casings.
- Portions of the front porch & main house roofs unstable and collapsing.

**INTERIOR BUILDING MATERIALS**

- Plaster with finish with skim coat throughout main level.
- Multiple types & layers of vinyl floor with & without mastics in the main level & basement.
- Wooden & ceramic tiled floors on the main level.
- Concrete walls with a skim coat in the basement.
- Drywall with joint compound & tape ceiling in the basement.
- HVAC "A" tape in the basement & crawlspace.
- The floors are unstable & collapsing throughout the main level.

## **SCOPE OF THE SURVEY**

The objectives of the asbestos and lead assessment included the following:

- Identification of suspect asbestos-containing material (ACM) and lead based paints (LBP) in readily observable locations. Limited demolition of building finishes was conducted.
- Asbestos survey with sample collection by a South Carolina accredited inspector.
- Suspect ACM analysis by polarized light microscopy (PLM) utilizing EMSL Analytical, Inc. (EMSL) as an NVLAP certified laboratory, their accreditation number is 200841-0.
- Transmission electron microscopy (TEM) analysis of non-friable organically bound materials suspected to contain asbestos and testing negatively by PLM analysis.
- Lead inspection by a lead inspector certified by the Environmental Protection Agency and licensed to conduct LBP surveys in South Carolina.
- In situ analysis of suspected lead based paints by X-ray fluorescence (XRF).
- Presenting the results in a report identifying confirmed ACMs and LBPs.

## **METHODS**

### **Asbestos Containing Materials**

In order to determine if the suspect materials observed during the visual survey contained asbestos, representative bulk samples were collected and placed in sealed packages. Forty-seven (47) bulk samples were collected during the survey and submitted to EMSL in Pineville, North Carolina for analysis using the EPA recommended method of Polarized Light Microscopy (PLM) coupled with dispersion staining (Method No. EPA 600/M4-82-020, Dec. 1982). EMSL participates in the National Voluntary Laboratory Accreditation Program (NVLAP). Their NVLAP accreditation number is 200841-0. EPA regulations require that multiple samples of each homogeneous material be collected for laboratory analysis. In accordance with South Carolina Regulation 61-86.1, non-friable organically bound materials that are reported to be non-asbestos containing by PLM analysis must also be analyzed by Transmission Electron Microscopy (TEM). Eleven (11) samples were analyzed using TEM.

### **Lead-Based Paint**

Lead painted surfaces were analyzed in place using X-ray fluorescence. Painted surfaces were selected based on color of topcoat, underlying layers and substrate on which it was painted.

## **RESULTS**

### **Asbestos Results**

The EPA defines an asbestos-containing material (ACM) as a material containing more than 1% asbestos. OSHA defines ACM as a material containing detectable amounts of asbestos. Provided below is a general discussion of the asbestos containing materials identified in the residence. A specific *PLM and TEM Data Table* is located in Appendix II of this report and identifies positive materials and designates approximate quantities.

Suspect asbestos containing materials that were identified to be asbestos containing include:

- Approximately 400 SF of tar on roof shingles on the front porch roof.
- Approximately 30 LF of tar on 1 chimney & on brick wall on the left side of the house at the previous roof location near the side door.
- Approximately 21 wooden/brick window casings with glazing.
- Approximately 4 wooden/brick door casings with caulk.
- Approximately 240 SF of tan & blue pattern vinyl floor in the kitchen & dining room (2<sup>nd</sup> layer) & pantry (top layer).
- Approximately 425 SF of 12" x 12" tan rock fissure pattern floor tile & black mastic throughout the finished portion of the basement.
- Approximately 425 SF of the drywall ceiling system throughout the finished portion of the basement.
- Approximately 50 SF of HVAC "A" tape on metal ducts throughout the finished portion of the basement & crawlspace.

#### Lead Based Paint

OSHA does not recognize a threshold level of lead for definition purposes, only the presence or absence of lead. The current OSHA regulations recognize an airborne action level of thirty micrograms per cubic meter (30  $\mu\text{g}/\text{m}^3$ ) during an eight-hour workday and a permissible exposure level of fifty micrograms per cubic meter (50  $\mu\text{g}/\text{m}^3$ ) for employees.

Currently, SCDHEC defines LBP as paint containing in excess of, or equal to, 1.0 mg/cm<sup>2</sup>. The laboratory analytical results are included in the LBP Analysis Report in Appendix II of this report. The approximate locations of the paint samples collected and analytical results are presented in the *LBP Data Table* included in Appendix II of this report.

Several surfaces in the building tested positive for lead in excess of the regulatory definition:

#### Exterior:

- White wooden doors & window systems.
- Beige wooden front porch columns & upper walls.
- Beige concrete front porch wall caps.
- Beige wooden soffits.
- White wooden roof overhang & shake shingle siding.
- White wooden back porch framing, ceiling & floor skirt.
- Grey wooden door casings.
- White metal window & door lintels.

#### Interior:

- Beige plaster walls.

- White ceramic tiled walls.
- White metal bath tub.

## **RECOMMENDATIONS AND DISCUSSION**

### **Asbestos Containing Materials**

If the above referenced asbestos materials are to be disturbed by renovations or demolition, the asbestos must be removed in accordance with EPA, State of South Carolina and OSHA asbestos regulations. The State of South Carolina, Department of Health and Environmental Control (DHEC) has specific regulations that must be adhered to during asbestos removal/abatement projects.

Apex recommends the following:

1. Abate the asbestos containing materials in the structure prior to renovation or demolition.
2. Follow applicable asbestos regulations during renovation or demolition of the structure. You should be aware that stringent requirements are imposed upon anyone renovating or demolishing a structure in which ACM will be disturbed. This work must be performed in accordance with OSHA asbestos regulations, 29 CFR 1910 & 1926, and NESHAP asbestos regulations 40 CFR 61, subpart M. South Carolina regulations require the accreditation of personnel who work in the asbestos field and notification and permitting fees for asbestos removal projects. There is a 10 working day notification period required prior to abatement of asbestos in a facility. Failure to take proper precautions and actions to protect human health and the environment can result in penalties, danger to personnel, and construction delays.

### **Lead-Based Paint**

Currently SCDHEC defines LBP as paint containing greater than 1.0 milligrams per square centimeter ( $\text{mg}/\text{cm}^2$ ) lead or in excess of, or equal to, 0.5 percent lead. Building materials identified as being painted with LBP should be segregated from the other building materials and recycled or disposed of in a municipal lined landfill.

Changes to SC DHEC and federal regulations have changed the disposal options for LBP waste and LBP residue. LBP waste is defined as material such as wood, brick, metal, etc. that is coated with LBP. LBP residue is defined as residue that is generated from the removal (scraped, chipped, sandblasted, chemical means, etc.) of LBP from a structure. The regulations allow LBP waste from residential and commercial structures to be disposed of in Class 2 (construction and demolition debris) and Class 3 (municipal solid waste or industrial) landfills in South Carolina. The management of LBP residue is based on the source and lead concentration characterized by Toxic Characteristic Leaching Procedures (TCLP) to determine if the waste is classified as hazardous or non-hazardous. LBP residues that have TCLP sample results less than 5 milligrams per liter ( $\text{mg}/\text{L}$ ) lead may be disposed of in a Class 3 landfill and is considered to be non-hazardous. LBP residues that have TCLP sample results equal to or greater than 5  $\text{mg}/\text{L}$  lead should be disposed of in a Subtitle C landfill and is considered to be hazardous. However, the landfills should be contacted to determine their specific disposal requirements.

*City of Spartanburg  
342 Ridgewood Avenue  
Apex Project No. 0119-09  
May 20, 2019*

Occupational Safety and Health Administration Lead Regulations apply to actions initiated on lead containing materials. This regulation applies to lead concentrations greater than the analytical limit of detection. This regulation sets exposure levels on airborne lead and does not reference the percent lead in paint. Therefore, initial personal air monitoring should be conducted on workers performing work on surfaces which have a lead concentration of 0.1 mg/cm<sup>2</sup> or above to satisfy the OSHA requirements. If a baseline exposure lower than the OSHA Action Level of 30 micrograms per cubic meter ( $\mu\text{g}/\text{m}^3$ ) is established, personal air monitoring may be terminated. The full OSHA lead standard should be referenced for compliance.

**A copy of this report must be submitted to SCDHEC at least ten (10) working days prior to demolition when applying for a demolition permit.**

**SECTION II**

**Asbestos & LBP Data Tables**

**ASBESTOS SURVEY FIELD DATA SHEET  
PLM & TEM ANALYSIS**

Project Name: COS 342 Ridgewood Avenue ACM/LBP

Sampled By: Tom Oliver

Project Location: 342 Ridgewood Avenue, Spartanburg, SC 29306

Project Manager: Tom Oliver

Project Number: 0119-09

Date: 5/3/2019

| Sample No. | Location   | Sample Description                             | Analytical Results                           | Friable/Non Friable | Condition             | Quantity |
|------------|--|--|--|---------------------|-----------------------|----------|
| 1          | Front porch roof   | Roof shingles (2 layers) with tar & felt       | PLM - 3% chry (tar)<br>NAD (shingles & felt) | Non-Friable         | Good                  | 400 SF   |
| 2          |  |  |  |                     |                       |          |
| 3          |  |  | TEM - NAD (shingles & felt)                  |                     |                       |          |
| 4          | Main house roof  | Roof shingles (1 layer) with tar & no felt     | PLM - NAD                                    | Non-Friable         | Good                  | 2,100 SF |
| 5          |  |  |  |                     |                       |          |
| 6          |  |  | TEM - NAD                                    |                     |                       |          |
| 7          | Tar on brick wall on left side of house on previous roof & chimney | Tar on previous roof flashing & chimney        | 4% chrysotile                                | Non-Friable         | Good                  | 30 LF    |
| 8          |  |  |  |                     |                       |          |
| 9          |  |  |  |                     |                       |          |
| 10         | Wooden/brick window casings  | Window casing glazing                          | 2% chrysotile                                | Non-Friable         | Good                  | 21 EA    |
| 11         |  |  |  |                     |                       |          |
| 12         |  |  |  |                     |                       |          |
| 13         | Wooden windows   | Window glazing                                 | PLM - NAD                                    | Non-Friable         | Good                  | 21 EA    |
| 14         |  |  |  |                     |                       |          |
| 15         |  |  | TEM - NAD                                    |                     |                       |          |
| 16         | Wooden/brick door casings  | Door casing caulk                              | 2% chrysotile                                | Non-Friable         | Good                  | 4 EA     |
| 17         |  |  |  |                     |                       |          |
| 18         |  |  |  |                     |                       |          |
| 19         | Throughout main level  | Plaster with finish with skim coat             | PLM - NAD                                    | Friable             | Significantly Damaged | 4,300 SF |
| 20         |  |  |  |                     |                       |          |
| 21         |  |  |  |                     |                       |          |
| 22         |  |  |  |                     |                       |          |
| 23         |  |  |  |                     |                       |          |
| 24         | Dining room & kitchen patches (top layer)                          | 12" x 12" wooden pattern self-stick floor tile | PLM - NAD                                    | Non-Friable         | Good                  | 75 SF    |
| 25         |  |  |  |                     |                       |          |
| 26         |  |  | TEM - NAD                                    |                     |                       |          |

**ASBESTOS SURVEY FIELD DATA SHEET  
PLM & TEM ANALYSIS**

Project Name: COS 342 Ridgewood Avenue ACM/LBP

Sampled By: Tom Oliver

Project Location: 342 Ridgewood Avenue, Spartanburg, SC 29306

Project Manager: Tom Oliver

Project Number: 0119-09

Date: 5/3/2019

| Sample No. | Location  | Sample Description  | Analytical Results                                  | Friable/Non Friable | Condition | Quantity |
|------------|---|---|---|---------------------|-----------|----------|
| 27         | Kitchen - top layer   | 12" x 12" beige multi-square pattern self-stick floor tile  | PLM - NAD   | Non-Friable         | Good      | 145 SF   |
| 28         |   |   | TEM - NAD   |                     |           |          |
| 29         |   |   |   |                     |           |          |
| 30         | Kitchen & dining room - 2nd & 3rd layers; pantry 1st & 2nd layers | Tan & blue pattern vinyl floor with no mastic over brown rectangle pattern vinyl floor with no mastic | PLM - 8% chry (tan & blue floor); NAD (brown floor) | Non-Friable         | Good      | 240 SF   |
| 31         |   |   | TEM - NAD (brown floor)                             |                     |           |          |
| 32         |   |   |   |                     |           |          |
| 33         | Beneath exterior brick siding                                     | Felt paper  | PLM - NAD   | Non-Friable         | Good      | 1,900 SF |
| 34         |   |   | TEM - NAD   |                     |           |          |
| 35         |   |   |   |                     |           |          |
| 36         | Throughout the finished portion of the basement                   | 12" x 12" tan rock fissure pattern floor tile & black mastic  | PLM - 3% chry (floor tile) 6% (black mastic)        | Non-Friable         | Good      | 425 SF   |
| 37         |   |   |   |                     |           |          |
| 38         |   |   |   |                     |           |          |
| 39         | Throughout the finished portion of the basement                   | Skim coat over concrete walls   | PLM - NAD   | Friable             | Good      | 650 SF   |
| 40         |   |   |   |                     |           |          |
| 41         |   |   |   |                     |           |          |
| 42         | Throughout the finished portion of the basement                   | Drywall with joint compound & tape ceilings   | PLM - 3% chrysotile                                 | Friable             | Good      | 425 SF   |
| 43         |   |   |   |                     |           |          |
| 44         |   |   |   |                     |           |          |
| 45         | Throughout the finished portion of the basement & crawlspace      | HVAC "A" tape on metal ducts  | 60% chrysotile                                      | Friable             | Good      | 50 SF    |
| 46         |   |   |   |                     |           |          |
| 47         |   |   |   |                     |           |          |

NAD = No Asbestos Detected

LF = Linear Feet

EA = Each

Amos = Amosite

**Bold = Positive For Asbestos**

SF = Square Feet

Chry = Chrysotile

FT3 = Cubic Feet

**FIELD DATA SHEET  
XRF LBP ANALYSIS**

Project Name: COS 342 Ridgewood Avenue ACM/LBP

Sampled By: Tom Oliver

Project Location: 342 Ridgewood Avenue, Spartanburg, SC 29306

Project Manager: Tom Oliver

Project Number: 0119-09

Date: 5/17/2019

| Sample No. | Sample Location       | Component                        | Color        | Substrate       | Analytical Result (mg/m <sup>3</sup> ) |
|------------|-----------------------|----------------------------------|--------------|-----------------|--|
| 1          |                       | Standardization                  |              |                 | 185.00                                 |
| 2          |                       | Calibration                      |              |                 | 1.20                                   |
| 3          |                       | Calibration                      |              |                 | 1.13                                   |
| 4          |                       | Calibration                      |              |                 | 1.12                                   |
| 5          | Exterior              | Door                             | Black        | Wood            | 0.09                                   |
| 6          | <b>Exterior</b>       | <b>Door casing</b>               | <b>White</b> | <b>Wood</b>     | <b>1.72</b>                            |
| 7          | <b>Exterior</b>       | <b>Window casing</b>             | <b>White</b> | <b>Wood</b>     | <b>1.24</b>                            |
| 8          | <b>Exterior</b>       | <b>Front porch column</b>        | <b>Beige</b> | <b>Wood</b>     | <b>2.61</b>                            |
| 9          | <b>Exterior</b>       | <b>Front porch wall cap</b>      | <b>Beige</b> | <b>Concrete</b> | <b>1.96</b>                            |
| 10         | <b>Exterior</b>       | <b>Front porch upper wall</b>    | <b>Beige</b> | <b>Wood</b>     | <b>5.00</b>                            |
| 11         | Exterior              | Front porch ceiling frame        | White        | Wood            | 0.00                                   |
| 12         | Exterior              | Shake shingle siding             | Beige        | Wood            | 0.40                                   |
| 13         | <b>Exterior</b>       | <b>Soffit</b>                    | <b>Beige</b> | <b>Wood</b>     | <b>2.07</b>                            |
| 14         | Exterior              | Fascia                           | Beige        | Wood            | 0.91                                   |
| 15         | Exterior              | Fascia                           | White        | Wood            | 0.90                                   |
| 16         | <b>Exterior</b>       | <b>Roof overhang</b>             | <b>White</b> | <b>Wood</b>     | <b>1.67</b>                            |
| 17         | <b>Exterior</b>       | <b>Shake shingle siding</b>      | <b>White</b> | <b>Wood</b>     | <b>2.61</b>                            |
| 18         | Exterior              | Door                             | White        | Wood            | 0.07                                   |
| 19         | <b>Exterior</b>       | <b>Back porch framing</b>        | <b>White</b> | <b>Wood</b>     | <b>1.41</b>                            |
| 20         | <b>Exterior</b>       | <b>Back porch ceiling</b>        | <b>White</b> | <b>Wood</b>     | <b>1.83</b>                            |
| 21         | <b>Exterior</b>       | <b>Back porch floor skirt</b>    | <b>White</b> | <b>Wood</b>     | <b>3.03</b>                            |
| 22         | <b>Exterior</b>       | <b>Door casing</b>               | <b>Grey</b>  | <b>Wood</b>     | <b>3.96</b>                            |
| 23         | Exterior              | Door                             | Red          | Wood            | 0.02                                   |
| 24         | <b>Exterior</b>       | <b>Door &amp; window lintels</b> | <b>White</b> | <b>Metal</b>    | <b>1.85</b>                            |
| 25         | Interior - Main Level | Fireplace                        | White        | Brick           | 0.06                                   |

# FIELD DATA SHEET XRF LBP ANALYSIS

Project Name: COS 342 Ridgewood Avenue ACM/LBP

Sampled By: Tom Oliver

Project Location: 342 Ridgewood Avenue, Spartanburg, SC 29306

Project Manager: Tom Oliver

Project Number: 0119-09

Date: 5/17/2019

| Sample No. | Sample Location              | Component        | Color        | Substrate           | Analytical Result (mg/m <sup>3</sup> ) |
|------------|------------------------------|------------------|--------------|---------------------|--|
| 26         | Interior - Main Level        | Wall             | White        | Plaster             | 0.06                                   |
| 27         | Interior - Main Level        | Door casing      | White        | Wood                | 0.20                                   |
| 28         | Interior - Main Level        | Base board       | White        | Wood                | 0.10                                   |
| 29         | Interior - Main Level        | Window           | White        | Wood                | 0.09                                   |
| 30         | Interior - Main Level        | Window casing    | White        | Wood                | 0.07                                   |
| <b>31</b>  | <b>Interior - Main Level</b> | <b>Wall</b>      | <b>Beige</b> | <b>Plaster</b>      | <b>1.00</b>                            |
| 32         | Interior - Main Level        | Cabinets         | Beige        | Wood                | 0.14                                   |
| 33         | Interior - Main Level        | Door casing      | Beige        | Wood                | 0.03                                   |
| 34         | Interior - Main Level        | Door casing      | Beige        | Wood                | 0.19                                   |
| 35         | Interior - Main Level        | Counter-top      | Beige        | Wood                | 0.65                                   |
| 36         | Interior - Main Level        | Pantry shelves   | White        | Wood                | 0.05                                   |
| 37         | Interior - Main Level        | Door             | White        | Wood                | 0.15                                   |
| 38         | Interior - Main Level        | Fireplace mantle | White        | Wood                | 0.06                                   |
| 39         | Interior - Main Level        | Floor            | Brown        | Wood                | 0.01                                   |
| <b>40</b>  | <b>Interior - Main Level</b> | <b>Wall</b>      | <b>White</b> | <b>Ceramic tile</b> | <b>1.61</b>                            |
| 41         | Interior - Main Level        | Floor            | Grey         | Ceramic tile        | 0.00                                   |
| <b>42</b>  | <b>Interior - Main Level</b> | <b>Bath tub</b>  | <b>White</b> | <b>Metal</b>        | <b>5.00</b>                            |
| 43         | Interior - Basement          | Wall             | Blue         | Concrete            | 0.01                                   |
| 44         | Interior - Basement          | Door casing      | Blue         | Wood                | 0.10                                   |
| 45         | Interior - Basement          | Column           | Blue         | Wood                | 0.00                                   |
| 46         | Interior - Basement          | Ceiling          | White        | Drywall             | 0.03                                   |
| 47         |                              | Calibration      |              |                     | 1.08                                   |
| 48         |                              | Calibration      |              |                     | 1.10                                   |
| 49         |                              | Calibration      |              |                     | 1.11                                   |

**Bold = LBP**

FFM = Factory Finish Metal

FFM = Factory Finish Vinyl

**SECTION III**

**Laboratory Analytical Results & Chain of Custody**



# EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / [charlottelab@emsl.com](mailto:charlottelab@emsl.com)

EMSL Order: 411904123

Customer ID: AXEM25

Customer PO:

Project ID: City of Spartanburg

**Attention:** Tom Oliver  
Apex Environmental Management  
7 Winchester Court  
Mauldin, SC 29662

**Phone:** (864) 640-5274

**Fax:**

**Received Date:** 05/06/2019 8:05 AM

**Analysis Date:** 05/10/2019 - 05/13/2019

**Collected Date:** 05/03/2019

**Project:** 0119-09 COS 342 Ridgewood Ave. (City of Spartanburg)

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample  | Description                              | Appearance                             | Non-Asbestos  |  | Asbestos                     |
|---|--|--|---------------|--|------------------------------|
|   |  |  | % Fibrous     | % Non-Fibrous  | % Type                       |
| 1-Shingle 1<br><small>411904123-0001</small>  | Roof Shingles (2 Layers) w/ Tar & Felt   | Black Fibrous Homogeneous              | 15% Cellulose | 85% Non-fibrous (Other)                                  | None Detected                |
| 1-Tar<br><small>411904123-0001A</small>       | Roof Shingles (2 Layers) w/ Tar & Felt   | Black Non-Fibrous Homogeneous          |               | 97% Non-fibrous (Other)                                  | 3% Chrysotile                |
| 1-Shingle 2<br><small>411904123-0001B</small> | Roof Shingles (2 Layers) w/ Tar & Felt   | Black Fibrous Homogeneous              | 15% Cellulose | 85% Non-fibrous (Other)                                  | None Detected                |
| 1-Tar<br><small>411904123-0001C</small>       | Roof Shingles (2 Layers) w/ Tar & Felt   | Black Non-Fibrous Homogeneous          |               | 10% Ca Carbonate<br>90% Non-fibrous (Other)              | None Detected                |
| 1-Felt<br><small>411904123-0001D</small>      | Roof Shingles (2 Layers) w/ Tar & Felt   | Black Fibrous Homogeneous              | 60% Cellulose | 40% Non-fibrous (Other)                                  | None Detected                |
| 2-Shingle 1<br><small>411904123-0002</small>  | Roof Shingles (2 Layers) w/ Tar & Felt   | Black Fibrous Homogeneous              | 10% Cellulose | 90% Non-fibrous (Other)                                  | None Detected                |
| 2-Tar<br><small>411904123-0002A</small>       | Roof Shingles (2 Layers) w/ Tar & Felt   |  |               |  | Positive Stop (Not Analyzed) |
| 2-Shingle 2<br><small>411904123-0002B</small> | Roof Shingles (2 Layers) w/ Tar & Felt   | Black Non-Fibrous Homogeneous          | 10% Cellulose | 90% Non-fibrous (Other)                                  | None Detected                |
| 2-Tar<br><small>411904123-0002C</small>       | Roof Shingles (2 Layers) w/ Tar & Felt   | Black Non-Fibrous Homogeneous          | 5% Cellulose  | 15% Ca Carbonate<br>80% Non-fibrous (Other)              | None Detected                |
| 2-Felt<br><small>411904123-0002D</small>      | Roof Shingles (2 Layers) w/ Tar & Felt   | Black Fibrous Homogeneous              | 60% Cellulose | 40% Non-fibrous (Other)                                  | None Detected                |
| 4-Shingle<br><small>411904123-0003</small>    | Roof Shingles (1 Layer) w/ Tar & No Felt | Gray/Tan/Black Non-Fibrous Homogeneous | 5% Glass      | 15% Ca Carbonate<br>80% Non-fibrous (Other)              | None Detected                |
| 4-Tar<br><small>411904123-0003A</small>       | Roof Shingles (1 Layer) w/ Tar & No Felt | Black Non-Fibrous Homogeneous          |               | 5% Ca Carbonate<br>95% Non-fibrous (Other)               | None Detected                |
| 5-Shingle<br><small>411904123-0004</small>    | Roof Shingles (1 Layer) w/ Tar & No Felt | White/Black Fibrous Homogeneous        | 5% Glass      | 8% Quartz<br>15% Ca Carbonate<br>72% Non-fibrous (Other) | None Detected                |
| 5-Tar<br><small>411904123-0004A</small>       | Roof Shingles (1 Layer) w/ Tar & No Felt | Black Non-Fibrous Homogeneous          | <1% Cellulose | 100% Non-fibrous (Other)                                 | None Detected                |
| 7<br><small>411904123-0005</small>            | Roof Flashing & Chimney Tar              | Black Non-Fibrous Homogeneous          |               | 96% Non-fibrous (Other)                                  | 4% Chrysotile                |
| 8<br><small>411904123-0006</small>            | Roof Flashing & Chimney Tar              |  |               |  | Positive Stop (Not Analyzed) |

Initial report from: 05/13/2019 09:06:00



# EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / [charlottelab@emsl.com](mailto:charlottelab@emsl.com)

EMSL Order: 411904123

Customer ID: AXEM25

Customer PO:

Project ID: City of Spartanburg

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                           | Description   | Appearance                               | Non-Asbestos  |  | Asbestos                     |
|----------------------------------|---|--|---------------|--|------------------------------|
|                                  |   |  | % Fibrous     | % Non-Fibrous  | % Type                       |
| 10<br>411904123-0007             | Window Casing<br>Glazing                              | Gray<br>Non-Fibrous<br>Homogeneous       |               | 20% Ca Carbonate<br>78% Non-fibrous (Other)              | 2% Chrysotile                |
| 11<br>411904123-0008             | Window Casing<br>Glazing                              |  |               |  | Positive Stop (Not Analyzed) |
| 13<br>411904123-0009             | Window Glazing  | Gray<br>Non-Fibrous<br>Homogeneous       |               | 15% Ca Carbonate<br>85% Non-fibrous (Other)              | None Detected                |
| 14<br>411904123-0010             | Window Glazing  | Gray/White<br>Non-Fibrous<br>Homogeneous |               | 10% Ca Carbonate<br>90% Non-fibrous (Other)              | None Detected                |
| 16<br>411904123-0011             | Door Caulk  | Gray<br>Non-Fibrous<br>Homogeneous       |               | 15% Ca Carbonate<br>83% Non-fibrous (Other)              | 2% Chrysotile                |
| 17<br>411904123-0012             | Door Caulk  |  |               |  | Positive Stop (Not Analyzed) |
| 19-Surfacing<br>411904123-0013   | Plaster w/ Finish<br>Walls & Ceilings w/<br>Skim Coat | Gray<br>Non-Fibrous<br>Homogeneous       |               | 40% Ca Carbonate<br>60% Non-fibrous (Other)              | None Detected                |
| 19-Skim Coat<br>411904123-0013A  | Plaster w/ Finish<br>Walls & Ceilings w/<br>Skim Coat | White<br>Non-Fibrous<br>Homogeneous      |               | 15% Ca Carbonate<br>85% Non-fibrous (Other)              | None Detected                |
| 19-Rough Coat<br>411904123-0013B | Plaster w/ Finish<br>Walls & Ceilings w/<br>Skim Coat | Tan<br>Non-Fibrous<br>Homogeneous        | <1% Synthetic | 30% Quartz<br>5% Ca Carbonate<br>65% Non-fibrous (Other) | None Detected                |
| 20-Surfacing<br>411904123-0014   | Plaster w/ Finish<br>Walls & Ceilings w/<br>Skim Coat | White<br>Non-Fibrous<br>Homogeneous      |               | 40% Ca Carbonate<br>60% Non-fibrous (Other)              | None Detected                |
| 20-Skim Coat<br>411904123-0014A  | Plaster w/ Finish<br>Walls & Ceilings w/<br>Skim Coat | White<br>Non-Fibrous<br>Homogeneous      |               | 10% Ca Carbonate<br>90% Non-fibrous (Other)              | None Detected                |
| 20-Rough Coat<br>411904123-0014B | Plaster w/ Finish<br>Walls & Ceilings w/<br>Skim Coat | Tan<br>Non-Fibrous<br>Homogeneous        | 1% Synthetic  | 30% Quartz<br>5% Ca Carbonate<br>64% Non-fibrous (Other) | None Detected                |
| 21-Surfacing<br>411904123-0015   | Plaster w/ Finish<br>Walls & Ceilings w/<br>Skim Coat | White<br>Non-Fibrous<br>Homogeneous      |               | 40% Ca Carbonate<br>60% Non-fibrous (Other)              | None Detected                |
| 21-Skim Coat<br>411904123-0015A  | Plaster w/ Finish<br>Walls & Ceilings w/<br>Skim Coat | White<br>Non-Fibrous<br>Homogeneous      |               | 15% Ca Carbonate<br>85% Non-fibrous (Other)              | None Detected                |
| 21-Rough Coat<br>411904123-0015B | Plaster w/ Finish<br>Walls & Ceilings w/<br>Skim Coat | Tan<br>Non-Fibrous<br>Homogeneous        | 1% Synthetic  | 30% Quartz<br>5% Ca Carbonate<br>64% Non-fibrous (Other) | None Detected                |
| 22-Surfacing<br>411904123-0016   | Plaster w/ Finish<br>Walls & Ceilings w/<br>Skim Coat | White<br>Non-Fibrous<br>Homogeneous      |               | 30% Ca Carbonate<br>70% Non-fibrous (Other)              | None Detected                |
| 22-Skim Coat<br>411904123-0016A  | Plaster w/ Finish<br>Walls & Ceilings w/<br>Skim Coat | White<br>Non-Fibrous<br>Homogeneous      |               | 5% Ca Carbonate<br>95% Non-fibrous (Other)               | None Detected                |
| 22-Rough Coat<br>411904123-0016B | Plaster w/ Finish<br>Walls & Ceilings w/<br>Skim Coat | Gray<br>Non-Fibrous<br>Homogeneous       | 1% Synthetic  | 25% Quartz<br>5% Ca Carbonate<br>69% Non-fibrous (Other) | None Detected                |
| 23-Surfacing<br>411904123-0017   | Plaster w/ Finish<br>Walls & Ceilings w/<br>Skim Coat | White<br>Non-Fibrous<br>Homogeneous      |               | 40% Ca Carbonate<br>60% Non-fibrous (Other)              | None Detected                |

Initial report from: 05/13/2019 09:06:00



# EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / [charlottelab@emsl.com](mailto:charlottelab@emsl.com)

**EMSL Order:** 411904123  
**Customer ID:** AXEM25  
**Customer PO:**  
**Project ID:** City of Spartanburg

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample                                | Description  | Appearance                         | Non-Asbestos                  |   | Asbestos                     |
|---------------------------------------|--|------------------------------------|-------------------------------|---|------------------------------|
|                                       |  |                                    | % Fibrous                     | % Non-Fibrous   | % Type                       |
| 23-Skim Coat<br>411904123-0017A       | Plaster w/ Finish Walls & Ceilings w/ Skim Coat            | White Non-Fibrous Homogeneous      |                               | 5% Ca Carbonate<br>95% Non-fibrous (Other)                | None Detected                |
| 23-Rough Coat<br>411904123-0017B      | Plaster w/ Finish Walls & Ceilings w/ Skim Coat            | Gray Non-Fibrous Homogeneous       | 1% Synthetic                  | 25% Quartz<br>5% Ca Carbonate<br>69% Non-fibrous (Other)  | None Detected                |
| 24<br>411904123-0018                  | Wooden Pattern 12"x12" Self-Stick Floor Tile               | Brown/Gray Non-Fibrous Homogeneous |                               | 20% Ca Carbonate<br>80% Non-fibrous (Other)               | None Detected                |
| 25<br>411904123-0019                  | Wooden Pattern 12"x12" Self-Stick Floor Tile               | Brown/Gray Non-Fibrous Homogeneous |                               | 30% Ca Carbonate<br>70% Non-fibrous (Other)               | None Detected                |
| 27<br>411904123-0020                  | Beige Multi-Square Pattern 12"x12" Self-Stick Floor Tile   | Beige Non-Fibrous Homogeneous      |                               | 20% Ca Carbonate<br>80% Non-fibrous (Other)               | None Detected                |
| 28<br>411904123-0021                  | Beige Multi-Square Pattern 12"x12" Self-Stick Floor Tile   | Beige Non-Fibrous Homogeneous      |                               | 30% Ca Carbonate<br>70% Non-fibrous (Other)               | None Detected                |
| 30-Top Flooring<br>411904123-0022     | Tan & Blue Pattern Vinyl Floor w/ 2nd Layer of Vinyl Floor | Tan/Blue Non-Fibrous Homogeneous   |                               | 10% Ca Carbonate<br>82% Non-fibrous (Other)               | 8% Chrysotile                |
| 30-Bottom Flooring<br>411904123-0022A | Tan & Blue Pattern Vinyl Floor w/ 2nd Layer of Vinyl Floor | Brown Non-Fibrous Homogeneous      | 40% Cellulose<br>3% Synthetic | 20% Ca Carbonate<br>37% Non-fibrous (Other)               | None Detected                |
| 31-Top Flooring<br>411904123-0023     | Tan & Blue Pattern Vinyl Floor w/ 2nd Layer of Vinyl Floor |                                    |                               |   | Positive Stop (Not Analyzed) |
| 31-Bottom Flooring<br>411904123-0023A | Tan & Blue Pattern Vinyl Floor w/ 2nd Layer of Vinyl Floor | Brown Fibrous Heterogeneous        | 40% Cellulose<br>3% Synthetic | 10% Ca Carbonate<br>47% Non-fibrous (Other)               | None Detected                |
| 33<br>411904123-0024                  | Felt Paper   | Black Fibrous Homogeneous          | 60% Cellulose                 | 40% Non-fibrous (Other)                                   | None Detected                |
| 34<br>411904123-0025                  | Felt Paper   | Black Fibrous Homogeneous          | 60% Cellulose                 | 40% Non-fibrous (Other)                                   | None Detected                |
| 36-Floor Tile<br>411904123-0026       | 12"x12" Tan Rock Fissure Pattern Floor Tile & Black Mastic | Brown Non-Fibrous Homogeneous      |                               | 30% Ca Carbonate<br>67% Non-fibrous (Other)               | 3% Chrysotile                |
| 36-Mastic<br>411904123-0026A          | 12"x12" Tan Rock Fissure Pattern Floor Tile & Black Mastic | Black Non-Fibrous Homogeneous      |                               | 94% Non-fibrous (Other)                                   | 6% Chrysotile                |
| 37-Floor Tile<br>411904123-0027       | 12"x12" Tan Rock Fissure Pattern Floor Tile & Black Mastic |                                    |                               |   | Positive Stop (Not Analyzed) |
| 37-Mastic<br>411904123-0027A          | 12"x12" Tan Rock Fissure Pattern Floor Tile & Black Mastic |                                    |                               |   | Positive Stop (Not Analyzed) |
| 39<br>411904123-0028                  | Skim Coat over Concrete Walls                              | Gray Non-Fibrous Homogeneous       |                               | 15% Quartz<br>10% Ca Carbonate<br>75% Non-fibrous (Other) | None Detected                |
| 40<br>411904123-0029                  | Skim Coat over Concrete Walls                              | White Non-Fibrous Homogeneous      |                               | 15% Quartz<br>5% Ca Carbonate<br>80% Non-fibrous (Other)  | None Detected                |
| 41<br>411904123-0030                  | Skim Coat over Concrete Walls                              | White Non-Fibrous Homogeneous      |                               | 5% Ca Carbonate<br>95% Non-fibrous (Other)                | None Detected                |

Initial report from: 05/13/2019 09:06:00



# EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / [charlottelab@emsl.com](mailto:charlottelab@emsl.com)

**EMSL Order:** 411904123  
**Customer ID:** AXEM25  
**Customer PO:**  
**Project ID:** City of Spartanburg

## Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

| Sample  | Description                               | Appearance                     | Non-Asbestos  |   | Asbestos                     |
|---|---|--------------------------------|---------------|---|------------------------------|
|   |   |                                | % Fibrous     | % Non-Fibrous                               | % Type                       |
| 42-Drywall<br><small>411904123-0031</small>         | Drywall w/ Joint Compound & Tape Ceilings | Brown/Gray Fibrous Homogeneous | 10% Cellulose | 90% Non-fibrous (Other)                     | None Detected                |
| 42-Joint Compound<br><small>411904123-0031A</small> | Drywall w/ Joint Compound & Tape Ceilings | Gray Non-Fibrous Homogeneous   |               | 30% Ca Carbonate<br>67% Non-fibrous (Other) | 3% Chrysotile                |
| 42-Tape<br><small>411904123-0031B</small>           | Drywall w/ Joint Compound & Tape Ceilings |                                |               |   | Positive Stop (Not Analyzed) |
| 43-Drywall<br><small>411904123-0032</small>         | Drywall w/ Joint Compound & Tape Ceilings |                                |               |   | Positive Stop (Not Analyzed) |
| 43-Joint Compound<br><small>411904123-0032A</small> | Drywall w/ Joint Compound & Tape Ceilings |                                |               |   | Positive Stop (Not Analyzed) |
| 43-Tape<br><small>411904123-0032B</small>           | Drywall w/ Joint Compound & Tape Ceilings |                                |               |   | Positive Stop (Not Analyzed) |
| 44-Drywall<br><small>411904123-0033</small>         | Drywall w/ Joint Compound & Tape Ceilings |                                |               |   | Positive Stop (Not Analyzed) |
| 44-Joint Compound<br><small>411904123-0033A</small> | Drywall w/ Joint Compound & Tape Ceilings |                                |               |   | Positive Stop (Not Analyzed) |
| 44-Tape<br><small>411904123-0033B</small>           | Drywall w/ Joint Compound & Tape Ceilings |                                |               |   | Positive Stop (Not Analyzed) |
| 45<br><small>411904123-0034</small>                 | HVAC A-Tape on Metal Ducts                | White Fibrous Homogeneous      | 20% Cellulose | 20% Non-fibrous (Other)                     | 60% Chrysotile               |
| 46<br><small>411904123-0035</small>                 | HVAC A-Tape on Metal Ducts                |                                |               |   | Positive Stop (Not Analyzed) |
| 47<br><small>411904123-0036</small>                 | HVAC A-Tape on Metal Ducts                |                                |               |   | Positive Stop (Not Analyzed) |

Analyst(s) \_\_\_\_\_  
 Eric Loomis (2)  
 Lacy Searcy (18)  
 Sarah Breneman (30)

Lee Plumley, Laboratory Manager  
 or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method"), but augmented with procedures outlined in the 1993 ("final") version of the method. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. All samples received in acceptable condition unless otherwise noted. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. EMSL recommends gravimetric reduction for all non-friable organically bound materials prior to analysis. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC NVLAP Lab Code 200841-0, VA 3333 00312

Initial report from: 05/13/2019 09:06:00



# EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / [charlottelab@emsl.com](mailto:charlottelab@emsl.com)

**EMSL Order:** 411904123

**Customer ID:** AXEM25

**Customer PO:**

**Project ID:** City of Spartanburg

**Attention:** Tom Oliver  
Apex Environmental Management  
7 Winchester Court  
Mauldin, SC 29662

**Phone:** (864) 640-5274  
**Fax:**  
**Received Date:** 05/06/2019 8:05 AM  
**Analysis Date:** 05/18/2019  
**Collected Date:** 05/03/2019

**Project:** 0119-09 COS 342 Ridgewood Ave. (City of Spartanburg)

## Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

| Sample ID                            | Description  | Appearance                                 | % Matrix Material | % Non-Asbestos Fibers | Asbestos Types       |
|--------------------------------------|--|--|-------------------|-----------------------|----------------------|
| 3-Shingle 1<br>411904123-0037        | Roof Shingles (2 Layers)<br>w/ Tar & Felt                        | Black<br>Non-Fibrous<br>Heterogeneous      | 100.0 Other       | None                  | No Asbestos Detected |
| 3-Shingle 2<br>411904123-0038        | Roof Shingles (2 Layers)<br>w/ Tar & Felt                        | Black<br>Non-Fibrous<br>Heterogeneous      | 100.0 Other       | None                  | No Asbestos Detected |
| 3-Tar<br>411904123-0039              | Roof Shingles (2 Layers)<br>w/ Tar & Felt                        | Black<br>Non-Fibrous<br>Heterogeneous      | 100.0 Other       | None                  | No Asbestos Detected |
| 3-Felt<br>411904123-0040             | Roof Shingles (2 Layers)<br>w/ Tar & Felt                        | Black<br>Non-Fibrous<br>Heterogeneous      | 100.0 Other       | None                  | No Asbestos Detected |
| 6-Shingle<br>411904123-0041          | Roof Shingles (1 Layer) w/<br>Tar & No Felt                      | Gray/Black<br>Non-Fibrous<br>Heterogeneous | 100.0 Other       | None                  | No Asbestos Detected |
| 6-Tar<br>411904123-0042              | Roof Shingles (1 Layer) w/<br>Tar & No Felt                      | Black<br>Non-Fibrous<br>Heterogeneous      | 100.0 Other       | None                  | No Asbestos Detected |
| 15<br>411904123-0043                 | Window Glazing   | White<br>Non-Fibrous<br>Heterogeneous      | 100.0 Other       | None                  | No Asbestos Detected |
| 26<br>411904123-0044                 | Wooden Pattern 12"x12"<br>Self-Stick Floor Tile                  | Brown<br>Non-Fibrous<br>Heterogeneous      | 100.0 Other       | None                  | No Asbestos Detected |
| 29<br>411904123-0045                 | Beige Multi-Square Pattern<br>12"x12" Self-Stick Floor<br>Tile   | Beige<br>Non-Fibrous<br>Heterogeneous      | 100.0 Other       | None                  | No Asbestos Detected |
| 32-Bottom Flooring<br>411904123-0046 | Tan & Blue Pattern Vinyl<br>Floor w/ 2nd Layer of Vinyl<br>Floor | Brown<br>Non-Fibrous<br>Heterogeneous      | 100.0 Other       | None                  | No Asbestos Detected |
| 35<br>411904123-0047                 | Felt Paper   | Gray<br>Non-Fibrous<br>Heterogeneous       | 100.0 Other       | None                  | No Asbestos Detected |

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC

Initial report from: 05/18/2019 16:14:21



EMSL ANALYTICAL, INC.  
LABORATORY • PRODUCTS • TRAINING

## Asbestos Bulk Building Material Chain of Custody

EMSL Order Number (Lab Use Only):

41904123

Pineville, NC 28134  
PHONE: (704) 525-2205  
FAX: (704) 525-2382

|  |                    |   |                 |
|--|--------------------|---|-----------------|
| Company : Apex Environmental Management, Inc.      |                    | EMSL-Bill to: <input checked="" type="checkbox"/> Same <input type="checkbox"/> Different<br><small>If Bill to is Different note instructions in Comments**</small> |                 |
| Street: 7 Winchester Court                         |                    | <i>Third Party Billing requires written authorization from third party</i>  |                 |
| City: Mauldin                                      | State/Province: SC | Zip/Postal Code: 29662  | Country: US     |
| Report To (Name): Tom Oliver                       |                    | Telephone #: 864-404-3210   |                 |
| Email Address: tolover@apex-ehs.com                |                    | Fax #: 864-404-3213   | Purchase Order: |
| Project Name/Number: 0119-09 COS 342 Ridgewood Ave |                    | Please Provide Results: <input type="checkbox"/> Fax <input checked="" type="checkbox"/> Email <input type="checkbox"/> Mail  |                 |
| U.S. State Samples Taken: SC                       |                    | CT Samples: <input type="checkbox"/> Commercial/Taxable <input type="checkbox"/> Residential/Tax Exempt   |                 |

**Turnaround Time (TAT) Options\* – Please Check**

3 Hour   
  6 Hour   
  24 Hour   
  48 Hour   
  72 Hour   
  96 Hour   
  1 Week   
  2 Week

\*For TEM Air 3 hr through 6 hr, please call ahead to schedule. \*There is a premium charge for 3 Hour TEM AHERA or EPA Level II TAT. You will be asked to sign an authorization form for this service. Analysis completed in accordance with EMSL's Terms and Conditions located in the Analytical Price Guide.

| PLM - Bulk (reporting limit)  | TEM - Bulk   |
|---|--|
| <input checked="" type="checkbox"/> PLM EPA 600/R-93/116 (<1%)  | <input checked="" type="checkbox"/> TEM EPA NOB – EPA 600/R-93/116 Section 2.5.5.1 |
| <input type="checkbox"/> PLM EPA NOB (<1%)  | <input type="checkbox"/> NY ELAP Method 198.4 (TEM)                                |
| Point Count <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%)               | <input type="checkbox"/> Chatfield Protocol (semi-quantitative)                    |
| Point Count w/Gravimetric <input type="checkbox"/> 400 (<0.25%) <input type="checkbox"/> 1000 (<0.1%) | <input type="checkbox"/> TEM % by Mass – EPA 600/R-93/116 Section 2.5.5.2          |
| <input type="checkbox"/> NIOSH 9002 (<1%)   | <input type="checkbox"/> TEM Qualitative via Filtration Prep Technique             |
| <input type="checkbox"/> NY ELAP Method 198.1 (friable in NY)   | <input type="checkbox"/> TEM Qualitative via Drop Mount Prep Technique             |
| <input type="checkbox"/> NY ELAP Method 198.6 NOB (non-friable-NY)                                    | <b>Other</b>   |
| <input type="checkbox"/> OSHA ID-191 Modified   | <input type="checkbox"/>   |
| <input type="checkbox"/> Standard Addition Method   |  |

Check For Positive Stop – Clearly Identify Homogenous Group      Date Sampled: 5-3-19

Samplers Name: Tom Oliver      Samplers Signature:

| Sample # | HA # | Sample Location                | Material Description |
|----------|------|--------------------------------|----------------------|
| 1        |      | Roof shingles (2 layers) w/    | PLM                  |
| 2        |      | tar & felt                     | PLM                  |
| 3        |      |                                | TEM                  |
| 4        |      | Roof shingles (1 layer) w/ tar | PLM                  |
| 5        |      | & no felt                      | PLM                  |
| 6        |      |                                | TEM                  |
| 7        |      | Roof flashing & chimney        | PLM                  |
| 8        |      | tar                            | PLM                  |
| 9        |      |                                | TEM                  |

|  |                                    |
|--|------------------------------------|
| Client Sample # (s): 1-47  | Total # of Samples: 47             |
| Relinquished (Client):   | Date: 5-3-19      Time: 4:30 PM    |
| Received (Lab):  | Date: 5/6/19      Time: 8:05 AM Pk |
| Comments/Special Instructions:<br><small>Positive stop on analysis. If joint compound on drywall is positive, then positive stop on drywall and tape layers. Bill according to Special City of Spartanburg project Pricing &amp; Layering.</small> |                                    |



EMSL ANALYTICAL, INC.  
LABORATORY • PRODUCTS • TRAINING

### Asbestos Bulk Building Material Chain of Custody

EMSL Order Number (Lab Use Only):

411904123

Pineville, NC 28134  
PHONE: (704) 525-2205  
FAX: (704) 525-2382

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

| Sample # | HA # | Sample Location                         | Material Description |
|----------|------|---|----------------------|
| 10       |      | Window casing glazing                   | PLM                  |
| 11       |      | ↓                                       | ↓                    |
| 12       |      |   | TEM                  |
| 13       |      | Window glazing                          | PLM                  |
| 14       |      | ↓                                       | ↓                    |
| 15       |      |   | TEM                  |
| 16       |      | Door caulk                              | PLM                  |
| 17       |      | ↓                                       | ↓                    |
| 18       |      |   | TEM                  |
| 19       |      | Plaster w/finish walls                  | PLM                  |
| 20       |      | + ceilings w/ skim coat                 | ↓                    |
| 21       |      | ↓                                       | ↓                    |
| 22       |      |   | ↓                    |
| 23       |      |   | ↓                    |
| 24       |      | Wooden pattern 12" x 12"                | PLM                  |
| 25       |      | self-stick floor tile                   | ↓                    |
| 26       |      | ↓                                       | TEM                  |
| 27       |      | Beige multi-square pattern              | PLM                  |
| 28       |      | 12" x 12" self-stick floor tile         | ↓                    |
| 29       |      | ↓                                       | TEM                  |
| 30       |      | Tan + blue pattern vinyl floor          | PLM                  |
| 31       |      | w/ 2 <sup>nd</sup> layer of vinyl floor | ↓                    |
| 32       |      | ↓                                       | TEM                  |

**\*Comments/Special Instructions:**

Positive stop on analysis. If joint compound on drywall is positive, then positive stop on drywall and tape layers. Bill according to Special City of Spartanburg project Pricing & Layering.





**EMSL Analytical, Inc.**

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / [charlottelab@emsl.com](mailto:charlottelab@emsl.com)

**EMSL Order:** 411904123  
**Customer ID:** AXEM25  
**Customer PO:**  
**Project ID:** City of Spartanburg

**Attention:** Tom Oliver  
Apex Environmental Management  
7 Winchester Court  
Mauldin, SC 29662  
**Phone:** (864) 640-5274  
**Fax:**  
**Received Date:** 05/06/2019 8:05 AM  
**Analysis Date:** 05/18/2019  
**Collected Date:** 05/03/2019  
**Project:** 0119-09 COS 342 Ridgewood Ave. (City of Spartanburg)

**Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1**

| Sample ID | Description | Appearance | % Matrix Material | % Non-Asbestos Fibers | Asbestos Types |
|-----------|-------------|------------|-------------------|-----------------------|----------------|
|-----------|-------------|------------|-------------------|-----------------------|----------------|

Analyst(s)  
\_\_\_\_\_  
Aaron Hartley (11)

  
\_\_\_\_\_  
Lee Plumley, Laboratory Manager  
or other approved signatory

This laboratory is not responsible for % asbestos in total sample when the residue only is submitted for analysis. The above report relates only to the items tested. This report may not be reproduced, except in full, without written approval by EMSL Analytical, Inc. Samples received in good condition unless otherwise noted. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC

Initial report from: 05/18/2019 16:14:21

**SECTION IV**  
**Photographic Log**




Photo 1 – 342 Ridgewood Avenue in Spartanburg, South Carolina



Photo 2 – Roof shingles with tar & felt on the front porch roof



Photo 3 – Roof shingles with tar & no felt on the main house roof



Photo 4 – Tar on chimney



Photo 5 – Tar on brick wall on left side of house on previous roof flashing



Photo 6 – Wooden/brick window casings with glazing



Photo 7 – Wooden window glazing



Photo 8 – Wooden/brick door casings with caulk



Photo 9 – 12" x 12" wooden pattern self-stick floor tile in the dining room & kitchen patches (top layer)



Photo 10 – 12" x 12" beige multi-square pattern self-stick floor tile in the kitchen (top layer)



Photo 11 – Tan & blue pattern vinyl floor with no mastic in the dining room & kitchen (2<sup>nd</sup> layer) & pantry (top layer)



Photo 12 – Brown rectangle pattern vinyl floor with no mastic in the dining room & kitchen (3<sup>rd</sup> layer) & pantry (2<sup>nd</sup> layer)



Photo 13 – 12" x 12" tan rock fissure pattern floor tile & black mastic throughout the finished portion of the basement



Photo 14 – Skim coat over concrete walls throughout the finished portion of the basement



Photo 15 – Drywall with joint compound & tape ceilings throughout the finished portion of the basement



Photo 16 – HVAC "A" tape on metal ducts throughout the finished & unfinished basement

**SECTION V**

**SC DHEC Asbestos Inspector License**

# SCDHEC ISSUED

Asbestos ID Card

**Thomas H Oliver**



**AIRSAMPLER AS-00202**  
**CONSULTBI BI-00680**

Expiration Date:

**04/04/19**

**01/18/20**