

Addendum 2

Q1) We were unable to locate the middle box structure during our site walk. Will you please provide us with the location of that box structure?

A1). The structure is inaccessible. Access will not be possible.

Q2) Is there a budget for this project?

A2). The City has not established a budget for this project.

Q3) The CIPP spec calls for no wrinkles in the CIPP. However, based on the condition of this pipe and the offset joints in the invert, that isn't likely to be possible.

A3). Wrinkles no more than 1/8" will be acceptable. The goal is to avoid creating hydraulic jump to the maximum extent practicable.