### **DAVIS & FLOYD**

**SINCE 1954** 

November 16, 2021

Mrs. Shealyn Barns Greenwood District 50 1855 Calhoun Road Greenwood, SC 29649

Re: Asbestos Report for 4805 Main Street

D&F Job Number: 013948.00

On November 1, 2021 Davis & Floyd, Inc. conducted an asbestos survey at a single-family home located at **4805 Main Street in Hodges, South Carolina**. The home was not occupied at the time of our survey.

The purpose of the survey was to identify suspect asbestos containing materials (ACM's) that may be present in the home. Sampling and analysis conform to the amendments of South Carolina Department of Health and Environmental Control (SCDHEC) Regulation 61-86.1 "Standards of Performance for Asbestos Projects", latest edition.

The Environmental Protection Agency (EPA) and the South Carolina Department of Health and Environmental Control (SCDHEC) define materials as asbestos-containing if an asbestos content of greater than one percent (>1%) is detected in a representative sample. **Asbestos, in concentrations greater than one percent** (>1%), was identified in some of the samples collected. Field conditions and quantities in this report should be verified prior to performing any asbestos removals; an asbestos project design is not required. The asbestos report is attached to this letter.

Please do not hesitate to contact us should you have any questions regarding this report at (864)229-5211 or <a href="mastevens@davisfloyd.com">mstevens@davisfloyd.com</a>

Very truly yours,

**DAVIS & FLOYD** 

Mark H. Stevens Designer II



### **Asbestos Survey for**

### **Greenwood School District 50**

Final Report – Nov 2021

## **4805 Main Street**Single-Family Dwelling

D&F Job No. 013948.00

#### PREPARED FOR:

Mrs. Shealyn Barnes Greenwood School District 50 1855 Calhoun Road Greenwood, SC 29649

#### PREPARED BY:

Davis & Floyd, Inc. 1319 Highway 72/221 E Greenwood, South Carolina 29649 (864) 229-5211







### Table of Contents

Section 1.0 Asbestos Survey Report	<b>.</b>
1.1 Introduction	
1.2 Homogeneous Material Assessment	
1.3 Bulk Sample Results	
1.4 Regulatory Requirements	4
1.5 Regulation 61-86.1 Standards of Performance for Asbestos Projects	4
Section 2.0 Sample Log with Sample Results	5
Section 3.0 Laboratory Analysis Reports	8
Section 4.0 Applicable Licenses	16
Section 5.0 Sample Location Plans & Photographs	

### Section 1.0 Asbestos Survey Report

#### **Sub-Section 1.1 Introduction**

On November 1, 2021 Davis & Floyd, Inc. conducted an asbestos survey at a single-family dwelling, located at **4805 Main Street in Hodges, South Carolina**. The purpose of this inspection was to locate, and to assess suspect asbestos containing materials (ACM's) and to perform supplemental bulk sampling and analysis to conform to the amendments to South Carolina Department of Health and Environmental Control (SCDHEC) Regulation 61-86.1 Standards of Performance for Asbestos Projects effective May 27, 2011, for the purpose of demolition. The home is approximately 1,560 square feet with wood framing and a gable roof. The home was originally constructed in or around 1895 but was renovated with newer building materials at an unknown date.

### **Debris Pile**

There is a 30 ft. x 30 ft. x 6 ft. (200 cy) debris pile located behind the home that has transite (asbestos) siding and other building materials mixed in. This debris pile will need to be disposed of as asbestos containing materials.

Bulk samples were collected from accessible suspect materials within the facility that were observed, and the samples were subsequently analyzed for asbestos content by an accredited laboratory. The suspect materials observed include: gypsum board, joint compound, popcorn ceiling finish, textured ceiling finish, vinyl flooring, asphalt shingles, tar paper, transite (asbestos) siding, and troweled cement (on foundation wall).

The Environmental Protection Agency (EPA) and the South Carolina Department of Health and Environmental Control (SCDHEC), define materials as asbestos containing if an asbestos content of greater than one percent (>1%) is detected in a representative sample. Eleven (11) Homogeneous Materials (Areas) were identified throughout the facility, but not all were asbestos containing. The following table identifies the asbestos containing materials (ACM's) as a result of the samples collected (see the Bulk Asbestos Sample Log for results and quantities of material):

#### **Sub-Section 1.2 Identified Asbestos Containing Materials (ACM):**

Homo. ID (# of samples)	Homogeneous Material (Cate	Overall Condition <sup>2</sup>	Potential for Further Disturbance <sup>3</sup>	
HM-7 (3)	Vinyl Floor Covering type 3 – 288 sf	Vinyl Floor Covering type 3 – 288 sf Miscellaneous		
HM-10 (3)	Exterior Siding (transite) – 1,800 sf	terior Siding (transite) – 1,800 sf Miscellaneous		
HM-10	Debris Pile with ACM – 200 cy	F-Good	High	

<sup>1-</sup>Homogeneous Material (Category): Surf. -Surfacing; Misc.-Miscellaneous; TSI-Thermal System Insulation

Category I — Nonfriable asbestos or nonfriable asbestos containing packing, gaskets, and resilient floor covering; and asphalt roofing products containing greater than one present (1%) asbestos as determined using the method specified in 40 CFR Part 763, Appendix E, Subpart E, or an accepted equivalent.

Category II — Any material that cannot when dry, be crumbled, pulverized, or reduced to powder by the forces expected to act upon it in the course of demolition or renovation operations, excluding Category I nonfriable ACM and containing greater than one percent (1%) asbestos as determined using the methods specified in 40 CFR Part 763, Appendix E, Subpart E, or an accepted equivalent.

<sup>&</sup>lt;sup>2</sup>-Overall Condition: (F) - Friable - Good, Fair, Poor; (NF)-Non-Friable - Good, Fair, Poor

<sup>&</sup>lt;sup>3</sup>-Potential for Further Disturbance: Low, Medium, High

### **Sub-Section 1.3 Bulk Sample Results**

Representative samples of each suspected homogenous material (area) were randomly collected from locations throughout the facility. According to 40 CFR 763.87, the Environmental Protection Agency defines a material to qualify as "asbestos-containing material" if any sample of the suspect material is found to contain asbestos in concentrations greater than one percent (>1%).

In addition, the South Carolina Department of Health and Environmental Control (SCDHEC) Regulation 61.86.1, "Standards of Performance for Asbestos Projects" (May 27, 2011), Section VI-Asbestos Building Inspection Requirements, D. Sampling, paragraph 2.0 states:

1. A licensed asbestos inspector shall collect, in a statistically random manner, at least three bulk samples from each homogeneous material of TSI and any miscellaneous material that is not assumed to be ACM. In accordance with ASTM E2356, and any subsequent amendments and editions, negative results for non-friable organically bound materials (NOB), such as flooring, mastics and roofing shall be verified with at least one TEM analysis.

To meet this requirement, one sample of each non-friable organically bound material (NOB) was sent to an independent lab for Transmission Electron Microscopy (TEM) analysis. The reports from the independent laboratory (licensed to perform TEM analysis) is also included in this report. During the laboratory analysis process, once a sample in a homogeneous area is found to be asbestos containing material (ACM), the remainder of the samples in that homogeneous area may not be analyzed by the laboratory (TEM or PLM).

### **Sub-Section 1.4 Regulatory Requirements**

- Confirmed asbestos containing materials (ACM's) should not be disturbed by untrained personnel. Damaged or ACM in poor condition should be removed or repaired by trained asbestos workers. Confirmed ACM should be periodically inspected.
- ➤ Before starting a renovation/demolition project, which involves disturbing the ACM, the ACM should be removed by a licensed asbestos abatement contractor. A copy of this report must be submitted to SCDHEC, along with the demolition license application, ten (10) weekdays prior to renovation / demolition activities.
- Any activity involving the ACM should be in compliance with South Carolina Department of Health and Environmental Control Regulation 61-86.1, "Standards of Performance for Asbestos Projects", latest edition.

### Sub-Section 1.5 Regulation (R 61-86.1)

SCDHEC Regulation 61-86.1 "Standards of Performance for Asbestos Projects" may be viewed at the following web address: <a href="https://live-sc-dhec.pantheonsite.io/sites/default/files/media/document/R.61-86.1.pdf">https://live-sc-dhec.pantheonsite.io/sites/default/files/media/document/R.61-86.1.pdf</a>

Section 2.0 Sample Log with Sample Results

### **DAVIS & FLOYD**

**SINCE 1954** 

 $_{Job\,No.}\,\overline{\textbf{13948.00}}$ **Building Name: 4805 Main Street** Building Address:

Single-Family Home 4805 Main Street

Hodges, SC Client: Greenwood School Dist. 50 Contact: Shealyn Barns

Collected By: Mark Stevens Date: November 1, 2021

### **BULK ASBESTOS SAMPLE LOG**

Sample	Description of Sampled Material	Sample Location	Present Condition	Potential Disturbance	HM I.D.	TEM (Y)	QTY.	Asbestos
4805-01	Gypsum Board	Kitchen	F-Good	High	1		3,260 sf	ND
4805-02	Gypsum Board	Bedroom 3 (B3)	F-Good	High	1		-	ND
4805-03	Gypsum Board	Living Room (LR)	F-Good	High	1		-	ND
4805-04	Gypsum Board	Bedroom 2 (B2)	F-Good	High	1		-	ND
4805-05	Gypsum Board	Bathroom 2 (T2)	F-Good	High	1		-	ND
4805-06	Joint Compound (on gypsum bd)	Kitchen	F-Good	High	2		3,260 sf	ND
4805-07	Joint Compound (on gypsum bd)	Bedroom 3 (B3)	F-Good	High	2		-	ND
4805-08	Joint Compound (on gypsum bd)	Living Room (LR)	F-Good	High	2		-	ND
4805-09	Joint Compound (on gypsum bd)	Bedroom 2 (B2)	F-Good	High	2		-	ND
4805-10	Joint Compound (on gypsum bd)	Bathroom 2 (T2)	F-Good	High	2		-	ND
4805-11	Popcorn Ceiling	Kitchen	F-Good	High	3		1,424 sf	ND
4805-12	Popcorn Ceiling	Living Room (LR)	F-Good	High	3		-	ND
4805-13	Popcorn Ceiling	Bedroom 1 (B1)	F-Good	High	3		-	ND
4805-14	Popcorn Ceiling	Bathroom 2 (T2)	F-Good	High	3		-	ND
4805-15	Textured Ceiling Finish	Bedroom 3 (B3)	F-Good	High	4		160 sf	ND
4805-16	Textured Ceiling Finish	Bedroom 3 (B3)	F-Good	High	4		-	ND
4805-17	Textured Ceiling Finish	Bedroom 3 (B3)	F-Good	High	4		-	ND
4805-18	Vinyl Floor Covering (Type 1)	Kitchen	NF-Good	Low	5		224 sf	ND
4805-19	Vinyl Floor Covering (Type 1)	Kitchen	NF-Good	Low	5		-	ND
4805-20	Vinyl Floor Covering (Type 1)	Kitchen	NF-Good	Low	5	Y	-	ND
4805-21	Vinyl Floor Covering (Type 2)	Kitchen	NF-Good	Low	6		336 sf	ND
4805-22	Vinyl Floor Covering (Type 2)	Kitchen	NF-Good	Low	6		-	ND
4805-23	Vinyl Floor Covering (Type 2)	Kitchen	NF-Good	Low	6	Y	-	ND
4805-24	Vinyl Floor Covering (Type 3)	Bedroom 2 (B2)	NF-Good	Low	7		288 sf	3.00%
4805-25	Vinyl Floor Covering (Type 3)	Bedroom 2 (B2)	NF-Good	Low	7		-	NA

Davis & Floyd, Inc. I P.O. Drawer 428 I Greenwood, SC 29648 I (864) 229-5211 I Fax (864) 229-7119

F - Friable NF-Non-Friable PC - Good, Fair, Poor

PD-Low, Medium, High

ND = No asbestos detected NA = Sample not analyzed PACM = Presumed Asbestos Containing Material

### **DAVIS & FLOYD**

**SINCE 1954** 

 $_{Job\,No.}\,\overline{\textbf{13948.00}}$ **Building Name: 4805 Main Street** Building Address:

Single-Family Home 4805 Main Street

Hodges, SC Client: Greenwood School Dist. 50 Contact: Shealyn Barns

Collected By: Mark Stevens Date: November 1, 2021

### **BULK ASBESTOS SAMPLE LOG**

Sample	Description of Sampled Material	Sample Location	Present Condition	Potential Disturbance	HM I.D.	TEM (Y)	QTY.	Asbestos
4805-26	Vinyl Floor Covering (Type 3)	Bedroom 2 (B2)	NF-Good	Low	7	Y	-	NA
4805-27	Asphalt Shingles	Roof	NF-Good	Low	8		2,400 sf	ND
4805-28	Asphalt Shingles	Roof	NF-Good	Low	8		-	ND
4805-29	Asphalt Shingles	Roof	NF-Good	Low	8	Y	-	ND
4805-30	Tar Paper	Roof	NF-Good	Low	9		2,400 sf	ND
4805-31	Tar Paper	Roof	NF-Good	Low	9		-	ND
4805-32	Tar Paper	Roof	NF-Good	Low	9	Y	-	ND
4805-33	Exterior Siding (transite)	Exterior Walls (under vinyl)	F-Good	High	10		1,800 sf	15.00%
4805-34	Exterior Siding (transite)	Exterior Walls (under vinyl)	F-Good	High	10		-	NA
4805-35	Exterior Siding (transite)	Exterior Walls (under vinyl)	F-Good	High	10		-	NA
4805-36	Troweled Cement	Foundation Wall	F-Good	High	11		560 sf	ND
4805-37	Troweled Cement	Foundation Wall	F-Good	High	11		-	ND
4805-38	Troweled Cement	Foundation Wall	F-Good	High	11		-	ND
	Debris Pile at rear of property	Exterior Siding (transite) mixed in	F-Good	High	10		200 cy	
					(004) 004			

Davis & Floyd, Inc. I P.O. Drawer 428 I Greenwood, SC 29648 I (864) 229-5211 I Fax (864) 229-7119

F - Friable NF-Non-Friable PC - Good, Fair, Poor PD-Low, Medium, High ND = No asbestos detected NA = Sample not analyzed PACM = Presumed Asbestos Containing Material

Section 3.0 Laboratory Analysis Reports	<u>s</u>



**EMSL Order:** 022108062 **Customer ID:** DAVI57 **Customer PO:** 01394800

Project ID:

**Phone:** (864) 229-5211

Fax: (864) 229-7119

**Received Date:** 11/03/2021 12:15 PM **Analysis Date:** 11/08/2021 - 11/09/2021

Collected Date: 11/01/2021

**Project:** 01394800

Attention: Mark Stevens

Davis & Floyd

P.O. Drawer 428

Greenwood, SC 29648

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-Asbestos			
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type	
4805-01	Gypsum Board	Gray Fibrous	1% Cellulose	99% Non-fibrous (Other)	None Detected	
022108062-0001 4805-02	Gypsum Board	Homogeneous White	2% Cellulose	98% Non-fibrous (Other)	None Detected	
022108062-0002		Non-Fibrous Homogeneous				
4805-03	Gypsum Board	Gray Non-Fibrous	2% Cellulose	98% Non-fibrous (Other)	None Detected	
022108062-0003		Homogeneous				
4805-04	Gypsum Board	Gray Fibrous	3% Cellulose	97% Non-fibrous (Other)	None Detected	
022108062-0004		Homogeneous				
4805-05	Gypsum Board	Gray Fibrous	3% Cellulose	97% Non-fibrous (Other)	None Detected	
022108062-0005		Homogeneous				
4805-06	Joint Compound	White Non-Fibrous		25% Ca Carbonate 75% Non-fibrous (Other)	None Detected	
022108062-0006		Homogeneous				
4805-07	Joint Compound	White Non-Fibrous		25% Ca Carbonate 75% Non-fibrous (Other)	None Detected	
022108062-0007		Homogeneous				
4805-08	Joint Compound	White Non-Fibrous		25% Ca Carbonate 75% Non-fibrous (Other)	None Detected	
022108062-0008		Homogeneous				
4805-09	Joint Compound	White Non-Fibrous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected	
022108062-0009		Homogeneous				
4805-10	Joint Compound				Not Submitted	
022108062-0010 No sample in bag						
4805-11	Popcorn Ceiling	White Non-Fibrous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected	
022108062-0011		Homogeneous		3373 . 131		
4805-12	Popcorn Ceiling	White Non-Fibrous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected	
022108062-0012		Heterogeneous				
4805-13	Popcorn Ceiling	White Non-Fibrous		25% Ca Carbonate 75% Non-fibrous (Other)	None Detected	
022108062-0013		Homogeneous				
4805-14	Popcorn Ceiling	White Non-Fibrous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected	
022108062-0014		Homogeneous				
4805-15	Textured Ceiling Fin.	White Non-Fibrous		25% Ca Carbonate 75% Non-fibrous (Other)	None Detected	
022108062-0015		Homogeneous				
4805-16	Textured Ceiling Fin.	White Non-Fibrous		25% Ca Carbonate 75% Non-fibrous (Other)	None Detected	
022108062-0016		Homogeneous				



**EMSL Order:** 022108062 **Customer ID:** DAVI57 **Customer PO:** 01394800

Project ID:

### Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

			Non-Ast		<u>Asbestos</u>	
Sample	Description	Appearance	% Fibrous	% Non-Fibrous	% Type	
4805-17	Textured Ceiling Fin.	White Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected	
4805-18	VFC- Type 1	Tan/Beige Fibrous	2% Glass	98% Non-fibrous (Other)	None Detected	
022108062-0018		Homogeneous				
4805-19	VFC- Type 1	Tan Non-Fibrous	3% Glass	97% Non-fibrous (Other)	None Detected	
022108062-0019	\/FQ_T===0	Homogeneous		4000/ New Shares (Others)	New Detected	
4805-21 022108062-0021	VFC- Type 2	Tan/Green Non-Fibrous Heterogeneous		100% Non-fibrous (Other)	None Detected	
4805-22	VFC- Type 2	Tan/Green		100% Non-fibrous (Other)	None Detected	
922108062-0022	VFC- Type 2	Non-Fibrous Homogeneous		100 % Noti-fibrous (Other)	None Detected	
4805-24	VFC- Type 3	Tan/Green/Beige		97% Non-fibrous (Other)	3% Chrysotile	
022108062-0024	0 .,,,,,	Fibrous Heterogeneous		0.70.101.13300 (0.10.7)	on conjecue	
4805-25	VFC- Type 3				Positive Stop (Not Analyzed)	
022108062-0025						
4805-27	Asphalt Shingles	Black Fibrous	7% Glass	93% Non-fibrous (Other)	None Detected	
022108062-0027		Homogeneous				
1805-28	Asphalt Shingles	Black Fibrous	10% Glass	90% Non-fibrous (Other)	None Detected	
022108062-0028		Homogeneous				
4805-30 022108062-0030	Tar Paper	Black Fibrous	15% Glass	85% Non-fibrous (Other)	None Detected	
	Tor Donor	Heterogeneous	20% Class	200/ Non fibrage (Other)	Nana Datastad	
1805-31 022108062-0031	Tar Paper	Black Fibrous Homogeneous	20% Glass	80% Non-fibrous (Other)	None Detected	
4805-33	Transite Siding	Gray/White Fibrous		10% Ca Carbonate 75% Non-fibrous (Other)	15% Chrysotile	
022108062-0033		Homogeneous		7370 Non-librous (Other)		
4805-34	Transite Siding	<u> </u>			Positive Stop (Not Analyzed)	
022108062-0034						
1805-35	Transite Siding				Positive Stop (Not Analyzed)	
022108062-0035						
4805-36-Gray Cement	Troweled Cement	Gray Non-Fibrous		40% Quartz 60% Non-fibrous (Other)	None Detected	
022108062-0036	Trouvaled Comment	Heterogeneous		400/ 000-4-	None Detected	
1805-36-Tan Cement	Troweled Cement	Tan Non-Fibrous Heterogeneous		40% Quartz 60% Non-fibrous (Other)	None Detected	
4805-37-Gray Cement	Troweled Cement	Gray Non-Fibrous		40% Quartz 60% Non-fibrous (Other)	None Detected	
022108062-0037		Heterogeneous		oo /o (4011-11b) oda (Ottiet)		
1805-37-Tan Cement	Troweled Cement	Tan Non-Fibrous		40% Quartz 60% Non-fibrous (Other)	None Detected	
022108062-0037A		Heterogeneous				
4805-38	Troweled Cement	Tan Non-Fibrous		40% Quartz 60% Non-fibrous (Other)	None Detected	
022108062-0038		Homogeneous		·		



**EMSL Order:** 022108062 **Customer ID:** DAVI57 **Customer PO:** 01394800

Project ID:

Analyst(s)

Philip Szabo (10) Ryan Rains (21) Stephen Bennett, Laboratory Manager or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis . Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Kernersville, NC NVLAP Lab Code 102104-0, Virginia 3333-000228, West Virginia LT000321



Davis & Floyd

P.O. Drawer 428

Greenwood, SC 29648

 EMSL Order:
 022108062

 Customer ID:
 DAVI57

 Customer PO:
 01394800

Project ID:

**Phone**: (864) 229-5211 **Fax**: (864) 229-7119

Received Date: 11/03/2021 12:15 PM

**Analysis Date:** 11/09/2021 **Collected Date:** 11/01/2021

Project: 01394800

Attention: Mark Stevens

### Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID	Description	Appearance	% Matrix Material	% Non-Asbestos Fibers	Asbestos Types
4805-20 022108062-0020	VFC- Type 1	Brown Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
4805-23 022108062-0023	VFC- Type 2	Tan/Green Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
4805-26 022108062-0026	VFC- Type 3				
Positive	Stop (Not Analyzed)				
4805-29 022108062-0029	Asphalt Shingles	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
4805-32 022108062-0032	Tar Paper	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected

Analyst(s)	
Stephen Bennett (4)	

Stephen Bennett, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. EMSL recommends that samples reported as none detected or <1% undergo additional analysis via PLM to avoid the possibility of false negatives.

Samples analyzed by EMSL Analytical, Inc. Kernersville, NC

OrderID: 022108062 Page 1 of 2

BMB.
EMSL ANALYTICAL, INC.

# Asbestos Lab Services Chain of Custody EMSL Order Number(Lab Use Only): China

Kernersville, NC 706 Gralin Street Kernersville, NC 27284 PHONE: (336) 992-1025 FAX: (336) 992-4175

		PONO			FAX: (33	36) 992-4175	
						Different	
Street: P O DRAW	ER 428		If Bill to is Different note instructions in Comments**  Third Party Billing requires written authorization from third party				
City/State/Zip: GR	EENWOOD, SC 2964	8				· · · · · ·	
Report To (Name):	MARK STEVENS		Fax: (864) 2	29-7844			
Telephone: (864) 22	29-5211		Email Addr	ess: mst	tevens@davisfloyd	com	
Project Name/Num	ber: 01294801	2					
Please Provide Res		hase Order: SAN	ΛE S	tate Sam	ples Taken: SC		
		around Time (TAT)	Options* – Ple	ase Che	ck		
3 Hour 6	Hour 24 Hour ours, please call ahead to sof	☐ 48 Hour	n charge for 3 Ho	ur TEM AHI	06 Hour S 1 Week FBA or FPA LeWa UTTAT	You will be asked to sign	
an authorization fo	orm for this service. Analysis	completed in accordance	with EMSL's Ten	ms and Con	ditions located in the Analy	tical Price Guide.	
PCM - Air NIOSH 7400		<u>TEM − Air</u>		A only)	TEM- Dust	D. ETTER	
☐ W/ OSHA 8hr TW/	٨	│	1, Part 763		☐ Microvac - ASTM ☐ Wipe - ASTM D64		
PLM - Bulk (reporting	·	☐ EPA Level II			☐ Carpet Sonication		
PLM EPA 600/R-93		☐ ISO 10312			Soi!/Rock/Vermiculi		
PLM EPA NOB (<1	· •	TEM - Bulk			PLM CARB 435 -		
Point Count	•	☑ TEM EPA NOB	(5)	'	PLM CARB 435 -		
400 (<0.25%) 🔲 10	000 (<0.1%)	NYS NOB 198.4	(port-friable-N	Y)	☐ TEM CARB 435 -	B (0.1% sensitivity)	
Point Count w/Gravim		☐ Chatfield SOP			☐ TEM CARB 435 -		
400 (<0.25%) 🗍 1	· ·	TEM Mass Anal		sec. 2.5	EPA Protocol (Sei	, , , , , , , , , , , , , , , , , , ,	
NYS 198.1 (friable	•	TEM - Water: EPA		-1.5	EPA Protocol (Quantitative)		
NYS 198.6 NOB (r	•	Fibers >10µm		_	Other:		
☐ NIOSH 9002 (<1%		ositive Stop – Cle	-	**	· <b>—</b>	·	
Samplers Name:	Mark H. Stevens		Samplers Si		<u>-</u>		
				gnataro.	Volume/Area (Air)	Date/Time	
Sample #		Sample Description			HA#(Bulk)	Sampled	
4805-01	GYPSUM B	OARD			<u> </u>	11-1-21	
4805-02	- 11				<u> </u>		
1805-03	1,				<u> </u>		
4805-04	- 1				11	<u>.</u>	
4605-05	\\				1	1 1 1	
4605.06	JOINT CO	MADUNI			71. 	4	
4605-07	• /				1	3.4	
4605-08	/ `				2		
Client Sample # (s):		<u> </u>			Total # of Samples:	20.	
Relinquished (Client)	1	Date:	11-1- =	<del>*</del> /	Time	1600	
Received (Lab):		Date:	11/2	121	Time	12:15	
Comments/Special	Instructions:		•	. —			
					1	185	
					U		
	estos Lab Services COC - A1 fl						

Controlled Document – Asbestos Lab Services COC – A1 0 – 11/23/2009

Page 1 of 🗘 Pages



### **Asbestos Lab Services Chain of Custody**

EMSL Order Number(Lab Use Only):

Kernersville, NC 706 Grafin Street Kernersville, NC 27284 PHONE: (336) 992-1025 FAX: (336) 992-4175

		FAA. (3s	) 99Z-4 F/D
Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
4805-09	JOINT CORPORT	1	11-1-21
480510	','	2	1
4805-11	for court in the	3	
4805-12	'\	3	
1605-13	11	3	:
4605-14	1)	3	;
1/205-15	TEXTURED CEILING IM,	initia	
AE05-16			; ; ;
400 17		*	;
-1625-18	VFC - TYPE 1	5	
4505-19	11	5	
4265-20	\1	5	
4/15-21	VFL-TYPE -	6	
AEUT-20		6	
4205-23	,	6	:
165-24	VFC-TYPE 4		•
Comments/Special	Instructions:		

Controlled Document – Asbestos Lab Services COC – A1.0 – 11/23/2009

Page 2 of 3 Pages

3

## MEL ANALY DICAL INC

## Asbestos Lab Services Chain of Custody EMSL Order Number(Lab Use Only):

Kernersville, NC 706 Gralin Street Kernersville, NC 2/284 PHONE: (336) 992-4025 FAX: (336) 992-4176

		FAX: (336) 992-4175	
Sample #	Sample Description	Volume/Area (Air) HA # (Bulk)	Date/Time Sampled
4805-25	VFC-TYPE 3	17	11-1-21
4805-26	· · ·	7	:
ABUS-27	ASPHALT SIEMMIES	{	
1605-28	1	٤	\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
1205-24	· ;	b	
4805-30	TARPAPER	()	
4605-31	, i	( )	
4805-32	1	()	
4805-33	TRANSITE SIDING	10	
4605-34	· :	10	
4805-35	( :	10	
4805-36	TROVIELED CEMENT	11	
-1505 37	١,		
Abur 38	N. Control of the con	1.1	


Controlled Document - Asbestos Lab Services COC - A1.0 - 11/23/2009

Page \_\_\_\_\_\_ of \_\_\_\_\_ Pages


Comments/Special Instructions:

Section 4.0 Copy of Applicable Inspector Asbestos Licenses	

### **COPY OF APPLICABLE ASBESTOS LICENSES**


**Building Inspector:** 


Mark H. Stevens Davis & Floyd, Inc. Environmental Services SCDHEC License No. ASB-22192 (exp. 11/16/21)



Section 5.0 Sample Location Plan &	<u>Photographs</u>	







LEGEND

SAMPLE LOCATION

DESIGNED MHS  DRAWN MHS  MHS	CHECKED	OWNER	DRAWING TITLE	DATE
[ MHS	TGJ	GREENWOOD DISTRICT 50		NOV 2021
DRAWN	APPROVED	PROJECT TITLE	4805 MAIN STREET	JOB NO.
MHS	TGH		SAMPLE LOCATION PLAN	013948.00
DAVIS & SINCE	& FLOYD	ASBESTOS REPORT		
SINCI	E 1854	PROJECT LOCATION	SKETCH REFERENCE	H-101
Jobse		####	SHEET X-XXX	
É WWW.BAVE	SFLEYD.SEM			PAGE 1 OF 1

H:JobsEven/13948-00/Production/Environmental/Asbestos/4805 Main Street/Drawings\Sample Location Plan.dwg, 11/16/2021 10:18:59 AM, mark stevens



Right rear corner of house



Right side of house



Asbestos contaminated debris pile



Rear of house



Asbestos contaminated debris pile



Asbestos contaminated debris pile



Asbestos floor covering under carpet



Asbestos exterior siding (transite) under vinyl siding



Front of house

**End of Report**