




Laboratory



Consulting



Industrial Hygiene

**Limited AHERA Asbestos
Survey**

At:

**Brown Early Childhood
Education Center
520 W 5th St
Portales, NM 88130**

Prepared for:

**Portales Municipal Schools
Attn: Nat Gomez
501 S Abilene Street
Portales, NM 88130**

By:

**Asbestos Consulting, LLC
March 4th, 2019**

Limited AHERA Asbestos Survey

Of:

**Brown Early Childhood Education Center
520 W 5th Street
Portales, NM 88130**

Submitted to:

**Portales Municipal Schools
Attn: Nat Gomez
501 S Abilene Street
Portales, NM 88130**

Submitted by:

**Asbestos Consulting, LLC
P.O. Box 249
Lovington, New Mexico 88260**

Inspection completed and prepared by:

**Steven Simpson
Certified Asbestos Inspector**

Purpose

Steven Simpson, representing Asbestos Consulting, LLC conducted a limited Asbestos Inspection of the Brown Early Childhood Education Center located at 520 W 5th St in Portales, New Mexico. The inspection was completed on Monday, March 4th, 2019 to determine the presence of asbestos in building materials identified to be impacted by the upcoming renovations identified on the drawings provided by Formative Architecture. The inspection consisted of obtaining a drawing from the Architect, performing a walk-through to identify the homogenous area building materials present that will be impacted by the upcoming renovation, conducting measurements, and collecting samples of the suspect materials that will be impacted by the upcoming renovation to be tested for the presence of asbestos.

Building Summary

Due to the limited scope of this inspection a full building summary was not performed. The interior walls identified to be impacted by the planned renovations were finished with plaster, and the exterior walls inspected were finished with stucco. The floors in the areas inspected were made up of concrete and finished with a combination of carpet, vinyl floor tile, or ceramic tile. Four different types of cove base were identified throughout the areas inspected however the original cove base mastic was still in place throughout. The ceilings inspected were made up of 3 different types of fiberboard ceiling tiles nailed on with a drop ceiling system installed below. The floors inspected were finished with a combination of 12x12 VCT, 9x9 VCT, carpet, or a combination of either one on a concrete slab. Please note it is assumed that piping is present above the ceilings with suspect asbestos containing insulation however due to the nondestructive nature of this inspection the piping was inaccessible and was not inspected. Once renovation work begins and the piping is exposed it will need to be inspected at that time before any work on the piping can be performed.

Inspection

The inspection was performed in general compliance with the Texas Asbestos Health Protection Rules (25 TAC § 295.31-73), the National Emission Standards for Hazardous Air Pollutants (NESHAP) issued by the U.S. Environmental Protection Agency (40 CFR 61, Subpart M – National Emission Standard for Asbestos), the Asbestos Hazard Emergency Response Act (AHERA, 40 CFR 763), and the Asbestos School Hazard Abatement Reauthorization Act of 1990 (ASHARA, 40 CFR 763, Appendix C to Subpart E).

Asbestos Consulting, LLC employed a sampling strategy which involved identifying homogeneous materials limited to the areas determined by the architects drawing provided and collecting bulk samples of the suspect materials for laboratory analysis to determine asbestos content present. The term "homogeneous," as defined by AHERA, means any material having the same color and texture, and having been installed in the same general time period. Twenty-three (23) homogeneous areas were identified during the course of this survey, from which fifty-three (53) bulk samples were collected. These materials are summarized in Table 1 on the next page.

Table 1 – Summary of Homogenous Materials

Suspect ACM	Location
White/Brown 1x1 Pinhole Ceiling Tile	Above Drop Ceilings in Hallways
White/Gray 2x4 Drop Ceiling Tile	Hallways, Classrooms, and Boys Restrooms
Brown Interior Window Caulking	Interior Side Windows
White/Brown Fiberboard Ceiling Tiles	Above Drop Ceilings in Classrooms
White/Gray 2x4 Pinhole Drop Ceiling Tile	Girls Restroom North of Boys Restroom
White/Peach Sand Texture Plaster	Walls in Classrooms, Closets and Closet Ceilings, Walls in Bathrooms and Bathrooms Ceilings
White Peach Plaster	South Wall in Boys Restroom West Side of School and in Girls Restroom East Side of School
Tan/Black 12x12 Tile and Mastic	Floors Under Carpet in Hallways
Black 9x9 Tile and Mastic	Under Carpet in Closets in Classrooms
Tan 9x9 Tile and Black Mastic	Floor in Hall by Multipurpose Room
Brown/Black 9x9 Tile and Mastic	Border Hall by Multipurpose Room
Tan/Black 12x12 Tile and Mastic	Floor in Girls Restroom in East Hall
White 12x12 Tile and Mastic	Floor in Boys Restroom in West Hall
Black Mastic	Under Carpet in Classrooms
Brown 4" Cove Base and Mastic	Wall Base in Girls Restroom East Hall
Black 4" Cove Base and Mastic	Wall Base in Boys Restroom West Hall
Brown 6" Cove Base and Mastic	Wall Base in Some Classrooms
Mauve 6" Cove Base and Mastic	Wall Base in Some Classrooms
Black 6" Cove Base and Mastic	Wall Base in Most Classrooms
Yellow/White Fiberglass Insulation	Pipe Wrap in Chase in Girls Restroom Near Gym
Tan Mastic	Behind FRP in Boys Restroom in West Hall
Brown Caulking	Exterior Side Windows
Peach/Orange Stucco	Exterior Walls and Around Windows

The homogeneous material was then assessed in terms of friability, condition, and quantity. The term "friable" means a material that when dry can be reduced to a powder using hand pressure (25 TAC § 295.32 (45)). Each bulk sample collected was carefully extracted and placed in its own self-sealing bag. Each bag was sealed, and labeled with a unique sample number. Appropriate chain of custody paperwork was completed listing each sample collected.

Laboratory Analysis

Fifty-three (53) samples were taken and shipped under standard chain of custody protocols to Quantem Laboratories in Oklahoma City, OK. This facility is accredited by the National Voluntary Laboratory Accreditation Program (NVLAP) for asbestos analysis, and licensed by the TDSHS as an asbestos laboratory (license number 30-0143). The bulk samples were broken down into layers and analyzed by Polarized Light Microscopy (PLM) coupled with Dispersion Staining in accordance with EPA Method 600-R-93-116. The laboratory reports with chain of custody documentation are attached to this report.

Summary of Findings

According to the lab report produced by Quantem Laboratories, eleven (11) of the sixty-four (64) samples analyzed contained asbestos greater than one percent. An ACM is defined as any material or product that contains more than one percent (1%) asbestos (25 TAC § 295.32 (15)). Asbestos containing materials include the following: black mastic, black floor tile, tan floor tile, brown floor tile, and black/yellow mastic (see attached floor plan for ACM locations). **All quantities listed are estimated and contractor should field verify before bidding.**

Recommendations:

- A. Before renovation can occur, all asbestos containing building materials greater than one percent, that will be impacted during renovation, must be removed by a Licensed Asbestos Contractor following all EPA, OSHA and State of New Mexico rules and recommendations due to the fact that disturbance may cause the asbestos to become regulated.
- B. If any suspect materials are encountered during renovation activities that do not show to have been tested, they should not be disturbed and should be considered asbestos containing until determined otherwise.
- C. All asbestos containing materials will have to be disposed of at an EPA/Solid Waste Asbestos certified landfill.

Asbestos Chart

The following chart has the Asbestos sample, locations, and conditions listed.

<u>Sample #</u>	<u>Building Material</u>	<u>Location</u>	<u>Friable or Non-Friable</u>	<u>Quantity</u>	<u>Condition</u>	<u>Percent Asbestos</u>
026a	Black Mastic	Under Floor Tile under Carpet in Hallways	N	3,885 SQFT	Fair	8% Chrysotile
030, 030a	Black Floor Tile and Black Mastic	Under Carpet in Closets in Classrooms	N	175 SQFT	Poor	8% Chrysotile
031, 031a, 033, 033a	Black Tile, Tan Tile and Black Mastic	Floor in Hall by Multipurpose Gym	N	475 SQFT	Fair	5% Chrysotile
035, 035a	Tan Floor Tile and Black Mastic	Floor in Girls Restroom East Hall	N	216 SQFT	Fair	Tile 3% Mastic 5% Chrysotile
039	Black/Yellow Mastic	Under Carpet in Classrooms	N	7,200 SQFT	Fair	5% Chrysotile
0045a	Yellow/Black Mastic	Behind Cove Base Throughout Areas Inspected	N	2,630 LNFT	Fair	4% Chrysotile
051, 052, 053	Peach Stucco	Exterior Walls	N	N/A	Fair	<1% Chrysotile

Asbestos Consulting, LLC would like to thank you for the opportunity to provide your organization with our services. If you have any questions, or if I can be of any further assistance, please feel free to contact me.

Respectfully,



Steven Simpson
Certified Asbestos Inspector

Acw Note: Cove base mastic throughout areas in speed contains asbestos 2,630 LNFt - 6'

- = Carpet and tile over asbestos containing mastic 3,885 sqft
- = 9x9 tile mastic containing asbestos 475 sqft
- = Tan 12x12 Tile mastic containing asbestos 216 sqft



- = Black mastic containing asbestos under carpet 7,200 sqft
- = 9x9 Tile mastic containing asbestos under carpet 175 sqft



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 306015	Client: Asbestos Consulting
Account Number: B316	P.O. Box 249
Date Received: 03/07/2019	Lovington, NM 88260
Received By: Gennifer Bridgewater	
Date Analyzed: 03/12/2019	Project: 520 W 5th St
Analyzed By: Dee Ammerman	Project Location: Portoles, NM
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
001	CT1-1	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 90	Paint
002	CT1-2	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 90	Paint
003	CT1-3	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 90	Paint
004	DC1-1	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 40 Glass Fiber 40	Perlite Paint
005	DC1-2	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 40 Glass Fiber 40	Perlite Paint
006	DC1-3	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 40 Glass Fiber 40	Perlite Paint
007	IWC-1	Homogeneous	Brown Window Glazing	Asbestos Not Present	NA	CaCO3 Binder

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

QuantEM Lab No. 306015	Client: Asbestos Consulting
Account Number: B316	P.O. Box 249
Date Received: 03/07/2019	Lovington, NM 88260
Received By: Gennifer Bridgewater	
Date Analyzed: 03/12/2019	Project: 520 W 5th St
Analyzed By: Dee Ammerman	Project Location: Portoles, NM
Methodology: EPA/600/R-93/116	Project Number: N/A

QuantEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
008	IWC-2	Homogeneous	Brown Caulk	Asbestos Not Present	NA	CaCO3 Binder
009	IWC-3	Homogeneous	Brown Caulk	Asbestos Not Present	NA	CaCO3 Binder
010	FBC-1	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 90	Paint
011	FBC-2	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 90	Paint
012	FBC-3	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 90	Paint
013	PCT-1	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 40 Glass Fiber 40	Perlite Paint

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

QuantEM is a NVLAP accredited PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 306015	Client: Asbestos Consulting
Account Number: B316	P.O. Box 249
Date Received: 03/07/2019	Lovington, NM 88260
Received By: Gennifer Bridgewater	
Date Analyzed: 03/12/2019	Project: 520 W 5th St
Analyzed By: Dee Ammerman	Project Location: Portoles, NM
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
014	PCT-2	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 40 Glass Fiber 40	Perlite Paint
015	PCT-3	Homogeneous	White Ceiling Tile	Asbestos Not Present	Cellulose 40 Glass Fiber 40	Perlite Paint
016	P1-1	Homogeneous	Peach Plaster	Asbestos Not Present	NA	CaCO3 Sand Paint
017	P1-2	Homogeneous	Peach Plaster	Asbestos Not Present	NA	CaCO3 Sand Paint
018	P1-3	Homogeneous	Peach Plaster	Asbestos Not Present	NA	CaCO3 Sand Paint
019	P1-4	Homogeneous	Peach Plaster	Asbestos Not Present	NA	CaCO3 Sand Paint

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 306015	Client: Asbestos Consulting
Account Number: B316	P.O. Box 249
Date Received: 03/07/2019	Lovington, NM 88260
Received By: Gennifer Bridgewater	
Date Analyzed: 03/12/2019	Project: 520 W 5th St
Analyzed By: Dee Ammerman	Project Location: Portoles, NM
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
020	P1-5	Homogeneous	Peach Plaster	Asbestos Not Present	NA	CaCO3 Sand Paint
021	P1-6	Homogeneous	Peach Plaster	Asbestos Not Present	NA	CaCO3 Sand Paint
022	P1-7	Homogeneous	Peach Plaster	Asbestos Not Present	NA	CaCO3 Sand Paint
023	P2-1	Layered	White Skim Coat	Asbestos Not Present	NA	CaCO3 Sand Paint
023a		Layered	Peach Plaster	Asbestos Not Present	NA	CaCO3 Sand
024	P2-2	Layered	White Skim Coat	Asbestos Not Present	NA	CaCO3 Sand Paint

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 306015	Client: Asbestos Consulting
Account Number: B316	P.O. Box 249
Date Received: 03/07/2019	Lovington, NM 88260
Received By: Gennifer Bridgewater	
Date Analyzed: 03/12/2019	Project: 520 W 5th St
Analyzed By: Dee Ammerman	Project Location: Portoles, NM
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
024a		Layered	Peach Plaster	Asbestos Not Present	NA	CaCO3 Sand
025	P2-3	Layered	White Skim Coat	Asbestos Not Present	NA	CaCO3 Sand Paint
025a		Layered	Peach Plaster	Asbestos Not Present	NA	CaCO3 Sand
026	T1-1	Layered	Tan Floor Tile	Asbestos Not Present	NA	CaCO3 Vinyl
026a		Layered	Black Mastic	Asbestos Present Chrysotile 8	NA	Tar
027	T1-2	Layered	Tan Floor Tile	Asbestos Not Present	NA	CaCO3 Vinyl
027a		Layered	** Mastic	**	Not Analyzed	

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 306015	Client: Asbestos Consulting
Account Number: B316	P.O. Box 249
Date Received: 03/07/2019	Lovington, NM 88260
Received By: Gennifer Bridgewater	
Date Analyzed: 03/12/2019	Project: 520 W 5th St
Analyzed By: Dee Ammerman	Project Location: Portoles, NM
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
Positive Stop						
028	T1-3	Layered	Tan Floor Tile	Asbestos Not Present	NA	CaCO3 Vinyl
028a		Layered	** Mastic	**	Not Analyzed	
Positive Stop						
029	T1-4	Layered	Tan Floor Tile	Asbestos Not Present	NA	CaCO3 Vinyl
029a		Layered	** Mastic	**	Not Analyzed	
Positive Stop						
030	T-2A-1	Layered	Black Floor Tile	Asbestos Present Chrysotile 8	NA	CaCO3 Vinyl
030a		Layered	Black Mastic	Asbestos Present Chrysotile 8	NA	Tar

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 306015	Client: Asbestos Consulting
Account Number: B316	P.O. Box 249
Date Received: 03/07/2019	Lovington, NM 88260
Received By: Gennifer Bridgewater	
Date Analyzed: 03/12/2019	Project: 520 W 5th St
Analyzed By: Dee Ammerman	Project Location: Portoles, NM
Methodology: EPA/600/R-93/116	Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
031	T2-1	Layered	Tan Floor Tile	Asbestos Present Chrysotile 5	NA	CaCO3 Vinyl
031a		Layered	Black Mastic	Asbestos Present Chrysotile 5	NA	Tar
032	T2-2	Layered	** Floor Tile	**	Not Analyzed	
Positive Stop						
032a		Layered	** Mastic	**	Not Analyzed	
Positive Stop						
033	T3-1	Layered	Brown Floor Tile	Asbestos Present Chrysotile 5	NA	CaCO3 Vinyl
033a		Layered	Black Mastic	Asbestos Present Chrysotile 5	NA	Tar
034	T3-2	Layered	** Floor Tile	**	Not Analyzed	

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 306015	Client: Asbestos Consulting
Account Number: B316	P.O. Box 249
Date Received: 03/07/2019	Lovington, NM 88260
Received By: Gennifer Bridgewater	
Date Analyzed: 03/12/2019	Project: 520 W 5th St
Analyzed By: Dee Ammerman	Project Location: Portoles, NM
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
Positive Stop						
034a		Layered	** Mastic	**		Not Analyzed
Positive Stop						
035	T4-1	Layered	Tan Floor Tile	Asbestos Present Chrysotile 3	NA	CaCO3 Vinyl
035a		Layered	Black Mastic	Asbestos Present Chrysotile 5	NA	Tar
036	T4-2	Layered	** Floor Tile	**		Not Analyzed
Positive Stop						
036a		Layered	** Mastic	**		Not Analyzed
Positive Stop						
037	T5-1	Layered	White Floor Tile	Asbestos Not Present	NA	CaCO3 Vinyl

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

Quantem Lab No. 306015	Client: Asbestos Consulting
Account Number: B316	P.O. Box 249
Date Received: 03/07/2019	Lovington, NM 88260
Received By: Gennifer Bridgewater	
Date Analyzed: 03/12/2019	Project: 520 W 5th St
Analyzed By: Dee Ammerman	Project Location: Portoles, NM
Methodology: EPA/600/R-93/116	Project Number: N/A

Quantem Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
037a		Layered	Yellow Mastic	Asbestos Not Present	NA	Glue
038	T5-2	Layered	White Floor Tile	Asbestos Not Present	NA	CaCO3 Vinyl
038a		Layered	Yellow Mastic	Asbestos Not Present	NA	Glue
039	BM-1	Homogeneous	Black/Yellow Mastic	Asbestos Present Chrysotile 5	NA	Tar Glue
040	BM-2	**	** **	**	Not Analyzed	
Positive Stop						
041	BM-3	**	** **	**	Not Analyzed	
Positive Stop						
042	CB1	Layered	Brown Cove Base	Asbestos Not Present	NA	CaCO3 Vinyl

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 306015	Client: Asbestos Consulting
Account Number: B316	P.O. Box 249
Date Received: 03/07/2019	Lovington, NM 88260
Received By: Gennifer Bridgewater	
Date Analyzed: 03/12/2019	Project: 520 W 5th St
Analyzed By: Dee Ammerman	Project Location: Portoles, NM
Methodology: EPA/600/R-93/116	Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
042a		Layered	Brown Mastic	Asbestos Not Present	NA	Glue
043	BCB-1	Layered	Black Cove Base	Asbestos Not Present	NA	CaCO3 Vinyl
043a		Layered	Yellow Mastic	Asbestos Not Present	NA	Glue CaCO3
044	BRC-1	Layered	Brown Cove Base	Asbestos Not Present	NA	CaCO3 Vinyl
044a		Layered	Tan Mastic	Asbestos Not Present	NA	Glue CaCO3
045	MC-1	Layered	Mauve Cove Base	Asbestos Not Present	NA	CaCO3 Vinyl

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

QuantEM Lab No. 306015	Client: Asbestos Consulting
Account Number: B316	P.O. Box 249
Date Received: 03/07/2019	Lovington, NM 88260
Received By: Gennifer Bridgewater	
Date Analyzed: 03/12/2019	Project: 520 W 5th St
Analyzed By: Dee Ammerman	Project Location: Portoles, NM
Methodology: EPA/600/R-93/116	Project Number: N/A

QuantEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
045a		Layered	Yellow/Black Mastic	Asbestos Present Chrysotile 4	NA	Tar Glue
046	BC-1	Layered	Black Cove Base	Asbestos Not Present	NA	CaCO3 Vinyl
046a		Layered	Tan Mastic	Asbestos Not Present	NA	Glue CaCO3
047	FI-1	Layered	Yellow Insulation	Asbestos Not Present	Glass Fiber 100	
047a		Layered	White Wrap	Asbestos Not Present	Cellulose 100	
048	CRP-1	Homogeneous	Tan Mastic	Asbestos Not Present	NA	Glue CaCO3
049	EWC-1	Homogeneous	Brown Caulk	Asbestos Not Present	NA	CaCO3 Binder

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

QuantEM is a NVLAP accredited PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.



2033 HERITAGE PARK DR, OKLAHOMA CITY, OK 73120 | 1.800.822.1650

Polarized Light Microscopy Asbestos Analysis Report

QuanTEM Lab No. 306015	Client: Asbestos Consulting
Account Number: B316	P.O. Box 249
Date Received: 03/07/2019	Lovington, NM 88260
Received By: Gennifer Bridgewater	
Date Analyzed: 03/12/2019	Project: 520 W 5th St
Analyzed By: Dee Ammerman	Project Location: Portoles, NM
Methodology: EPA/600/R-93/116	Project Number: N/A

QuanTEM Sample ID	Client Sample ID	Composition	Color / Description	Asbestos (%)	Non-Asbestos Fiber (%)	Non Fibrous
050	EWC-2	Homogeneous	Brown Caulk	Asbestos Not Present	NA	CaCO3 Binder
051	S1-1	Homogeneous	Peach Stucco	Asbestos Present Chrysotile <1	NA	CaCO3 Sand Paint
052	S1-2	Homogeneous	Peach Stucco	Asbestos Present Chrysotile <1	NA	CaCO3 Sand Paint
053	S1-3	Homogeneous	Peach Stucco	Asbestos Present Chrysotile <1	NA	CaCO3 Sand Paint

Dee Ammerman

Dee Ammerman, Laboratory Manager

3/12/2019

Date of Report

Unless otherwise noted, upon receipt the condition of the sample was acceptable for analysis.

Quantem is a NVLAP accredited PLM laboratory (Lab Code: 101959-0). This report relates only to the specific items tested. NVLAP accreditation applies only to analysis performed utilizing EPA/600/M4-82-020 and EPA/600/R-93/116 methods. This report may not be used to claim product endorsement by NVLAP or any agency of the US Government. This report may not be reproduced except in full, without the written approval of the laboratory.

3/12/05



ASBESTOS CHAIN OF CUSTODY

2033 Heritage Park Drive, Oklahoma City, OK 73120-7502
(800) 822-1650 • (405) 755-7272 • Fax: (405) 755-2058

LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

Contact Information		Project Information	
Company: <i>Asbestos Consulting LLC</i>	Phone: <i>575-396-8492</i>	Project Name: <i>520 W 5th St</i>	Report Results (<input checked="" type="checkbox"/> one box)
Contact: <i>Steven Simpson</i>	Cell Phone: <i>575-704-9366</i>	Project Location: <i>Portales NM</i>	Quantem Website <input type="checkbox"/>
Account #: <i>6316</i>	E-mail: <i>asbestos consulting @ eg.com</i>	Project ID:	Email <input type="checkbox"/>
SAMPLED BY: Name: <i>Steven Simpson</i>	Date: <i>3-4-19</i>	P.O. Number:	Other <input type="checkbox"/>

RELINQUISHED BY <i>Steven Simpson</i>	DATE & TIME <i>3-5-19</i>	VIA <i>Fed Ex</i>	RECEIVED BY <i>[Signature]</i>	DATE & TIME <i>3/7/19 01:10</i>
--	------------------------------	----------------------	-----------------------------------	------------------------------------

REQUESTED SERVICES (Please the Appropriate Boxes)

	PLM		TEM		TEM		TURNAROUND TIME	
	<input checked="" type="checkbox"/> Bulk Analysis (EPA 600/R-93/116)	<input type="checkbox"/> Vermiculite Attic Insulation (EPA 600/R-04/004)	<input type="checkbox"/> Air-AHERA	<input type="checkbox"/> Air-NIOSH 7402	<input type="checkbox"/> Bulk-Presence / Absence EPA600/R-93/116	<input type="checkbox"/> Bulk-Quantitative [weight%]- Chatfield	<input type="checkbox"/> Rush	<input type="checkbox"/> Same Day
<input type="checkbox"/> 400 Point Count	<input type="checkbox"/> Other	<input type="checkbox"/> Air-ISO 10312	<input type="checkbox"/> Drinking Water- EPA 100.2	<input type="checkbox"/> Dust-Presence / Absence	<input type="checkbox"/> Dust-Quantitative [fibers/sq.cm]- ASTM D5755	<input type="checkbox"/> 24 - Hour	<input checked="" type="checkbox"/> 3 - Day	<input type="checkbox"/> 5 - Day
<input type="checkbox"/> 1000 Point Count	PCM		<input type="checkbox"/> Waste Water- EPA 600/4-83-043	Other				
<input type="checkbox"/> Gravimetric Preparation	NIOSH 7400							
<input type="checkbox"/> Particle ID								

No.	Sample ID (10 Characters Max)	To Be Analyzed <input checked="" type="checkbox"/>	Color	Description	Volume / Area (as applicable)	Comments / Notes
1	CTI-1	<input type="checkbox"/>	White/Beige	1x1 Pinhole ceiling tile		Above drop ceiling in hallway 5
2	CTI-2	<input type="checkbox"/>	White/Beige	1x1 Pinhole ceiling tile		" "
3	CTI-3	<input type="checkbox"/>	White/Beige	1x1 Pinhole ceiling tile		" "
4	Del-1	<input type="checkbox"/>	White/gray	2x4 drop ceiling tile		Hallway 5 classrooms, boys area
5	Del-2	<input type="checkbox"/>	White/gray	2x4 drop ceiling tile		" "
6	Del-3	<input type="checkbox"/>	White/gray	2x4 drop ceiling tile		" "
7	IWC-1	<input type="checkbox"/>	Brown	Interior window caulking		" "
8	IWC-2	<input type="checkbox"/>	Brown	Interior window caulking		Front side windows
9	IWC-3	<input type="checkbox"/>	Brown	Interior window caulking		" "
10	FBC-1	<input type="checkbox"/>	White/Beige	Fiber-board ceiling tiles		Above drop ceilings in classrooms

105 SATURDAY FEDEX SAMPLE DELIVERY - CALL TO SCHEDULE • Use this address for Saturday Delivery only: 4220 N. Santa Fe Ave., Oklahoma City, OK 73105-8517 • Mark Package "Hold for Saturday Pickup"

519 Please Note - UPS and USPS are NOT available for Saturday Delivery



ASBESTOS CHAIN OF CUSTODY

2033 Heritage Park Drive, Oklahoma City, OK 73120-7502
 (800) 822-1650 • (405) 755-7272 • Fax: (405) 755-2058

LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

For Lab Use Only

Lab No. 306015

Accept Reject

Project Information		Project Name:	Project Location:	Volume / Area (as applicable)	Comments / Notes
Company: <u>Asbestos consulting LLC</u>		<u>Brom ECEC 520 W 5th St</u>			<u>portables rm</u>
No.	Sample ID (10 Characters Max)	To Be Analyzed <input checked="" type="checkbox"/>	Color	Description	
11	<u>FBC-2</u>	<input type="checkbox"/>	<u>white/brown</u>	<u>Fiberboard ceiling tile</u>	<u>Above boy ceiling classrooms</u>
12	<u>FBC-3</u>	<input type="checkbox"/>	<u>white/brown</u>	<u>Fiberboard ceiling tile</u>	<u>" " "</u>
13	<u>PCT-1</u>	<input type="checkbox"/>	<u>white/grey</u>	<u>2x4 pinhole drop ceiling tile</u>	<u>GIRLS RESTROOM N. of boys</u>
14	<u>PCT-2</u>	<input type="checkbox"/>	<u>white/grey</u>	<u>2x4 pinhole drop ceiling tile</u>	<u>GIRLS RESTROOM N. of boys</u>
15	<u>PCT-3</u>	<input type="checkbox"/>	<u>white/grey</u>	<u>2x4 pinhole drop ceiling tile</u>	<u>" " "</u>
16	<u>P1-1</u>	<input type="checkbox"/>	<u>white/peach</u>	<u>Sand texture plaster</u>	<u>walls classrooms, closets & closet ceilings walls in both boys & bathroom-ceiling's.</u>
17	<u>P1-2</u>	<input type="checkbox"/>	<u>white/peach</u>	<u>Sand texture plaster</u>	<u>" " "</u>
18	<u>P1-3</u>	<input type="checkbox"/>	<u>white/peach</u>	<u>Sand texture plaster</u>	<u>" " "</u>
19	<u>P1-4</u>	<input type="checkbox"/>	<u>white/peach</u>	<u>Sand texture plaster</u>	<u>" " "</u>
20	<u>P1-5</u>	<input type="checkbox"/>	<u>white/peach</u>	<u>Sand texture plaster</u>	<u>" " "</u>
21	<u>P1-6</u>	<input type="checkbox"/>	<u>white/peach</u>	<u>Sand texture plaster</u>	<u>" " "</u>
22	<u>P1-7</u>	<input type="checkbox"/>	<u>white/peach</u>	<u>Sand texture plaster</u>	<u>" " "</u>
23	<u>P2-1</u>	<input type="checkbox"/>	<u>white/peach</u>	<u>plaster</u>	<u>5 walls in boys & E side school</u>
24	<u>P2-2</u>	<input type="checkbox"/>	<u>white/peach</u>	<u>plaster</u>	<u>1 in GIRLS & E side school</u>
25	<u>P2-3</u>	<input type="checkbox"/>	<u>white/peach</u>	<u>plaster</u>	<u>" " "</u>
26	<u>T1-1</u>	<input type="checkbox"/>	<u>tan/black</u>	<u>12x12 tile & waste</u>	<u>Flours under car port in Hallways</u>
27	<u>T1-2</u>	<input type="checkbox"/>	<u>tan/black</u>	<u>12x12 tile & waste</u>	<u>" " "</u>
28	<u>T1-3</u>	<input type="checkbox"/>	<u>tan/black</u>	<u>12x12 tile & waste</u>	<u>" " "</u>
29	<u>T1-4</u>	<input type="checkbox"/>	<u>tan/black</u>	<u>12x12 tile & waste</u>	<u>" " "</u>
30	<u>T-2A1</u>	<input type="checkbox"/>	<u>Black</u>	<u>9x9 tile & waste</u>	<u>under carpet in closets in classrooms</u>



ASBESTOS CHAIN OF CUSTODY

2033 Heritage Park Drive, Oklahoma City, OK 73120-7502
 (800) 822-1650 • (405) 755-7272 • Fax: (405) 755-2058

LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

For Lab Use Only
Lab No. <u>360013</u>
<input checked="" type="checkbox"/> Accept <input type="checkbox"/> Reject

Project Information		Project Name:	Project Location:	Comments / Notes		
Company: <u>Asbestos consulting LLC</u>		<u>Born Ecc 520 W 5th St</u>	<u>Portales NM</u>			
No.	Sample ID (10 Characters Max)	To Be Analyzed	Color	Description	Volume / Area (as applicable)	Comments / Notes
31	TZ-1	<input type="checkbox"/>	Tan/black	9x9 tile mastic		Floor Hall by multi-purpose gym
32	TZ-2	<input type="checkbox"/>	Tan/black	9x9 tile mastic		Floor Hall by multi-purpose gym
33	T3-1	<input type="checkbox"/>	Brown/black	9x9 tile mastic		Border Hall by multi-purpose gym
34	T3-2	<input type="checkbox"/>	Brown/black	9x9 tile mastic		Border Hall by multi-purpose gym
35	T4-1	<input type="checkbox"/>	Tan/black	12x12 tile mastic		Floor Girls RR E Hall
36	T4-2	<input type="checkbox"/>	Tan/black	12x12 tile mastic		Floor Girls RR E Hall
37	T5-1	<input type="checkbox"/>	White	12x12 tile mastic		Floor Boys RR W Hall
38	T5-2	<input type="checkbox"/>	White	12x12 tile mastic		Floor Boys RR W Hall
39	Bm-1	<input type="checkbox"/>	Black	mastic		Under carpet in classrooms
40	Bm-2	<input type="checkbox"/>	Black	mastic		Under carpet in classrooms
41	Bm-3	<input type="checkbox"/>	Black	mastic		Under carpet in classrooms
42	CB1	<input type="checkbox"/>	Brown	4" core base mastic		Wall base Girls RR E Hall
43	BCB-1	<input type="checkbox"/>	Black	4" core base mastic		Wall base Boys RR W Hall
44	BCC-1	<input type="checkbox"/>	Brown	6" core base mastic		Wall base in ^{base} classrooms
45	mc-1	<input type="checkbox"/>	White	6" core base mastic		Wall base in base classrooms
46	Bc-1	<input type="checkbox"/>	Black	6" core base mastic		Wall base in base classrooms
47	FI-1	<input type="checkbox"/>	Yellowish	Fiberglass Insulation		Pipe wrap in chase Girls RR E Hall
48	CCP-1	<input type="checkbox"/>	Tan	mastic		Behind FRP in boys RR W Hall
49	FWC-1	<input type="checkbox"/>	Brown	Conkby		Ext side windows
50	EWc-2	<input type="checkbox"/>	Brown	Conkby		Ext side windows



ASBESTOS CHAIN OF CUSTODY
 2033 Heritage Park Drive, Oklahoma City, OK 73120-7502
 (800) 822-1650 • (405) 755-7272 • Fax: (405) 755-2058

LEGAL DOCUMENT - PLEASE PRINT LEGIBLY

For Lab Use Only
 Lab No. 300015
 Accept Reject

Project Information		Project Name:	Project Location:	Volume / Area (as applicable)	Comments / Notes	
Company: <u>Asbestos Consulting LLC</u>		<u>Som Ecic 520 W. 5th St</u>	<u>Portals m</u>			
No.	Sample ID (10 Characters Max)	To Be Analyzed	Color	Description	Volume / Area (as applicable)	Comments / Notes
<u>S1</u>	<u>S1-1</u>	<input type="checkbox"/>	<u>pink/gray</u>	<u>stucco</u>		<u>Ext walls around windows</u>
<u>S2</u>	<u>S1-2</u>	<input type="checkbox"/>	<u>pink/gray</u>	<u>stucco</u>		<u>Ext walls around windows</u>
<u>S3</u>	<u>S1-3</u>	<input type="checkbox"/>	<u>pink/gray</u>	<u>stucco</u>		<u>11</u>
<u>-4</u>		<input type="checkbox"/>				
<u>-5</u>		<input type="checkbox"/>				
<u>-6</u>		<input type="checkbox"/>				
<u>-7</u>		<input type="checkbox"/>				
<u>-8</u>		<input type="checkbox"/>				
<u>-9</u>		<input type="checkbox"/>				
<u>-0</u>		<input type="checkbox"/>				
<u>-1</u>		<input type="checkbox"/>				
<u>-2</u>		<input type="checkbox"/>				
<u>-3</u>		<input type="checkbox"/>				
<u>-4</u>		<input type="checkbox"/>				
<u>-5</u>		<input type="checkbox"/>				
<u>-6</u>		<input type="checkbox"/>				
<u>-7</u>		<input type="checkbox"/>				
<u>-8</u>		<input type="checkbox"/>				
<u>-9</u>		<input type="checkbox"/>				
<u>-0</u>		<input type="checkbox"/>				