

**ESTILL MORRISON AVENUE NEIGHBORHOOD DEMOLITION AUGUST 27, 2021
CDBG #4-CE-18-009**

| | HOUSE Location: | PARCEL # | APPROX SF OF STRUCTURE | ASBESTOS TESTING/RESULTS | DETAILS |
|--------|--|---------------|------------------------|--------------------------|---|
| UNIT # | | | | | |
| 1 | 113 Morrison Ave | 068-04-17-002 | 1200 | ABATEMENT | Popcorn ceiling texture & drywall/joint compound positive for asbestos. |
| 2 | 160 Morrison Ave | 068-04-16-008 | 1500 | ABATEMENT | Window glazing positive for asbestos. |
| 3 | 285 Morrison Ave | 068-04-17-006 | 1000 | NO ABATEMENT | Window glazing & exterior caulking contain <1% Anthophyllite. Not classified as ACM. |
| 4 | Morrison Ave (wooden open frame structure) | 069-01-15-026 | 2000 | NO ABATEMENT | None of the material sampled were positive for asbestos. No Abatement prior to demolition. |
| 5 | 353 Morrison Ave | 069-01-17-011 | 1600 | ABATEMENT | Silver roof coating and drywall/joint compound positive for asbestos. |
| 6 | 493 Morrison Ave | 069-01-17-019 | 1100 | NO ABATEMENT | None of the material sampled were positive for asbestos. No Abatement prior to demolition. |
| 7 | South MLK BLVD next to 443 (totally overgrown) | 069-01-03-006 | 1200 | NO ABATEMENT | None of the material sampled were positive for asbestos. No Abatement prior to demolition. |
| 8 | South MLK BLVD (block building only) | 069-01-03-007 | 500 | NO ABATEMENT | None of the material sampled were positive for asbestos. No Abatement prior to demolition. |
| 9 | 316 First Street | 069-01-14-003 | 1300 | ABATEMENT | Transite siding found under exterior wood siding and the sheet flooring are positive for asbestos. |
| 10 | 648 First Street | 069-01-14-004 | 1600 | DEMO/RACM | Transite siding is positive for asbestos. Due to condition of unit, abatement will need to be Demo with RACM. |