



South side –
Front of
Schoolhouse –
Facing Hwy 98

EAST WALL – looking North



EAST Wall – looking South



NORTH Wall – looking South



NORTH Wall – from the NE corner





North Wall detail – showing example of wood that needs replacing.



Close up of North wall

WEST Wall – from the NW corner looking south



WEST Wall – from the SW corner looking northeast



WEST Wall – details (example of repairs required)



West Wall Details

