



Asbestos & Lead Based Paint Assessment

City of Spartanburg
706 West Main Street, Building 1
Spartanburg, South Carolina 29301

Prepared for:

The City of Spartanburg
440 South Church St., Suite B
Spartanburg, South Carolina 29306

Prepared by:

Apex Environmental Management, Inc.
7 Winchester Court
Mauldin, South Carolina 29662

Project Number: 0521-99

June 15, 2021





Apex Project Number 0521-99

June 15, 2021

Mr. Jeff Tillerson
City of Spartanburg
440 South Church Street, Suite B
Spartanburg, SC 29306

Reference: Asbestos and Lead-Based Paint Assessment Services
706 West Main Street, Building 1
Spartanburg, South Carolina 29301

Dear Mr. Tillerson:

Apex Environmental Management, Inc. (Apex) is pleased to provide the results of our assessment services for the referenced property.

This report and the associated attachments summarize our evaluation of the conditions observed at the project site. The findings presented by Apex are based upon sampling performed in the subject building. There is a chance that undetected ACM may exist in the building between walls or in other areas that would only be exposed during demolition or structural renovations. Should material be discovered that could potentially contain asbestos during the demolition process, additional samples of the material should be collected by a licensed asbestos inspector and submitted to an accredited laboratory for analytical interpretation. Our recommendations are based on the guidelines presented in EPA and/or OSHA regulations.

Please note that this document is not a specification for asbestos removal. It does not contain means and methods for abatement. Quantities are estimates and contractors must verify amounts prior to bidding or removal. If you are planning an abatement project, please contact Apex to discuss the requirements. Use of this document without the express written consent of Apex is at the sole risk of the user and or/abatement contractor.

The conclusions and/or recommendations contained in this report are based on our understanding of the applicable standards at the time this report was prepared. No warranty, expressed or implied, is made. If you have any questions, please feel free to contact us at (864) 404-3210.

Respectfully submitted,
APEX ENVIRONMENTAL MANAGEMENT, INC.

Stephanie Hamby
Project Manager

Tom Oliver
Vice President

Appendices

7 Winchester Court
Mauldin, SC 29662
864.404.3210 office
864.404.3213 fax

802 E. Martintown Rd.
Suite 208
N. Augusta, SC 29841
803.440.2790 office

www.apex-ehs.com

SERVICES

Indoor Air Quality

Mold Remediation

Asbestos & Lead

Industrial Hygiene

Worker Health &
Safety

Mold Consulting

Moisture
Management
Plans

Safety
Assessment

Environmental Site
Assessments

Hazard
Communication

ASBESTOS AND LEAD BASED PAINT ASSESSMENT

**CITY OF SPARTANBURG
706 WEST MAIN STREET, BUILDING 1
SPARTANBURG, SOUTH CAROLINA 29301**

APEX PROJECT NO. 0521-99

TABLE OF CONTENTS

SECTION

- I Asbestos & Lead Evaluation Report
- II Asbestos & LBP Data Tables
- III Laboratory Analytical Results & Chain of Custody
- IV Photographic Log
- V SC DHEC Asbestos Inspector License

SECTION I

Asbestos & Lead Evaluation Report

ASBESTOS EVALUATION REPORT APEX PROJECT NUMBER: 0521-99
--

Date:	6/15/2021	Page Number:	1 of 4
Client:	City of Spartanburg	Client Contact:	Mr. Jeff Tillerson
Client Address:	440 South Church Street Suite B Spartanburg, SC 29306	Client Phone Number:	(864) 596-2911
Project:	Asbestos Evaluation and Lead Based Paint Assessment		
Property Address:	706 West Main Street, Building 1 Spartanburg, SC 29301		
Assessor:	Stephanie Hamby	Date of Assessment:	5/21/2021
Company:	Apex Environmental Management 7 Winchester Court Mauldin, SC 29662	Phone Number:	(864) 404-3210
Purpose of Assessment:	Demolition	Age of Structure:	Approximately 60 years
Building Type:	Commercial	Number of Stories:	1
Foundation:	Slab-on Grade	Approximate Square Footage:	3,200 SF

EXTERIOR BUILDING MATERIALS

- Flat wooden rear roof with five layers of shingles with felt paper.
- Multi pitched front roof top layer of foam with sealant followed by two layers of shingles with felt over metal roof with silver sealant and tar.
- CMU block walls.
- Wood paneling with rock veneer over the front of building.
- Three metal doors. 706 B door has caulk.

INTERIOR BUILDING MATERIALS

- Yellow/tan carpet adhesive throughout.
- Wood paneling located on walls.
- Tan mastic sporadically over wood panel walls.
- Exposed 2"x4" studs with remnants of drywall dust.
- Skim coat over ceiling beams and wall located in section A/B.
- Multiple types of flooring with and without mastic and adhesives.

- Three wood windows without caulk or glaze.
- 706 C metal window has caulk and silicone.
- Damage to the roof was identified.
- Ceiling tiles located in section C.
- Building debris has been stacked in the back hallway of section C and closet located in section A/B.

SCOPE OF THE SURVEY

The objectives of the asbestos and lead assessment included the following:

- Identification of suspect asbestos-containing material (ACM) and lead based paints (LBP) in readily observable locations. Limited demolition of building finishes was conducted.
- Asbestos survey with sample collection by a South Carolina accredited inspector.
- Suspect ACM analysis by polarized light microscopy (PLM) utilizing EMSL Analytical, Inc. (EMSL) as an NVLAP certified laboratory, their accreditation number is 200841-0.
- Transmission electron microscopy (TEM) analysis of non-friable organically bound materials suspected to contain asbestos and testing negatively by PLM analysis.
- Lead inspection by a lead inspector certified by the Environmental Protection Agency and licensed to conduct LBP surveys in South Carolina.
- In situ analysis of suspected lead based paints by X-ray fluorescence (XRF).
- Presenting the results in a report identifying confirmed ACMs and LBPs.

METHODS

Asbestos Containing Materials

In order to determine if the suspect materials observed during the visual survey contained asbestos, representative bulk samples were collected and placed in sealed packages. Sixty (60) bulk samples were collected during the survey and submitted to EMSL in Pineville, North Carolina for analysis using the EPA recommended method of Polarized Light Microscopy (PLM) coupled with dispersion staining (Method No. EPA 600/M4-82-020, Dec. 1982). EMSL participates in the National Voluntary Laboratory Accreditation Program (NVLAP). Their NVLAP accreditation number is 200841-0. EPA regulations require that multiple samples of each homogeneous material be collected for laboratory analysis. Eighty-seven (87) samples were analyzed due to layering by PLM and positive stop methods. In accordance with South Carolina Regulation 61-86.1, non-friable organically bound materials that are reported to be non-asbestos containing by PLM analysis must also be analyzed by Transmission Electron Microscopy (TEM). Twenty-nine (29) samples were analyzed using TEM.

Lead-Based Paint

Lead painted surfaces were analyzed in place using X-ray fluorescence. Painted surfaces were selected based on color of topcoat, underlying layers and substrate on which it was painted.

RESULTS

Asbestos Results

The EPA defines an asbestos-containing material (ACM) as a material containing more than 1% asbestos. OSHA defines ACM as a material containing detectable amounts of asbestos. Provided

below is a general discussion of the asbestos containing materials identified in the residence. A specific *PLM and TEM Data Table* is located in Appendix II of this report and identifies positive materials and designates approximate quantities.

Building debris was observed shoved into a back hallway and closet. The building was fully assessed; however, if additional ACM is discovered during demolition activities, Apex recommends that work activities stop until the suspect building materials may be sampled and analyzed.

Suspect asbestos containing materials that were identified to be asbestos containing include:

- Approximately 2,400 SF of silver sealant with tar on the metal front roof under two layers of shingles with felt paper.
- Approximately 150 SF of mesh paper with tar located on the parapet wall.

Lead Based Paint

OSHA does not recognize a threshold level of lead for definition purposes, only the presence or absence of lead. The current OSHA regulations recognize an airborne action level of thirty micrograms per cubic meter ($30 \mu\text{g}/\text{m}^3$) during an eight-hour workday and a permissible exposure level of fifty micrograms per cubic meter ($50 \mu\text{g}/\text{m}^3$) for employees.

Currently, EPA defines LBP as paint containing in excess of, or equal to, $1.0 \text{ mg}/\text{cm}^2$. *XRF LBP Data Sheets* providing XRF results for testing combinations can be found in the Appendices at the conclusion of this report. Paint-chip sampling was not required for XRF inconclusive values.

No lead based paint was identified within the structure on site.

RECOMMENDATIONS AND DISCUSSION

Asbestos Containing Materials

If the above referenced asbestos materials are to be disturbed by renovations or demolition, the asbestos must be removed in accordance with EPA, State of South Carolina and OSHA asbestos regulations. The State of South Carolina, Department of Health and Environmental Control (DHEC) has specific regulations that must be adhered to during asbestos removal/abatement projects.

APEX recommends the following:

1. Abate the asbestos containing materials in the structure prior to renovation or demolition.
2. Follow applicable asbestos regulations during renovation or demolition of the structure. You should be aware that stringent requirements are imposed upon anyone renovating or demolishing a structure in which ACM will be disturbed. This work must be performed in accordance with OSHA asbestos regulations, 29 CFR 1910 & 1926, and NESHAP asbestos regulations 40 CFR 61, subpart M. South Carolina regulations require the accreditation of personnel who work in the asbestos field and notification and permitting fees for asbestos removal projects. There is a 10 working day notification period required prior to abatement of asbestos in a facility. Failure to take proper precautions and actions to protect human health and the environment can result in penalties, danger to personnel, and construction delays.

Lead-Based Paint

Currently the Environmental Protection Agency (EPA) define LBP as paint containing greater than 1.0 milligrams per square centimeter (mg/cm^2) lead or in excess of, or equal to, 0.5 percent lead. Building materials identified as being painted with LBP should be segregated from the other building materials and recycled or disposed of in a municipal lined landfill. The removed wastes would need to be containerized and further tested by Toxic Characteristic Leaching procedures (TCLP) to determine if the waste is classified as hazardous. The remaining building materials that are not painted with LBP may be disposed of in a construction and demolition landfill. However, the landfills should be contacted to determine their specific disposal requirements.

Occupational Safety and Health Administration Lead Regulations apply to actions initiated on lead containing materials. This regulation applies to lead concentrations greater than the analytical limit of detection. This regulation sets exposure levels on airborne lead and does not reference the percent lead in paint. Therefore, initial personal air monitoring should be conducted on workers performing work on surfaces which have a lead concentration of $0.1 \text{ mg}/\text{cm}^2$ or above to satisfy the OSHA requirements. If a baseline exposure lower than the OSHA Action Level of 30 micrograms per cubic meter ($\mu\text{g}/\text{m}^3$) is established, personal air monitoring may be terminated. The full OSHA lead standard should be referenced for compliance.

A copy of this report must be submitted to SCDHEC at least ten (10) working days prior to demolition when applying for a demolition permit.

SECTION II

Asbestos & LBP Data Tables

**ASBESTOS SURVEY FIELD DATA SHEET
PLM & TEM ANALYSIS**

Project Name: COS 706 West Main Street ACM-LBP

706 West Main Street, Building 1, Spartanburg, South Carolina

Project Location: 29301

Project Number: 0521-99

Sampled By: Stephanie Hamby

Project Manager: Tom Oliver

Date: 5/21/2021

Sample No.	Location	Sample Description	Analytical Results	Friable/Non Friable	Condition	Quantity
1	Front roof	Foam with grey sealant	PLM - NAD	Non-Friable	Damaged	2,400 SF
2			TEM - NAD			
3						
4	Front roof under foam	Two layers of shingle with felt paper	PLM - NAD	Friable	Damaged	2,400 SF
5			TEM - NAD			
6						
7	Front metal roof under shingles	Silver sealant and tar	PLM - 8% chrysotile (silver sealant), 8% chrysotile (tar)	Non-Friable	Damaged	2,400 SF
8						
9						
10	Parapet Wall	Mesh paper with tar	PLM - 10% chrysotile	Non-Friable	Good	150 SF
11						
12						
13	Rear flat roof	Five layers of shingles with one layer of felt paper	PLM - NAD	Friable	Good	775 SF
14			TEM - NAD			
15						
16	706-B door frame	White caulk	PLM - NAD	Non-Friable	Damaged	1 EA
17			TEM - NAD			
18						
19	706-C metal window	White caulk	PLM - NAD	Non-Friable	Good	4 EA
20			TEM - NAD			
21						
22	Floor in section A/B green painted room	12"x12" white with grey speckled floor tile with grey and tan mastic	PLM - NAD	Non-Friable	Damaged	350 SF
23			TEM - NAD			
24						

**ASBESTOS SURVEY FIELD DATA SHEET
PLM & TEM ANALYSIS**

Project Name: COS 706 West Main Street ACM-LBP

Sampled By: Stephanie Hamby

706 West Main Street, Building 1, Spartanburg, South Carolina
Project Location: 29301

Project Manager: Tom Oliver

Project Number: 0521-99

Date: 5/21/2021

Sample No.	Location	Sample Description	Analytical Results	Friable/Non Friable	Condition	Quantity
25	Floor in section A/B back white paneled room	12"x12" floor tile with tan adhesive	PLM - NAD	Friable	Damaged	350 SF
26			TEM - NAD			
27						
28	Section A/B green painted wall	Skim coat over CMU block wall	PLM - NAD	Friable	Significantly Damaged	23 SF
29						
30						
31	Section A/B under covebase	Tan mastic	PLM - NAD	Non-Friable	Good	200 LF
32			TEM - NAD			
33						
34	Section A/B bathroom floor under concrete	Grey 12"x12" floor tile	PLM - NAD	Non-Friable	Good	26 SF
35			TEM - NAD			
36						
37	Section A/B bathroom floor under grey 12"x12" floor tile	12"x12" tan floor tile with tan mastic	PLM - NAD	Non-Friable	Good	26 SF
38			TEM - NAD			
39						
40	Section A/B back wall over wall paneling	Tan mastic	PLM - NAD	Non-Friable	Good	50 SF
41			TEM - NAD			
42						
43	Section C hallway floor	12"x12" wood pattern self-stick floor tile with adhesive	PLM - NAD	Non-Friable	Damaged	50 SF
44			TEM - NAD			
45						

**ASBESTOS SURVEY FIELD DATA SHEET
PLM & TEM ANALYSIS**

Project Name: COS 706 West Main Street ACM-LBP

Sampled By: Stephanie Hamby

706 West Main Street, Building 1, Spartanburg, South Carolina

Project Location: 29301

Project Manager: Tom Oliver

Project Number: 0521-99

Date: 5/21/2021

Sample No.	Location	Sample Description	Analytical Results	Friable/Non Friable	Condition	Quantity
46	Section C hallway floor	Wood pattern roll vinyl flooring	PLM - NAD	Non-Friable	Damaged	165 SF
47			TEM - NAD			
48						
49	Section C bathroom floor	Tan rock pattern roll vinyl flooring	PLM - NAD	Non-Friable	Damaged	30 SF
50			TEM - NAD			
51						
52	Section A/B under wall studs	Second layer of white floor tile with mastic	PLM - NAD	Non-Friable	Damaged	100 SF
53			TEM - NAD			
54						
55	Section C ceiling	12"x12" ceiling tile with no mastic	PLM - NAD	Friable	Damaged	60 SF
56						
57						
58	Sporadically located on section A/B walls and joint compound skim coat ceiling beams	Drywall, joint compound and tape	PLM - NAD	Friable	Damaged	25 SF
59						
60						

NAD = No Asbestos Detected

LF = Linear Feet

EA = Each

Bold = Positive For Asbestos

SF = Square Feet

Chry = Chrysotile

**FIELD DATA SHEET
XRF LBP ANALYSIS**

Project Name: COS 706 West Main Street ACM-LBP

Sampled By: Stephanie Hamby

706 West Main Street, Commercial Building,
Project Location: Spartanburg, South Carolina 29301

Project Manager: Tom Oliver

Project Number: 0521-99

Date: 5/21/2021

Sample No.	Sample Location	Component	Color	Substrate	Analytical Result (mg/m ³)
1		Standardization			184.00/Pass
2		Calibration			1.16
3		Calibration			1.10
4		Calibration			1.07
5	Exterior	Header board	White	Wood	0.13
6	Exterior	Awning ceiling	White	Wood	0.43
7	Exterior	Window trim	White	Wood	0.00
8	Exterior	Door casing	White	Wood	0.17
9	Exterior	Security bars around windows	Black	Metal	0.02
10	Exterior	Wall	White	CMU block	0.00
11	Interior	Floor	Gray	Concrete	0.00
12	Interior	Wall	White	Wood panel	0.00
13	Interior	Window	White	Wood	0.00
14	Interior	Window sill	Yellow	Wood	0.00
15	Interior	Beam	Purple	Wood	0.11
16	Interior	Beam	Yellow	Wood	0.08
17	Interior	Door frame	Purple	Wood	0.00
18	Interior	Door frame	White	Wood	0.00
19	Interior	Wall	White	CMU block	0.19
20	Interior	Wall	Gray	CMU block	0.00
21	Interior	Crown molding	Light gray	Wood	0.00
22	Interior	Wall	Salmon	CMU block	0.00
23	Interior	Window sill	Gray	Concrete	0.00
24	Interior	Window sill	Salmon	Concrete	0.00

**FIELD DATA SHEET
XRF LBP ANALYSIS**

Project Name: COS 706 West Main Street ACM-LBP

Sampled By: Stephanie Hamby

706 West Main Street, Commercial Building,
Project Location: Spartanburg, South Carolina 29301

Project Manager: Tom Oliver

Project Number: 0521-99

Date: 5/21/2021

Sample No.	Sample Location	Component	Color	Substrate	Analytical Result (mg/m ³)
25	Interior	Cabinets	Gray	Wood	0.00

Bold = LBP

FFM = Factory Finished Metal

FFV = Factory Finished Vinyl

SECTION III

Laboratory Analytical Results & Chain of Custody



EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / charlottelab@emsl.com

EMSL Order: 412104487

Customer ID: AXEM25

Customer PO:

Project ID: City of Spartanburg

Attention: Stephanie Hamby
Apex Environmental Management
7 Winchester Court
Mauldin, SC 29662

Phone: (864) 918-1433

Fax:

Received Date: 05/27/2021 9:55 AM

Analysis Date: 06/02/2021 - 06/03/2021

Collected Date:

Project: 0521-99 COS 706 West Main St. Bldg. 1 ACM/LBP (City of Spartanburg)

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
1-Foam <small>412104487-0001</small>	Foam with Sealant	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
1-Sealant <small>412104487-0001A</small>	Foam with Sealant	Brown/Gray Non-Fibrous Homogeneous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
2-Foam <small>412104487-0002</small>	Foam with Sealant	Tan/Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
2-Sealant <small>412104487-0002A</small>	Foam with Sealant	Brown/Gray Non-Fibrous Homogeneous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
3-Foam <small>412104487-0002B</small>	Foam with Sealant	Yellow Non-Fibrous Homogeneous		100% Non-fibrous (Other)	None Detected
4-Shingle 1 <small>412104487-0003</small>	2 Layers of Roof Shingle with Felt Paper	White/Black Non-Fibrous Homogeneous	20% Cellulose	5% Quartz 75% Non-fibrous (Other)	None Detected
4-Shingle 2 <small>412104487-0003A</small>	2 Layers of Roof Shingle with Felt Paper	Black Non-Fibrous Homogeneous	5% Glass	5% Quartz 15% Ca Carbonate 75% Non-fibrous (Other)	None Detected
4-Felt <small>412104487-0003B</small>	2 Layers of Roof Shingle with Felt Paper	Black Fibrous Homogeneous	75% Cellulose	25% Non-fibrous (Other)	None Detected
5-Shingle 1 <small>412104487-0004</small>	2 Layers of Roof Shingle with Felt Paper	White/Black Non-Fibrous Homogeneous	20% Cellulose	10% Quartz 70% Non-fibrous (Other)	None Detected
5-Shingle 2 <small>412104487-0004A</small>	2 Layers of Roof Shingle with Felt Paper	Gray/Black Non-Fibrous Homogeneous	15% Glass	15% Quartz 70% Non-fibrous (Other)	None Detected
5-Felt <small>412104487-0004B</small>	2 Layers of Roof Shingle with Felt Paper	Brown/Black Non-Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected
7-Silver Paint <small>412104487-0005</small>	Silver Sealant w/ Tar	Silver Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile
7-Tar <small>412104487-0005A</small>	Silver Sealant w/ Tar	Black Non-Fibrous Homogeneous		92% Non-fibrous (Other)	8% Chrysotile
8-Silver Paint <small>412104487-0006</small>	Silver Sealant w/ Tar				Positive Stop (Not Analyzed)
8-Tar <small>412104487-0006A</small>	Silver Sealant w/ Tar				Positive Stop (Not Analyzed)
10-Mesh/Tar <small>412104487-0007</small> <i>Layers not separable.</i>	Mesh Paper w/ Tar	White Fibrous Homogeneous	10% Glass	80% Non-fibrous (Other)	10% Chrysotile

Initial report from: 06/03/2021 16:14:06



EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / charlottelab@emsl.com

EMSL Order: 412104487

Customer ID: AXEM25

Customer PO:

Project ID: City of Spartanburg

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
11-Mesh/Tar	Mesh Paper w/ Tar				Positive Stop (Not Analyzed)
412104487-0008 <i>Layers not seperable</i>					
13-Shingle 1	5 Layers of Shingles & 1 Layer of Felt Paper	Black Non-Fibrous Homogeneous	20% Cellulose	10% Quartz 70% Non-fibrous (Other)	None Detected
412104487-0009 <i>No 5th shingle present.</i>					
13-Shingle 2	5 Layers of Shingles & 1 Layer of Felt Paper	Black Non-Fibrous Homogeneous	5% Glass	10% Quartz 15% Ca Carbonate 70% Non-fibrous (Other)	None Detected
412104487-0009A					
13-Shingle 3	5 Layers of Shingles & 1 Layer of Felt Paper	Black Non-Fibrous Homogeneous	5% Glass	8% Quartz 15% Ca Carbonate 72% Non-fibrous (Other)	None Detected
412104487-0009B					
13-Shingle 4	5 Layers of Shingles & 1 Layer of Felt Paper	Black Non-Fibrous Homogeneous		5% Quartz 15% Ca Carbonate 80% Non-fibrous (Other)	None Detected
412104487-0009C					
13-Felt	5 Layers of Shingles & 1 Layer of Felt Paper	Black Fibrous Homogeneous	75% Cellulose	25% Non-fibrous (Other)	None Detected
412104487-0009D					
14-Shingle 1	5 Layers of Shingles & 1 Layer of Felt Paper	White/Black Non-Fibrous Homogeneous	20% Cellulose	10% Quartz 70% Non-fibrous (Other)	None Detected
412104487-0010 <i>No 5th shingle present.</i>					
14-Shingle 2	5 Layers of Shingles & 1 Layer of Felt Paper	White/Black Non-Fibrous Homogeneous	20% Cellulose	10% Quartz 70% Non-fibrous (Other)	None Detected
412104487-0010A					
14-Shingle 3	5 Layers of Shingles & 1 Layer of Felt Paper	Black Non-Fibrous Homogeneous	15% Glass	15% Quartz 70% Non-fibrous (Other)	None Detected
412104487-0010B					
14-Shingle 4	5 Layers of Shingles & 1 Layer of Felt Paper	Black Non-Fibrous Homogeneous	15% Glass	15% Quartz 70% Non-fibrous (Other)	None Detected
412104487-0010C					
14-Felt	5 Layers of Shingles & 1 Layer of Felt Paper	Black Non-Fibrous Homogeneous	65% Cellulose	35% Non-fibrous (Other)	None Detected
412104487-0010D					
16	Caulk (White) (Door)	White Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
412104487-0011					
17	Caulk (White) (Door)	White Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
412104487-0012					
19	White Caulk (Window)	White Non-Fibrous Homogeneous		30% Ca Carbonate 70% Non-fibrous (Other)	None Detected
412104487-0013					
20	White Caulk (Window)	Gray/Tan/White Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
412104487-0014					
22-Floor Tile	12"x12" White with Gray Specks w/ Gray & Tan Mastic	White Non-Fibrous Homogeneous		40% Ca Carbonate 60% Non-fibrous (Other)	None Detected
412104487-0015					
22-Mastic	12"x12" White with Gray Specks w/ Gray & Tan Mastic	Tan Non-Fibrous Homogeneous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
412104487-0015A					
22-Leveler	12"x12" White with Gray Specks w/ Gray & Tan Mastic	Gray Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
412104487-0015B					

Initial report from: 06/03/2021 16:14:06



EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / charlottelab@emsl.com

EMSL Order: 412104487

Customer ID: AXEM25

Customer PO:

Project ID: City of Spartanburg

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
23-Floor Tile 412104487-0016	12"x12" White with Gray Specks w/ Gray & Tan Mastic	White Non-Fibrous Homogeneous		45% Ca Carbonate 55% Non-fibrous (Other)	None Detected
23-Mastic 412104487-0016A	12"x12" White with Gray Specks w/ Gray & Tan Mastic	Tan Non-Fibrous Homogeneous	2% Cellulose	98% Non-fibrous (Other)	None Detected
23-Leveler 412104487-0016B	12"x12" White with Gray Specks w/ Gray & Tan Mastic	Gray Non-Fibrous Homogeneous	5% Cellulose	25% Ca Carbonate 70% Non-fibrous (Other)	None Detected
24-Leveler 412104487-0016C	12"x12" White with Gray Specks w/ Gray & Tan Mastic	Gray Non-Fibrous Homogeneous	3% Cellulose	20% Ca Carbonate 77% Non-fibrous (Other)	None Detected
25-Floor Tile 412104487-0017	12"x12" Floor Tile w/ Tan Adhesive White w/ Blue Specks	White Non-Fibrous Homogeneous		40% Ca Carbonate 60% Non-fibrous (Other)	None Detected
25-Mastic 412104487-0017A	12"x12" Floor Tile w/ Tan Adhesive White w/ Blue Specks	Yellow Non-Fibrous Homogeneous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
26-Floor Tile 412104487-0018	12"x12" Floor Tile w/ Tan Adhesive White w/ Blue Specks	White Non-Fibrous Homogeneous		45% Ca Carbonate 55% Non-fibrous (Other)	None Detected
26-Mastic 412104487-0018A	12"x12" Floor Tile w/ Tan Adhesive White w/ Blue Specks	Tan Non-Fibrous Homogeneous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
28-Skim Coat 412104487-0019	Skim Coat over CMU Block Wall	White Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
28-Block 412104487-0019A	Skim Coat over CMU Block Wall	Gray Non-Fibrous Homogeneous		15% Quartz 10% Ca Carbonate 75% Non-fibrous (Other)	None Detected
29-Skim Coat 412104487-0020	Skim Coat over CMU Block Wall	White Non-Fibrous Homogeneous		10% Ca Carbonate 90% Non-fibrous (Other)	None Detected
29-Block 412104487-0020A	Skim Coat over CMU Block Wall	Gray Non-Fibrous Homogeneous		20% Quartz 5% Ca Carbonate 75% Non-fibrous (Other)	None Detected
30-Skim Coat 412104487-0021	Skim Coat over CMU Block Wall	White Non-Fibrous Homogeneous		35% Ca Carbonate 65% Non-fibrous (Other)	None Detected
30-Block 412104487-0021A	Skim Coat over CMU Block Wall	Gray Non-Fibrous Homogeneous		25% Quartz 5% Ca Carbonate 70% Non-fibrous (Other)	None Detected
31 412104487-0022	Tan Adhesive/Mastic	Gray/Tan Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
32 412104487-0023	Tan Adhesive/Mastic	Tan Non-Fibrous Homogeneous		10% Ca Carbonate 90% Non-fibrous (Other)	None Detected
34-Floor Tile 412104487-0024	Gray 12"x12" Floor Tile	Gray Non-Fibrous Homogeneous		40% Ca Carbonate 60% Non-fibrous (Other)	None Detected
34-Mastic 412104487-0024A	Gray 12"x12" Floor Tile	Tan Non-Fibrous Homogeneous	1% Cellulose	99% Non-fibrous (Other)	None Detected
35-Floor Tile 412104487-0025	Gray 12"x12" Floor Tile	Gray Non-Fibrous Homogeneous		45% Ca Carbonate 55% Non-fibrous (Other)	None Detected

Initial report from: 06/03/2021 16:14:06



EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / charlottelab@emsl.com

EMSL Order: 412104487

Customer ID: AXEM25

Customer PO:

Project ID: City of Spartanburg

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
35-Mastic 412104487-0025A	Gray 12"x12" Floor Tile	Gray/Tan Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
35-Leveler 412104487-0025B	Gray 12"x12" Floor Tile	Gray Non-Fibrous Homogeneous		25% Quartz 5% Ca Carbonate 70% Non-fibrous (Other)	None Detected
36-Leveler 412104487-0025C	Gray 12"x12" Floor Tile	Gray Non-Fibrous Homogeneous		20% Quartz 5% Ca Carbonate 75% Non-fibrous (Other)	None Detected
37-Top Mastic 412104487-0026	12"x12" Tan Floor Tile w/ Tan Mastic	Yellow Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (Other)	None Detected
37-Floor Tile 412104487-0026A	12"x12" Tan Floor Tile w/ Tan Mastic	White Non-Fibrous Homogeneous		40% Ca Carbonate 60% Non-fibrous (Other)	None Detected
37-Bottom Mastic 412104487-0026B	12"x12" Tan Floor Tile w/ Tan Mastic	Yellow Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (Other)	None Detected
38-Top Mastic 412104487-0027	12"x12" Tan Floor Tile w/ Tan Mastic	Tan Non-Fibrous Homogeneous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
38-Floor Tile 412104487-0027A	12"x12" Tan Floor Tile w/ Tan Mastic	White Non-Fibrous Homogeneous		45% Ca Carbonate 55% Non-fibrous (Other)	None Detected
38-Bottom Mastic 412104487-0027B	12"x12" Tan Floor Tile w/ Tan Mastic	Tan Non-Fibrous Homogeneous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
40 412104487-0028	Tan Mastic over Wall Paneling	Tan/White Non-Fibrous Homogeneous	<1% Cellulose	100% Non-fibrous (Other)	None Detected
41 412104487-0029	Tan Mastic over Wall Paneling	Gray/White Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
43-Flooring 412104487-0030	12"x12" Wood Pattern Self-Stick Floor Tile w/ Adhesive	Tan Non-Fibrous Homogeneous		20% Ca Carbonate 80% Non-fibrous (Other)	None Detected
43-Mastic 412104487-0030A	12"x12" Wood Pattern Self-Stick Floor Tile w/ Adhesive	Clear Non-Fibrous Homogeneous	1% Cellulose <1% Fibrous (Other)	99% Non-fibrous (Other)	None Detected
43-Leveler 412104487-0030B	12"x12" Wood Pattern Self-Stick Floor Tile w/ Adhesive	Tan Non-Fibrous Homogeneous	1% Cellulose	5% Ca Carbonate 94% Non-fibrous (Other)	None Detected
44-Flooring 412104487-0031	12"x12" Wood Pattern Self-Stick Floor Tile w/ Adhesive	Brown/Gray/Black Non-Fibrous Homogeneous		15% Ca Carbonate 85% Non-fibrous (Other)	None Detected
44-Mastic 412104487-0031A	12"x12" Wood Pattern Self-Stick Floor Tile w/ Adhesive	Gray/Tan Non-Fibrous Homogeneous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
44-Leveler 412104487-0031B	12"x12" Wood Pattern Self-Stick Floor Tile w/ Adhesive	Gray/Tan Non-Fibrous Homogeneous	5% Glass	5% Quartz 15% Ca Carbonate 75% Non-fibrous (Other)	None Detected
46 412104487-0032	Wod Pattern Roll Vinyl Floor	Tan Non-Fibrous Homogeneous	15% Cellulose 1% Glass	84% Non-fibrous (Other)	None Detected
47 412104487-0033	Wod Pattern Roll Vinyl Floor	Brown/Tan Non-Fibrous Homogeneous	10% Cellulose 2% Glass	88% Non-fibrous (Other)	None Detected

Initial report from: 06/03/2021 16:14:06



EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / charlottelab@emsl.com

EMSL Order: 412104487
Customer ID: AXEM25
Customer PO:
Project ID: City of Spartanburg

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 Method using Polarized Light Microscopy

Sample	Description	Appearance	Non-Asbestos		Asbestos
			% Fibrous	% Non-Fibrous	% Type
49 412104487-0034	Tan Rock Pattern Roll Vinyl Floor	Tan Fibrous Homogeneous	20% Cellulose 1% Glass	79% Non-fibrous (Other)	None Detected
50 412104487-0035	Tan Rock Pattern Roll Vinyl Floor	Gray/White Non-Fibrous Homogeneous	5% Glass	10% Ca Carbonate 85% Non-fibrous (Other)	None Detected
52-Top Mastic 412104487-0036	2nd Layer of Floor Tile (White) w/ Mastic	Tan Non-Fibrous Homogeneous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
52-Floor Tile 412104487-0036A	2nd Layer of Floor Tile (White) w/ Mastic	White Non-Fibrous Homogeneous		40% Ca Carbonate 60% Non-fibrous (Other)	None Detected
52-Bottom Mastic 412104487-0036B	2nd Layer of Floor Tile (White) w/ Mastic	Tan Non-Fibrous Homogeneous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
53-Top Mastic 412104487-0037	2nd Layer of Floor Tile (White) w/ Mastic	Tan Non-Fibrous Homogeneous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
53-Floor Tile 412104487-0037A	2nd Layer of Floor Tile (White) w/ Mastic	Gray Non-Fibrous Homogeneous		45% Ca Carbonate 55% Non-fibrous (Other)	None Detected
53-Bottom Mastic 412104487-0037B	2nd Layer of Floor Tile (White) w/ Mastic	Tan Non-Fibrous Homogeneous		5% Ca Carbonate 95% Non-fibrous (Other)	None Detected
55 412104487-0038	12"x12" Ceiling Tile w/ No Mastic	Gray/White Fibrous Homogeneous	60% Cellulose 10% Min. Wool	20% Perlite 10% Non-fibrous (Other)	None Detected
56 412104487-0039	12"x12" Ceiling Tile w/ No Mastic	Gray/White Fibrous Homogeneous	60% Cellulose 10% Min. Wool	20% Perlite 10% Non-fibrous (Other)	None Detected
57 412104487-0040	12"x12" Ceiling Tile w/ No Mastic	Gray/White Non-Fibrous Homogeneous	50% Cellulose 15% Min. Wool	25% Perlite 10% Non-fibrous (Other)	None Detected
58-Joint Compound 412104487-0041 <i>No drywall present</i>	Drywall w/ Joint Compound & Tape	White Non-Fibrous Homogeneous		40% Ca Carbonate 60% Non-fibrous (Other)	None Detected
58-Tape 412104487-0041A	Drywall w/ Joint Compound & Tape	Tan Fibrous Homogeneous	99% Cellulose	1% Non-fibrous (Other)	None Detected
59-Joint Compound 412104487-0042 <i>No drywall present</i>	Drywall w/ Joint Compound & Tape	White Non-Fibrous Homogeneous		40% Ca Carbonate 60% Non-fibrous (Other)	None Detected
59-Tape 412104487-0042A	Drywall w/ Joint Compound & Tape	Tan Fibrous Homogeneous	99% Cellulose	1% Non-fibrous (Other)	None Detected
60-Drywall 412104487-0043	Drywall w/ Joint Compound & Tape	Gray Non-Fibrous Homogeneous	5% Cellulose	95% Non-fibrous (Other)	None Detected
60-Joint Compound 412104487-0043A	Drywall w/ Joint Compound & Tape	White Non-Fibrous Homogeneous		45% Ca Carbonate 55% Non-fibrous (Other)	None Detected
60-Tape 412104487-0043B	Drywall w/ Joint Compound & Tape	White Non-Fibrous Homogeneous	95% Cellulose	5% Non-fibrous (Other)	None Detected

Initial report from: 06/03/2021 16:14:06



EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / charlottelab@emsl.com

EMSL Order: 412104487

Customer ID: AXEM25

Customer PO:

Project ID: City of Spartanburg

Analyst(s)

Brant Alyea (42)

Sarah Breneman (45)

Lee Plumley, Laboratory Manager
or Other Approved Signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. The above analyses were performed in general compliance with Appendix E to Subpart E of 40 CFR (previously EPA 600/M4-82-020 "Interim Method") but augmented with procedures outlined in the 1993 ("final") version of the method. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Estimation of uncertainty is available on request.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC NVLAP Lab Code 200841-0, VA 3333 00312

Initial report from: 06/03/2021 16:14:06



EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / charlottelab@emsl.com

EMSL Order: 412104487

Customer ID: AXEM25

Customer PO:

Project ID: City of Spartanburg

Attention: Stephanie Hamby
Apex Environmental Management
7 Winchester Court
Mauldin, SC 29662

Phone: (864) 918-1433

Fax:

Received Date: 05/27/2021 9:55 AM

Analysis Date: 06/09/2021

Collected Date:

Project: 0521-99 COS 706 West Main St. Bldg. 1 ACM/LBP (City of Spartanburg)

Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID	Description	Appearance	% Matrix Material	% Non-Asbestos Fibers	Asbestos Types
3-Seal 412104487-0044	Foam with Sealant	Gray Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
6-Shingle 1 412104487-0045	2 Layers of Roof Shingle with Felt Paper	White/Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
6-Shingle 2 412104487-0046	2 Layers of Roof Shingle with Felt Paper	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
6-Felt 412104487-0047	2 Layers of Roof Shingle with Felt Paper	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
15-Shingle 1 412104487-0048	5 Layers of Shingles & 1 Layer of Felt Paper	White/Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
15-Shingle 2 412104487-0049	5 Layers of Shingles & 1 Layer of Felt Paper	White/Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
15-Shingle 3 412104487-0050	5 Layers of Shingles & 1 Layer of Felt Paper	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
15-Shingle 4 412104487-0051	5 Layers of Shingles & 1 Layer of Felt Paper	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
15-Felt 412104487-0052	5 Layers of Shingles & 1 Layer of Felt Paper	Black Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
18 412104487-0053	Caulk (White) (Door)	White Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
21 412104487-0054	White Caulk (Window)	White Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
24-Floor Tile 412104487-0055	12"x12" White with Gray Specks w/ Gray & Tan Mastic	White Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. EMSL recommends that samples reported as none detected or <1% undergo additional analysis via PLM to avoid the possibility of false negatives.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC

Initial report from: 06/10/2021 08:37:54



EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / charlottelab@emsl.com

EMSL Order: 412104487

Customer ID: AXEM25

Customer PO:

Project ID: City of Spartanburg

Attention: Stephanie Hamby
Apex Environmental Management
7 Winchester Court
Mauldin, SC 29662

Phone: (864) 918-1433

Fax:

Received Date: 05/27/2021 9:55 AM

Analysis Date: 06/09/2021

Collected Date:

Project: 0521-99 COS 706 West Main St. Bldg. 1 ACM/LBP (City of Spartanburg)

Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID	Description	Appearance	% Matrix Material	% Non-Asbestos Fibers	Asbestos Types
24-Mastic 412104487-0056	12"x12" White with Gray Specks w/ Gray & Tan Mastic	Gray/Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
27-Floor Tile 412104487-0057	12"x12" Floor Tile w/ Tan Adhesive White w/ Blue Specks	White Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
27-Mastic 412104487-0058	12"x12" Floor Tile w/ Tan Adhesive White w/ Blue Specks	Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
33 412104487-0059	Tan Adhesive/Mastic	Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
36-Floor Tile 412104487-0060	Gray 12"x12" Floor Tile	Gray Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
36-Mastic 412104487-0061	Gray 12"x12" Floor Tile	Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
39-Top Mastic 412104487-0062	12"x12" Tan Floor Tile w/ Tan Mastic	Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
39-Floor Tile 412104487-0063	12"x12" Tan Floor Tile w/ Tan Mastic	White Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
39-Bottom Mastic 412104487-0064	12"x12" Tan Floor Tile w/ Tan Mastic	Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
42 412104487-0065	Tan Mastic over Wall Paneling	Gray Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
45-Flooring 412104487-0066	12"x12" Wood Pattern Self-Stick Floor Tile w/ Adhesive	Brown Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
45-Mastic 412104487-0067	12"x12" Wood Pattern Self-Stick Floor Tile w/ Adhesive	Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. EMSL recommends that samples reported as none detected or <1% undergo additional analysis via PLM to avoid the possibility of false negatives.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC

Initial report from: 06/10/2021 08:37:54



EMSL Analytical, Inc.

10801 Southern Loop Blvd Pineville, NC 28134

Tel/Fax: (704) 525-2205 / (704) 525-2382

<http://www.EMSL.com> / charlottelab@emsl.com

EMSL Order: 412104487

Customer ID: AXEM25

Customer PO:

Project ID: City of Spartanburg

Attention: Stephanie Hamby
Apex Environmental Management
7 Winchester Court
Mauldin, SC 29662

Phone: (864) 918-1433

Fax:

Received Date: 05/27/2021 9:55 AM

Analysis Date: 06/09/2021

Collected Date:

Project: 0521-99 COS 706 West Main St. Bldg. 1 ACM/LBP (City of Spartanburg)

Test Report: Asbestos Analysis of Non-Friable Organically Bound Materials by TEM via EPA/600/R-93/116 Section 2.5.5.1

Sample ID	Description	Appearance	% Matrix Material	% Non-Asbestos Fibers	Asbestos Types
48 412104487-0068	Wood Pattern Roll Vinyl Floor	Brown Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
51 412104487-0069	Tan Rock Pattern Roll Vinyl Floor	Tan Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
54-Top Mastic 412104487-0070	2nd Layer of Floor Tile (White) w/ Mastic	Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
54-Floor Tile 412104487-0071	2nd Layer of Floor Tile (White) w/ Mastic	Gray Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected
54-Bottom Mastic 412104487-0072	2nd Layer of Floor Tile (White) w/ Mastic	Tan Non-Fibrous Homogeneous	100.0 Other	None	No Asbestos Detected

Analyst(s)

Derrick Young (29)

Lee Plumley, Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. Interpretation and use of test results are the responsibility of the client. This report relates only to the samples reported above, and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. Results are generated from the field sampling data (sampling volumes and areas, locations, etc.) provided by the client on the Chain of Custody. Samples are within quality control criteria and met method specifications unless otherwise noted. EMSL recommends that samples reported as none detected or <1% undergo additional analysis via PLM to avoid the possibility of false negatives.

Samples analyzed by EMSL Analytical, Inc. Pineville, NC

Initial report from: 06/10/2021 08:37:54



EMSL Order Number / Lab Use Only

Pineville, NC 28134
PHONE: (704) 525-2205
EMAIL:

EMSL ANALYTICAL, INC.
LABORATORY - PRODUCTS - TRAINING

412104487

Customer Information	Customer ID:	Billing ID:
	Company Name: Apex Environmental Management, Inc.	Company Name: Apex Environmental Management, Inc.
	Contact Name: Staphanie Hamby	Billing Contact: Rebecca Shultz
	Street Address: 7 Winchester Court	Street Address: 7 Winchester Court
	City, State, Zip: Mauldin SC 29662 Country: US	City, State, Zip: Mauldin SC Country: USA
Phone: 8644043210	Phone: 8644043210	
Email(s) for Report: shamby@apex-ehs.com	Email(s) for Invoice: rshultz@apex-ehs.com	

Project Information

Project Name/No: 0521-99 COS 706 West Main St. Bldg 1 ACM/LBP Purchase Order:

EMSL LIMS Project ID: (If applicable, EMSL will provide) US State where samples collected: SC State of Connecticut (CT) must select project location: Commercial (Taxable) Residential (Non-Taxable)

Sampled By Name: Stephanie Hamby Sampled By Signature: *[Signature]* No. of Samples in Shipment:

Turn-Around-Time (TAT)

3 Hour 6 Hour 24 Hour 32 Hour 48 Hour 72 Hour 96 Hour 1 Week 2 Week

Please call ahead for large projects and/or turnaround times 6 Hours or Less. *32 Hour TAT available for select tests only; samples must be submitted by 11:30am.

Test Selection

PLM - Bulk (reporting limit)

PLM EPA 600/R-93/116 (<1%)
 PLM EPA NOB (<1%)
 POINT COUNT
 400 (<0.25%) 1,000 (<0.1%)
 POINT COUNT w/ GRAVIMETRIC
 400 (<0.25%) 1,000 (<0.1%)
 NIOSH 9002 (<1%)
 NYS 198.1 (Friable - NY)
 NYS 198.6 NOB (Non-Friable - NY)
 NYS 198.8 (Vermiculite SM-V)

TEM - Bulk

TEM - Bulk
 TEM EPA NOB
 NYS NOB 198.4 (Non-Friable-NY)
 TEM EPA 600/R-93/116 w Milling Prep (0.1%)

Other Tests (please specify)

Positive Stop - Clearly Identified Homogeneous Areas (HA)

Sample Number	HA Number	Sample Location	Material Description
1		Foam with Sealant	PLM
2		↓	↓
3			TEM
4			PLM
5		2 layers of roof shingle with felt paper	↓
6		↓	TEM
7			PLM
8		↓	↓
9			TEM

Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.)

Method of Shipment: Fed Ex Sample Condition Upon Receipt:

Relinquished by: *[Signature]* Date/Time: 5-21-21 5:00 PM Received by: *[Signature]* Date/Time: 5/21/21 9:55 AM

Controlled Document - Asbestos Bulk R5 03/18/2021 AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.



Asbestos Bulk Building Materials - Chain of Custody

EMSL Order Number / Lab Use Only

EMSL Analytical, Inc.
10801 Southern Loop Blvd

EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

4487

Pineville, NC 28134
PHONE: (704) 525-2205
EMAIL:

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.)

Sample Number	HA Number	Sample Location	Material Description
10		Mesh paper w/ tar	PLM
11			↓
12			TEM
13		5 layers of shingles &	PLM
14		1 layer of felt paper	↓
15			TEM
16		Caulk (white)	PLM
17		(door)	↓
18			TEM
19		white caulk	PLM
20		(window)	↓
21			TEM
22		12"x12" white with gray	PLM
23		specks w/ gray & tan mastic	↓
24		(analyze mastics only)	TEM
25		12"x12" floor tile w/	PLM
26		tan adhesive white w/ blue specks	↓
27		Analyze tile adhesive	TEM
28		skim coat over CMU	PLM
29		block wall	↓
30			↓
31		tan adhesive/mastic	PLM
32			↓
33			TEM

Method of Shipment:		Sample Condition Upon Receipt:	
Relinquished by:	Date/Time:	Received by:	Date/Time:
Relinquished by:	Date/Time:	Received by:	Date/Time:

Controlled Document - Asbestos Bulk R5 03/16/2021 AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.



Asbestos Bulk Building Materials - Chain of Custody

EMSL Order Number / Lab Use Only

EMSL Analytical, Inc.
10801 Southern Loop Blvd

EMSL ANALYTICAL, INC.
LABORATORY-PRODUCTS-TRAINING

4487

Pineville, NC 28134
PHONE: (704) 525-2205
EMAIL:

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.)

Sample Number	HA Number	Sample Location	Material Description
34		Gray 12"x12" floor tile	PLM
35			↓
36			TEM
37		12"x12" tan floor tile	PLM
38		w/ tan mastic	↓
39			TEM
40		Tan mastic over	PLM
41		wall paneling	↓
42			TEM
43		12"x12" wood pattern	PLM
44		self-stick floor tile w/	↓
45		adhesive	TEM
46		wood pattern roll vinyl	PLM
47		floor	↓
48			TEM
49		Tan rock pattern roll	PLM
50		vinyl floor	↓
51			TEM
52		2 nd layer of floor tile	PLM
53		(white) w/ mastic	↓
54			TEM
55		12"x12" ceiling tile	PLM
56		w/ no mastic	↓
57			↓

Method of Shipment:		Sample Condition Upon Receipt:	
Relinquished by:	Date/Time:	Received by:	Date/Time:
Relinquished by:	Date/Time:	Received by:	Date/Time:

Controlled Document - Asbestos Bulk R5 03/18/2021

AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.



EMSL ANALYTICAL, INC.
LABORATORY PRODUCTS TRAINING

Asbestos Bulk Building Materials - Chain of Custody

EMSL Order Number / Lab Use Only

EMSL Analytical, Inc.
10801 Southern Loop Blvd

Pineville, NC 28134
PHONE: (704) 525-2205
EMAIL:

4487

Additional Pages of the Chain of Custody are only necessary if needed for additional sample information

Special Instructions and/or Regulatory Requirements (Sample Specifications, Processing Methods, Limits of Detection, etc.)

Sample Number	HA Number	Sample Location	Material Description
58		Drywall w/ joint compound & tape	PLM
59			
60			

Method of Shipment:		Sample Condition Upon Receipt:	
Relinquished by:	Date/Time:	Received by:	Date/Time:
Relinquished by:	Date/Time:	Received by:	Date/Time:

Controlled Document - Asbestos Bulk R5 03/18/2021 AGREE TO ELECTRONIC SIGNATURE (By checking, I consent to signing this Chain of Custody document by electronic signature.)

EMSL Analytical, Inc.'s Laboratory Terms and Conditions are incorporated into this Chain of Custody by reference in their entirety. Submission of samples to EMSL Analytical, Inc. constitutes acceptance and acknowledgment of all terms and conditions by Customer.

Page 4 of 4

SECTION IV
Photographic Log



Photo 1 – 706 West Main Street in Spartanburg, South Carolina 29301



Photo 2 – Foam with grey sealant on top layer and mesh paper with tar on parapet wall.



Photo 3 – Front roof has a metal roof with silver sealant and tar under two layers of shingles.



Photo 4 – Flat roof with five layers of shingles and one layer of felt paper located at back of building



Photo 5 – 706B door frame with white caulk



Photo 6 – 706C metal window with white caulk



Photo 7 – Close up of 706C metal window with white caulk



Photo 8 – Interior view of back portion of 706A/B



Photo 9 – 12"x12" white with gray/blue specks floor tile with gray and tan mastic located in section A/B



Photo 10 – 12"x12" white with gray/blue specks floor tile with tan adhesive



Photo 11 – Skim coat over CMU block wall located in section A/B.



Photo 12 – Tan mastic under cove base located in section A/B



Photo 13 – Grey 12"x12" floor tile over 12"x12" tan floor tile with mastic under concrete in section A/B bathroom



Photo 14 – Tan mastic over paneling on back wall in section A/B



Photo 15 – 12"x12" wood pattern self-stick floor tile with adhesive in section C hallway



Photo 16 – Wood pattern roll vinyl floor located in section C hallway



Photo 17 – Tan rock pattern roll vinyl flooring located in section C bathroom



Photo 18 – Second layer of white floor tile under wood framing throughout located in section A/B



Photo 19 – 12"x12" white ceiling tiles without mastic located in section C



Photo 20 – 12"x12" ceiling tiles located on floor in section C



Photo 21 – Joint compound skim coat over ceiling beams located in section A/B



Photo 22 – Drywall, joint compound and tape on walls sporadic in section A/B



Photo 23 – Various types of building debris placed in section A/B closet.



Photo 24 – Various types of building debris stacked in back hallway of section C

SECTION V

SC DHEC Asbestos Inspector License



January 8, 2021

To whom it may concern:

Due to an unforeseen printer outage the SC Department of Health and Environmental Control Asbestos Program cannot issue a Standard Asbestos License

AS-000632 exp 8/13/2021
for license number: BI-01894 exp 1/12/2022

Please accept this correspondence as a temporary acknowledgment

of Air Sampler & Building Inspector licensing status.

Stephanie Hamby will be issued a standard license card once our systems are fully operational.

Keep this letter with you all the time during work at the job site.

If you have any questions, please call the Asbestos Section at 803-898-4289.

Sincerely,

A handwritten signature in black ink that reads "Jennifer Lynn Boryk".

Jennifer Lynn Boryk
Manager, Asbestos Section
Bureau of Air Quality