



Please Reply To:

AmeriSci Los Angeles

24416 S. Main Street, Ste 308

Carson, California 90745

TEL: (310) 834-4868 • FAX: (310) 834-4772

LABORATORY ELECTRONIC TRANSMITTAL

To: Yesenia Galeana
Executive Environmental Services Corporatio
Fax #:
Email: info@execenv.com, ygaleana@execenv.com

From: Rosa E. Pena
AmeriSci Job #: 923011443
Subject: PLM 3 day Results
Client Project: 23-Z0172-0024; Building K MPR

Date: Tuesday, January 31, 2023

Time: 12:50:16

Comments:

Number of Pages: _____
(including cover sheet)

NOTE: Attached report is to be considered preliminary until final review with accompanying analysis summary letter is issued.

CONFIDENTIALITY NOTICE: Unless otherwise indicated, the information contained in this communication is confidential information intended for use of the individual named above. If the reader of this communication is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is prohibited. If you have received this communication in error, please immediately notify the sender by telephone and return the original message to the above address via the US Postal Service at our expense. Samples are disposed of in 60 days or unless otherwise instructed by the protocol or special instructions in writing. Thank you.

Certified Analysis Service 24 Hours A Day • 7 Days A Week Competitive Prices
visit our web site - www.amerisci.com

Boston • Los Angeles • New York • Richmond



AmeriSci Los Angeles

24416 S. Main Street, Ste 308
Carson, California 90745
TEL: (310) 834-4868 • FAX: (310) 834-4772

PLM Bulk Asbestos Report

Executive Environmental Services Corpor	Date Received 01/27/23	AmeriSci Job # 923011443
Attn: Yesenia Galeana	Date Examined 01/29/23	P.O. #
310 East Foothill Blvd.		Page 1 of 3
Suite 200	RE: 23-Z0172-0024; Building K MPR	
Arcadia, CA 91006		

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2301250024RK-01	923011443-01L1	No	NAD
Location: Dining Area, South / 12x12 White Floor Tile And Mastic / Dining Area, Serving Area, Entryway			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: White, Homogeneous, Non-Fibrous, Floor Tile			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250024RK-01	923011443-01L2	No	NAD
Location: Dining Area, South / 12x12 White Floor Tile And Mastic / Dining Area, Serving Area, Entryway			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Mastic			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250024RK-02	923011443-02L1	No	NAD
Location: Dining Area, NW / 12x12 White Floor Tile And Mastic / Dining Area, Serving Area, Entryway			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: White, Homogeneous, Non-Fibrous, Floor Tile			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250024RK-02	923011443-02L2	No	NAD
Location: Dining Area, NW / 12x12 White Floor Tile And Mastic / Dining Area, Serving Area, Entryway			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Yellow, Homogeneous, Non-Fibrous, Mastic			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250024RK-03	923011443-03L1	No	NAD
Location: Serving Area, North / 12x12 White Floor Tile And Mastic / Dining Area, Serving Area, Entryway			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: White, Homogeneous, Non-Fibrous, Floor Tile			
Asbestos Types:			
Other Material: Non-fibrous 100%			

PLM Bulk Asbestos Report

23-Z0172-0024; Building K MPR

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2301250024RK-03	923011443-03L2	No	NAD
Location: Serving Area, North / 12x12 White Floor Tile And Mastic / Dining Area, Serving Area, Entryway			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Tan, Homogeneous, Non-Fibrous, Mastic			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250024RK-03	923011443-03L3	No	NAD
Location: Serving Area, North / 12x12 White Floor Tile And Mastic / Dining Area, Serving Area, Entryway			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: White, Homogeneous, Non-Fibrous, Compound			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250024RK-04	923011443-04L1	No	NAD
Location: Dining Area, West Wall / Vinyl Baseboard Adhesive (Multiple Layers) / Dining Area, Serving Area, Entryway Walls			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Cream, Homogeneous, Non-Fibrous, Baseboard			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250024RK-04	923011443-04L2	No	NAD
Location: Dining Area, West Wall / Vinyl Baseboard Adhesive (Multiple Layers) / Dining Area, Serving Area, Entryway Walls			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Tan, Heterogeneous, Non-Fibrous, Adhesive			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250024RK-05	923011443-05L1	No	NAD
Location: Dining Area, North Wall / Vinyl Baseboard Adhesive (Multiple Layers) / Dining Area, Serving Area, Entryway Walls			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Cream, Homogeneous, Non-Fibrous, Baseboard			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250024RK-05	923011443-05L2	No	NAD
Location: Dining Area, North Wall / Vinyl Baseboard Adhesive (Multiple Layers) / Dining Area, Serving Area, Entryway Walls			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Tan, Heterogeneous, Non-Fibrous, Adhesive			
Asbestos Types:			
Other Material: Non-fibrous 100%			

Client Name: Executive Environmental Services Corporation

PLM Bulk Asbestos Report

23-Z0172-0024; Building K MPR

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2301250024RK-06	923011443-06L1	No	NAD
Location: Serving Area, East Wall / Vinyl Baseboard Adhesive (Multiple Layers) / Dining Area, Serving Area, Entryway Walls			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Cream, Homogeneous, Non-Fibrous, Baseboard Asbestos Types: Other Material: Non-fibrous 100%			
2301250024RK-06	923011443-06L2	No	NAD
Location: Serving Area, East Wall / Vinyl Baseboard Adhesive (Multiple Layers) / Dining Area, Serving Area, Entryway Walls			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Tan, Heterogeneous, Non-Fibrous, Adhesive Asbestos Types: Other Material: Non-fibrous 100%			

Reporting Notes:

Analyzed by: Rosa E. Pena
 Date: 1/29/2023



Reviewed by: Patricia Weakley



*NAD = no asbestos detected; Detection Limit <1%; Reporting Limits: CVES = 1%, 400 Pt Ct = 0.25%, 1000 Pt Ct = 0.1%; NA = not analyzed; NA/PS = not analyzed / positive stop; NVA = No Visible Asbestos; PLM (polarized light microscopy) Bulk Asbestos Analysis by EPA 600/R-93/116, including requirements for EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #200346-0); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full with the approval of the laboratory. This PLM report relates ONLY to the items tested.

973011443

ENVIRONMENTAL HEALTH & SAFETY SIMPLIFIED

Industrial Hygiene Laboratory
Asbestos -- PLM

Originating Office: 240 E. Foothill Blvd., Suite 200, Arcadia, CA 91006
 Phone: 626.441.7050 Fax: 626.441.0016

Lab Submitted to: AmeriSci
 EMLab (Glendale)
 LA Testing

Project #: 23-Z0172-0024

Sampled by: Rhys Kuzmick

Site Zip Code: 91723

Sample Date: 01/25/2023

Page 2 of 1

The receiving Laboratory is required to complete the following:

- All invoices are to be sent to: 310 E. Foothill Blvd., Suite 200, Arcadia, CA 91006 with a copy of the lab report.
- Analyze all samples by PLM by EPA 600/R-93/116.
- Stop analysis of homogeneous groups at first positive that is greater than or equal to 1.0%.

Optional items to be completed by the laboratory (if check marked): Email Report to: Info@execenv.com Other: ygalearna@execenv.com

US Mail Report to: Originating office check marked above Other: Alternate billing address

Sample No.:	Sample Location - Include Room information where appropriate	Material Description	Homogeneous Location	No.	Quantity	Percent Damaged
-01	Dining Area, south	12x12 white floor tile and plaster	Dining Area, SERVING AREA Entryway	1	5,400 SF	0
-02	Dining Area, NW	↓		↓	↓	↓
-03	Serving Area, north					
-04	Dining Area, west wall	Vinyl baseboard adhesive	Dining Area, SERVING AREA Entryway walls	2	300 LF	0
-05	Dining Area, north wall	Composite layers				
-06	Serving Area, east wall	↓		↓	↓	↓

Prefix: 2301250024RK

Notes:

Released By, Date, & Time: Rhys Kuzmick 01/27/2023 5:55PM

Received By, Date, & Time: Dariana Meza 01-27-2023 17:25

Released By, Date, & Time: