

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Robb Lloyd	Date: 2018-06-21
City: Arlington	State: VA	Test Hole: 1 of

General Location: Corner of N. Woodrow St.

UTILITY INFORMATION

Utility Size: 2 1/2"	Material: P.E.	Good Condition: YES
Utility Type: Communication Conduit		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Grass Area	Pavement thickness: N/A
Ground Condition: Brown Soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Wooden Hub	Elevation:
Offset/Direction: Hub is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>2.28'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: West	Utility Width/Spacing:
---------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-07-23
City: Arlington	State: VA	Test Hole: 2 of

General Location: N. Vernon St.

UTILITY INFORMATION

Utility Size: 30"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt	Pavement thickness: 16"
Ground Condition: Brown soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>7.27'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: North	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW

COORDINATES

	Northing:	Easting:
	COMMENTS/NOTES	

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-07-23
City: Arlington	State: VA	Test Hole: 3 of

General Location: N. Vernon St.

UTILITY INFORMATION

Utility Size: 30"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt	Pavement thickness: 18"
Ground Condition: Brown soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>7.89'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: North	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW

COORDINATES

	Northing:	Easting:
	<u>COMMENTS/NOTES</u>	

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Robb Lloyd	Date: 2018-06-21
City: Arlington	State: VA	Test Hole: 4 of

General Location: 25th St. and N. Vernon St.

UTILITY INFORMATION

Utility Size: 4 1/2"	Material: Epoxy Coated Steel	Good Condition: YES
Utility Type: Gas Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 18"
Ground Condition: Brown Soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>3.96'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: South	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-07-20
City: Arlington	State: VA	Test Hole: 5 of

General Location: N. Vernon St.

UTILITY INFORMATION

Utility Size: 7 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size: 30"	Material: Cast Iron	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt	Pavement thickness: 8"
Ground Condition: Brown soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>A. 4.71'</u> Elevation:
	Bottom of utility field measurement: <u>B. 9.21'</u> Elevation: <u>None</u>

Facing: North	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW

COORDINATES

	Northing:	Easting:
	<u>COMMENTS/NOTES</u>	

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-07-20
City: Arlington	State: VA	Test Hole: 6 of

General Location: N. Vernon St.

UTILITY INFORMATION

Utility Size: 30"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt	Pavement thickness: 11"
Ground Condition: Brown soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION


Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	

PROFILE VIEW

	Top of utility field measurement: <u>8.79'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: North	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW **COORDINATES**

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-06-21
City: Arlington	State: VA	Test Hole: 7 of

General Location: 25th St. N. and N. Vernon St.

UTILITY INFORMATION

Utility Size: 6 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 10"
Ground Condition: Brown Soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>5.03'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: Northwest	Utility Width/Spacing:
--------------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Stephen Russell	Date: 2018-07-31
City: Arlington	State: VA	Test Hole: 8 of

General Location: 2351 N. Vernon St.

UTILITY INFORMATION

Utility Size: 2 1/2"	Material: Epoxy Coated Steel	Good Condition: YES
Utility Type: Unknown Function Pipe		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 8 1/2"
Ground Condition: Brown Soil/ Rocks	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>3.55'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: Northwest	Utility Width/Spacing:
--------------------------	-------------------------------

PLAN VIEW

COORDINATES



Northing:	Easting:
COMMENTS/NOTES	
<p>Crew notes that upon excavation that the unknown utility appears to be an abandoned gas line. Miss Utility has blacked out gas marks on ground as well.</p>	

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-07-03
City: Arlington	State: VA	Test Hole: 9 of

General Location: N. Vernon St. and N. Veron St.

UTILITY INFORMATION

Utility Size: 2 1/2"	Material: Paper Wrapped Steel	Good Condition: YES
Utility Type: Gas Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 11"
Ground Condition: Brown Soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION


Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	

PROFILE VIEW

	Top of utility field measurement: <u>3.93'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: West	Utility Width/Spacing:
---------------------	-------------------------------

PLAN VIEW **COORDINATES**

	<p>Northing:</p> <p>Easting:</p> <p style="text-align: center;"><u>COMMENTS/NOTES</u></p>
------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Tommy Lockhart	Date: 2018-06-18
City: Arlington	State: VA	Test Hole: 11 of

General Location: 4433 N. Vacation Ln.

UTILITY INFORMATION

Utility Size: 6 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 9"
Ground Condition: Stone Dust	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>4.11'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: West	Utility Width/Spacing:
---------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Tommy Lockhart	Date: 2018-06-18
City: Arlington	State: VA	Test Hole: 12 of

General Location: 4433 N. Vacation Ln.

UTILITY INFORMATION

Utility Size: 6 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 9"
Ground Condition: Brown Soil/ Stone Dust	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>4.89'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: North	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;"><u>COMMENTS/NOTES</u></td> </tr> </table>	Northing:	Easting:	<u>COMMENTS/NOTES</u>	
Northing:	Easting:				
<u>COMMENTS/NOTES</u>					



TEST HOLE FORM



4501 DALY DRIVE | CHANTILLY, VA 20151 | 703.378.0100 | WWW.MIDATLANTICLOCATING.COM

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Tommy Lockhart	Date: 2018-06-18
City: Arlington	State: VA	Test Hole: 13 of

General Location: 4419 N. Vacation Ln.

UTILITY INFORMATION

Utility Size: 5"	Material: Terracotta	Good Condition: YES
Utility Type: Storm Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 6"
Ground Condition: Brown Soil/ Rocks	

FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	

PROFILE VIEW

	Top of utility field measurement: <u>2.84'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: Northeast	Utility Width/Spacing:
--------------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;"><u>COMMENTS/NOTES</u></td> </tr> </table>	Northing:	Easting:	<u>COMMENTS/NOTES</u>	
Northing:	Easting:				
<u>COMMENTS/NOTES</u>					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Tommy Lockhart	Date: 2018-06-18
City: Arlington	State: VA	Test Hole: 14 of

General Location: 4419 N. Vacation Ln.

UTILITY INFORMATION

Utility Size: 6 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 6"
Ground Condition: Brown Soil/ Rocks/ Stone Dust	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>4.80'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: Northeast	Utility Width/Spacing:
--------------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-07-25
City: Arlington	State: VA	Test Hole: 15 of

General Location: N. Vacation Ln. and N. Utah St.

UTILITY INFORMATION

Utility Size: 6 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Roadway	Pavement thickness: 6"
Ground Condition: Brown Soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>5.80'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: North	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;"><u>COMMENTS/NOTES</u></td> </tr> </table>	Northing:	Easting:	<u>COMMENTS/NOTES</u>	
Northing:	Easting:				
<u>COMMENTS/NOTES</u>					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Tommy Lockhart	Date: 2018-06-19
City: Arlington	State: VA	Test Hole: 16 of

General Location:

UTILITY INFORMATION

Utility Size: 4 1/2"	Material: Epoxy Coated Steel	Good Condition: YES
Utility Type: Gas Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 10"
--------------------------------------	--------------------------------

Ground Condition:

FIRST & SECOND BENCHMARK INFORMATION


1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
---------------------------	-------------------


Offset/Direction: Nail is set C/L of the Utility.

PROFILE VIEW

	Top of utility field measurement: <u>4.67'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: North	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW **COORDINATES**

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> <tr> <td colspan="2">Crew had to redo ties to test hole due to bad survey of structures from Arlington.</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES		Crew had to redo ties to test hole due to bad survey of structures from Arlington.	
Northing:	Easting:						
COMMENTS/NOTES							
Crew had to redo ties to test hole due to bad survey of structures from Arlington.							



TEST HOLE FORM



4501 DALY DRIVE | CHANTILLY, VA 20151 | 703.378.0100 | WWW.MIDATLANTICLOCATING.COM

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-06-19
City: Arlington	State: VA	Test Hole: 17 of

General Location: 2460 N. Utah St.

UTILITY INFORMATION

Utility Size: 4 1/2"	Material: Epoxy Coated Steel	Good Condition: YES
Utility Type: Gas Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 10"
Ground Condition: Gravel	

FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	

PROFILE VIEW

	Top of utility field measurement: <u>4.33'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: North	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW

COORDINATES

	Northing: Easting: COMMENTS/NOTES
--	----------------------------------------------------------------------

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Stephen Russell	Date: 2018-06-18
City: Arlington	State: VA	Test Hole: 18 of

General Location: N.Utah St. & N. Taylor St.

UTILITY INFORMATION

Utility Size: 6 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 6"
Ground Condition: Brown Soil/ Rocks	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>5.04'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: North	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-06-19
City: Arlington	State: VA	Test Hole: 19 of

General Location: 2454 N. Utah St.

UTILITY INFORMATION

Utility Size: 4 1/2"	Material: Epoxy Coated Steel	Good Condition: YES
Utility Type: Gas Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 4"
Ground Condition: Brown Soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION


Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	

PROFILE VIEW

	Top of utility field measurement: <u>4.18'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: North	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW **COORDINATES**

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Stephen Russell	Date: 2018-06-18
City: Arlington	State: VA	Test Hole: 20 of

General Location: N. Taylor St.

UTILITY INFORMATION

Utility Size: 6 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 9"
Ground Condition: Brown Soil/ Rock	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>4.98'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: North	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW

COORDINATES

 <p style="text-align: center;">N Taylor St.</p>	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Stephen Russell	Date: 2018-06-18
City: Arlington	State: VA	Test Hole: 21 of

General Location: 2420 N. Taylor St.

UTILITY INFORMATION

Utility Size: 6 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 9"
Ground Condition: Brown Soil/ Rock	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>5.36'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: North	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW

COORDINATES

	Northing: Easting: COMMENTS/NOTES
-------------------------------------------------------------------------------------	----------------------------------------------------------------------

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Stephen Russell	Date: 2018-06-20
City: Arlington	State: VA	Test Hole: 22 of

General Location: N. 24th Rd. & N. Taylor St.

UTILITY INFORMATION

Utility Size: 6 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 8"
Ground Condition: Brown Soil/ Rock	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>4.82'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: Southwest	Utility Width/Spacing:
--------------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Tommy Lockhart	Date: 2018-07-11
City: Arlington	State: VA	Test Hole: 23 of

General Location: N. 24th Rd. & N. Taylor St.

UTILITY INFORMATION

Utility Size: 10"	Material: RCCP	Good Condition: YES
Utility Type: Sanitary Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 15"
Ground Condition: Brown Soil/ Rock	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>5.08'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: Southwest	Utility Width/Spacing:
--------------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;"><u>COMMENTS/NOTES</u></td> </tr> </table>	Northing:	Easting:	<u>COMMENTS/NOTES</u>	
Northing:	Easting:				
<u>COMMENTS/NOTES</u>					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Stephen Russell	Date: 2018-06-20
City: Arlington	State: VA	Test Hole: 24 of

General Location: N. 24th Rd. & N. Taylor St.

UTILITY INFORMATION

Utility Size: 2 1/2"	Material: Epoxy Coated Steel	Good Condition: YES
Utility Type: Gas Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 12"
Ground Condition: Brown Soil/ Rock	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>4.75'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: Northwest	Utility Width/Spacing:
--------------------------	-------------------------------

PLAN VIEW

COORDINATES

	Northing: Easting: <u>COMMENTS/NOTES</u>
------------------------------------------------------------------------------------	----------------------------------------------------------------------

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-06-19
City: Arlington	State: VA	Test Hole: 25 of

General Location:

UTILITY INFORMATION

Utility Size: 2 1/2"	Material: Epoxy Coated Steel	Good Condition: YES
Utility Type: Gas Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Roadway	Pavement thickness: 6"
Ground Condition: Brown Soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION


Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	

PROFILE VIEW

	<p>Top of utility field measurement: <u>3.63'</u> Elevation:</p> <p>Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u></p>
-------------------------------------------------------------------------------------	---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------

Facing: North	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW COORDINATES

	<p>Northing:</p> <p>Easting:</p> <p style="text-align: center;"><u>COMMENTS/NOTES</u></p>
------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------------------

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Stephen Russell	Date: 2018-07-03
City: Arlington	State: VA	Test Hole: 26 of

General Location: 24th St. & N. Taylor St.

UTILITY INFORMATION

Utility Size: 6 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 9"
Ground Condition: Brown Soil/ Rock	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>5.97'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: South	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW

COORDINATES

	Northing: _____ Easting: _____ COMMENTS/NOTES
------------------------------------------------------------------------------------	--------------------------------------------------------------------------

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Stephen Russell	Date: 2018-07-03
City: Arlington	State: VA	Test Hole: 27 of

General Location: 24th St. & N. Taylor St.

UTILITY INFORMATION

Utility Size: 6 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 8"
Ground Condition: Brown Soil/ Rock	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>4.81'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: South	Utility Width/Spacing:
----------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-07-16
City: Arlington	State: VA	Test Hole: 28 of

General Location: 2338 N. Taylor St.

UTILITY INFORMATION

Utility Size: 4 1/2"	Material: Epoxy Coated Steel	Good Condition: YES
Utility Type: Gas Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt	Pavement thickness: 10"
Ground Condition: Brown soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>3.79'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: East	Utility Width/Spacing:
---------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					



TEST HOLE FORM



4501 DALY DRIVE | CHANTILLY, VA 20151 | 703.378.0100 | WWW.MIDATLANTICLOCATING.COM

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-07-03
City: Arlington	State: VA	Test Hole: 29 of

General Location: N. Vacation Ln. & N. Taylor St.

UTILITY INFORMATION

Utility Size: 6 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 8 1/2"
Ground Condition: Brown Soil	

FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	

PROFILE VIEW

	Top of utility field measurement: <u>4.25'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: Northwest	Utility Width/Spacing:
--------------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-07-03
City: Arlington	State: VA	Test Hole: 30 of

General Location: N. Vacation Ln. & N. Taylor St.

UTILITY INFORMATION

Utility Size: 6 1/2"	Material: Cast Iron	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 8"
Ground Condition: Brown Soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>4.20'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: West	Utility Width/Spacing:
---------------------	-------------------------------

PLAN VIEW

COORDINATES

	Northing: Easting: COMMENTS/NOTES
------------------------------------------------------------------------------------	----------------------------------------------------------------------

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Tommy Lockhart	Date: 2018-07-19
City: Arlington	State: VA	Test Hole: 31 of

General Location: 2375 N. Vernon St.

UTILITY INFORMATION

Utility Size: 2 1/4"	Material: Epoxy Coated Steel	Good Condition: YES
Utility Type: Gas Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size:	Material:	See Test Hole No.:
Utility Type: None		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Roadway	Pavement thickness: 6"
Ground Condition: Brown Soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Utility.	


PROFILE VIEW

	Top of utility field measurement: <u>3.34'</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: Northwest	Utility Width/Spacing:
--------------------------	-------------------------------

PLAN VIEW

COORDINATES

	<table border="1"> <tr> <td>Northing:</td> <td>Easting:</td> </tr> <tr> <td colspan="2" style="text-align: center;">COMMENTS/NOTES</td> </tr> </table>	Northing:	Easting:	COMMENTS/NOTES	
Northing:	Easting:				
COMMENTS/NOTES					

Project: M-0618-0201-5356 (Lorcom Lane)	Prepared By: Yassin Aloumouati	Date: 2018-07-11
City: Arlington	State: VA	Test Hole: 32 of

General Location: N. Vermont St.

UTILITY INFORMATION

Utility Size: 1 1/4"	Material: Copper	Good Condition: YES
Utility Type: Water Line		Utility Owner:

ADDITIONAL UTILITY INFORMATION

Utility Size: 4"	Material: Cast Iron	See Test Hole No.:
Utility Type: Sanitary Lateral		Utility Owner:

SITE CONDITIONS

Field Condition: Asphalt Road	Pavement thickness: 7"
Ground Condition: Brown Soil	


FIRST & SECOND BENCHMARK INFORMATION

1st Elevation:	1st Benchmark Description:
BM Check:	
2nd Elevation:	2nd Benchmark Description:
Elevation Datum:	

FIELD MARKER INFORMATION

Type set: Mag Nail	Elevation:
Offset/Direction: Nail is set C/L of the Configuration.	


PROFILE VIEW

	Top of utility field measurement: <u>See Notes</u> Elevation:
	Bottom of utility field measurement: <u>None</u> Elevation: <u>None</u>

Facing: Northeast	Utility Width/Spacing: 7"
--------------------------	----------------------------------

PLAN VIEW

COORDINATES

	Northing: Easting: COMMENTS/NOTES A=4.19' to the top B=4.69' to the top
-------------------------------------------------------------------------------------	----------------------------------------------------------------------------------------------------