

August 23, 2021

21-186

Mr. Kevin Wagner XL Construction 851 Buckeye Court Milpitas, CA 95035 (415) 624-4112 kwagner@xlconstruction.com

Limited Asbestos and Lead Survey with PCBs 2118 Milvia Street, Floors 1-3 & Roof Berkelev, CA

Dear Mr. Wagner:

Pursuant to your request and authorization, EnviroNova, LLC. (EnviroNova) is pleased to present this report to XL Construction (XLC) for a limited asbestos, lead and polychlorinated biphenyls (PCBs) survey completed on the roof and Floors 1-3 of the building located at 2118 Milvia Street in Berkeley, California (Site). All work was conducted by properly certified field and professional staff according to applicable federal, state, and local regulations.

On August 13, 2021, EnviroNova collected suspect material samples from areas of the Site where construction activities will disturb floor, wall, and ceiling materials. The asbestos and lead samples were submitted under chain of custody procedures to Environmental Laboratories P&K in South San Francisco, California. The asbestos samples were analyzed via polarized light microscopy (PLM) in accordance with the method specified in appendix A subpart F 40 CFR Part 763, Section 1, and the lead samples were analyzed via atomic absorption in accordance with EPA Method 7000B. A map detailing sample locations is also attached.

EnviroNova also performed a survey of all existing universal and electronic waste in the building for recycling and disposal purposes. "The City of Berkeley requires that 100% of asphalt, concrete, excavated soil and land-clearing debris and a minimum of 65% of other nonhazardous construction and demolition waste shall be diverted from disposal at subject building projects by recycling, reuse, or salvage." Therefore, XLC shall meet these requirements when completing the demolition scope.

ASBESTOS

Suspect asbestos materials were organized into fifty (50) homogeneous areas of materials, resulting in one hundred twenty-one (121) bulk samples analyzed. Based on the certified analytical report, fourteen (14) of the materials sampled tested positive for asbestos and the remainder were reported as "None Detected." Therefore, asbestos abatement procedures will be required.

Table I below summarizes the materials and locations of the samples found to contain asbestos. The certified report of laboratory analysis and chain of custody documentation are attached.

Table IA – Asbestos Content in Sampled Material

Material Description and Location	Asbestos %	TSI	Surfacing	Miscellaneous	RACM	*Cat. I Non- Friable	*Cat. II Non- Friable
Off-White Joint Compound in White Drywall System, Floor 3 Walls Throughout	2% CH			X	X		
Off-White Compound with Paint (Texture) in White Drywall System, Floor 3 Walls Throughout	2% CH		X		X		
Black Roofing Mastic with Silver Coating, Roof Perimeter Seal	3% CH			X		X	
Black Roofing Mastic with Silver Coating, Roof Penetrations	3% CH			X		X	
Black + Yellow Mastic on Beige Vinyl Floor Tile and Red Sheet Flooring, Floor 3, Kitchen Floor	3% CH			X		X	
Black Mastic, Mirror Mastic in Restrooms Throughout	10% CH			X		X	
Off-White Joint Compound in White Drywall System, Floor 2 Walls Throughout	2% CH			X	X		
Off-White Compound with Paint (Texture) in White Drywall System, Floor 2 Walls Throughout	2% CH		X		X		
Black + Yellow Mastic on Beige Vinyl Floor Tile, Floor 2, Kitchen/Lounge Area Floor	3% CH			X		X	
Black Sink Undercoat, Floor 2 Break Area Sink	5% CH			X		X	

Table IA – Asbestos Content in Sampled Material (Continued)

Material Description and Location	Asbestos %	TSI	Surfacing	Miscellaneous	RACM	*Cat. I Non- Friable	*Cat. II Non- Friable
Black + Yellow Mastic on Blue Carpet Squares, Floor 1, Entry Floor	2% CH			X		X	
Black + Yellow Mastic on Brown Roll-out Carpet, Floor 1, Office Floors	2% CH			X		X	
Black Mastic on Electrical Closet Floor & Under Tile, Floor 1, Elevator Lobby	6% CH			Х		X	
Black + Yellow Mastic on Beige Vinyl Floor Tile, Floor 1, Hallway Sink Floor	3% CH			X		X	

CH=Chrysotile Asbestos. AA=Anthophyllite Asbestos *Point Count Needed to remove RACM designation. ND="Non-Detect"

Table IB – Asbestos Content in Point Counted Samples

Sample ID	Material Description and Location	Asbestos Type	Asbestos Points counts	Asbestos Concentration
3-DW-2	Off-White Compound with Paint (Texture) in White Drywall System, Floor 3 Walls Throughout	СН	8	0.8%
3-DW-2	White Drywall System with Off-White Joint Compound (Composite), Floor 3, Walls Throughout	СН	0	ND <0.1%
2-DW-1	Off-White Compound with Paint (Texture) in White Drywall System, Floor 2 Walls Throughout	СН	11	1.1%
2-DW-2	White Drywall System with Off-White Joint Compound (Composite), Floor 2, Walls Throughout	СН	1	0.1%

CH=Chrysotile Asbestos. AA=Anthophyllite Asbestos. ND="Non-Detect"

Table II below summarizes the materials and locations of samples found NOT to contain asbestos. The certified laboratory report of analysis and chain of custody documentation are attached.

Table II- Materials Found NOT to Contain Asbestos

Material Description	Material Location
White Ceiling Tile	Floor 3, Ceiling Throughout
Blue Vinyl Baseboard + Yellow Mastic	Floor 3, Walls Throughout
Brown Carpet + Yellow Mastic	Floor 3, Carpet Flooring Throughout
Gray Stucco + White Stucco w/ Paint	Floor 3, Cinderblock Walls
Black Roofing Tar and Felt + Black Roofing Material + Silver Coating	Roof, Sheet Roofing Material Throughout
White Mastic + White Sealant + Black Roofing Material	Roof, Perimeter Seal
Gray Coating + Black Roofing Material	Roof, Patches Throughout
Gray Stucco + White Stucco w/ Paint	Roof & Building Exterior, Throughout Façade
Gray Mastic + Black Roofing Material	Roof, HVAC Mastic
White Sink Undercoat	Floor 3, Kitchen Sink
Gray Flooring Material + White Fibrous Material	Floor 3, Balcony Floor
Pink Ceramic Tile + White Compound	Floor 3, Women's Restroom Wall
Beige Ceramic Tile + Gray Mortar	Floor 3, Women's Restroom Floor
Blue Ceramic Tile + White Compound	Floor 3, Men's Restroom Wall
Gray Ceramic Tile + Gray Mortar	Floor 3, Men's Restroom Floor
Beige Mastic	HVAC Duct Mastic Throughout Building
Blue Vinyl Baseboard + Yellow Mastic	Floor 2, Walls Throughout
Brown Carpet + Yellow Mastic + Gray Fibrous Material	Floor 2, Carpet Flooring Throughout
Pink Ceramic Tile + White Compound	Floor 2, Women's Restroom Wall
Beige Ceramic Tile + Gray Mortar + Gray Grout	Floor 2, Women's Restroom Floor
Cream Ceramic Tile + White Compound	Floor 2, Men's Restroom Wall
Gray Ceramic Tile + Gray Mortar + Gray Grout	Floor 2, Men's Restroom Floor
Gray Vinyl Floor Tile + Yellow Mastic + Gray Leveling Compound	Floor 2, Kitchen / Lounge Area Floor
Gray Stucco w/ Paint	Floor 2, Cinderblock Walls

Table II- Materials Found NOT to Contain Asbestos (Continued)

Material Description	Material Location
Tan Tall Vinyl Baseboard + Multicolored Mastic	Floor 2, Walls Throughout
White Ceiling Tile	Floor 2, Ceiling Throughout
White Drywall System	Floor 1, Walls Throughout
Pink Ceramic Tile + White Compound + Yellow Adhesive	Floor 1, Women's Restroom Wall
Beige Ceramic Tile + Gray Mortar + Gray Sealant	Floor 1, Women's Restroom Floor
Cream Ceramic Tile	Floor 1, Men's Restroom Wall
White Ceramic Tile + Gray Mortar + Gray Sealant	Floor 1, Men's Restroom Floor
Tan Vinyl Baseboard + Yellow Mastic	Floor 1, Entry Walls
Gray Vinyl Baseboard + Yellow Mastic	Floor 1, Office Walls
White Ceiling Tile (Square)	Floor 1, Entry Ceiling
White Ceiling Tile (Rectangle)	Floor 1, Office Ceilings
Gray Stucco w/ Paint	Floor 1, Cinderblock Walls
Brown/Orange Vinyl Baseboard + Yellow Mastic	Floor 1, Electrical Closet Walls
White Caulk	Building Exterior, Windows on Milvia Street
Black Caulk	Building Exterior, Windows on Center Street

Assumed Asbestos Containing Materials

Roofing materials and materials outside of the planned work areas were not addressed during this limited asbestos survey, but if disturbance of such materials becomes necessary, the materials would be assumed to be positive for asbestos unless further survey sampling is completed.

The remainder of this page left intentionally blank.

LEAD

Twenty-four (24) paint and material samples from homogeneous areas were collected and analyzed for lead content, resulting in none (0) of the samples testing above the 600 ppm limit for paint as defined in Title 8 CCR 1532.1.

Table III below summarizes the tested materials and locations. The certified laboratory report of analysis and chain of custody documentation are attached.

Table III – Lead Content in Sampled Materials

Material Description	Sample Location	Lead Content
Beige Paint	Roof, Building Exterior Walls	58 ppm
Brown Paint	Floor 3, Balcony Railing	ND <59 ppm
Beige Ceramic Tile	Floor 3, Women's Restroom Floor	ND <38 ppm
Pink Ceramic Tile	Floor 3, Women's Restroom Wall	53 ppm
Gray Ceramic Tile	Floor 3, Men's Restroom Floor	ND <40 ppm
Blue Ceramic Tile	Floor 3, Men's Restroom Wall	46 ppm
Yellow Paint	Floor 3, Accent Walls	ND <37 ppm
White Paint	Floor 3, Walls Throughout	ND <40 ppm
Beige Ceramic Tile	Floor 2, Women's Restroom Floor	ND <36 ppm
Pink Ceramic Tile	Floor 2, Women's Restroom Wall	ND <39 ppm
Gray Ceramic Tile	Floor 2, Men's Restroom Floor	ND <39 ppm
Cream Ceramic Tile	Floor 2, Men's Restroom Wall	ND <39 ppm
White Paint	Floor 2, Walls Throughout	ND <38 ppm
Yellow Paint	Floor 2, Accent Walls	640 ppm
Beige Ceramic Tile	Floor 1, Women's Restroom Floor	ND <38 ppm
Pink Ceramic Tile	Floor 1, Women's Restroom Wall	ND <37 ppm
Gray Ceramic Tile	Floor 1, Men's Restroom Floor	60 ppm
Cream Ceramic Tile	Floor 1, Men's Restroom Wall	ND <40 ppm
Red Paint	Floor 1, Steel Beams at Entry	490 ppm
Yellow Paint	Floor 1, Accent Walls	ND <40 ppm
White Paint	Floor 1, Walls Throughout	ND <40 ppm
Gray Paint	Floor 1, Sheetrock on Entry Desks	ND <38 ppm

Table III – Lead Content in Sampled Materials (Continued)

Material Description	Sample Location	Lead Content
Beige Paint	Building Exterior, Milvia Street Façade	160 ppm
White Paint	Building Exterior, Center Street Façade	230 ppm

ppm = Parts per million, ND = Not detected above indicated reporting limit,

Bold = Abatement procedures required prior to significant disturbance due to Lead-Containing Paint or materials **Bold** + **Red** = Abatement procedures and hazardous waste disposal required prior to significant disturbance due to Lead-Based Paint or Materials

POLYCHLORINATED BIPHENYLS

The Environmental Protection Agency (EPA) believes that there was a potentially widespread use of PCB-containing building materials in schools and other buildings built or renovated between 1950 and 1979. Historically, PCBs were used as a plasticizing agent for caulking and glazing materials, as additives to paints and floor finishes, as a sealant for heating systems and plumbing, and as insulators in ballast and other electrical equipment. The manufacture and use of PCBs were banned in the United States in 1976, and PCB compounds were phased out between 1978 and 1979. The EPA has set forth two classifications of PCB product:

- 1. PCB Bulk Product Waste (≥ 50 ppm). According to Environmental Protection Agency (EPA), Memorandum, "PCB Bulk Product Waste Reinterpretation" dated October 24, 2012, Building materials "Coated or serviced" with PCB bulk product waste (e.g., caulk, paint, mastic, sealants) at the time of designation for disposal to be managed as a PCB bulk product waste. The reinterpretation document allows for disposal of both PCB Bulk Product Waste and PCB Remediation Waste together as a single waste stream (PCB Bulk Product Waste).
- 2. **Excluded PCB Product.** This is classified as all materials containing <50 ppm.

EnviroNova collected samples of suspect PCBs-containing window caulking, and noted the presence of ballasts in the fluorescent lighting. However, due to limited sampling capabilities, EnviroNova did not collect ballasts for laboratory analytical testing. Table IV below summarizes the tested materials and locations.

Table IV – PCBs Content in Sampled Materials

Material Description	Sample Location	Analytical Results	EPA PCB Waste Classification
White Caulk	Building Exterior, Milvia St. Windows	1,600 mg/kg	PCB Bulk Product
Black Caulk	Building Exterior, Center St. Windows	1,500 mg/kg	PCB Bulk Product

1 mg/kg = 1 ppm

CONCLUSIONS AND RECOMMENDATIONS

Based upon the results of analyses for asbestos, which indicated that asbestos and lead are present, EnviroNova recommends a properly certified abatement contractor be utilized to remove/abate asbestos- and lead-containing materials prior to disturbance related to any demolition/renovation activities. Additionally, the removal or abatement activities should be monitored for compliance, and clearance testing of contained areas is recommended before considering the abatement complete.

Based upon the results of analyses for PCBs, which indicated that PCB Bulk Product Waste materials are present, EnviroNova recommends a properly certified abatement contractor be utilized to remove these materials prior to disturbance related to any demolition/renovation activities. Follow all regulatory requirements for disposal.

During construction activities, if other suspected asbestos or lead-containing materials, including paint are encountered, those materials must be assumed to contain asbestos and/or lead. Therefore, any suspect materials must be sampled prior to their disturbance.

Lead Work Guidelines and Regulations

Loose and flaking paints should be scraped down to intact paint (and the resulting paint chips captured for disposal), prior to demolition by a registered lead abatement contractor. Only components with intact, well-adhered paint will then remain during demolition. Ceramic tile with high lead content should also be removed prior to demolition. The owner or removal/demolition contractor should conduct appropriate segregation of waste created during the removal or dismantling/demolition process and dispose of the different waste streams in accordance regulatory requirements based on appropriate testing results.

The current Cal/OSHA Lead in Construction Safety Standard (Title 8 CCR 1532.1) regulation applies to all construction work where an employee may be occupationally exposed to lead. Therefore, work performed on surfaces (including manual demolition, scraping, welding, etc.) containing any amount of lead must comply with the standard, including an exposure assessment (personal air monitoring) to determine if the airborne lead exposure levels are within acceptable limits. Therefore, any work performed on a surface containing any amount of lead must comply with this regulation. Any paint not represented by a result that is below the analytical limit of detection should be considered to contain lead and be treated as such until proven otherwise.

Lead waste is considered a hazardous waste if the result of the Toxicity Characterization Leaching Procedure (TCLP) test exceeds 5 mg/liter (5 ppm), under the Resource Conservation and Recovery Act (RCRA), 40 CFR 261, Appendix II. In California, a waste is also considered hazardous if the result of soluble lead content by a Waste Extraction Test (WET) is greater than 5 mg/l, or if the total lead content exceeds 1,000 mg/kg in accordance with Title 22 of the CCR. When TTLC results are below 50 mg/kg, STLC/TCLP limits cannot be exceeded, so the waste is classified as non-hazardous. For detailed regulatory requirements in specific situations, EnviroNova may be consulted, and the applicable regulations should be examined.

As required by the California Department of Public Health, Title 17, Article 16 Regulations, dated January 8, 1999, EnviroNova will forward Form 8552 to CDPH notifying them of the presence/absence of lead-based paint in the areas tested at the subject property.

Limitations

This survey was conducted as a limited renovation survey. Materials that were not included within the agreed upon scope of work, or could not be sampled discretely, were assumed to contain asbestos and/or lead. Until rebutted by appropriate sampling and analysis, these materials should be assumed to contain asbestos.

The survey was planned and implemented on the basis of a mutually agreed upon scope of work, and EnviroNova's previous experience in performing building surveys for asbestos and lead containing materials. EnviroNova uses only qualified professionals and laboratories to perform building surveys and sample analyses. PLM is generally not capable of detecting extremely fine fibers (<0.3µm in diameter). Further analysis by transmission electron microscopy is able to detect smaller fibers. However, this is a concern only with certain materials such as floor tiles.

This document was prepared by EnviroNova at the direction of XLC for the sole use of XLC and their sub-contractors, whom are the only intended beneficiaries of this work. No other party should rely on the information contained herein without the prior written consent of EnviroNova. This report and the interpretations, conclusions, and recommendations contained within are based in part on information presented in other documents or by other parties that are cited in the text. Therefore, this report is subject to the limitations and qualifications presented in the referenced information.

EnviroNova appreciates the opportunity to present this report. Please contact Basil Falcone at (415) 599-6657 if you have any questions. We look forward to working with you again.

Respectfully submitted,

ENVIRONOVA Eninomnal Health & Salety Rasagement

Brenna Deane, CSST (#19-6572)

Staff Scientist

John B. Adams, CAC (#12-4899), CDPH-I/A (#LRC-059)

Senior Environmental Scientist

Basil Falcone, REA, CAC (#04-3597)

President

Attachments Table of Electronic & Universal Waste

Certified Laboratory Analytical Report

Chain of Custody Documentation

Map of Sample Locations

21-186 2118 Milvia Street, Berkeley CA

Item	Floor 3	Floor 2	Floor 1	TOTALS
Lights	82	139	151	372
Fire Extinguisher	1	3	3	7
Speaker/Strobe	7	23	17	47
Smoke Detector	22	52	40	114
Exit Signs	3	8	13	24
Thermostat	5	5	4	14
Fire Alarm Pull	1	1	4	6
HVAC Oil	7 (roof)			7
Fire Doors	2	2	2	6



Report for:

Mr. Basil Falcone Enviro Nova 235 Montgomery Street Suite 1105 San Francisco, CA 94104

Regarding: Project: 21-186; 2118 Milvia Street, Berkeley, CA

EML ID: 2709217

Approved by:

Dates of Analysis: Asbestos PLM: 08-16-2021 and 08-17-2021

Approved Signatory Amber Rutter

Service SOPs: Asbestos PLM (EPA 40CFR App E to Sub E of Part 763 & EPA METHOD 600/R-93-116, SOP EM-AS-S-1267) NVLAP Lab Code 500053-0

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. The results relate only to the samples as received and tested. The results include an inherent uncertainty of measurement associated with estimating percentages by polarized light microscopy. Measurement uncertainty data for sample results with >1% asbestos concentration can be provided when requested.

Eurofins EMLab P&K ("the Company") shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

Lab ID-Version 1: 12958461-1

EMLab ID: 2709217, Page 2 of 34

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova Date of Sampling: 08-13-2021 Date of Receipt: 08-13-2021 C/O: Mr. Basil Falcone Re: 21-186; 2118 Milvia Street, Berkeley, CA Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Total Samples Submitted: 121 **Total Samples Analyzed:** 121

Total Samples with Layer Asbestos Content > 1%: 28

Location: 3-CT-1 Ceiling tile floor 3 rectangular white ceiling tile throughout

Location: 3-CT-1, Ceiling tile, floor 3, rectangular white	e ceiling tile throughout Lab ID-Version‡: 12958460-1
Sample Layers	Asbestos Content
Beige Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	40% Cellulose
-	40% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 3-CT-2, Ceiling tile, floor 3, rectangular white ceiling tile throughout

Sample Layers	Asbestos Content
Beige Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	
	40% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 3-BB-1, Vinvl baseboard, floor 3, blue vinvl baseboard and white/vellow mastic throughout Lab ID-Version 1: 12958462-1

Sample Layers	Asbestos Content	
Blue Baseboard	ND	
Yellow Mastic	ND	
Sample Composite Homogeneity: Moderate		

Location: 3-BB-2, Vinyl baseboard, floor 3, blue vinyl baseboard and white/yellow mastic throughout Lab ID-Version †: 12958463-1

	240 15 (0151014, 12500 100 1
Sample Layers	Asbestos Content
Blue Baseboard	ND
Yellow Mastic	ND
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

EMLab ID: 2709217, Page 3 of 34

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 3-YCM-1, Carpet mastic, floor 3, yellow mastic under brown carpet and gray

pad Lab ID-Version‡: 12958464-1

Sample Layers	Asbestos Content	
Brown Carpet	ND	
Yellow Mastic	ND	
Composite Non-Asbestos Content: 40% Synthetic Fibers		
Sample Composite Homogeneity:	Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 3-YCM-2, Carpet mastic, floor 3, yellow mastic under brown carpet and gray

pad Lab ID-Version‡: 12958465-1

Sample Layers	Asbestos Content	
Brown Carpet	ND	
Yellow Mastic	ND	
Composite Non-Asbestos Content: 40% Synthetic Fibers		
Sample Composite Homogeneity:	Moderate	

Location: 3-DW-1, Drywall system, floor 3, white drywall system on walls throughout Lab ID-Version;: 12958466-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Off-White Compound with Paint	2% Chrysotile
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Good

Location: 3-DW-2, Drywall system, floor 3, white drywall system on walls throughout Lab ID-Version‡: 12958467-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Off-White Joint Compound	2% Chrysotile
Cream Tape	ND
Off-White Compound with Paint	2% Chrysotile
Composite Asbestos Fibrous Content:	< 1% Asbestos
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

Comments: Composite asbestos content provided is only for Drywall/Joint compound. Composite content provided for this analysis has been performed by following the NESHAP guidelines.

Location: 3-DW-3, Drywall system, floor 3, white drywall system on walls throughout Lab ID-Version‡: 12958468-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Off-White Joint Compound	2% Chrysotile
Cream Tape	ND
Off-White Compound with Paint	2% Chrysotile
Composite Asbestos Fibrous Content:	< 1% Asbestos
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

Comments: Composite asbestos content provided is only for Drywall/Joint compound. Composite content provided for this analysis has been performed by following the NESHAP guidelines.

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street , Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 3-DW-4, Drywall system, floor 3, white drywall system on walls throughout Lab ID-Version‡: 12958469-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Off-White Joint Compound	2% Chrysotile
Cream Tape	ND
Off-White Compound with Paint	2% Chrysotile
Composite Asbestos Fibrous Content:	< 1% Asbestos
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

Comments: Composite asbestos content provided is only for Drywall/Joint compound. Composite content provided for this analysis has been performed by following the NESHAP guidelines.

Location: 3-DW-5, Drywall system, floor 3, white drywall system on walls throughout Lab ID-Version‡: 12958470-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Off-White Joint Compound	2% Chrysotile
Cream Tape	ND
Off-White Compound with Paint	2% Chrysotile
Composite Asbestos Fibrous Content:	< 1% Asbestos
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

Comments: Composite asbestos content provided is only for Drywall/Joint compound. Composite content provided for this analysis has been performed by following the NESHAP guidelines.

Location: 3-DW-6, Drywall system, floor 3, white drywall system on walls throughout Lab ID-Version‡: 12958471-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Off-White Joint Compound	2% Chrysotile
Cream Tape	ND
Off-White Compound with Paint	2% Chrysotile
Composite Asbestos Fibrous Content:	< 1% Asbestos
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

Comments: Composite asbestos content provided is only for Drywall/Joint compound. Composite content provided for this analysis has been performed by following the NESHAP guidelines.

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

EMLab ID: 2709217, Page 6 of 34

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 3-DW-7, Drywall system, floor 3, white drywall system on walls throughout Lab ID-Version‡: 12958472-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Off-White Joint Compound	2% Chrysotile
Cream Tape	ND
Off-White Compound with Paint	2% Chrysotile
Composite Asbestos Fibrous Content:	< 1% Asbestos
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

Comments: Composite asbestos content provided is only for Drywall/Joint compound. Composite content provided for this analysis has been performed by following the NESHAP guidelines.

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 3-CBW-1, Cinderblock and stucco, floor 3, gray cinderblock wall and white

stucco inside Lab ID-Version 1: 12958473-1

Sample Layers	Asbestos Content
Gray Stucco	ND
White Stucco with Paint	ND
Sample Composite Homogeneity: Moderate	

Location: 3-CBW-2, Cinderblock and stucco, floor 3, gray cinderblock wall and white stucco inside

Lab ID-Version‡: 12958474-1

Sample Layers	Asbestos Content
Gray Stucco	ND
White Stucco with Paint	ND
Sample Composite Homogeneity: Moderate	

Location: 3-CBW-3, Cinderblock and stucco, floor 3, gray cinderblock wall and white stucco inside

Lab ID-Version‡: 12958475-1

Sample Layers	Asbestos Content
Gray Stucco	ND
White Stucco with Paint	ND
Sample Composite Homogeneity: Moderate	

Location: R-A, Roofing material, roof, gray and black sheet roofing material throughout roof

Lab ID-Version‡: 12958476-1

Sample Layers	Asbestos Content
Black Roofing Tar and Felt	ND
Black Roofing Material	ND
Silver Coating	ND
Composite Non-Asbestos Content:	15% Glass Fibers
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Lab ID-Version‡: 12958479-1

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: R-B, Roofing material, roof, gray and black sheet roofing material throughout

roof

Lab ID-Version‡: 12958477-1

Sample Layers	Asbestos Content
Black Roofing Tar and Felt	ND
Black Roofing Material	ND
Silver Coating	ND
Composite Non-Asbestos Content:	15% Glass Fibers
Sample Composite Homogeneity:	Poor

Location: R-C, Roofing material, roof, gray and black sheet roofing material throughout

roof Lab ID-Version‡: 12958478-1

Sample Layers	Asbestos Content
Black Roofing Tar and Felt	ND
Black Roofing Material	ND
Silver Coating	ND
Composite Non-Asbestos Content:	15% Glass Fibers
Sample Composite Homogeneity:	Poor

Location: R-D, Perimeter seal, roof, white seal material around perimeter of roof

Sample Layers	Asbestos Content
White Sealant	ND
Sample Composite Homogeneity:	Good

Location: R-E, Perimeter seal, roof, white seal material around perimeter of roof Lab ID-Version‡: 12958480-1

Sample Layers	Asbestos Content
White Sealant	ND
Black Roofing Mastic with Silver Coating	3% Chrysotile
Sample Composite Homogeneity:	Poor

Comments: Some layers in the sample were inseparable without cross contamination.

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: R-F, Perimeter seal, roof, white seal material around perimeter of roof

Lab ID-Version‡: 12958481-1

Sample Layers	Asbestos Content
Black Roofing Material	ND
White Sealant	ND
Silver Coating	ND
Sample Composite Homogeneity:	Poor

Location: R-G, Penetration mastic, roof, white/gray mastic at penetrations throughout Lab ID-Version‡: 12958482-1

Sample Layers	Asbestos Content
White Mastic	ND
White Sealant	ND
Black Roofing Mastic with Silver Coating	3% Chrysotile
Sample Composite Homogeneity: Poor	

Comments: Some layers in the sample were inseparable without cross contamination.

Location: R-H, Penetration mastic, roof, white/gray mastic at penetrations throughout Lab ID-Version‡: 12958483-1

Sample Layers	Asbestos Content
White Mastic	ND
Black Mastic	ND
Silver Coating	ND
Sample Composite Homogeneity: Poor	

Location: R-J, Patching material, roof gray/black material on patches throughout Lab ID-Version‡: 12958484-1

	1 8
Sample Layers	Asbestos Content
Gray Coating	ND
Black Roofing Material	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: R-K, Patching material, roof gray/black material on patches throughout

Lab ID-Version‡: 12958485-1

Sample Layers	Asbestos Content
Gray Coating	ND
Black Roofing Material	ND
Sample Composite Homogeneity: Moderate	

Location: R-M, Exterior stucco, roof, gray stucco on building exterior

Lab ID-Version‡: 12958486-1

Sample Layers	Asbestos Content
Gray Stucco	ND
White Stucco with Paint	ND
Sample Composite Homogeneity: Moderate	

Location: R-N, Exterior stucco, roof, gray stucco on building exterior

Lab ID-Version 1: 12958487-1

Sample Layers	Asbestos Content
Gray Stucco	ND
Sample Composite Homogeneity:	Good

Location: R-O, Exterior stucco, roof, gray stucco on building exterior

Lab ID-Version‡: 12958488-1

Sample Layers	Asbestos Content
Gray Stucco	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: BE-Stucco-1, Exterior stucco, building exterior, gray stucco throughout facade

Lab ID-Version‡: 12958489-1

Sample Layers	Asbestos Content
Gray Stucco	ND
White Stucco with Paint	ND
Sample Composite Homogeneity: Moderate	

Location: BE-Stucco-2, Exterior stucco, building exterior, gray stucco throughout facade

Lab ID-Version‡: 12958490-1

Sample Layers	Asbestos Content
Gray Stucco	ND
White Stucco with Paint	ND
Sample Composite Homogeneity:	Moderate

Location: BE-Stucco-3, Exterior stucco, building exterior, gray stucco throughout facade

Lab ID-Version‡: 12958491-1

Sample Layers	Asbestos Content
Gray Stucco	ND
White Stucco with Paint	ND
Sample Composite Homogeneity:	Moderate

Location: BE-Stucco-4, Exterior stucco, building exterior, gray stucco throughout facade

Lab ID-Version‡: 12958492-1

Sample Layers	Asbestos Content
Gray Stucco	ND
White Stucco with Paint	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Lab ID-Version‡: 12958493-1

Lab ID-Version 1: 12958494-1

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: R-Q, HVAC mastic, roof, black/gray mastic on HVAC units

Sample Layers	Asbestos Content
Gray Mastic	ND
Black Roofing Material	ND
Composite Non-Asbestos Content:	20% Synthetic Fibers
Sample Composite Homogeneity:	Moderate

Location: R-R, HVAC mastic, roof, black/gray mastic on HVAC units

Sample Layers	Asbestos Content
Gray Mastic	ND
Black Roofing Material	ND
Composite Non-Asbestos Content:	20% Synthetic Fibers
Sample Composite Homogeneity:	Moderate

Location: 3-VFT-1, Vinyl floor tile, floor 3, red and beige vinyl floor tile on kitchen floor

Lab ID-Version 1: 12958495-1

Sample Layers	Asbestos Content
Beige Floor Tile	ND
Black/Yellow Mastic	3% Chrysotile
Red Sheet Flooring with Fibrous Backing	ND
Composite Non-Asbestos Content:	30% Cellulose
Sample Composite Homogeneity:	Poor

Location: 3-VFT-2, Vinyl floor tile, floor 3, red and beige vinyl floor tile on kitchen floor

Lab ID-Version‡: 12958496-1

Sample Layers	Asbestos Content
Beige Floor Tile	ND
Black/Yellow Mastic	3% Chrysotile
Red Sheet Flooring with Fibrous Backing	ND
Composite Non-Asbestos Content:	30% Cellulose
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Lab ID-Version †: 12958497-1

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 3-Sink, Sink undercoat, floor 3, white undercoat on kitchen sink

boution, b blink, blink under cour, more by white under cour on kitchen blink	
Sample Layers	Asbestos Content
White Sink Undercoating	ND
Sample Composite Homogeneity:	Good

Location: 3B-Floor-1, Balcony flooring material, floor 3 balcony, gray flooring material

exterior Lab ID-Version‡: 12958498-1

Sample Layers	Asbestos Content
Gray Flooring	ND
White Fibrous Material	ND
Composite Non-Asbestos Content:	10% Glass Fibers
Sample Composite Homogeneity:	Moderate

Location: 3B-Floor-2, Balcony flooring material, floor 3 balcony, gray flooring material

exterior Lab ID-Version‡: 12958499-1

Sample Layers	Asbestos Content
Gray Flooring	ND
White Fibrous Material	ND
Composite Non-Asbestos Content:	10% Glass Fibers
Sample Composite Homogeneity:	Moderate

Location: 3-BWT-1W, Ceramic wall tile, floor 3, pale pink ceramic tile on women's

restroom wall Lab ID-Version‡: 12958500-1

Sample Layers	Asbestos Content	
Pink Ceramic Tile	ND	
White Compound	ND	
Sample Composite Homogeneity: Moderate		

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 3-BWT-2W, Ceramic wall tile, floor 3, pale pink ceramic tile on women's

restroom wall

Lab ID-Version 1: 12958501-1

Sample Layers	Asbestos Content	
Pink Ceramic Tile	ND	
White Compound	ND	
Sample Composite Homogeneity: Moderate		

Location: 3-BFT-1W, Ceramic floor tile, floor 3, beige and white ceramic wall tile on women's restroom floor

Lab ID-Version 1: 12958502-1

Sample Layers	Asbestos Content
Beige Ceramic Tile	ND
Gray Mortar	ND
Sample Composite Homogeneity: Moderate	

Location: 3-BFT-2W, Ceramic floor tile, floor 3, beige and white ceramic wall tile on women's restroom floor

Lab ID-Version‡: 12958503-1

Sample Layers	Asbestos Content
Beige Ceramic Tile	ND
Gray Mortar	ND
Sample Composite Homogeneity: Moderate	

Location: 3-BWT-1M, Ceramic wall tile, floor 3, pale blue ceramic tile on men's restroom wall

Lab ID-Version‡: 12958504-1

Sample Layers	Asbestos Content
Pink Ceramic Tile	ND
White Compound	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova Date of Sampling: 08-13-2021 C/O: Mr. Basil Falcone Date of Receipt: 08-13-2021 Re: 21-186; 2118 Milvia Street, Berkeley, CA Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 3-BWT-2M, Ceramic wall tile, floor 3, pale blue ceramic tile on men's restroom

wall Lab ID-Version 1: 12958505-1

Sample Layers	Asbestos Content	
Pink Ceramic Tile	ND	
White Compound	ND	
Sample Composite Homogeneity: Moderate		

Location: 3-BFT-1M, Ceramic floor tile, floor 3, gray and white ceramic tile on men's restroom floor

Lab ID-Version 1: 12958506-1

Sample Layers	Asbestos Content	
Gray Ceramic Tile	ND	
Gray Mortar	ND	
Sample Composite Homogeneity: Moderate		

Location: 3-BFT-2M, Ceramic floor tile, floor 3, gray and white ceramic tile on men's restroom floor

Lab ID-Version‡: 12958507-1

Sample Layers	Asbestos Content
Gray Ceramic Tile	ND
Gray Mortar	ND
Sample Composite Homogeneity: Moderate	

Location: 3-Mirror-1, Mirror mastic, floor 3, black mastic behind mirrors

Location: 3-Mirror-1, Mirror mastic, floor 3, black mastic behind mirrors		Lab ID-Version‡: 12958508-1
Sample Layers	Asbestos Content	
Black Mastic	10% Chry	sotile
Sample Composite Homogeneity: Good		

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Lab ID-Version‡: 12958509-1

Lab ID-Version 1: 12958510-1

Lab ID-Version 1: 12958511-1

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 3-Mirror-2, Mirror mastic, floor 3, black mastic behind mirrors

Sample Layers	Asbestos Content
Black Mastic	10% Chrysotile
Sample Composite Homogeneity: Good	

Location: HVAC-1, HVAC duct mastic, beige mastic on HVAC ducts above ceiling throughout all floors

Sample Layers

Beige Mastic

Sample Composite Homogeneity: Good

Location: HVAC-2, HVAC duct mastic, beige mastic on HVAC ducts above ceiling throughout all floors

Sample Layers

Beige Mastic

Sample Composite Homogeneity: Good

Location: 2-DW-1, Drywall system, floor 2, white drywall system on walls throughout Lab ID-Version‡: 12958512-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Off-White Compound with Paint	2% Chrysotile
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 2-DW-2, Drywall system, floor 2, white drywall system on walls throughout Lab ID-Version‡: 12958513-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Off-White Joint Compound	2% Chrysotile
Cream Tape	ND
White Compound with Paint	ND
Composite Asbestos Fibrous Content:	< 1% Asbestos
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

Comments: Composite content provided for this analysis has been performed by following the NESHAP guidelines.

Location: 2-DW-3, Drywall system, floor 2, white drywall system on walls throughout Lab ID-Version: 12958514-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
White Joint Compound	ND
Cream Tape	ND
White Compound with Paint	ND
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

Location: 2-DW-4, Drywall system, floor 2, white drywall system on walls throughout Lab ID-Version:: 12958515-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
White Joint Compound	ND
Cream Tape	ND
White Compound with Paint	ND
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street , Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 2-DW-5, Drywall system, floor 2, white drywall system on walls throughout Lab ID-Version‡: 12958516-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Off-White Joint Compound	2% Chrysotile
Cream Tape	ND
Off-White Compound with Paint	2% Chrysotile
Composite Asbestos Fibrous Content:	< 1% Asbestos
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

Comments: Composite asbestos content provided is only for Drywall/Joint compound. Composite content provided for this analysis has been performed by following the NESHAP guidelines.

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 2-DW-6, Drywall system, floor 2, white drywall system on walls throughout Lab ID-Version‡: 12958517-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
Off-White Joint Compound	2% Chrysotile
Cream Tape	ND
Off-White Compound with Paint	2% Chrysotile
Composite Asbestos Fibrous Content:	< 1% Asbestos
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

Comments: Composite asbestos content provided is only for Drywall/Joint compound. Composite content provided for this analysis has been performed by following the NESHAP guidelines.

Location: 2-DW-7, Drywall system, floor 2, white drywall system on walls throughout Lab ID-Version‡: 12958518-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
White Compound with Paint	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Moderate

Location: 2-BB-1, Vinyl baseboard, floor 2, blue vinyl baseboard yellow mastic on walls

Lab ID-Version‡: 12958519-1

Sample Layers	Asbestos Content
Blue Baseboard	ND
Yellow Mastic	ND
Sample Composite Homogeneity: Moderate	

Location: 2-BB-2, Vinyl baseboard, floor 2, blue vinyl baseboard yellow mastic on walls

Lab ID-Version 1: 12958520-1

Sample Layers	Asbestos Content
Blue Baseboard	ND
Yellow Mastic	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova Date of Sampling: 08-13-2021 Date of Receipt: 08-13-2021 C/O: Mr. Basil Falcone Re: 21-186; 2118 Milvia Street, Berkeley, CA Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 2-YCM-1, Carpet mastic, floor 2, yellow mastic under brown carpet and gray

pad throughou Lab ID-Version 1: 12958521-1

Sample Layers	Asbestos Content
Brown Carpet	ND
Yellow Mastic	ND
Gray Fibrous Material	ND
Composite Non-Asbestos Content: 60% Synthetic Fibers	
Sample Composite Homogeneity:	Moderate

Location: 2-YCM-2, Carpet mastic, floor 2, yellow mastic under brown carpet and gray

pad throughou Lab ID-Version 1: 12958522-1

Sample Layers	Asbestos Content
Brown Carpet	ND
Yellow Mastic	ND
Gray Fibrous Material	ND
Composite Non-Asbestos Content: 60% Synthetic Fibers	
Sample Composite Homogeneity:	Moderate

Location: 2-BWT-1W, Ceramic wall tile, floor 2, pale pink ceramic tile on women's

restroom wall Lab ID-Version 1: 12958523-1

Sample Layers	Asbestos Content
Pink Ceramic Tile	ND
White Compound	ND
Sample Composite Homogeneity: Moderate	

Location: 2-BWT-2W, Ceramic wall tile, floor 2, pale pink ceramic tile on women's restroom wall

Lab ID-Version 1: 12958524-1

Sample Layers	Asbestos Content
Pink Ceramic Tile	ND
White Compound	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 2-BFT-1W, Ceramic floor tile, floor 2, beige and white ceramic tile on women's

restroom floor

Lab ID-Version‡: 12958525-1

Sample Layers	Asbestos Content
Beige Ceramic Tile	ND
Gray Grout	ND
Gray Mortar	ND
Sample Composite Homogeneity:	Poor

Location: 2-BFT-2W, Ceramic floor tile, floor 2, beige and white ceramic tile on women's

restroom floor

Lab ID-Version‡: 12958526-1

Sample Layers	Asbestos Content
Beige Ceramic Tile	ND
Gray Grout	ND
Gray Mortar	ND
Sample Composite Homogeneity: Poor	

Location: 2-BWT-1M, Ceramic wall tile, floor 2, cream tile on men's restroom wall Lab ID-Version:: 12958527-1

Sample Layers	Asbestos Content
Pink Ceramic Tile	ND
White Compound	ND
Sample Composite Homogeneity:	Moderate

Location: 2-BWT-2M, Ceramic wall tile, floor 2, cream tile on men's restroom wall Lab ID-Version‡: 12958528-1

Sample Layers	Asbestos Content
Pink Ceramic Tile	ND
White Compound	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 2-BFT-1M, Ceramic wall tile, floor 2, gray and white ceramic tile on men's

restroom floor

Lab ID-Version‡: 12958529-1

Sample Layers	Asbestos Content
Gray Ceramic Tile	ND
Gray Grout	ND
Gray Mortar	ND
Sample Composite Homogeneity:	Poor

Location: 2-BFT-2M, Ceramic wall tile, floor 2, gray and white ceramic tile on men's restroom floor

Lab ID-Version‡: 12958530-1

Sample Layers	Asbestos Content
Gray Ceramic Tile	ND
Gray Grout	ND
Gray Mortar	ND
Sample Composite Homogeneity: Poor	

Location: 2-BVFT-1, Vinyl floor tile, floor 2, beige vinyl floor tile and black mastic in kitchen/lounge area

Lab ID-Version‡: 12958531-1

Sample Layers	Asbestos Content
Beige Floor Tile	ND
Black/Yellow Mastic	3% Chrysotile
Sample Composite Homogeneity: Poor	

Location: 2-BVFT-2, Vinyl floor tile, floor 2, beige vinyl floor tile and black mastic in kitchen/lounge area

Lab ID-Version‡: 12958532-1

Sample Layers	Asbestos Content
Beige Floor Tile	ND
Black/Yellow Mastic	3% Chrysotile
Sample Composite Homogeneity: Poor	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 2-GVFT-1, Vinyl floor tile, floor 2, gray vinyl floor tile and yellow mastic in

kitchen/lounge area Lab ID-Version‡: 12958533-1

Sample Layers	Asbestos Content
Gray Floor Tile	ND
Yellow Mastic	ND
Gray Leveling Compound	ND
Sample Composite Homogeneity: Poor	

Location: 2-GVFT-2, Vinyl floor tile, floor 2, gray vinyl floor tile and yellow mastic in kitchen/lounge area

Lab ID-Version 1: 12958534-1

Sample Layers	Asbestos Content
Gray Floor Tile	ND
Yellow Mastic	ND
Sample Composite Homogeneity: Moderate	

Location: 2-CBW-1, Cinderblock wall, floor 2, gray painted cinderblock walls throughout

Sample Layers	Asbestos Content
Gray Stucco with Paint	ND
Sample Composite Homogeneity:	Good

Location: 2-CBW-2, Cinderblock wall, floor 2, gray painted cinderblock walls throughout

Lab ID-Version‡: 12958536-1

Lab ID-Version 1: 12958535-1

Sample Layers	Asbestos Content
Gray Stucco with Paint	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 2-TBB-1, Vinyl baseboard, floor 2, tan tall vinyl baseboard and yellow/brown

mastic on walls

Lab ID-Version:: 12958537-1

Sample Layers	Asbestos Content
Tan Baseboard	ND
Multicolored Mastic	ND
Sample Composite Homogeneity: Moderate	

Location: 2-TBB-2, Vinyl baseboard, floor 2, tan tall vinyl baseboard and yellow/brown mastic on walls

Lab ID-Version 1: 12958538-1

Lab ID-Version 1: 12958539-1

Lab ID-Version‡: 12958540-1

Sample Layers	Asbestos Content
Tan Baseboard	ND
Multicolored Mastic	ND
Sample Composite Homogeneity:	Moderate

Location: 2-CT-1, Ceiling tile, floor 2, white ceiling tiles throughout

Sample Layers	Asbestos Content
Beige Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	40% Cellulose 40% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 2-CT-2, Ceiling tile, floor 2, white ceiling tiles throughout

Sample Layers	Asbestos Content
Beige Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	
	40% Glass Fibers
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova Date of Sampling: 08-13-2021 Date of Receipt: 08-13-2021 C/O: Mr. Basil Falcone Re: 21-186; 2118 Milvia Street, Berkeley, CA Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 2-Sink, Sink under coat, floor 2, black undercoat on break area sink

	Lab ID-Version‡: 12958541-1
s Conte	nt
rvsotile	

Sample Layers	Asbestos Content
Black Sink Undercoating	5% Chrysotile
Sample Composite Homogeneity:	Good

Location: 1-DW-1, Drywall system, floor 1, white drywall system on walls throughout Lab ID-Version‡: 12958542-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
White Compound with Paint	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Good

Location: 1-DW-2, Drywall system, floor 1, white drywall system on walls throughout Lab ID-Version 1: 12958543-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
White Joint Compound	ND
Cream Tape	ND
White Compound with Paint	ND
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

Location: 1-DW-3, Drywall system, floor 1, white drywall system on walls throughout Lab ID-Version 1: 12958544-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
White Joint Compound	ND
Cream Tape	ND
White Compound with Paint	ND
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 1-DW-4, Drywall system, floor 1, white drywall system on walls throughout

Lab ID-Version:: 12958545-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
White Joint Compound	ND
Cream Tape	ND
White Compound with Paint	ND
Composite Non-Asbestos Content: 15% Cellulose	
Sample Composite Homogeneity:	Poor

Location: 1-DW-5, Drywall system, floor 1, white drywall system on walls throughout Lab ID-Version:: 12958546-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
White Compound with Paint	ND
Composite Non-Asbestos Content:	10% Cellulose
Sample Composite Homogeneity:	Good

Location: 1-DW-6, Drywall system, floor 1, white drywall system on walls throughout Lab ID-Version: 12958547-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
White Joint Compound	ND
Cream Tape	ND
White Compound with Paint	ND
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

Location: 1-DW-7, Drywall system, floor 1, white drywall system on walls throughout

Lab ID-Version‡: 12958548-1

Sample Layers	Asbestos Content
White Drywall with Brown Paper	ND
White Joint Compound	ND
Cream Tape	ND
White Compound with Paint	ND
Composite Non-Asbestos Content:	15% Cellulose
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Lab ID-Version 1: 12958550-1

Lab ID-Version 1: 12958551-1

Lab ID-Version 1: 12958552-1

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 1-CSM-1, Carpet square mastic, floor 1, yellow and black mastic under blue

carpet squares in entry

Lab ID-Version‡: 12958549-1

Sample Layers	Asbestos Content
Brown Carpet	ND
Black/Yellow Mastic	2% Chrysotile
White Leveling Compound	ND
Composite Non-Asbestos Content:	60% Synthetic Fibers
Sample Composite Homogeneity:	Poor

Location: 1-CSM-2, Carpet square mastic, floor 1, yellow and black mastic under blue carpet squares in entry

	· · · · · · · · · · · · · · · · · · ·
Sample Layers	Asbestos Content
Brown Carpet	ND
Black/Yellow Mastic	2% Chrysotile
White Leveling Compound	ND
Composite Non-Asbestos Content:	60% Synthetic Fibers
Sample Composite Homogeneity:	Poor

Location: 1-CM-1, Carpet mastic, floor 1, yellow and black mastic under brown roll out carpet in offices

Sample Layers	Asbestos Content
Brown Carpet	ND
Black/Yellow Mastic	2% Chrysotile
Composite Non-Asbestos Content:	60% Synthetic Fibers
Sample Composite Homogeneity:	Poor

Location: 1-CM-2, Carpet mastic, floor 1, yellow and black mastic under brown roll out carpet in offices

Sample Layers

Brown Carpet

Black/Yellow Mastic

Composite Non-Asbestos Content:

Sample Composite Homogeneity:

Poor

Asbestos Content

ND

2% Chrysotile

Chrysotile

Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Lab ID-Version 1: 12958554-1

Lab ID-Version 1: 12958555-1

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

ND

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 1-ECM-1, Floor mastic, floor 1, black mastic on electrical closet floor, next to

elevator and under tile

Lab ID-Version:: 12958553-1

Sample Layers	Asbestos Content
Black Mastic	6% Chrysotile
Sample Composite Homogeneity: Good	

Location: 1-ECM-2, Floor mastic, floor 1, black mastic on electrical closet floor, next to elevator and under tile

Sample Layers	Asbestos Content
Black Mastic	6% Chrysotile
Sample Composite Homogeneity:	Good

Location: 1-BWT-1W, Ceramic wall tile, floor 1, pale pink ceramic tile on women's restroom wall

Sample Layers Asbestos Content

Pink Ceramic Tile ND

Yellow Adhesive ND

White Compound

Sample Composite Homogeneity: Poor

Location: 1-BWT-2W, Ceramic wall tile, floor 1, pale pink ceramic tile on women's

restroom wall

Lab ID-Version‡: 12958556-1

Sample Layers	Asbestos Content
Pink Ceramic Tile	ND
Yellow Adhesive	ND
White Compound	ND
Sample Composite Homogeneity:	Poor

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

Lab ID-Version 1: 12958559-1

Lab ID-Version 1: 12958560-1

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 1-BFT-1W, Ceramic floor tile, floor 1, beige and white ceramic tile on women's

restroom floor

Lab ID-Version 1: 12958557-1

Sample Layers	Asbestos Content
Beige Ceramic Tile	ND
Gray Mortar	ND
Gray Sealant	ND
Sample Composite Homogeneity:	Poor

Location: 1-BFT-2W, Ceramic floor tile, floor 1, beige and white ceramic tile on women's restroom floor Lab ID-Version‡: 12958558-1

 Sample Layers
 Asbestos Content

 Beige Ceramic Tile
 ND

 Gray Mortar
 ND

 Gray Sealant
 ND

 Sample Composite Homogeneity:
 Poor

Location: 1-BWT-1M, Ceramic wall tile, floor 1, cream ceramic tile on men's restroom wall

Sample Layers	Asbestos Content
Cream Ceramic Tile	ND
Sample Composite Homogeneity:	Good

Location: 1-BWT-2M, Ceramic wall tile, floor 1, cream ceramic tile on men's restroom wall

Sample Layers	Asbestos Content
Cream Ceramic Tile	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 1-BFT-1M, Ceramic wall tile, floor 1, gray and white ceramic tile on men's

restroom floor

Lab ID-Version‡: 12958561-1

Sample Layers	Asbestos Content
White Ceramic Tile	ND
Gray Mortar	ND
Gray Sealant	ND
Sample Composite Homogeneity:	Poor

Location: 1-BFT-2M, Ceramic wall tile, floor 1, gray and white ceramic tile on men's restroom floor

Lab ID-Version‡: 12958562-1

Sample Layers	Asbestos Content
White Ceramic Tile	ND
Gray Mortar	ND
Gray Sealant	ND
Sample Composite Homogeneity: Poor	

Location: 1-TBB-1, Vinyl baseboard, floor 1, tan vinyl baseboard and yellow mastic on entry walls

 Eab ID-Version‡: 12958563-1

 Sample Layers
 Asbestos Content

 Tan Baseboard
 ND

 Yellow Mastic
 ND

 Sample Composite Homogeneity:
 Moderate

Location: 1-TBB-2, Vinyl baseboard, floor 1, tan vinyl baseboard and yellow mastic on entry walls

Lab ID-Version‡: 12958564-1

Sample Layers	Asbestos Content
Tan Baseboard	ND
Yellow Mastic	ND
Sample Composite Homogeneity:	Moderate

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 1-GBB-1, Vinyl baseboard, floor 1, gray vinyl baseboard and yellow mastic on

office walls

Lab ID-Version:: 12958565-1

Sample Layers	Asbestos Content
Gray Baseboard	ND
Yellow Mastic	ND
Sample Composite Homogeneity: Moderate	

Location: 1-GBB-2, Vinyl baseboard, floor 1, gray vinyl baseboard and yellow mastic on

office walls

Lab ID-Version‡: 12958566-1

Sample Layers	Asbestos Content
Gray Baseboard	ND
Yellow Mastic	ND
Sample Composite Homogeneity: Moderate	

Location: 1-SCT-1, Ceiling tile, floor 1, square ceiling tiles throughout entry ceiling Lab ID-Version:: 12958567-1

9 3, 11 3 1 9	
Sample Layers	Asbestos Content
Beige Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	40% Cellulose
_	40% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 1-SCT-2, Ceiling tile, floor 1, square ceiling tiles throughout entry ceiling Lab ID-Version:: 12958568-1

Asbestos Content
ND
40% Cellulose
40% Glass Fibers
Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 1-RCT-1, Ceiling tile, floor 1, rectangular ceiling tiles throughout office ceiling

Lab ID-Version 1: 12958569-1

Sample Layers	Asbestos Content
Beige Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	40% Cellulose
	40% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 1-RCT-2, Ceiling tile, floor 1, rectangular ceiling tiles throughout office ceiling

Lab ID-Version 1: 12958570-1

Sample Layers	Asbestos Content
Beige Ceiling Tile with White Surface	ND
Composite Non-Asbestos Content:	40% Cellulose
_	40% Glass Fibers
Sample Composite Homogeneity:	Good

Location: 1-CBW-1, Cinderblock walls, floor 1, gray cinderblock walls

Lab ID-Version‡: 12958571-1

Lab ID-Version 1: 12958572-1

Sample Layers	Asbestos Content
Gray Stucco with Paint	ND
Sample Composite Homogeneity:	Good

Location: 1-CBW-2, Cinderblock walls, floor 1, gray cinderblock walls

Sample Layers	Asbestos Content
Gray Stucco with Paint	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: 1-VFT-1, Vinyl floor tile, floor 1, beige vinyl floor tile and black/yellow mastic

in hall sink room

Lab ID-Version:: 12958573-1

Sample Layers	Asbestos Content
Beige Floor Tile	ND
Black/Yellow Mastic	3% Chrysotile
Sample Composite Homogeneity: Poor	

Location: 1-VFT-2, Vinyl floor tile, floor 1, beige vinyl floor tile and black/yellow mastic in hall sink room

Lab ID-Version‡: 12958574-1

Sample Layers	Asbestos Content
Beige Floor Tile	ND
Black/Yellow Mastic	3% Chrysotile
Sample Composite Homogeneity: Poor	

Location: 1-BBB-1, Vinyl baseboard, floor 1, brown/orange vinyl baseboard and yellow mastic in electrical closet

Lab ID-Version‡: 12958575-1

Sample Layers	Asbestos Content
Brown Baseboard	ND
Yellow Mastic	ND
Sample Composite Homogeneity: Moderate	

Location: 1-BBB-2, Vinyl baseboard, floor 1, brown/orange vinyl baseboard and yellow mastic in electrical closet

Lab ID-Version‡: 12958576-1

Sample Layers	Asbestos Content
Brown Baseboard	ND
Yellow Mastic	ND
Sample Composite Homogeneity: Moderate	

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova Date of Sampling: 08-13-2021 Date of Receipt: 08-13-2021 C/O: Mr. Basil Falcone Re: 21-186; 2118 Milvia Street, Berkeley, CA Date of Report: 08-17-2021

ASBESTOS PLM REPORT

Location: BE-WC-1M, Window caulk, building exterior, white window caulk on Milvia

street Lab ID-Version : 12958577-1

Sample Layers	Asbestos Content
White Caulk	ND
Sample Composite Homogeneity:	Good

Location: BE-WC-2M, Window caulk, building exterior, white window caulk on Milvia

street Lab ID-Version 1: 12958578-1

Sample Layers	Asbestos Content
White Caulk	ND
Sample Composite Homogeneity:	Good

Location: BE-WC-1C, Window caulk, building exterior, black window caulk on Center street

Lab ID-Version 1: 12958579-1

Sample Layers	Asbestos Content
Black Caulk	ND
Sample Composite Homogeneity:	Good

Location: BE-WC-2C, Window caulk, building exterior, black window caulk on Center

street Lab ID-Version 1: 12958580-1

Sample Layers	Asbestos Content
Black Caulk	ND
Sample Composite Homogeneity:	Good

The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified.

Inhomogeneous samples are separated into homogeneous subsamples and analyzed individually. ND means no fibers were detected. When detected, the minimum detection and reporting limit is less than 1% unless point counting is performed. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.



Report for:

Mr. Basil Falcone **Enviro Nova** 235 Montgomery Street Suite 1105 San Francisco, CA 94104

Regarding: Project: 21-186; 2118 Milvia Street, Berkeley, CA

EML ID: 2709217

Approved by:

Dates of Analysis: Asbestos-EPÁ 1000 point count: 08-30-2021

Approved Signatory Amber Rutter

Service SOPs: Asbestos-EPA 1000 point count (EPA 40CFR App E to Sub E of Part 763 & EPA METHOD 600/R-93-116, SOP EM-AS-S-1262)

NVLAP Lab Code 500053-0

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. Due to the nature of the analyses performed, field blank correction of results is not applied. The results relate only to the samples as received and tested.

Eurofins EMLab P&K ("the Company") shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

4955 Yarrow Street, Arvada, CO 80002

(800) 651-4802 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021 Date of Receipt: 08-13-2021 Date of Report: 08-30-2021

ASBESTOS POINT COUNT REPORT

Location:	Drywall system, floo	3-DW-2 r 3, white drywall system	n on walls throughout
Total Points Counted:		1000	
Lab ID-Version‡:		13005847-1	
Sample Layers	Asbestos Type	Asbestos Points Counted	Asbestos Concentration (%)
Off-White Compound	Chrysotile	8	0.8
Layer Totals:		8	0.8
White Drywall with Off-White Joint Compound Composite	Chrysotile	0	< 0.1
Layer Totals:		0	NA

Comments: Composite asbestos content provided is only for Drywall/Joint compound. Composite content provided for this analysis has been performed by following the NESHAP guidelines. Asbestos was detected, but no points counted in composite.

Location:	Drywall system, floo	2-DW-1 r 2, white drywall systen	n on walls throughout
Total Points Counted:	, , , , , , , , , , , , , , , , , , ,	1000	V
Lab ID-Version‡:		13005848-1	
Sample Layers	Asbestos Type	Asbestos Points Counted	Asbestos Concentration (%)
Off-White Compound	Chrysotile	11	1.1
Layer Totals:		11	1.1

Location:	Drywall system, floo	2-DW-2 or 2, white drywall system	n on walls throughout
Total Points Counted:	,	1000	· ·
Lab ID-Version‡:		13005849-1	
Sample Layers	Asbestos Type	Asbestos Points Counted	Asbestos Concentration (%)
White Drywall with Off-White Joint Compound Composite	Chrysotile	1	0.1
Layer Totals:	·	1	0.1

Comments: Composite content provided for this analysis has been performed by following the NESHAP guidelines.

The analytical sensitivity is 1 asbestos point. The limit of detection is 1 asbestos point divided by the total number of points counted and multiplied by 100.

The results relate only to the items tested. Interpretation is left to the company and/or persons who conducted the field work. The test report shall not be reproduced except in full, without written approval of the laboratory. The report must not be used by the client to claim product certification, approval, or endorsement by any agency of the federal government.

All samples were received in acceptable condition unless otherwise noted. Eurofins EMLab P&K reserves the right to dispose of all samples after a period of thirty (30) days, according to all state and federal guidelines, unless otherwise specified. Floor tile samples may contain large amounts of interference material and it is recommended that the sample be analyzed by gravimetric point count analysis to lower the detection limit and to aid in asbestos identification.



ACM BULK SAMI 002709217

☐ Stop Analysis at First Positive

Analyze All Samples

* PLM Analysis

☐ Point Count Analysis (400-point)

Project Name/A	Address: 2118 Milvia	Street, Berke	eley CA		
Project #: 21-18	86	Sampled By	: Brenna Deane	Sam	pling Date 8/13/21
	To: AsbestosTEM		711	Turr	Around Time: 3-5 Days
EMAIL TO:	Basil Falcone bfalcone@environova.con	1			William Morales wmorales@environova.com

HM#	Material Description: ceiling tile
Sample ID	Sample Location & Material Location Quantity:
3-CT-1	Floor 3, rectangular white ceiling tile throughout
3-CT-2	Floor 3, rectangular white ceiling tile throughout
HM#	Material Description: vinyl baseboard
Sample ID	Sample Location & Material Location Quantity:
3-BB-1	Floor 3, blue vinyl baseboard + white/yellow mastic throughout
3-BB-2	Floor 3, blue vinyl baseboard + white/yellow mastic throughout
HM#	Material Description: carpet mastic
Sample ID	Sample Location & Material Location Quantity:
3-YCM-1	Floor 3, yellow mastic under brown carpet + gray pad
3-YCM-2	Floor 3, yellow mastic under brown carpet + gray pad
HM#	Material Description: drywall system
Sample ID	Sample Location & Material Location Quantity:
3-DW-1	Floor 3, white drywall system on walls throughout
3-DW-2	Floor 3, white drywall system on walls throughout
3-DW-3 ,	Floor 3, white drywall system on walls throughout
3-DW-4	Floor 3, white drywall system on walls throughout
3-DW-5	Floor 3, white drywall system on walls throughout
3-DW-6	Floor 3, white drywall system on walls throughout
3-DW-7	Floor 3, white drywall system on walls throughout

Received By:

Signature:

Date/Time:



ACM BULK SAM

* PLM Analysis



0027092

Stop	Analysis	at	First	Positive

Analyze All Samples

☐ Point Count Analysis (400-point)

Project Name/A	Address: 2118 Milvia	Street, Berkeley	CA		
Project #: 21-18	36	Sampled By: B	Brenna Deane	Sam	pling Date 8/13/21
Sample(s) Sent	To: AsbestosTEM			Turr	Around Time: 3-5 Days
EMAIL TO:	Basil Falcone		John Adams dams@environova.com		William Morales wmorales@environova.com

HM#	Material Description: cinderblock + stucco					
Sample ID	Sample Location & Material Location	Quantity				
3-CBW-1 ·	Floor 3, gray cinderblock wall + white stucco	inside				
3-CBW-2	Floor 3, gray cinderblock wall + white stucco					
3-CBW-3	Floor 3, gray cinderblock wall + white stucco	inside				
HM#	Material Description: roofing material					
Sample ID	Sample Location & Material Location	Quantity:				
R-A	Roof, gray + black sheet roofing material thro	oughout roof				
R-B	Roof, gray + black sheet roofing material thro	oughout roof				
R-C	Roof, gray + black sheet roofing material thro	oughout roof				
HM#	Material Description: perimeter seal					
Sample ID	Sample Location & Material Location	Quantity:				
R-D '	Roof, white seal material around perimeter of	roof				
R-E	Roof, white seal material around perimeter of roof					
R-F	Roof, white seal material around perimeter of roof					
HM#	Material Description: penetration mastic					
Sample ID	Sample Location & Material Location	Quantity:				
R-G	Roof, white/gray mastic at penetrations through	ghout				
R-H	Roof, white/gray mastic at penetrations through					
HM#	Material Description patching material					
Sample ID	Sample Location & Material Location	Quantity:				
R-J	Roof, gray/black material on patches throughout					
R-K	Roof, gray/black material on patches throughout					

Reling	uished
Rv.	

Received By:

Brenna Deane

Signature:

Signature:

Brenna Deane

Date/Time:

8/13/21

Date/Time:

8/13/20 1442



ACM BULK SAMP 002709217

* PLM Analysis

☐ Stop Analysis at First Positive

Analyze All Samples

☐ Point Count Analysis (400-point)

	Address: 2118 Milvia	Street, Berke	eley CA		
Project #: 21-186 Sampled By: Brenna Deane Sampling Date 8/13/21					
Sample(s) Sent	To: AsbestosTEM			Turn Around Time: 3-5 Days	
EMAIL TO:	Basil Falcone bfalcone@environova.com	ı .		William Morales wmorales@environova.com	

HM#	Material Description: exterior stucco			
Sample ID	Sample Location & Material Location	Quantity:		
R-M	Roof, gray stucco on building exterior			
R-N	Roof, gray stucco on building exterior			
R-O	Roof, gray stucco on building exterior			
BE-Stucco-1	Building Exterior, gray stucco throughout façade			
BE-Stucco-2	Building Exterior, gray stucco throughout façade			
BE-Stucco-3	Building Exterior, gray stucco throughout façade			
BE-Stucco-4	Building Exterior, gray stucco throughout façade			
HM#	Material Description: HVAC mastic			
Sample ID	Sample Location & Material Location Quanti			
R-Q	Roof, black/gray mastic on HVAC units			
R-R	Roof, black/gray mastic on HVAC units			
HM#	Material Description: vinyl floor tile			
Sample ID	Sample Location & Material Location Quantity:			
3-VFT-1	Floor 3, red & beige vinyl floor tile on kitchen flor			
3-VFT-2	Floor 3, red & beige vinyl floor tile on kitchen flor			
HM#	Material Description sink undercoat			
Sample ID	Sample Location & Material Location Quantity:			
3-Sink	Floor 3, white undercoat on kitchen sink			

Relinquished By:

Brenna Deane

Signature: Brenna Deane

Date/Time:

8/13/21

Received By:

Signature:

Date/Time:





ACM BULK SAMF 002709217

* PLM Analysis

☐ Stop Analysis at First Positive

Analyze All Samples

☐ Point Count Analysis (400-point)

Project Name/A	Address: 2118 Milvia	Street, Berkeley CA	
Project #: 21-186 Sampled By: Brenna Deane Sampling Date 8/13/21			
Sample(s) Sent	To: AsbestosTEM		Turn Around Time: 3-5 Days
EMAIL TO:	Basil Falcone		

HM#	Material Description: balcony flooring material			
Sample ID	Sample Location & Material Location Quantity:			
3B-Floor-1	Floor 3 Balcony, gray flooring material exteri	or		
3B-Floor-2	Floor 3 Balcony, gray flooring material exteri			
НМ#	Material Description: ceramic wall tile			
Sample ID	Sample Location & Material Location	Quantity:		
3-BWT-1W	Floor 3, pale pink ceramic tile on women's re-	stroom wall		
3-BWT-2W	Floor 3, pale pink ceramic tile on women's re-			
HM#	Material Description: ceramic floor tile			
Sample ID	Sample Location & Material Location	Quantity:		
3-BFT-1W	Floor 3, beige + white ceramic tile on women	's restroom floor		
3-BFT-2W	Floor 3, beige + white ceramic tile on women			
НМ#	Material Description: ceramic wall tile			
Sample ID	Sample Location & Material Location	Quantity:		
3-BWT-1M	Floor 3, pale blue ceramic tile on men's restro	om wall		
3-BWT-2M	Floor 3, pale blue ceramic tile on men's restro			
HM#	Material Description: ceramic floor tile			
Sample ID	Sample Location & Material Location	Quantity:		
3-BFT-1M	Floor 3, gray + white ceramic tile on men's re-	stroom floor		
3-BFT-2M	Floor 3, gray + white ceramic tile on men's re-	etroom floor		

Rei	ınq	uis	hed
Ru			

Brenna Deane

Signature:

Brenna Deane

Date/Time:

8/13/21

Received By: Signature:

4

Date/Time:

14412



ACM BULK SAM

* PLM Analysis

☐ Stop Analysis at First Positive

Analyze All Samples

☐ Point Count Analysis (400-point)

Project Name/A	ddress: 2118 Milvia	Street, Berkeley CA	
Project #: 21-18	Project #: 21-186 Sampled By: Brenna Deane Sampling Date 8/13/21		
	To: AsbestosTEM		Turn Around Time: 3-5 Days
EMAIL TO:	Basil Falcone bfalcone@environova.com	John Adams jadams@environova.com	

HM#	Material Description: mirror mastic			
Sample ID	Sample Location & Material Location	Quantity:		
3-Mirror-1	Floor 3, black mastic behind mirrors			
3-Mirror-2	Floor 3, black mastic behind mirrors			
HM#	Material Description: HVAC duct mastic			
Sample ID	Sample Location & Material Location	Quantity:		
HVAC-1	Beige mastic on HVAC ducts above ceiling thr	oughout all floors		
HVAC-2	Beige mastic on HVAC ducts above ceiling thr			
HM#	Material Description: drywall system			
Sample ID	Sample Location & Material Location	Quantity:		
2-DW-1	Floor 2, white drywall system on walls throughout			
2-DW-2	Floor 2, white drywall system on walls throughout			
2-DW-3	Floor 2, white drywall system on walls through			
2-DW-4	Floor 2, white drywall system on walls through			
2-DW-5	Floor 2, white drywall system on walls through			
2-DW-6	Floor 2, white drywall system on walls through			
2-DW-7	Floor 2, white drywall system on walls through			
HM#	Material Description vinyl baseboard			
Sample ID	Sample Location & Material Location Quantity:			
2-BB-1	Floor 2, blue vinyl baseboard yellow mastic on walls			
2-BB-2	Floor 2, blue vinyl baseboard yellow mastic on walls			

Relinquished By:	Brenna Deane	Signature:	Brenna Deane	Date/Time:	8/13/21	
Received By:	27	Signature:	97	Date/Time:	8/13/27 /	4



ACM BULK SAN



* PLM Analysis

☐ Stop Analysis at First Positive

☐ Point Count Analysis (400-point)

Project Name//	Address: 2118 Milvia	Street, Berke	ley CA		
Project #: 21-1	86	Sampled By	: Brenna Deane	Sam	pling Date 8/13/21
	To: AsbestosTEM			Turn	Around Time: 3-5 Days
EMAIL TO:	Basil Falcone		John Adams		William Morales wmorales@environova.com

HM#	Material Description: carpet mastic			
Sample ID	Sample Location & Material Location	Quantity:		
2-YCM-1	Floor 2, yellow mastic under brown carpet -	gray pad throughout		
2-YCM-2	Floor 2, yellow mastic under brown carpet + gray pad throughout			
HM#	Material Description: ceramic wall tile			
Sample ID	Sample Location & Material Location	Quantity:		
2-BWT-1W	Floor 2, pale pink ceramic tile on women's	restroom wall		
2-BWT-2W	Floor 2, pale pink ceramic tile on women's	restroom wall		
HM#	Material Description: ceramic floor tile			
Sample ID	Sample Location & Material Location	Quantity:		
2-BFT-1W	Floor 2, beige + white ceramic tile on wome	en's restroom floor		
2-BFT-2W	Floor 2, beige + white ceramic tile on wome	en's restroom floor		
HM#	Material Description: ceramic wall tile			
Sample ID	Sample Location & Material Location	Quantity:		
2-BWT-1M ·	Floor 2, cream ceramic tile on men's restroo	m wall		
2-BWT-2M .	Floor 2, cream ceramic tile on men's restroo	m wall		
HM#	Material Description: ceramic wall tile			
Sample ID	Sample Location & Material Location	Quantity:		
2-BFT-1M	Floor 2, gray + white ceramic tile on men's	restroom floor		
2-BFT-2M	Floor 2, gray + white ceramic tile on men's restroom floor			

Relinquished

Brenna Deane

Signature:

Brenna Deane

Date/Time:

8/13/21

Received By:

Signature:

Date/Time:



Project Name/Address: 2118 Milvia Street, Berkeley CA

235 Montgomery Street, Suite 1105 San Francisco, CA 94104 Tel 415.883.7575 Fax 415.883.7475

HM#

Sample ID 2-CT-1

2-CT-2

ACM BULK SAN

* PLM Analysis

☐ Stop Analysis at First Positive

Analyze All Samples

□ Point Count Analysis (400-point)

AN	002709217
ive	

Quantity:

8/13/21

			ed By: Brenna Deane	Sampling Date 8/13/21	
Sample(s) Sen				Turn Around Time: 3-5 Days	
EMAIL TO:	Basil F	il Falcone		William Morales wmorales@environova.com	
НМ#		Material Desc			
Sample ID		Sample Locat	tion & Material Location	Quantity:	
2-BVFT-1	4.	Floor 2, be	ige vinyl floor tile + bla	ack mastic in kitchen / lounge area	
2-BVFT-2				ack mastic in kitchen / lounge area	
HM#			cription: vinyl floor tile		
Sample ID		Sample Locat	tion & Material Location	Quantity:	
2-GVFT-1	- 41	Floor 2, gra	or 2, gray vinyl floor tile + yellow mastic in kitchen / lounge area		
2-GVFT-2	- 4	Floor 2, gray vinyl floor tile + yellow mastic in kitchen / lounge area			
HM#			ription: cinderblock wa	all	
Sample ID	*	Sample Locat	tion & Material Location	Quantity:	
2-CBW-1		Floor 2, gra	ay painted cinderblock v	walls throughout	
2-CBW-2		Floor 2, gray painted cinderblock walls throughout			
HM#		Material Desci		ird	
Sample ID		Sample Locati	tion & Material Location	Quantity:	
2-TBB-1	10	Floor 2, tan	tall vinyl baseboard +	yellow/brown mastic on walls	
2-TBB-2 Floor 2, ta			tall vinyl baseboard + yellow/brown mastic on walls		

ceiling tile

Relinquished By:	Brenna Deane	Signature:	Brenna Deane	Date/Tim
Dy				

Material Description

Received By: Date/Tin

Sample Location & Material Location

Floor 2, white ceiling tiles throughout

Floor 2, white ceiling tiles throughout



ACM BULK SAN

* PLM Analysis

☐ Stop Analysis at First Positive

Analyze All Samples

☐ Point Count Analysis (400-point)

Project Name/Address: 2118 Milvia Street, Berkeley CA					
Project #: 21-186		Sampled By: Brenna Deane	Sampling Date 8/13/21		
Sample(s) Sent To: AsbestosTEM			Turn Around Time: 3-5 Days		
EMAIL TO:	☐Basil Falcone bfalcone@environova.com	John Adams jadams@environova.com	William Morales wmorales@environova.com		

HM#	Material Description: sink undercoat				
Sample ID	Sample Location & Material Location	Quantity:			
2-Sink	Floor 2, black undercoat on break area sink				
HM#	Material Description: drywall system				
Sample ID	Sample Location & Material Location	Quantity:			
1-DW-1	Floor 1, white drywall system on walls throu	aghout			
1-DW-2 .	Floor 1, white drywall system on walls throu				
1-DW-3	Floor 1, white drywall system on walls throu	~			
1-DW-4	Floor 1, white drywall system on walls throu				
1-DW-5	Floor 1, white drywall system on walls throu				
1-DW-6	Floor 1, white drywall system on walls throughout				
1-DW-7	Floor 1, white drywall system on walls throughout				
HM#	Material Description: carpet square mastic				
Sample ID	Sample Location & Material Location	Quantity:			
1-CSM-1	Floor 1, yellow + black mastic under blue ca	rpet squares in entry			
1-CSM-2	Floor 1, yellow + black mastic under blue carpet squares in ent				
HM#	Material Description carpet mastic				
Sample ID	Sample Location & Material Location	Quantity:			
1-CM-1	Floor 1, yellow + black mastic under brown roll	out carpet in offices			
1-CM-2	Floor 1, yellow + black mastic under brown roll out carpet in offices				

Re	linq	uis	hed
Rv			

By: Received By:

Brenna Deane

Signature:

Brenna Deane

Date/Time:

8/13/21

Signature:

Date/Time:



ACM BULK SAI

* PLM Analysis



00270921

Stop Analysis	at First	Positivo
---------------	----------	----------

Analyze All Samples

☐ Point Count Analysis (400-point)

	Address: 2118 Milvia	Street, Berke	ley CA		
Project #: 21-186 Sampled By		: Brenna Deane	Sampling Date 8/13/21		
	To: AsbestosTEM			Turr	Around Time: 3-5 Days
EMAIL TO:	Basil Falcone				William Morales wmorales@environova.com

HM#	Material Description: floor mastic					
Sample ID	Sample Location & Material Location	Quantity:				
1-ECM-1	Floor 1, black mastic on electrical closet floor (ne	ext to elevator & under tile)				
1-ECM-2	Floor 1, black mastic on electrical closet floor (next to elevator & under tile)					
HM#	Material Description: ceramic wall tile					
Sample ID	Sample Location & Material Location	Quantity:				
1-BWT-1W	Floor 1, pale pink ceramic tile on women's restro	om wall				
1-BWT-2W	Floor 1, pale pink ceramic tile on women's restro					
HM#	Material Description: ceramic floor tile					
Sample ID	Sample Location & Material Location	Quantity:				
1-BFT-1W	Floor 1, beige + white ceramic tile on women's restroom floor					
1-BFT-2W	Floor 1, beige + white ceramic tile on women's restroom floor					
HM#	Material Description: ceramic wall tile					
Sample ID	Sample Location & Material Location	Quantity:				
1-BWT-1M ·	Floor 1, cream ceramic tile on men's restroom wa	11				
1-BWT-2M	Floor 1, cream ceramic tile on men's restroom wa	11				
HM#	Material Description: ceramic wall tile					
Sample ID	Sample Location & Material Location	Quantity:				
1-BFT-1M	Floor 1, gray + white ceramic tile on men's restroom floor					
1-BFT-2M	Floor 1, gray + white ceramic tile on men's restroom floor					

Relinquished

By:

Brenna Deane Signature:

Brenna Deane

Date/Time:

8/13/21

Received By:

Signature:

Date/Time:

8 3 27 1442



ACM BULK SAN

☐ Stop Analysis at First Positive

Analyze All Samples

* PLM Analysis

☐ Point Count Analysis (400-point)

Project Name/A	Address: 2118 Milvia	Street, Berke	ley CA		
Project #: 21-186 Sampled F		Sampled By	: Brenna Deane	Sampling Date 8/13/21	
	To: AsbestosTEM			Turr	Around Time: 3-5 Days
EMAIL TO:	Basil Falcone		John Adams jadams@environova.com		William Morales wmorales@environova.com

HM#	Material Description: vinyl baseboard			
Sample ID	Sample Location & Material Location Quantity			
1-TBB-1 ·	Floor 1, tan vinyl baseboard + yellow mast	ic on entry walls		
1-TBB-2	Floor 1, tan vinyl baseboard + yellow mast	ic on entry walls		
HM#	Material Description: vinyl baseboard			
Sample ID	Sample Location & Material Location	Quantity		
1-GBB-1	Floor 1, gray vinyl baseboard + yellow mas	stic on office walls		
1-GBB-2	Floor 1, gray vinyl baseboard + yellow mas	stic on office walls		
HM#	Material Description: ceiling tile			
Sample ID	Sample Location & Material Location	Quantity:		
1-SCT-1	Floor 1, square ceiling tiles throughout entr	v ceiling		
1-SCT-2	Floor 1, square ceiling tiles throughout entr			
HM#	Material Description: ceiling tile			
Sample ID	Sample Location & Material Location	Quantity:		
1-RCT-1	Floor 1, rectangular ceiling tiles throughout	office ceiling		
1-RCT-2	Floor 1, rectangular ceiling tiles throughout			
HM#	Material Description cinderblock walls			
Sample ID	Sample Location & Material Location	Quantity:		
1-CBW-1	Floor 1, gray cinderblock walls	170		
1-CBW-2	Floor 1, gray cinderblock walls			

Relinq	uished
Rv.	

Received By:

Brenna Deane

Signature:

Brenna Deane

Date/Time:

8/13/21

Signature:

Date/Time:





* PLM Analysis

☐ Stop Analysis at First Positive

Analyze All Samples

☐ Point Count Analysis (400-point)

Project Name/Address: 2118 Milvia Street, Berkeley CA					
Project #: 21-186		Sampled By: Brenna Deane	Sampling Date 8/13/21		
Sample(s) Sent To: AsbestosTEM			Turn Around Time: 3-5 Days		
EMAIL TO:	Basil Falcone		William Morales wmorales@environova.com		

HM#	Material Description vinyl floor tile	
Sample ID	Sample Location & Material Location	Quantity:
1-VFT-1 (Floor 1, beige vinyl floor tile + black/yellov	w mastic in hall sink room
1-VFT-2	Floor 1, beige vinyl floor tile + black/yellov	
HM#	Material Description vinyl baseboard	
Sample ID	Sample Location & Material Location	Quantity:
1-BBB-1	Floor 1, brown/orange vinyl baseboard + ye	ellow mastic in electrical closet
1-BBB-2	Floor 1, brown/orange vinyl baseboard + ye	
HM#	Material Description window caulk	
Sample ID	Sample Location & Material Location	Quantity:
BE-WC-1M	Building Exterior, white window caulk on M	Milvia Street
BE-WC-2M	Building Exterior, white window caulk on M	
HM#	Material Description window caulk	
Sample ID	Sample Location & Material Location	Quantity:
BE-WC-1C	Building Exterior, black window caulk on C	enter Street
BE-WC-2C	Building Exterior, black window caulk on C	Center Street
HM#	Material Description	
Sample ID	Sample Location & Material Location	Quantity:
Relinquished I	Brenna Signature: Zagana Daga Date	/Time: 8/13/21

Reling	uished
Rv.	

Received By:

Brenna Deane

Signature:

Signature: Brenna Deane

Date/Time:

8/13/21

Date/Time:



Report for:

Mr. Basil Falcone Enviro Nova 235 Montgomery Street Suite 1105 San Francisco, CA 94104

Regarding: Project: 21-186; 2118 Milvia Street, Berkeley, CA

EML ID: 2709197

Approved by:

Laboratory Manager

Danny Li

Dates of Analysis: Lead - Flame AA: 08-17-2021

Service SOPs: Lead - Flame AA (EM-BC-S-8443) AIHA-LAP, LLC accredited service, Lab ID #178697

All samples were received in acceptable condition unless noted in the Report Comments portion in the body of the report. Due to the nature of the analyses performed, field blank correction of results is not applied. The results relate only to the samples as received and tested. Sample size, as it relates to Wipe samples only, is supplied by the client.

Eurofins EMLab P&K ("the Company") shall have no liability to the client or the client's customer with respect to decisions or recommendations made, actions taken or courses of conduct implemented by either the client or the client's customer as a result of or based upon the Test Results. In no event shall the Company be liable to the client with respect to the Test Results except for the Company's own willful misconduct or gross negligence nor shall the Company be liable for incidental or consequential damages or lost profits or revenues to the fullest extent such liability may be disclaimed by law, even if the Company has been advised of the possibility of such damages, lost profits or lost revenues. In no event shall the Company's liability with respect to the Test Results exceed the amount paid to the Company by the client therefor.

Eurofins EMLab P&K's LabServe® reporting system includes automated fail-safes to ensure that all AIHA-LAP, LLC quality requirements are met and notifications are added to reports when any quality steps remain pending.

EMLab ID: 2709197, Page 2 of 7

17461 Derian Ave, Suite 100, Irvine, CA 92614

(866) 888-6653 Fax (623) 780-7695 www.emlab.com

Date of Sampling: 08-13-2021 Client: Enviro Nova C/O: Mr. Basil Falcone Date of Receipt: 08-13-2021 Re: 21-186; 2118 Milvia Street, Berkeley, CA Date of Report: 08-17-2021

LEAD: FLAME ATOMIC ABSORPTION SPECTROMETRY

Location:	3-BFT-LW: Beige, white ceramic tile, floor 3, women's restroom floor	3-BWT-LW: Pale pink ceramic tile, floor 3, women' s restroom wall	3-BFT-LM: Gray, white ceramic tile, floor 3, men's restroom floor	3-BWT-LM: Pale blue ceramic tile, floor 3, men's restroom wall
Comments (see below)	None	None	None	None
Lab ID-Version‡:	12958591-1	12958592-1	12958593-1	12958594-1
Analysis Date:	08/17/2021	08/17/2021	08/17/2021	08/17/2021
Sample type	Bulk sample	Bulk sample	Bulk sample	Bulk sample
Method*	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified
† Method Reporting Limit	38 ppm	37 ppm	40 ppm	40 ppm
Sample size	0.2613 grams	0.2703 grams	0.2528 grams	0.2473 grams
§Total Lead Result	< 38 ppm	53 ppm	< 40 ppm	46 ppm

Comments:

Sample results have not been corrected for blank values.

Bulk samples are not covered under the AIHA-LAP, LLC service accreditation.

- *Sample preparation and analytical methods are based upon NIOSH 7082 and EPA 7000B.
- † The Method Reporting Limit is the minimum concentration of Lead that the laboratory can confidently detect in the sample.
- § Total Lead Result has been rounded to two significant figures to reflect analytical precision.
- ‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab ID: 2709197, Page 3 of 7

17461 Derian Ave, Suite 100, Irvine, CA 92614 (866) 888-6653 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova
C/O: Mr. Basil Falcone
Date of Sampling: 08-13-2021
Date of Receipt: 08-13-2021
Date of Report: 08-17-2021

LEAD: FLAME ATOMIC ABSORPTION SPECTROMETRY

Location:	2-BFT-LW: Beige, pink ceramic tile, floor 2, women' s restroom floor	2-BWT-LW: Pale pink ceramic tile, floor 2, women's restroom wall		2-BWT-LM: Cream ceramic tile, floor 2, men's restroom wall
Comments (see below)	None	None	None	None
Lab ID-Version‡:	12958595-1	12958596-1	12958597-1	12958598-1
Analysis Date:	08/17/2021	08/17/2021	08/17/2021	08/17/2021
Sample type	Bulk sample	Bulk sample	Bulk sample	Bulk sample
Method*	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified
† Method Reporting Limit	36 ppm	39 ppm	39 ppm	39 ppm
Sample size	0.2748 grams	0.2541 grams	0.2591 grams	0.2565 grams
§Total Lead Result	< 36 ppm	< 39 ppm	< 39 ppm	< 39 ppm

Comments:

Sample results have not been corrected for blank values.

Bulk samples are not covered under the AIHA-LAP, LLC service accreditation.

- *Sample preparation and analytical methods are based upon NIOSH 7082 and EPA 7000B.
- † The Method Reporting Limit is the minimum concentration of Lead that the laboratory can confidently detect in the sample.
- § Total Lead Result has been rounded to two significant figures to reflect analytical precision.
- \ddagger A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab ID: 2709197, Page 4 of 7

17461 Derian Ave, Suite 100, Irvine, CA 92614

(866) 888-6653 Fax (623) 780-7695 www.emlab.com

Date of Sampling: 08-13-2021 Client: Enviro Nova C/O: Mr. Basil Falcone Date of Receipt: 08-13-2021 Re: 21-186; 2118 Milvia Street, Berkeley, CA Date of Report: 08-17-2021

LEAD: FLAME ATOMIC ABSORPTION SPECTROMETRY

Location:	1-BFT-LW: Beige, pink ceramic tile, floor 1, women' s restroom floor	1-BWT-LW: Pale pink ceramic tile, floor 1, women' s restroom wall		1-BWT-LM: Cream ceramic tile, floor 1, men's restroom wall
Comments (see below)	None	None	None	None
Lab ID-Version‡:	12958599-1	12958600-1	12958601-1	12958602-1
Analysis Date:	08/17/2021	08/17/2021	08/17/2021	08/17/2021
Sample type	Bulk sample	Bulk sample	Bulk sample	Bulk sample
Method*	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified
† Method Reporting Limit	38 ppm	37 ppm	40 ppm	40 ppm
Sample size	0.2609 grams	0.2723 grams	0.2502 grams	0.2506 grams
§Total Lead Result	< 38 ppm	< 37 ppm	60 ppm	< 40 ppm

Comments:

Sample results have not been corrected for blank values.

Bulk samples are not covered under the AIHA-LAP, LLC service accreditation.

- *Sample preparation and analytical methods are based upon NIOSH 7082 and EPA 7000B.
- † The Method Reporting Limit is the minimum concentration of Lead that the laboratory can confidently detect in the sample.
- § Total Lead Result has been rounded to two significant figures to reflect analytical precision.
- ‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

EMLab ID: 2709197, Page 5 of 7

17461 Derian Ave, Suite 100, Irvine, CA 92614

(866) 888-6653 Fax (623) 780-7695 www.emlab.com

Date of Sampling: 08-13-2021 Client: Enviro Nova C/O: Mr. Basil Falcone Date of Receipt: 08-13-2021 Re: 21-186; 2118 Milvia Street, Berkeley, CA Date of Report: 08-17-2021

LEAD: FLAME ATOMIC ABSORPTION SPECTROMETRY

Location:	L-R:	3B-Rail-P:	3-Yellow-P:	3-White-P:
	Beige paint, roof,	Brown paint, floor	Yellow paint, floor	White paint, floor
	building exterior	3	3, accent walls	3,
	walls	balcony, railing		walls throughout
Comments (see below)	None	None	None	None
Lab ID-Version‡:	12958603-1	12958604-1	12958605-1	12958606-1
Analysis Date:	08/17/2021	08/17/2021	08/17/2021	08/17/2021
Sample type	Paint Chip sample	Paint Chip sample	Paint Chip sample	Paint Chip sample
Sample type Method*	Paint Chip sample NIOSH 7082 & EPA 7000B modified	Paint Chip sample NIOSH 7082 & EPA 7000B modified	Paint Chip sample NIOSH 7082 & EPA 7000B modified	Paint Chip sample NIOSH 7082 & EPA 7000B modified
* **	NIOSH 7082 & EPA			
Method*	NIOSH 7082 & EPA 7000B modified			

Comments:

Sample results have not been corrected for blank values.

Bulk samples are not covered under the AIHA-LAP, LLC service accreditation.

- *Sample preparation and analytical methods are based upon NIOSH 7082 and EPA 7000B.
- † The Method Reporting Limit is the minimum concentration of Lead that the laboratory can confidently detect in the sample.
- § Total Lead Result has been rounded to two significant figures to reflect analytical precision.
- ‡ A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

17461 Derian Ave, Suite 100, Irvine, CA 92614 (866) 888-6653 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

LEAD: FLAME ATOMIC ABSORPTION SPECTROMETRY

Location:	2-White-P: White paint, floor 2, walls throughout	2-Yellow-P: Yellow paint, floor 2, accent walls	1-RedBeam-P: Red paint, floor 1, painted beam at entry	1-Yellow-P: Yellow paint, floor 1, accent walls
Comments (see below)	None	None	None	None
Lab ID-Version‡:	12958607-1	12958608-1	12958609-1	12958610-1
Analysis Date:	08/17/2021	08/17/2021	08/17/2021	08/17/2021
Sample type	Paint Chip sample	Paint Chip sample	Paint Chip sample	Paint Chip sample
Sample type Method*	Paint Chip sample NIOSH 7082 & EPA 7000B modified	Paint Chip sample NIOSH 7082 & EPA 7000B modified	Paint Chip sample NIOSH 7082 & EPA 7000B modified	Paint Chip sample NIOSH 7082 & EPA 7000B modified
* **	NIOSH 7082 & EPA	NIOSH 7082 & EPA	NIOSH 7082 & EPA	NIOSH 7082 & EPA
Method*	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified

Comments:

Sample results have not been corrected for blank values.

Bulk samples are not covered under the AIHA-LAP, LLC service accreditation.

- *Sample preparation and analytical methods are based upon NIOSH 7082 and EPA 7000B.
- † The Method Reporting Limit is the minimum concentration of Lead that the laboratory can confidently detect in the sample.
- § Total Lead Result has been rounded to two significant figures to reflect analytical precision.
- \ddagger A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

17461 Derian Ave, Suite 100, Irvine, CA 92614 (866) 888-6653 Fax (623) 780-7695 www.emlab.com

Client: Enviro Nova

C/O: Mr. Basil Falcone

Re: 21-186; 2118 Milvia Street, Berkeley, CA

Date of Sampling: 08-13-2021

Date of Receipt: 08-13-2021

Date of Report: 08-17-2021

LEAD: FLAME ATOMIC ABSORPTION SPECTROMETRY

Location:	1-White-P: White paint, floor 1, walls throughout	1-Gray-P: Gray paint, floor 1, entry desks, sheetrock support	BE-Beige-P: Beige paint, building exterior, walls on Milvia St	BE-White-P: White paint, building exterior, entry and walls on Center St
Comments (see below)	A	A	A	A
Lab ID-Version‡:	12958611-1	12958612-1	12958613-1	12958614-1
Analysis Date:	08/17/2021	08/17/2021	08/17/2021	08/17/2021
Sample type	Paint Chip sample	Paint Chip sample	Paint Chip sample	Paint Chip sample
Method*	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified	NIOSH 7082 & EPA 7000B modified
† Method Reporting Limit	40 ppm	38 ppm	40 ppm	38 ppm
Sample size	0.2517 grams	0.2628 grams	0.2497 grams	0.2598 grams
§Total Lead Result	< 40 ppm	< 38 ppm	160 ppm	230 ppm

Comments: A) The relative percent difference of the matrix duplicate pair was above control limits. The laboratory control sample and matrix blank were both within control limits and validated the batch.

Sample results have not been corrected for blank values.

Bulk samples are not covered under the AIHA-LAP, LLC service accreditation.

- † The Method Reporting Limit is the minimum concentration of Lead that the laboratory can confidently detect in the sample.
- § Total Lead Result has been rounded to two significant figures to reflect analytical precision.
- \ddagger A "Version" indicated by -"x" after the Lab ID# with a value greater than 1 indicates a sample with amended data. The revision number is reflected by the value of "x".

^{*}Sample preparation and analytical methods are based upon NIOSH 7082 and EPA 7000B.



* Lead Analysis - Flame AA (EPA 7420)

I E A D BIII K	D.4	
LEAD BULK	DA	002709197

PAGE _ OF _

235 Montgomery Street, Suite 1105 San Francisco, CA 94104 Tel 415.883.7575 Fax 415.883.7475

Sample ID	Material Description and Sample Location								
L-R	Color:	Beige	Material:	Paint	Composite Sample:	Y/N:			
	Sample Lo	ocation: Roof, Build	ing Exterior V	Walls			1		
3B-Rail-P	Color:	Brown	Material:	Paint	Composite Sample:	Y/N:			
	Sample Lo	ocation: Floor 3 Bale	cony, Railing						
3-BFT-LW	Color:	Beige, white	Material:	Ceramic tile_	Composite Sample:	Y/N:			
	Sample Lo	cation: Floor 3, Wo	men's restroc	om floor					
3-BWT-LW	Color:	Pale pink	Material:	Ceramic tile	Composite Sample:	Y/N:			
	Sample Lo	cation: Floor 3, wo	men's restroo	m wall					
3-BFT-LM	Color:	Gray, white	Material:	Ceramic tile	Composite Sample:	Y/N:			
	Sample Lo	cation: Floor 3, men	n's restroom f	loor			1		
3-BWT-LM	Color:	Pale blue	Material:	Ceramic tile ,	Composite Sample:	Y/N:			
	Sample Lo	cation: Floor 3, mer	n's restroom v	vall			-		
3-Yellow-P	Color:	Yellow	Material:	Paint .	Composite Sample:	Y/N:			
	Sample Loc	cation: Floor 3, acco	ent walls				-		



* Lead Analysis
- Flame AA (EPA 7420)



PAGE __ OF __

235 Montgomery Street, Suite 1105 San Francisco, CA 94104 Tel 415.883.7575 Fax 415.883.7475

Quant			le Location	and Samp	l Description	Materia	Sample ID
	Y/N:	Composite Sample:	paint	Material:	white	Color:	3-White-P
				lls throughout	cation: Floor 3, wa	Sample Lo	
	Y/N:	Composite Sample:	Ceramic tile	Material:	Beige, pink	Color:	2-BFT-LW
			n floor	men's restroo	cation: Floor 2, wo	Sample Loc	
	Y/N:	Composite Sample:	Ceramic tile	Material:	Pale pink	Color:	2-BWT-LW
			m wall	omen's restroo	cation: Floor 2, wo	Sample Loc	
	Y/N:	Composite Sample:	Ceramic tile	Material:	Gray, blue	Color:	2-BFT-LM
			oor	n's restroom f	cation: Floor 2, me	Sample Loc	
	Y/N:	Composite Sample:	Ceramic tile	Material:	Cream	Color:	2-BWT-LM
			rall	n's restroom w	cation: Floor 2, me	Sample Loc	
	Y/N:	Composite Sample:	Paint	Material:	White	Color:	2-White-P
				ls throughout	cation: Floor 2, wal	Sample Loc	
_	Y/N:	Composite Sample:	Paint .	Material:	Yellow	Color:	2-Yellow-P
_				ent walls	ation: Floor 2, acco	Sample Loc	



LEAD BULK D 002709197

* Lead Analysis - Flame AA (EPA 7420)

PAGE _ OF _

		ΓΟ: ⊠ Basil F	Willian	n Morales wmor	☑ John Adams jad ales@environova.com	anisaschvironov	acom
Sample ID	Materia	I Description	and Samp	ole Location			Quantit
1-BFT-LW	Color:	Beige, pink	Material:	Ceramicatile	Composite Sample:	Y/N:	
	Sample Lo	ocation: Floor 1, wo	omen's restroc	om floor		1	7
I-BWT-LW	Color:	Pale pink	Material:	Ceramic tile	Composite Sample:	Y/N:	
	Sample Lo	ocation: Floor 1, w	omen's restro	om wall			
1-BFT-LM	Color:	Gray, blue	Material:	Ceramic tile	Composite Sample:	Y/N:	
	Sample Lo	cation: Floor 1, me	en's restroom	floor			
1-BWT-LM	Color:	Cream	Material:	Ceramic tile	Composite Sample:	Y/N:	
	Sample Lo	cation: Floor 1, me	n's restroom	wall			
1-RedBeam-P	Color:	Red	Material:	Paint	Composite Sample:	Y/N:	
	Sample Lo	cation: Floor 1, pai	nted beams at	entry			1
l-Yellow-P	Color:	Yellow	Material:	Paint ·	Composite Sample:	Y/N:	
	Sample Loc	cation: Floor 1, acc	ent walls				-
1-White-P	Color:	White	Material:	Paint	Composite Sample:	Y/N:	
	Sample Loc	cation: Floor 1, wal	lls throughout				1



Project Name/Address: 2118 Milvia Street, Berkeley CA

LEAD BULK DA 002709197

002700407

* Lead Analysis - Flame AA (EPA 7420)

PAGE	OF

235 Montgomery Street, Suite 1105 San Francisco, CA 94104 Tel 415.883.7575 Fax 415.883.7475

Sample ID	Material Description and Sample Location												
1-Gray-P	Color:	Gray	Material:	paint	Composite Sample:	Y/N:							
	Sample Location: Floor 1, Entry Desks (sheetrock support)												
BE-Beige-P	Color:	Beige	Material:	Paint	Composite Sample:	Y/N:							
	Sample Location: Building Exterior, Walls on Milvia St												
BE-White-P	Color:	White	Material:	Paint	Composite Sample:	Y/N;	1						
	Sample Location: Building Exterior, Entry & Walls on Center St												
	Color:		Material:		Composite Sample:	Y/N:							
	Sample Location:												
	Color:		Material:		Composite Sample:	Y/N:							
	Sample Location:												
	Color:	1	Material:		Composite Sample:	Y/N:							
	Sample Loc	cation:											
	Color:		Material:		Composite Sample:	Y/N:							
		cation:					4						



McCampbell Analytical, Inc.

"When Quality Counts"

Analytical Report

WorkOrder: 2108723

Report Created for: EnviroNova

1116 S Amphlett Blvd; Suite 1

San Mateo, CA 94402

Project Contact: Basil Falcone

Project P.O.:

Project: 21-186; 2118 Milvia Street, Berkely CA

Project Received: 08/13/2021

Analytical Report reviewed & approved for release on 08/23/2021 by:

Yen Cao

Project Manager

The report shall not be reproduced except in full, without the written approval of the laboratory. The analytical results relate only to the items tested. Results reported conform to the most current NELAP standards, where applicable, unless otherwise stated in a case narrative.



1534 Willow Pass Rd. Pittsburg, CA 94565 ♦ TEL: (877) 252-9262 ♦ FAX: (925) 252-9269 ♦ www.mccampbell.com

CA ELAP 1644 ♦ NELAP 4033 ORELAP

Glossary of Terms & Qualifier Definitions

Client: EnviroNova

Project: 21-186; 2118 Milvia Street, Berkely CA

WorkOrder: 2108723

Glossary Abbreviation

%D Serial Dilution Percent Difference

95% Interval 95% Confident Interval

CPT Consumer Product Testing not NELAP Accredited

DF Dilution Factor

DI WET (DISTLC) Waste Extraction Test using DI water

DISS Dissolved (direct analysis of 0.45 µm filtered and acidified water sample)

DLT Dilution Test (Serial Dilution)

DUP Duplicate

EDL Estimated Detection Limit

ERS External reference sample. Second source calibration verification.

ITEF International Toxicity Equivalence Factor

LCS Laboratory Control Sample
LQL Lowest Quantitation Level

MB Method Blank

MB % Rec % Recovery of Surrogate in Method Blank, if applicable

MDL Method Detection Limit

ML Minimum Level of Quantitation

MS Matrix Spike

MSD Matrix Spike Duplicate

N/A Not Applicable

ND Not detected at or above the indicated MDL or RL

NR Data Not Reported due to matrix interference or insufficient sample amount.

PDS Post Digestion Spike

PDSD Post Digestion Spike Duplicate

PF Prep Factor

RD Relative Difference

RL Reporting Limit (The RL is the lowest calibration standard in a multipoint calibration.)

RPD Relative Percent Deviation
RRT Relative Retention Time

SPK Val Spike Value

SPKRef Val Spike Reference Value

SPLP Synthetic Precipitation Leachate Procedure

ST Sorbent Tube

TCLP Toxicity Characteristic Leachate Procedure

TEQ Toxicity Equivalents

TZA TimeZone Net Adjustment for sample collected outside of MAI's UTC.

WET (STLC) Waste Extraction Test (Soluble Threshold Limit Concentration)

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Toll Free Telephone: (877) 252-9262 / Fax: (925) 252-9269 http://www.mccampbell.com / E-mail: main@mccampbell.com

Glossary of Terms & Qualifier Definitions

Client: EnviroNova

Project: 21-186; 2118 Milvia Street, Berkely CA

WorkOrder: 2108723

Analytical Qualifiers

A The reported value is determined using a "single point" calibration by GC-ECD as allowed by the method.

S Surrogate recovery outside accepted recovery limits.

a4 Reporting limits raised due to the sample's matrix prohibiting a full volume extraction.

c1 Surrogate recovery outside of the control limits due to the dilution of the sample.

h4 Sulfuric acid permanganate (EPA 3665) cleanup.



Analytical Report

Client: EnviroNova WorkOrder: 2108723

Date Received: 08/13/2021 16:22 Extraction Method: SW3550B/3630C

Date Prepared: 08/13/2021 **Analytical Method:** SW8082 **Project:** 21-186; 2118 Milvia Street, Berkely CA Unit: mg/kg

Polychlorinated Biphenyls (PCBs) Aroclors w/ Column S	tyle Clean-up

Client ID	Lab ID	Matrix	Date Coll	lected	Instrument	Batch ID
BE-Wcaulk-1M	2108723-001	A Caulk	08/13/2021	13:06	GC22 08192146.D	227645
Analytes	Result	<u>Qualifiers</u>	<u>RL</u>	<u>DF</u>		Date Analyzed
Aroclor1016	ND		250	500		08/19/2021 21:41
Aroclor1221	ND		250	500		08/19/2021 21:41
Aroclor1232	ND		250	500		08/19/2021 21:41
Aroclor1242	ND		250	500		08/19/2021 21:41
Aroclor1248	ND		250	500		08/19/2021 21:41
Aroclor1254	1600	Α	250	500		08/19/2021 21:41
Aroclor1260	ND		250	500		08/19/2021 21:41
PCBs, total	1600		250	500		08/19/2021 21:41
Surrogates	REC (%)	<u>Qualifiers</u>	<u>Limits</u>			
Decachlorobiphenyl	208	S	70-130			08/19/2021 21:41

Analyst(s): CK Analytical Comments: a4,c1,h4

Client ID	Lab ID	Matrix	Date Coll	lected	Instrument	Batch ID
BE-Wcaulk-1C	2108723-002A	Caulk	08/13/2021	13:15	GC22 08182114.D	227645
Analytes	Result	Qualifiers	<u>RL</u>	<u>DF</u>		Date Analyzed
Aroclor1016	ND		250	500		08/18/2021 14:57
Aroclor1221	ND		250	500		08/18/2021 14:57
Aroclor1232	ND		250	500		08/18/2021 14:57
Aroclor1242	ND		250	500		08/18/2021 14:57
Aroclor1248	ND		250	500		08/18/2021 14:57
Aroclor1254	1500	Α	250	500		08/18/2021 14:57
Aroclor1260	ND		250	500		08/18/2021 14:57
PCBs, total	1500		250	500		08/18/2021 14:57
Surrogates	<u>REC (%)</u>	<u>Qualifiers</u>	<u>Limits</u>			
Decachlorobiphenyl	220	S	70-130			08/18/2021 14:57
Analyst(s): CK			Analytical Com	nments: a4	,c1,h4	

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Toll Free Telephone: (877) 252-9262 / Fax: (925) 252-9269 http://www.mccampbell.com / E-mail: main@mccampbell.com

Quality Control Report

 Client:
 EnviroNova
 WorkOrder:
 2108723

 Date Prepared:
 08/13/2021
 BatchID:
 227645

Date Analyzed: 08/17/2021 Extraction Method: SW3550B/3630C

Instrument:GC22Analytical Method:SW8082Matrix:Bulk MaterialUnit:mg/kg

Project: 21-186; 2118 Milvia Street, Berkely CA Sample ID: MB/LCS/LCSD-227645

Analyte	MB Result		MDL	RL		SPK Val	MB SS %REC		IB SS imits
Aroclor1016	ND		0.0500	0.0500		-	-	-	
Aroclor1221	ND		0.0500	0.0500		-	-	-	
Aroclor1232	ND		0.0500	0.0500		-	-	-	
Aroclor1242	ND		0.0500	0.0500		-	-	-	
Aroclor1248	ND		0.0500	0.0500		-	-	-	
Aroclor1254	ND		0.0500	0.0500		-	-	-	
Aroclor1260	ND		0.0500	0.0500		-	-	-	
Surrogate Recovery									
Decachlorobiphenyl	0.0518					0.05	104	7	0-130
Analyte	LCS Result	LCSD Result	SPK Val		LCS %REC	LCSD %REC	LCS/LCSD Limits	RPD	RPD Limit
Aroclor1016	0.151	0.155	0.15		101	103	70-130	2.44	20
Aroclor1260	0.145	0.150	0.15		97	100	70-130	3.48	20
Surrogate Recovery									
Decachlorobiphenyl	0.0430	0.0448	0.050		86	90	70-130	4.06	20

McCampbell Analytical, Inc.

CHAIN-OF-CUSTODY RECORD

Page 1 of 1

☐ ThirdParty

☐ J-flag

1534 W: Pittsburg (925) 25

415-883-7575

1534 Willow Pass Rd Pittsburg, CA 94565-1701 (925) 252-9262

☐ Detection Summary ☐ Excel

Report to: Bill to: Requested TAT: 5 days;

Basil Falcone Email: bfalcone@environova.com; jadams@envir Leah Luciani EnviroNova cc/3rd Party: EnviroNova

1116 S Amphlett Blvd; Suite 1 PO: 235 Montgomery Street, Ste. 1105 Date Received: 08/13/2021

San Mateo, CA 94402 Project: 21-186; 2118 Milvia Street, Berkely CA San Francisco, CA 94104 Date Logged: 08/13/2021

					Requested Tests (See legend below)											
Lab ID	Client ID	Matrix	Collection Date	Hold	1	2	3	4	5	6	7	8	9	10	11	12
		1				ı				Т	1		Т			
2108723-001	BE-Wcaulk-1M	Caulk	8/13/2021 13:06		Α	Α										
2108723-002	BE-Wcaulk-1C	Caulk	8/13/2021 13:15		Α	Α										

Test Legend:

1 8082_PCB_SG_Caulk	2 PRDisposal Fee	3	4
5	6	7	8
9	10	11	12

Project Manager: Angela Rydelius Prepared by: Adrianna Cardoza

Comments:

NOTE: Soil samples are discarded 60 days after results are reported unless other arrangements are made (Water samples are 30 days).

Hazardous samples will be returned to client or disposed of at client expense.



McCampbell Analytical, Inc.

"When Quality Counts"

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Toll Free Telephone: (877) 252-9262 / Fax: (925) 252-9269 http://www.mccampbell.com / E-mail: main@mccampbell.com

WORK ORDER SUMMARY

Client	Name:	ENVIRONO	OVA				Project:	21-186; 2118 M	Iilvia S	treet, B	erkely CA			Work Ord	er: 2108723	
Client	Contact:	Basil Falcor	ne											QC Lev	vel: LEVEL 2	
Contac	et's Email:	bfalcone@e ckhoury@er			ams@enviroi	nova.com;	Comments:							Date Logge	ed: 8/13/2021	
			WaterT	rax	WriteOn	EDF	Exce	EQuIS	•	Email	HardCop	/ 🔲 🏻	ThirdParty	J-flag		
LabID	ClientS	ampID	Matrix	Test Na	me		Containers /Composites	Bottle & Preservative		Dry- Weight	Collection Date & Time	TAT	Test Due	Date Sedin Cont	nent Hold Sub tent	Out
001A	BE-Wcaulk-1	lM	Caulk	SW8082 up)	(PCBs w/ Colur	nn Style Clean-	1	Plastic Baggie, Medium			8/13/2021 13:06	5 days	8/23/20	21		
002A	BE-Wcaulk-1	IC	Caulk	SW8082	(PCBs w/ Colur	nn Style Clean-	1	Plastic Baggie,			8/13/2021 13:15	5 days	8/23/20	21		

NOTES: * STLC and TCLP extractions require 2 days to complete; therefore, all TATs begin after the extraction is completed (i.e., One-day TAT yields results in 3 days from sample submission).

- MAI assumes that all material present in the provided sampling container is considered part of the sample - MAI does not exclude any material from the sample prior to sample preparation unless requested in writing by the client.

V		On (DW)	П	EQu d Pro	Ļ	ָ ב	Clai	10 E	AY	2
_		Req							300		
E.FA 524,27 6247 8200 (VOC.S)	EPA 525.2 / 625 / 8270 (SVOCs)	EPA 8270 SIM / 8310 (PAHs / PNAs)	CAM 17 Metals (200.8 / 6020)***	LUFT 5 Metals (200.8 / 6020)***	Metals (200.8 / 6020)***	Lab to Filter sample for Dissolved metals analysis	Multi TPH scan (g,d,mo)				
		ngerm wing u				brief,	glove	d, opp	pen al	r, sam	nple

HAZARDOUS:

CHAIN OF (McCampbell Analytical, Inc. TURN AROUND TIME: RUSH 1534 Willow Pass Rd. / Pittsburg, CA 94565-1701 GeoTracker EDF PDF www.mccampbell.com / main@mccampbell.com Telephone: (877) 252-9262 / Fax: (925) 252-9269 Effluent Sample Requiring "J" flag-Report To: Basil Falcone Bill To: EnviroNova Company: 235 Montgomery Street, Suite 1105 San Francisco, CA94104 Tele: () 415-599-6657 E-Mail:bfalcone@environova.com Grease (1664 / 5520 BTEX & TPH as Gas (8021/ 8015) MTBE Project #: 21-186 Project Name: 2118 Milvia Street, Berkely 8151 (Acidic Cl Herbicides) Berkeley, CA Purchase Order# Project Location: Sampler Signature: MATRIX METHOD SAMPLING PRESERVED Fotal Petroleum Oil & Location/ Drinking Water SAMPLE ID Ground Water Field Point Date Name Time Other Other Milviost BE-Wauk-M 13:06 BE-Wauk-10 13:15 **MAI clients MUST disclose any dangerous chemicals known to be present in their submitted samples in concentrations that may cause immediate harm or serious future he handling by MAI staff. Non-disclosure incurs an immediate \$250 surcharge and the client is subject to full legal liability for harm suffered. Thank you for your understanding a *** If metals are requested for water samples and the water type is not specified on the chain of custody, then MAI will default to metals by E2Q0.8. Relinquished By: Date: Time: 8-13-21 4.22 GOOD CONDITION Drenna Deano HEAD SPACE ABSENT Relinquished By: Received By: Date: Time: DECHLORINATED IN LAB APPROPRIATE CONTAINERS PRESERVED IN LAB Relinquished By: Date: Time: Received By

PRESERVATION

VOAS O&G METALS OTHER

1534 Willow Pass Road, Pittsburg, CA 94565-1701 Toll Free Telephone: (877) 252-9262 / Fax: (925) 252-9269 http://www.mccampbell.com / E-mail: main@mccampbell.com

Sample Receipt Checklist

Client Name: Project:	EnviroNova 21-186; 2118 Milvia Street, Berkely CA			Date and Time Received: Date Logged: Received by:	8/13/2021 16:22 8/13/2021 Adrianna Cardoza
WorkOrder №: Carrier:	2108723 Matrix: Caulk Client Drop-In			Logged by:	Adrianna Cardoza
	Chain of C	Custody	(COC) Infor	<u>mation</u>	
Chain of custody	present?	Yes	•	No 🗆	
Chain of custody	signed when relinquished and received?	Yes	✓	No 🗌	
Chain of custody	agrees with sample labels?	Yes	•	No 🗌	
Sample IDs noted	d by Client on COC?	Yes	✓	No 🗌	
Date and Time of	collection noted by Client on COC?	Yes	✓	No 🗌	
Sampler's name	noted on COC?	Yes	✓	No 🗌	
COC agrees with	Quote?	Yes		No 🗆	NA 🗹
	Samp	le Rece	eipt Informati	i <u>on</u>	
Custody seals int	act on shipping container/cooler?	Yes		No 🗆	NA 🗹
Custody seals int	act on sample bottles?	Yes	•	No 🗆	NA 🗌
Shipping contained	er/cooler in good condition?	Yes	✓	No 🗆	
Samples in prope	er containers/bottles?	Yes	•	No 🗆	
Sample container	rs intact?	Yes	•	No 🗆	
Sufficient sample	volume for indicated test?	Yes	✓	No 🗆	
	Sample Preservati	on and	Hold Time (I	HT) Information	
All samples recei	ved within holding time?	Yes	✓	No 🗌	NA 🗌
Samples Receive	ed on Ice?	Yes	✓	No 🗌	
	(Ice Typ	e: WE			
Sample/Temp Bla	ank temperature		Temp: 2.3		NA 🗌
	analyses: VOA meets zero headspace Cs, TPHg/BTEX, RSK)?	Yes		No 🗆	NA 🗹
Sample labels ch	ecked for correct preservation?	Yes	•	No 🗌	
pH acceptable up <2; 522: <4; 218.	on receipt (Metal: <2; Nitrate 353.2/4500NO3: 7: >8)?	Yes		No 🗆	NA 🗹
UCMR Samples:			_	_	_
	acceptable upon receipt (200.8: ≤2; 525.3: ≤4; 3; 544: <6.5 & 7.5)?	Yes		No 🗆	NA 🗹
Free Chlorine to	ested and acceptable upon receipt (<0.1mg/L)?	Yes		No 🗆	NA 🗹
Comments:					=======







