

LEGEND

⊗ Sample Location

◊ Asbestos Containing Sample Location

Asbestos containing black mastic associated with non-asbestos containing floor tile designated as F2 and F4 (Approximately 600 sf). Please know that the black mastic is underlying 1 layer of floor tile in the corridor and record room and underlying two layers of flooring in the kitchens.


HVAC system and insulation piping above ceiling tiles in public lobby



HVAC system and insulation piping above ceiling tiles in public lobby



HVAC system and insulation piping above ceiling tiles in public lobby



HVAC system and insulation piping above ceiling tiles in public lobby



HVAC system and insulation piping above ceiling tiles in public lobby



Roof



Roof



Roof



Roof



Pipe insulation above ceiling tiles in public lobby



HVAC system above ceiling tiles in public lobby



HVAC system above ceiling tiles in public lobby



Above the ceiling tiles in public lobby



Corridor A



Office (new addition)



Office (new addition)



Office (new addition)



Office (new addition)




Clerk



Administrative Assistant room



Mayor's room



Meeting room



Council chambers



Council chambers



Corridor C



Women's restroom sheet floor in corridor C



Women's restroom in corridor C



Storage room at end of corridor C





Storage room at end of Corridor C



Corridor B



Office (right side of lobby)



Copy/work room



Breakroom with F4 over F2 on right side of lobby



Breakroom with F4 over F2 on right side of lobby



Office (right side of lobby)



Public lobby



Public lobby backside



Public lobby front side



Women's restroom in public lobby



Janitorial closet in women's restroom in public lobby



Customer service




Building and Planning area



Reception (back, left side of lobby)



Pipe insulation elbows



Pipe insulation



Data room



Waiting room



Office (back, left side of lobby)



Office (back, left side of lobby)



Work station (back, left side of lobby)



Files room



Office with panel box



Conference room 142



Corridor at collections window



Storage/office



Air vent



Collection window



Customer service



Office (left side of lobby)



Conference room






Hallway from breakroom at women's restroom



Work room near breakroom and women's restroom



Corridor D



Office (left side of lobby)



Office (left side of lobby)



Office (left side of lobby)



Open work area



Breakroom with F4 floor tile over F2 floor tile



Women's restroom with F5 floor tile



Women's restroom with F5 floor tile



Public lobby ceiling



Right side of building



Backside of building



Backside of building



Backside of building



Backside of building















120

d  
e  
at  
St

