

## **ECS Carolinas, LLP**

Report of Limited Asbestos Survey

4748 Wright Avenue North Charleston, South Carolina ECS Project Number 49-2970

September 30, 2016



Geotechnical • Construction Materials • Environmental • Facilities

NC Registered Engineering Firm F-1078 NC Registered Geologists Firm C-406 SC Registered Engineering Firm 3239

September 30, 2016

Ms. Angela McJunkin, CCEA, CFM Director of Code Enforcement City of North Charleston PO Box 190016 North Charleston, SC 29419

Reference: Report of Limited Asbestos Survey

4748 Wright Avenue

North Charleston, South Carolina ECS Project Number: 49-2970

Dear Ms. McJunkin:

ECS is pleased to submit this report of our limited asbestos survey at the above referenced site. This report includes a description of our understanding of the project background information, a description of the scope of work performed, including our findings, conclusions and comments.

### **PROJECT UNDERSTANDING**

ECS Carolinas, LLP (ECS) understands the subject site is located at 4748 Wright Avenue in North Charleston, Charleston County, South Carolina. The site is further identified as Charleston County Parcel Identification Number (PIN) 4700300238. The site is developed with an approximate 900 square-foot manufactured home reportedly constructed in the early 1970's. The residence is slated for demolition. ECS was requested to conduct a limited asbestos survey of the interior and exterior portions of the residence prior to demolition activities.

### PROCEDURE/METHODOLOGY

### **Limited Asbestos Containing Materials (ACM) Assessment**

ECS was requested to perform a limited asbestos survey of the subject property to identify asbestos-containing materials (ACM) which could be disturbed during demolition or renovation. The National Emission Standard for Hazardous Air Pollutants (NESHAP) requires the identification of friable ACM and non-friable ACM likely to become friable during demolition and/or renovation activities. NESHAP requires that the identified ACM be removed prior to initiating activities likely to disturb the ACM. The EPA defines an ACM as a material containing more than one percent (>1%) asbestos.

The limited asbestos survey was performed on September 12, 2016 by Mr. Justin Roth (South Carolina Asbestos Inspector No. BI-01189). The survey consisted of observing the accessible areas of the building for the presence of suspect materials which may contain asbestos. The survey involved detecting both friable materials (materials which can be pulverized or reduced to a powder by hand pressure when dry) and non-friable materials (materials which pose a hazard when sawn, sanded, drilled or pulverized). Homogeneous materials (based on material type, color, texture, etc.) were identified in various functional spaces during the survey.

As per the South Carolina Department of Health and Environmental Control (SCDHEC), samples were collected from random locations of each homogeneous area, with the material's number of samples based upon the following criteria:

- Thermal Insulation Materials (piping, breeching, boiler insulation, etc.) A minimum of three (3) samples are required. Patch areas (less than 6 square or linear feet) may have one (1) sample collected.
- Surfacing Materials (plaster, fireproofing, etc.) A minimum of seven (7) samples are to be taken for areas greater than 5,000 square feet; five (5) for areas greater than 1,000 square feet, but less than 5,000 square feet; three (3) for areas less than 1,000 square feet.
- Miscellaneous Materials (flooring, adhesives, roofing, wallboard, etc.) A minimum of three (3) samples are required.

In order to determine if the suspect materials observed during the visual survey contained asbestos, representative bulk samples were collected and placed in sealed packages. Samples were placed under chain of custody and submitted to Scientific Analytical Institute, Inc. (SAI) in Greensboro, North Carolina for analysis under standard chain of custody procedures. The analysis was performed using the EPA recommended method of Polarized Light Microscopy (PLM) coupled with dispersion staining (Method No. EPA 600/M4-020-82, Dec. 1982). SAI participates in the National Voluntary Laboratory Accreditation Program (NVLAP). Their NVLAP accreditation number is 200664-0. Samples determined to be negative by PLM but were classified as non-friable organically bound (NOB) materials were reanalyzed by transmission electron microscopy (TEM) using the Chatfield method in accordance with SCDHEC requirements. If a sample of a material from a homogeneous area is found to be positive, then that material is considered positive, regardless of the results of the other samples of that material, within that area. The material type, sample location and analytical results of each bulk sample are also summarized in the attached Asbestos Bulk Analysis report in **Attachments**.

### **RESULTS**

The analytical data indicated that asbestos was not detected in the samples obtained by ECS. Some samples are considered multi-layered. These samples were comprised of more than one material, and each one is analyzed separately as per NESHAP requirements. The following table summarizes the samples collected during ECS' site visit and the laboratory analysis data.

# SUMMARY OF ASBESTOS-CONTAINING MATERIALS 4748 Wright Avenue North Charleston, South Carolina ECS Project 49-2970

Sample #	Materials	Sample Location	Approx. Quantity	Condition/ Friable or Non-Friable	Lab	Asbestos %
4878-1A-A	12" Floor			Good/Non-	PLM	None Detected
4878-1B-A	Tiles - Layer	Kitchen	50 SF	Friable	PLM	None Detected
4878-1C-A	1 - Floor Tile			Friable	TEM	None Detected
4878-1A-B	Floor Tile			Good/Non-	PLM	None Detected
4878-1B-B	Mastic	Kitchen	10 SF	10 SF Friable	PLM	None Detected
4878-1C-B	IVIdSUC				TEM	None Detected
4878-1A-C	12" Floor			Good/Non-	PLM	None Detected
4878-1B-C	Tiles - Layer	Kitchen	10 SF	Friable	PLM	None Detected
4878-1C-C	2 - Linoleum			riable	TEM	None Detected
4878-1A-D	Linoleum			Cood/Non	PLM	None Detected
4878-1B-D	Mastic	Kitchen	10 SF	Good/Non- Friable	PLM	None Detected
4878-1C-D	iviaStic			Friable	TEM	None Detected

# SUMMARY OF ASBESTOS-CONTAINING MATERIALS 4748 Wright Avenue North Charleston, South Carolina ECS Project 49-2970

200110)000 40 2070						
Sample #	Materials	Sample Location	Approx. Quantity	Condition/ Friable or Non-Friable	Lab	Asbestos %
4748-2A	\A/b:+ o			Cood/Non	PLM	None Detected
4748-2B	White	Entrance	10 SF	Good/Non-	PLM	None Detected
4748-2C	Linoleum			Friable	TEM	None Detected
4748-3A-A	Off Mile:to			Cood/Non	PLM	None Detected
4748-3B-A	Off-White	Bathroom	50 SF	Good/Non-	PLM	None Detected
4748-3C-A	Linoleum			Friable	TEM	None Detected
4748-3A-B	Linglaces			Cood/Non	PLM	None Detected
4748-3B-B	Linoleum	Bathroom	50 SF	Good/Non-	PLM	None Detected
4748-3C-B	Mastic			Friable	TEM	None Detected
4748-4A-A	Orange			Cood/Non	PLM	None Detected
4748-4B-A	Linoleum -	Bedroom #1	100 SF	Good/Non-	PLM	None Detected
4748-4C-A	Layer 1			Friable	TEM	None Detected
4748-4A-B	Orange			Cood/Non	PLM	None Detected
4748-4B-B	Linoleum -	Bedroom #1	100 SF	Good/Non-	PLM	None Detected
4748-4C-B	Layer 2			Friable	TEM	None Detected
4748-4A-C	Orange			Cood/Non	PLM	None Detected
4748-4B-C	Linoleum -	Bedroom #1	100 SF	Good/Non-	PLM	None Detected
4878-4C-C	Mastic			Friable	TEM	None Detected
4748-5A	\A/:			Const /Non	PLM	None Detected
4748-5B	Window	Exterior	200 LF	Good/Non- Friable	PLM	None Detected
4748-5C	Caulking			Friable	TEM	None Detected
4748-6A	Tous			Cood/Non	PLM	None Detected
4748-6B	Tan	Bedroom #2	100 SF	Good/Non-	PLM	None Detected
4748-6C	Linoleum			Friable	TEM	None Detected
4748-7A	Doof			Cood/Non	PLM	None Detected
4748-7B	Roof	Main Roof	800 SF	Good/Non-	PLM	None Detected
4748-7C	Material			Friable	TEM	None Detected
4748-8A-A	A cobalt			Cood/Non	PLM	None Detected
4748-8B-A	Asphalt	Roof - Entrances	100 SF	Good/Non-	PLM	None Detected
4748-8C-A	Shingles			Friable	TEM	None Detected
4748-8A-B				Cood/Non	PLM	None Detected
4748-8B-B	Felt Paper	Roof - Entrances	100 SF	Good/Non- Friable	PLM	None Detected
4748-8C-B				riable	TEM	None Detected
4748-9A-A	Linoleum -			Good/Non-	PLM	None Detected
4748-9B-A		Bedroom #3	100 SF	Friable	PLM	None Detected
4748-9C-A	Layer 1			riidble	TEM	None Detected
4748-9A-B	Linoleum -			Good/Non-	PLM	None Detected
4748-9B-B	Linoleum - Layer 2	Bedroom #3	100 SF	Friable	PLM	None Detected
4748-9C-B	Layer Z			THADIC	TEM	None Detected

# SUMMARY OF ASBESTOS-CONTAINING MATERIALS 4748 Wright Avenue North Charleston, South Carolina

ECS Project 49-2970

Sample #	Materials	Sample Location	Approx. Quantity	Condition/ Friable or Non-Friable	Lab	Asbestos %
4748-10A-A	Asphalt			Good/Non-	PLM	None Detected
4748-10B-A	Shingles	Shed #1	100 SF	Friable	PLM	None Detected
4748-10C-A	Sillingles			TTIADIC	TEM	None Detected
4748-10A-B				Good/Non-	PLM	None Detected
4748-10B-B	Felt Paper	Shed #1	100 SF	Friable	PLM	None Detected
4748-10C-B				THADIC	TEM	None Detected
4748-11A-A	Asphalt			Good/Non-	PLM	None Detected
4748-11B-A	Shingles	Shed #2	100 SF	Friable	PLM	None Detected
4748-11C-A	Silligies			riable	TEM	None Detected
4748-11A-B	·			Good/Non-	PLM	None Detected
4748-11B-B	Felt Paper	Shed #2	100 SF	Friable	PLM	None Detected
4748-11C-B				Filable	TEM	None Detected

Bold = Asbestos-Containing Material

SF = Square Feet

LF = Linear Feet

### **CONCLUSIONS AND RECOMMENDATIONS**

Based on the findings from laboratory analysis, asbestos concentrations in excess of EPA and State levels were not identified in the samples obtained. ECS does not recommend additional assessment pertaining to asbestos at this time. This report summarizes our evaluation of the conditions observed at the site. The findings prepared by ECS are based upon testing performed in the buildings. ACM may exist (undetected) in other areas due to their inaccessibility or due to the limited nature of our testing. The assessment did not include destructive measures to look in chases, above fixed ceilings, behind permanent or attached fixtures, behind walls, etc. Suspect materials observed in inaccessible areas will have to be assumed positive or be evaluated at the time of discovery.

ECS appreciates the opportunity to provide our asbestos services for this project. If you have questions or need additional information, please contact us.

Respectfully,

**ECS CAROLINAS, LLP** 

Braxton B. Dawson
Environmental Scientist
bdawson@ecslimited.com

(910) 686-9114

Lindsey B. Lucas, REM Environmental Principal


<u>llucas1@ecslimited.com</u>

Attachments: Figure

**Photographs** 

Laboratory Bulk Asbestos Analysis & Chain of Custody

SC Asbestos Building Inspector License



## **Sample Locations**

ECS Project Number 49-2970

Not to Scale



### **Limited Asbestos Assessment**

4748 Wright Avenue North Charleston, Charleston County, South Carolina



Photo 1: View of the residence at 4748 Wright Avenue.



Photo 2: Multi-layered 12"x12" floor tile/linoleum & associated adhesive.





Photo 3: White linoleum.



Photo 4: Off-white linoleum.





Photo 5: Tan linoleum.



Photo 6: Roof material.





By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020

Attn: Justin Roth

Customer: ECS Carolinas, LLP

3820 Faber Place

North Charleston, SC 29405

**Project:** 4746 Wright **Lab Order ID:** 1618042

**Analysis ID:** 1618042\_PLM

**Date Received:** 9/13/2016 **Date Reported:** 9/19/2016

Sample ID	Description	Ashastas	Fibrous	Non-Fibrous	Attributes
Lab Sample ID	Lab Notes	Asbestos	Components	Components	Treatment
4746-1A - A	12x12 VFT	None Detected		100% Other	Beige Non Fibrous Heterogeneous
1618042PLM_1	floor tile				Dissolved
4746-1A - B	12x12 VFT	None Detected		100% Other	Tan Non Fibrous Heterogeneous
1618042PLM_34	mastic 1				Dissolved
4746-1A - C	12x12 VFT	None Detected	30% Cellulose	70% Other	Yellow Non Fibrous Heterogeneous
1618042PLM_35	linoleum				Teased
4746-1A - D	12x12 VFT	None Detected		100% Other	Brown Non Fibrous Heterogeneous
1618042PLM_36	mastic 2				Dissolved
4746-1B - A	12x12 VFT	None Detected		100% Other	Beige Non Fibrous Heterogeneous
1618042PLM_2	floor tile				Dissolved
4746-1B - B	12x12 VFT	None Detected		100% Other	Tan Non Fibrous Heterogeneous
1618042PLM_37	mastic 1				Dissolved
4746-1B - C	12x12 VFT	None Detected	30% Cellulose	70% Other	Yellow Non Fibrous Heterogeneous
1618042PLM_38	linoleum				Teased
4746-1B - D	12x12 VFT	None Detected		100% Other	Brown Non Fibrous Heterogeneous
1618042PLM_39	mastic 2				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or bestamine. For the Charles of the Line of the Line of the Carles of the

Byron Stroble (63)

Analyst



By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020



Customer: ECS Carolinas, LLP

3820 Faber Place

North Charleston, SC 29405

**Project:** 4746 Wright Attn: Justin Roth **Lab Order ID:** 1618042

> **Analysis ID:** 1618042\_PLM

**Date Received:** 9/13/2016

**Date Reported:** 9/19/2016

Sample ID	Description	A albaataa	Fibrous	Non-Fibrous	Attributes
Lab Sample ID	Lab Notes	Asbestos	Components	Components	Treatment
4746-1C - A	12x12 VFT	None Detected		100% Other	Beige Non Fibrous Heterogeneous
1618042PLM_3	floor tile - TEM				Dissolved
4746-1C - B	12x12 VFT	None Detected		100% Other	Tan Non Fibrous Heterogeneous
1618042PLM_40	mastic 1 - TEM				Dissolved
4746-1C - C	12x12 VFT	None Detected	30% Cellulose	70% Other	Yellow Non Fibrous Heterogeneous
1618042PLM_41	linoleum - TEM				Teased
4746-1C - D	12x12 VFT	None Detected		100% Other	Brown Non Fibrous Heterogeneous
1618042PLM_42	mastic 2 - TEM				Dissolved
4746-2A	White linoleum	None Detected	30% Cellulose	70% Other	White Non Fibrous Heterogeneous
1618042PLM_4					Teased
4746-2B	White linoleum	None Detected	30% Cellulose	70% Other	White Non Fibrous Heterogeneous
1618042PLM_5					Teased
4746-2C	White linoleum	None Detected	30% Cellulose	70% Other	White Non Fibrous Heterogeneous
1618042PLM_6	TEM				Teased
4746-3A - A	Off white linoleum	None Detected	30% Cellulose	70% Other	Beige Non Fibrous Heterogeneous
1618042PLM_7	linoleum				Teased
		•			

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or bestamine. For the Charles of the Line of the Line of the Carles of the

Byron Stroble (63)

Analyst





By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020

Customer: ECS Carolinas, LLP

3820 Faber Place

North Charleston, SC 29405

**Project:** 4746 Wright Attn: Justin Roth **Lab Order ID:** 1618042

> **Analysis ID:** 1618042\_PLM

**Date Received:** 9/13/2016 **Date Reported:** 9/19/2016

Sample ID	Description		Fibrous	Non-Fibrous	Attributes
Lab Sample ID	Lab Notes	Asbestos	Components	Components	Treatment
4746-3A - B	Off white linoleum	None Detected		100% Other	Beige Non Fibrous Heterogeneous
1618042PLM_43	mastic				Dissolved
4746-3B - A	Off white linoleum	None Detected	30% Cellulose	70% Other	Beige Non Fibrous Heterogeneous
1618042PLM_8	linoleum				Teased
4746-3B - B	Off white linoleum	None Detected		100% Other	Beige Non Fibrous Heterogeneous
1618042PLM_44	mastic				Dissolved
4746-3C - A	Off white linoleum	None Detected	30% Cellulose	70% Other	Beige Non Fibrous Heterogeneous
1618042PLM_9	linoleum - TEM				Teased
4746-3C - B	Off white linoleum	None Detected		100% Other	Beige Non Fibrous Heterogeneous
1618042PLM_45	mastic - TEM				Dissolved
4746-4A - A	Orange linoleum	None Detected	30% Cellulose	70% Other	Yellow Non Fibrous Heterogeneous
1618042PLM_10	linoleum 1				Teased
4746-4A - B	Orange linoleum	None Detected	30% Cellulose	70% Other	Brown, Yellow Non Fibrous Heterogeneous
1618042PLM_46	linoleum 2				Teased
4746-4A - C	Orange linoleum	None Detected		100% Other	Beige Non Fibrous Heterogeneous
1618042PLM_47	mastic				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Byron Stroble (63)

Analyst



By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020

Attn: Justin Roth

Customer: ECS Carolinas, LLP

3820 Faber Place

North Charleston, SC 29405

**Project:** 4746 Wright **Lab Order ID:** 1618042

**Analysis ID:** 1618042\_PLM

**Date Received:** 9/13/2016 **Date Reported:** 9/19/2016

Sample ID	Description	A 1 /	Fibrous	Non-Fibrous	Attributes
Lab Sample ID	Lab Notes	Asbestos	Components	Components	Treatment
4746-4B - A	Orange linoleum	None Detected	30% Cellulose	70% Other	Yellow Non Fibrous Heterogeneous
1618042PLM_11	linoleum 1				Teased
4746-4B - B	Orange linoleum	None Detected	30% Cellulose	70% Other	Brown, Yellow Non Fibrous Heterogeneous
1618042PLM_48	linoleum 2				Teased
4746-4B - C	Orange linoleum	None Detected		100% Other	Beige Non Fibrous Heterogeneous
1618042PLM_49	mastic				Dissolved
4746-4C - A	Orange linoleum	None Detected	30% Cellulose	70% Other	Yellow Non Fibrous Heterogeneous
1618042PLM_12	linoleum 1 - TEM				Teased
4746-4C - B	Orange linoleum	None Detected	30% Cellulose	70% Other	Brown, Yellow Non Fibrous Heterogeneous
1618042PLM_50	linoleum 2 - TEM				Teased
4746-4C - C	Orange linoleum	None Detected		100% Other	Beige Non Fibrous Heterogeneous
1618042PLM_51	mastic - TEM				Dissolved
4746-5A	Caulking	None Detected		100% Other	Gray Non Fibrous Heterogeneous
1618042PLM_13					Dissolved
4746-5B	Caulking	None Detected		100% Other	Gray Non Fibrous Heterogeneous
1618042PLM_14					Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Byron Stroble (63)

Analyst



By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020

Attn: Justin Roth

Customer: ECS Carolinas, LLP

3820 Faber Place

North Charleston, SC 29405

**Project:** 4746 Wright **Lab Order ID:** 1618042

**Analysis ID:** 1618042\_PLM

**Date Received:** 9/13/2016 **Date Reported:** 9/19/2016

Sample ID	Description	A albaataa	Fibrous	Non-Fibrous	Attributes
Lab Sample ID	Lab Notes	Asbestos	Components	Components	Treatment
4746-5C	Caulking	None Detected		100% Other	Gray Non Fibrous Heterogeneous
1618042PLM_15	TEM				Dissolved
4746-6A	Tan linoleum	None Detected	30% Cellulose	70% Other	Beige Non Fibrous Heterogeneous
1618042PLM_16					Teased
4746-6B	Tan linoleum	None Detected	30% Cellulose	70% Other	Beige Non Fibrous Heterogeneous
1618042PLM_17	-				Teased
4746-6C	Tan linoleum	None Detected	30% Cellulose	70% Other	Beige Non Fibrous Heterogeneous
1618042PLM_18	TEM				Teased
4746-7A	Roof material	None Detected		100% Other	Black Non Fibrous Heterogeneous
1618042PLM_19	-				Dissolved
4746-7B	Roof material	None Detected		100% Other	Black Non Fibrous Heterogeneous
1618042PLM_20	-				Dissolved
4746-7C	Roof material	None Detected		100% Other	Black Non Fibrous Heterogeneous
1618042PLM_21	TEM				Dissolved
4746-8A - A	Asphalt shingle & felt	None Detected	10% Fiber Glass	90% Other	Black Non Fibrous Heterogeneous
1618042PLM_22	shingle				Dissolved
	<u> </u>		ļ		

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or bestamine. For the Charles of the Line of the Line of the Carles of the

Byron Stroble (63)

Analyst



By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020

Customer: ECS Carolinas, LLP

3820 Faber Place

North Charleston, SC 29405

**Project:** 4746 Wright Attn: Justin Roth **Lab Order ID:** 1618042

> **Analysis ID:** 1618042\_PLM

**Date Received:** 9/13/2016 **Date Reported:** 9/19/2016

Sample ID	Description	Anlandan	Fibrous	Non-Fibrous	Attributes
Lab Sample ID	Lab Notes	Asbestos	Components	Components	Treatment
4746-8A - B	Asphalt shingle & felt	None Detected	70% Cellulose	30% Other	Black Fibrous Heterogeneous
1618042PLM_52	felt				Teased, Dissolved
4746-8B - A	Asphalt shingle & felt	None Detected	10% Fiber Glass	90% Other	Black Non Fibrous Heterogeneous
1618042PLM_23	shingle				Dissolved
4746-8B - B	Asphalt shingle & felt	None Detected	70% Cellulose	30% Other	Black Fibrous Heterogeneous
1618042PLM_53	felt				Teased, Dissolved
4746-8C - A	Asphalt shingle & felt	None Detected	10% Fiber Glass	90% Other	Black Non Fibrous Heterogeneous
1618042PLM_24	shingle - TEM				Dissolved
4746-8C - B	Asphalt shingle & felt	None Detected	70% Cellulose	30% Other	Black Fibrous Heterogeneous
1618042PLM_54	felt - TEM				Teased, Dissolved
4746-9A - A	Linoleum	None Detected	30% Cellulose	70% Other	Red Non Fibrous Heterogeneous
1618042PLM_25	lkinoleum 1				Teased
4746-9A - B	Linoleum	None Detected	30% Cellulose	70% Other	Orange Non Fibrous Heterogeneous
1618042PLM_55	linoleum 2				Teased
4746-9B - A	Linoleum	None Detected	30% Cellulose	70% Other	Red Non Fibrous Heterogeneous
1618042PLM_26	linoleum 1				Teased

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or bestamine. For the Charles of the Line of the Line of the Carles of the

Byron Stroble (63)

Analyst





By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020

Customer: ECS Carolinas, LLP

3820 Faber Place

North Charleston, SC 29405

**Project:** 4746 Wright Attn: Justin Roth **Lab Order ID:** 1618042

> **Analysis ID:** 1618042\_PLM

**Date Received:** 9/13/2016 **Date Reported:** 9/19/2016

Sample ID	Description	A ab astas	Fibrous	Non-Fibrous	Attributes
Lab Sample ID	Lab Notes	Asbestos	Components	Components	Treatment
4746-9B - B	Linoleum	None Detected	30% Cellulose	70% Other	Orange Non Fibrous Heterogeneous
1618042PLM_56	linoleum 2				Teased
4746-9C - A	Linoleum	None Detected	30% Cellulose	70% Other	Red Non Fibrous Heterogeneous
1618042PLM_27	linoleum 1 - TEM				Teased
4746-9C - B	Linoleum	None Detected	30% Cellulose	70% Other	Orange Non Fibrous Heterogeneous
1618042PLM_57	linoleum 2 - TEM				Teased
4746-10A - A	Asphalt shingle	None Detected	10% Fiber Glass	90% Other	Gray, Black Non Fibrous Heterogeneous
1618042PLM_28	shingle				Dissolved
4746-10A - B	Asphalt shingle	None Detected	70% Cellulose	30% Other	Black Fibrous Heterogeneous
1618042PLM_58	felt				Teased, Crushed
4746-10B - A	Asphalt shingle	None Detected	10% Fiber Glass	90% Other	Gray, Black Non Fibrous Heterogeneous
1618042PLM_29	shingle				Dissolved
4746-10B - B	Asphalt shingle	None Detected	70% Cellulose	30% Other	Black Fibrous Heterogeneous
1618042PLM_59	felt				Teased, Dissolved
4746-10C - A	Asphalt shingle	None Detected	10% Fiber Glass	90% Other	Gray, Black Non Fibrous Heterogeneous
1618042PLM_30	shingle - TEM				Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or bestamine. For the Charles of the Line of the Line of the Carles of the

Byron Stroble (63)

Analyst



AIHA LAP, LLC

ACCREDITED LABORATORY

NOSTRAL VIGENE

HOME: VIRENE SINN

WAS APPROVIDENT AND A



By Polarized Light Microscopy EPA Method: 600/R-93/116 and 600/M4-82-020

Attn: Justin Roth

Customer: ECS Carolinas, LLP

3820 Faber Place

North Charleston, SC 29405

**Project:** 4746 Wright

**Lab Order ID:** 1618042

**Analysis ID:** 1618042\_PLM

Date Received: 9/13/2016 Date Reported: 9/19/2016

Sample ID	Description	Asbestos	Fibrous	Non-Fibrous	Attributes
Lab Sample ID	Lab Notes	Asucsius	Components	Components	Treatment
4746-10C - B	Asphalt shingle	None Detected	70% Cellulose	30% Other	Black Fibrous Heterogeneous
1618042PLM_60	felt - TEM				Teased, Dissolved
4746-11A - A	Asphalt shingle	None Detected	10% Fiber Glass	90% Other	Gray, Black Non Fibrous Heterogeneous
1618042PLM_31	shingle				Dissolved
4746-11A - B	Asphalt shingle	None Detected	70% Cellulose	30% Other	Black Fibrous Heterogeneous
1618042PLM_61	felt				Teased, Dissolved
4746-11B - A	Asphalt shingle	None Detected	10% Fiber Glass	90% Other	Gray, Black Non Fibrous Heterogeneous
1618042PLM_32	shingle				Dissolved
4746-11B - B	Asphalt shingle	None Detected	70% Cellulose	30% Other	Black Fibrous Heterogeneous
1618042PLM_62	felt				Teased, Dissolved
4746-11C - A	Asphalt shingle	None Detected	10% Fiber Glass	90% Other	Gray, Black Non Fibrous Heterogeneous
1618042PLM_33	shingle - TEM				Dissolved
4746-11C - B	Asphalt shingle	None Detected	70% Cellulose	30% Other	Black Fibrous Heterogeneous
1618042PLM_63	felt - TEM				Teased, Dissolved

Disclaimer: Due to the nature of the EPA 600 method, asbestos may not be detected in samples containing low levels of asbestos. We strongly recommend that analysis of floor tiles, vermiculite, and/or heterogeneous soil samples be conducted by TEM for confirmation of "None Detected" by PLM. This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government. Analytical uncertainty available upon request. Scientific Analytical Institute participates in the NVLAP Proficiency Testing program. Unless otherwise noted blank sample correction was not performed. Estimated MDL is 0.1%.

Byron Stroble (63)




Scientific Analytical Institute 4604 Dundas Dr. Greensboro, NC 27407 Phone: 336.292.3888 Fax: 336.292.3313 www.sailab.com lab@sailab.com

Lab Use Only	1618042
Lab Order ID:	1410010
Client Code:	

	itact Information		Vertical Value	Asbestos Test Typ	es
	arolinas, LLP	Contact: Justin Roth		PLM EPA 600/R-93/116 (PLM)	
Address: 3820 Fal	ber Place Drive, Suite 500	Phone : 843-654-4448		Positive stop	- >
	harleston, SC 29405	Fax 🔲:		PLM Point Count 400 (PT4)	TE
		Email ]Roth	@ecslimited.com	PLM Point Count 1000 (PTM)	I
				PCM NIOSH 7400-A Rules (PCM)	TE
Billing/Invoice	Information	Turn Arc	ound Times	B Rules (PCB) TWA (PT	A) [
Company: SAME		90 Min.	48 Hours	TEM AHERA (AHE)	
Contact:		3 Hours	72 Hours	TEM Level II (LII)	TE
Address:		6 Hours	96 Hours	TEM NIOSH 7402 (TNI)	E
		12 Hours	120 Hours	TEM Bulk Qualitative (TBL)	E
	30 59), 5-185 15-452 504 1-4-4	24 Hours	144 Hours	TEM Bulk Chatfield (TBS)	2
			- 10	TEM Bulk Quantitative (TBQ)	TC
PO Number:	Access to the contract of the			TEM Wipc ASTM D6480-05	
Project Name/N	umber: 4746	Wrigh	1	TEM Microvac ASTM D5755-02	Ē
			1	TEM Water EPA 100.2 (TW1)	L
		3/A-2//	9	Other:	Ē
Sample ID #			Volume/A	Area Comments	
Sample ID #	As per SCDHEC require	ements. Please a		Area Comments by PLM. For NOB Materia	ıls,
Sample ID #	please analyze one samp		nalyze all samples		ıls,
Sample ID #			nalyze all samples	by PLM. For NOB Materia	als,
Sample ID #	please analyze one samp		nalyze all samples	by PLM. For NOB Materia	als,
Sample ID #	please analyze one samp		nalyze all samples	by PLM. For NOB Material f the samples are reported	als,
Sample ID #	please analyze one samp		nalyze all samples	by PLM. For NOB Material f the samples are reported	als,
Sample ID #	please analyze one samp		nalyze all samples	by PLM. For NOB Materia	ıls,
Sample ID #	please analyze one samp		nalyze all samples	by PLM. For NOB Material f the samples are reported	als,
Sample ID #	please analyze one samp		nalyze all samples	by PLM. For NOB Material f the samples are reported	lls,
Sample ID #	please analyze one samp		nalyze all samples	by PLM. For NOB Material f the samples are reported	lls,
Sample ID #	please analyze one samp		nalyze all samples	by PLM. For NOB Material f the samples are reported	als,
Sample ID #	please analyze one samp		nalyze all samples	by PLM. For NOB Materia f the samples are reported	lls, /
Sample ID #	please analyze one samp negative by PLM.	ple from each gro	nalyze all samples oup by TEM if all o	by PLM. For NOB Materia f the samples are reported  Total # of Samples3	3
	please analyze one samp negative by PLM.		nalyze all samples pup by EM if all o	by PLM. For NOB Materia f the samples are reported  Total # of Samples3	3



Surveyor Signature:



### **Asbestos Survey Field Data Sheet**

Project Name Project Locati		Wright			Manager:	2
Building Num	ber:			Project N	lumber:	
Sample No.	Homogeneous Area	Sample Description	Quantity	Friable Y/N	Location	Accessibility/Potential for Damage
4746-1A,B	e Floor	DHOVET	SOSF	N	Kitchen	multiple degers
4746 ZAB	•	white lindeau	IOSE	N	Pew Entrace	
4746-3A,B,		Offwhite inchem	SOSP	N	Bertween	
4746 44,8	The second secon	Drange Imolain	10051	N	Bed Run #	<b>4</b> /
4746 SA3		Caulky	200 LF	N	window	
4746-64,B,		Tan Imolema	LOOSE	N	Bed Ron #	2
4746-7AB,	c Roof	Roof material	42008	N.	Doos	
4746 8AB	_	Asphalt Showle	100SF	N	entraces	
4746-94,3	200 2	lindem	100SF	N	Red Ron 43	
4746-10A,B.	1	Asphalo Shigh	10051-	N	Thed #1	
4746-11A,B,		Asphallshyle	100 S.P	Ν	Shed #2	
		3.				7
						Lis Comments



### Semi-Quantitative Chatfield SOP 1988-02 Rev. 1

Customer: ECS Carolinas, LLP

Attn: Justin Roth

Lab Order ID:

1618488

3820 Faber Place

**Analysis ID:** 

1618488 TBS

North Charleston, SC 29405

**Date Received:** 

9/19/2016

**Project:** 4746 Wright

**Date Reported:** 

9/26/2016

Sample ID	Description	Organic	Acid Sol.	Asbestos	LCL-UCL
Lab Sample ID	Lab Notes	(Wt. %)	(Wt. %)	(Wt. %)	(Wt. %)
4746-1C-A	12x12 VFT	19%	77%	None Detected	
1618488TBS_1	floor tile				
4746-1C-B	12x12 VFT	53%	_	None Detected	
1618488TBS_2	mastic				
4746-1C-C	12x12 VFT	82%	-	None Detected	
1618488TBS_3	linoleum				
4746-1C-D	12x12 VFT	82%	1	None Detected	
1618488TBS_4	mastic				
4746-2C	White linoleum	60.%	-	None Detected	
1618488TBS_5	linoleum				
4746-3C-B	Off white linoleum	85%	-	None Detected	
1618488TBS_6	mastic				

Disclaimer: This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

Ired Gulley (21)



### Semi-Quantitative Chatfield SOP 1988-02 Rev. 1

Customer: ECS Carolinas, LLP

Attn: Justin Roth

Lab Order ID:

1618488

3820 Faber Place

**Analysis ID:** 

1618488 TBS

North Charleston, SC 29405

**Date Received:** 

9/19/2016

**Project:** 4746 Wright

**Date Reported:** 

9/26/2016

Sample ID	Description	Organic	501.	Asbestos	LCL-UCL
Lab Sample ID	Lab Notes	(Wt. %)	(Wt. %)	(Wt. %)	(Wt. %)
4746-3C-A	Off white linoleum	34%	-	None Detected	
1618488TBS_21	linoleum				
4746-4C-A	Orange linoleum	78%	-	None Detected	
1618488TBS_7	linoleum 1				
4746-4C-B	Orange linoleum	83%	-	None Detected	
1618488TBS_8	linoleum 2				
4746-4C-C	Orange linoleum	72%	-	None Detected	
1618488TBS_9	mastic				
4746-5C	Caulking	21%	-	None Detected	
1618488TBS_10	mastic				
4746-6C	Tan linoleum	50.%	_	None Detected	
1618488TBS_11					

Disclaimer: This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

Ired Gulley (21)

Analyst

T-F-010 r15 1/15/2018



### Semi-Quantitative Chatfield SOP 1988-02 Rev. 1

Customer: ECS Carolinas, LLP

3820 Faber Place

North Charleston, SC 29405

**Project:** 4746 Wright Attn: Justin Roth Lab Order ID: 1618488

**Analysis ID:** 

1618488 TBS

**Date Received:** 

9/19/2016

**Date Reported:** 

9/26/2016

Sample ID	Description	Organic	Acid Sol.	Asbestos	LCL-UCL
Lab Sample ID	Lab Notes	(Wt. %)	(Wt. %)	(Wt. %)	(Wt. %)
4746-7C	Roof material	82%	-	None Detected	
1618488TBS_12					
4746-8C-A	Asphalt shingle & felt	18%		None Detecto	ed
1618488TBS_13	shingle				
4746-8С-В	Asphalt shingle & felt	87%	1	None Detecte	ed
1618488TBS_14	felt				
4746-9C-A	Linoleum	56%	-	None Detecte	ed
1618488TBS_15	linoleum 1				
4746-9C-B	Linoleum	64%	1	None Detecte	ed
1618488TBS_16	linoleum 2			Tione Detected	
4746-10C-A	Asphalt shingle	30.%	-	None Detecte	ed
1618488TBS_17	shingle				

Disclaimer: This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

Ired Gulley (21)

Analyst



### Semi-Quantitative Chatfield SOP 1988-02 Rev. 1

Customer: ECS Carolinas, LLP

3820 Faber Place

North Charleston, SC 29405

**Project:** 4746 Wright Attn: Justin Roth Lab Order ID: 1618488

**Analysis ID:** 

1618488 TBS

**Date Received:** 

9/19/2016

**Date Reported:** 

9/26/2016

Sample ID	Description	Organic	Acid Sol.	Asbestos	LCL-UCL
Lab Sample ID	Lab Notes	(Wt. %)	(Wt. %)	(Wt. %)	(Wt. %)
4746-10C-B	Asphalt shingle	97%		None Detected	
1618488TBS_18	felt				
4746-11C-A	Asphalt shingle	23%		None Detected	
1618488TBS_19	shingle				
4746-11C-B	Asphalt shingle	97%	1	None Detected	
1618488TBS_20	felt				

Disclaimer: This report relates only to the samples tested and may not be reproduced, except in full, without the written approval of SAI. This report may not be used by the client to claim product endorsement by NVLAP or any other agency of the U.S. government.

Ired Gulley (21)

Analyst




### Scientific Analytical Institute 4604 Dundas Dr. Greensboro, NC 27407 Phone: 336.292.3888 Fax: 336.292.3313 www.sailab.com lab@sailab.com

	1418488
Lab Use Only Lab Order ID:	He18042
Client Code:	

Company Cor	ntact Information		Art Shart	Asbestos Test Typ	es
27//	Carolinas, LLP	Contact: Justin	Roth	PLM EPA 600/R-93/116 (PLM)	P
Address: 3820 Fa	ber Place Drive, Suite 500	Phone □: 843	-654-4448	Positive stop	. 0
North Charleston, SC 29405		Fax :		PLM Point Count 400 (PF4)	
		Email    ] Roth	@ecslimited.com	PLM Point Count 1000 (PTM)	
				PCM NIOSH 7400-A Rules (PCM)	
Billing/Invoice	e Information	Turn Aro	und Times	B Rules (PCB) TWA (PT	A) 🔲
Company: SAME		90 Min.	48 Hours	TEM AHERA (AHE)	
Contact:		3 Hours	72 Hours	TEM Level II (LII)	
Address:		6 Hours	96 Hours	TEM NIOSH 7402 (TNI)	
		12 Hours	120 Hours D	TEM Bulk Qualitative (TBL)	
		24 Hours	144 Hours	TEM Bulk Charlicld (TBS)	×
MARKET STATE OF THE STATE OF TH			10	TEM Bulk Quantitative (TBQ)	
PO Number:				TEM Wipc ASTM D6480-05	
Project Name/N	umber: 4746	Wright		TEM Microvac ASTM D5755-02	
				TEM Water EPA 100.2 (TW1)	To
				[	
Sample ID #	To to AGS from the A		Volume/	Other:	巨
Sample ID #	As per SCDHEC requir			Other:	
Sample ID #	As per SCDHEC require please analyze one samp		nalyze all samples up by TEM if all o	Other:  Comments  by PLM. For NOB Materia f the samples are reported	
Sample ID #	As per SCDHEC require please analyze one samp		nalyze all samples up by TEM if all o	Other:  Comments  by PLM. For NOB Materia f the samples are reported	No.
Sample ID#	As per SCDHEC require please analyze one samp		nalyze all samples up by TEM if all o	Other:  Comments  by PLM. For NOB Materia f the samples are reported	
Sample ID #	As per SCDHEC require please analyze one samp		nalyze all samples up by TEM if all o	Other:  Comments  by PLM. For NOB Materia  f the samples are reported	
	As per SCDHEC require please analyze one samp negative by PLM.		nalyze all samples up by TEM if all o	Comments by PLM. For NOB Materia f the samples are reported  Total # of Samples 3	ls, /





### **Asbestos Survey Field Data Sheet**

Project Name	4746	Wright		Sampled	By: SAC	- 10 W 300 Lold
Project Locati	on:	<del></del>	-	Project N	Manager:	
Building Num	ber:		- yo-	Project N	lumber:	
Sample No.	Homogeneous Area	Sample Description	Quantity	Friable Y/N	Location	Accessibility/Potential for Damage
4746-1A,B	e Floor	DHAVET	SOSF	N	Hitchon	multiple degrees
4746 JAB		white linden	IOSE	l (i	Pew Entrue	
4746-3A,B,		off white indem	SOSP	N	Bestween	
4746-44.8		Drage Imoleur	1005	: 10	Bed Ru #	4/
4746-543	C windows		200 LF	N ·	windows	A secondary
4746-64.B.	The second secon	Tan Imoleum	BOSE	N	Bad Ron #	2
4746-7A.B.	_	Roof material	42008	N.	Dook	
47468AB		Asphalt shangle	100SF	N	entracos	
4746-94,3		linolem	100SF	N	Bed Rm #3	
4746-10A,B.	F	Asphala Shigh	100 S.F	N	Thed #1	<u> </u>
4746-114,8,		Asphallshyle	10051	Ν	Shed #2	
					with a family and the second s	
Carlo						1
Surveyor Sig	nature:			Date: _	9/12/16 :	

## **SCDHEC ISSUED**

Asbestos ID Card

### **Braxton B Dawson III**

**Expiration Date** 

CONSULTBI BI-01194 03/16/17 CONSULTPD PD-00163 03/16/17



## SCDHEC ISSUED

Asbestos ID Card

## **Lindsey Lucas**

Expiration Date



CONSULTBI BI-00603 06/21/17 CONSULTPD PD-00140 08/18/16 AIRSAMPLER AS-00176 06/20/17