Accelerate Progress for Students

Rennette R. Apodaca, MPA, CPPO   Scott Elder
Executive Director   Superintendent

DATE: 02/22/2022
RFP NUMBER: 22-043RR
RFP TITLE: E-Rate Wireless Expansion 2022-2023
ADDENDUM NUMBER: 1

 See Question and Answers

 Question: Can we please get a configuration sample on Albuquerque Public Schools current switches so that we can bid on the labor and create accurate SOW's?

Response: Please see details listed below concerning our 5130 switch configuration:

VLANs = 13
ACLs = 3 (All three are just a few lines long)
Interface Configs - most ports are trunks with only our VLANs allowed
SNMP - short config for our network management
NTP - short config to a local NTP server
Local Users - 3 user roles
Routing - 1 Default route

Question: We have two clarifying questions pertaining to RFP#22-043RR E-Rate Wireless Expansion 2022-2023. They are both related to Project 2. We have found that the Eaton product part numbers provided on Appendix A are invalid, and appear to have typos in each. Can you clarify the part numbers needed for the proposal?

 Response: The correct part numbers are as follows:

The listed part number of Eaton #5PXEEM72RT2U should be EATON# 5PXEBM72RT2U.
 The listed part number of Eaton #EBP-10036 should be EATON# EBP-1003.

Question: During the walk through it was mentioned that you are looking for replacement batteries only for your existing the Eaton UPS units and no new UPS units, please clarify.

Response: APS believes that the chassis are in good condition and only the batteries need to be replaced. If any complete units need to be replaced then they will be addressed on a case by case basis and should not be considered in this RFP response

Question: Are you requesting quotes for any new copper cabling or fiber runs in this RFP?

Response: No new cabling, either copper or fiber are part of this RFP with the exception of new fiber jumpers.

Question: On the walk through it was mentioned two power-supplies per switch. In the RFP there are four power supplies per switch, please clarify the desired quantity of switch power supplies.

Response: The Aruba 6300M (JL658A) does not come with a power supply. APS would like dual power supplies (JL085A) in each switch thus the quantity in the RFP is correct. The JL085A#ABA is the US power cable needed for the power supplies, thus the quantity in the RFP is correct.

ACKNOWLEDGE ADDENDUM WITH SUBMITTED PROPOSAL:
Addenda not signed and returned may consider the RFP non-responsive and may be rejected.

_____

COMPANY/FIRM NAME

_____

SIGNATURE

_____

DATE