

Exhibit 2- Photos

Re: KHM Wall and Brick Paver Repairs RFB

Date: October 9, 2019



Photo No. 1

Description: View of damaged brick wall looking South. Remove approximately 8'-7" of wall section including footing.



Photo No. 2

Description: View of damaged brick wall looking North. Remove approximately 8'-7" of wall section including footing.

Exhibit 2- Photos

Re: KHM Wall and Brick Paver Repairs RFB

Date: October 9, 2019



Photo No. 3

Description: View of brick paver area looking East.



Photo No. 4

Description: View of brick paver area looking West.