

GENERAL NEW NOTES:

- 1. ALL CAMERAS SHOWN ARE NEW UNLESS OTHERWISE NOTED. PROVIDE NEW CATEGORY 6 CABLE TO NEAREST IDF AND SALIENT LICENSING.
- 2. INTEGRATE EXISTING NEW CAMERAS AND VIDEO INTERCOMS WITH RS2 ACCESS CONTROL SYSTEM. PROVIDE ANY ADDITIONAL LICENSING REQUIRED TO COMPLETE INTEGRATION.

SECURITY PLAN NOTES

4

- PROVIDE OVERHEAD DOOR MONITOR. PROVIDE RECESSED MOUNT ACCESSORY. PROVIDE WALL ARM AND CORNER MOUNT BRACKET. EXISTING ADA OPERATOR. INTEGRATE ADA OPERATOR WITH ACCESS CONTROL SYSTEM.
- REMOVE EXISTING ANALOG CAMERA. INSTALL 5 NEW IP CAMERA.
- PROVIDE P3717-PLE AND CORNER MOUNT BRACKET. PROVIDE NEW CATEGORY 6 CABLE TO NEAREST IDF.
- PROVIDE CORNER MOUNT ADAPTER. CONFIRM EXACT LOCATION OF CAMERA WITHIN SHOP CLASSES WITH SCHOOL ADMINISTRATION/INSTRUCTORS PRIOR TO
- INSTALLATION. EXISTING FALCON ELECTRIFIED PANIC BAR, 9 DOOR MONITOR AND PIR REQUEST TO EXIT. MODIFY, RETROFIT, OR REPLACE AS NECESSARY TO PROVIDE ELECTRIFIED LATCH RETRACTION AND ELECTRIC DOGGING FUNCTION. ADD ADDITIONAL DOOR POSITION MONITOR TO SECOND LEAF.
- 10 PROVIDE NEW DOOR MONITOR. ALL EQUIPMENT SERVED FROM IDF. PROVIDE 11 NEW SALIENT SERVER AND LICENSING FOR NORTHLAND CAREER CENTER CAMERAS. MOUNT AT HIGHEST ELEVATION POSSIBLE. 12



TY102