

ADDENDUM NO. 3 TO RFQ 2020-3282-6136-41D

- Under the first item, **Box and Lid for 5/8" or 3/4" T-10 Meter**, the number should be LYLVP141-233-**T** instead of LYLVP141-233-**P**

- The following item is being added:

Yokebox Service Pack Set 5/8" x 3/4": \$ _____

HHC133-322-EC23-SET-NL

(1) HHC133-322 / (1) EC-23 / (2) GT-118 /

In service pack envelope / No Lead

- Items were copied over to Addendum 1 and Addendum 2 original documents in error. These items appeared at the very bottom of the addendums and have now been removed.