
Kope MIII Ka



			•		
Rope Mill Rd Improvements: Mill Park Entrance	Unit	QTY	Unit Price	Total	
Total 2' Curb and Gutter	LF	303			
Island 1	LF	32			
Island 2	LF	86			
Island 3	LF	30			
Island 4	LF	80			
Island 5	LF	75			
ADA Ramps - Red Truncated		4			
Thermoplastic Solid Traffic Stripe, 24 In, White Continental Crosswalk	LF	42			
Grading Complete - Saw cutting Asphalt, New Dirt to build out islands, Removing Old Curb	LS				
Traffic Control	LS				
City to provide grass for new islands					
Meet GDOT Specs for Radius and ADA Ramps					

Mill Park Chase

Island 4

Install 2 Continental

Crosswalks

Radius to meet GDOT standards 25' min.

ADA Ramps

Island 5

Brownlee Road

Island 3



Public Works

Department

Martyn Detz

At the Mill Park entrance, our objective is to improve the line of sight for residents when they leave the Mill Park neighborhood. We accomplish this by eliminating the parking spaces immediately to the left and right of the entrance to the neighborhood by building out landscaped medians. Furthermore, with the road shifting two feet to the west, the existing 3 landscape islands need to be built out further to prevent anyone from parking in front of these medians where the mailboxes are located.


06/15/20

Rope Mill Rd

East Side

Mill Park Entrance

PW-19 266





Public Works

Department

Martyn Detz

At the Mill Park entrance, our objective is to improve the line of sight for residents when they leave the Mill Park neighborhood. We accomplish this by eliminating the parking spaces immediately to the left and right of the entrance to the neighborhood by building out landscaped medians. Furthermore, with the road shifting two feet to the west, the existing 3 landscape islands need to be built out further to prevent anyone from parking in front of these medians where the mailboxes are located.

06/15/20

Rope Mill Rd

East Side

Mill Park Entrance

PW-19 266





Public Works
Department
Martyn Detz

At the Mill Park entrance, our objective is to improve the line of sight for residents when they leave the Mill Park neighborhood. We accomplish this by eliminating the parking spaces immediately to the left and right of the entrance to the neighborhood by building out landscaped medians. Furthermore, with the road shifting two feet to the west, the existing 3 landscape islands need to be built out further to prevent anyone from parking in front of these medians where the mailboxes are located.

06/15/20

Rope Mill Rd

East Side

Mill Park Entrance

PW-19 266





Public Works

Department

Martyn Detz

At the Mill Park entrance, our objective is to improve the line of sight for residents when they leave the Mill Park neighborhood. We accomplish this by eliminating the parking spaces immediately to the left and right of the entrance to the neighborhood by building out landscaped medians. Furthermore, with the road shifting two feet to the west, the existing 3 landscape islands need to be built out further to prevent anyone from parking in front of these medians where the mailboxes are located.

06/15/20

Rope Mill Rd

East Side

Mill Park Entrance

PW-19 266