Scope of Work

Mira Monte Elementary School
Playground Restoration & Parking Lot Slurry Project # 2019-1201

Playground:

- 1. Removal & replacement of critically failed areas of 3" thick asphalt pavement.
- 2. Asphalt will be dumped on-site or at another OUSD site.
- 3. Cut and remove intruding surface roots to a depth of 12" as needed.
- 4. Fine grade and recompact the existing subgrade.
- 5. Install approx. 452lf header board.
- 6. Apply tack oil to the vertical surfaces of the existing pavement.
- 7. Install 3" (after compaction) of hot mix asphalt pavement.
- 8. Re-stripe the asphalt surface per the existing layout using 1 coat of traffic paint.

Parking Lot:

- 1. Crack Seal: Remove weeds and loose debris from cracks ¼" wide and wider. Seal cracks with a hot pour rubberized sealant, removing excess material from the surface with squeegees. Repair & skim coat of asphalt on cracks and swales over 3".
- 2. Sealcoat: Blow and sweep the asphalt surface, burning oil spots and removing vegetation as needed. Apply 2 coats of sealcoat. First coat to include sand and 2% latex. Second coat to include 2% latex. Re-stripe the asphalt surface per the existing layout using 1 coat of traffic paint. Re-stripe ADA stalls to be compliant. Install 6 ADA stall signs with brackets and 1 post. Install 2 ADA entrance signs with brackets and 2 posts. Replace 2 wheel stops and pin in place.