

BID TABULATION FOR PUMP REPAIRS/WELL CLEANINGS

Engineer's Estimate = \$349,550.00

TECH. SPEC. SECTION	DESCRIPTION OF SERVICE	EST QTY	UNIT	OHIO DRILLING	
				UNIT PRICE	TOTAL PRICE
PUMP REPAIRS					
3.4.A	Overhaul of the Discharge Head				
	- High Service Pump	2	EA	\$900.00	\$1,800.00
	- Well Pump	9		\$800.00	\$7,200.00
3.4.B	Clean and Straighten the Line Shaft				
	- 1-1/2" Shaft	60	EA	\$30.00	\$1,800.00
	- 1-15/16" Shaft	70	EA	\$35.00	\$2,450.00
	- 2-3/16" Shaft	30	EA	\$40.00	\$1,200.00
3.4.C	Sandblast Bearing Retainer Assemblies and Replace the Line Shaft Bearing				
	- High Service Pump	10	EA	\$70.00	\$700.00
	- Well Pump	90	EA	\$35.00	\$3,150.00
3.4.D	Overhaul of the Pump				
	- High Service Pump	2	EA	\$2,500.00	\$5,000.00
	- Well Pump	9	EA	\$1,500.00	\$13,500.00
WATER WELL CLEANING					
4.0	Water Well Cleaning	9	EA	\$26,000.00	\$234,000.00

TOTAL AMOUNT \$270,800.00