BID TABULATION FOR PUMP REPAIRS/WELL CLEANINGS

Engineer's Estimate = \$299,100.00

| | | | | | OHIO DRILLING | |
|---------------------------|--|------------|------|---------------|----------------|--|
| TECH. SPEC. SECTION | DESCRIPTION OF SERVICE | EST QTY | UNIT | UNIT PRICE | TOTAL PRICE | |
| | | | | | | |
| PUMP REPAIRS | | | | | | |
| 3.4.A | Overhaul of the Discharge Head | | | | | |
| | - High Service Pump | 2 | EA | \$1,000.00 | \$2,000.00 | |
| | - Well Pump | 9 | EA | \$850.00 | \$7,650.00 | |
| 3.4.B | Clean and Straighten the Line Shaft | | | | | |
| | - 1-1/2" Shaft | 60 | EA | \$30.00 | \$1,800.00 | |
| | - 1-15/16" Shaft | 70 | EA | \$35.00 | \$2,450.00 | |
| | - 2-3/16" Shaft | 30 | EA | \$40.00 | \$1,200.00 | |
| 3.4.C | Sandblast Bearing Retainer Assemblies and Replace the Line Shaft Bearing | | | | | |
| | - High Service Pump | 10 | EA | \$70.00 | \$700.00 | |
| | - Well Pump | 90 | EA | \$35.00 | \$3,150.00 | |
| 3.4.D | Overhaul of the Pump | | | | | |
| | - High Service Pump | 2 | EA | \$2,500.00 | \$5,000.00 | |
| | - Well Pump | 9 | EA | \$1,500.00 | \$13,500.00 | |
| WATER W | ELL CLEANING | - | - | | | |
| 4.0 | Water Well Cleaning | 9 | EA | \$26,000.00 | \$234,000.00 | |
| | | | | | | |

TOTAL AMOUNT

\$271,450.00