

Addendum 2

City of Canton, Ohio
Purchasing Department
218 Cleveland Ave. SW, 4th floor
Canton, Ohio 44702

Turbine Service Pump Repair and Well Maintenance Program

Item/Project

Water Department

Responsible Department

Monday, January 27, 2020 on or before 2:00 PM local time

Bids Due On or Before

Bid Proposal Submitted By:

Company Name

Street Address

City

State

Zip

Contact Person

Phone No.

Email Address

Turbine Service Pump Repair and Well Maintenance Program
Water Department

Question 1.

In section VI: Technical Specifications, Item 4.0, 5)-F does not specify the volume of acid to be injected. Typically the volume is specified as 'equal to volume of screen', '50% of the screen volume', or an exact quantity such as '1000 gallons of 20 degree Baume inhibited muriatic acid". What does the City of Canton require as an effective volume of acid for well redevelopment? This is an important volume for effective redevelopment and cost preparation.

Answer:

Our records indicate that typically the volume is between 700 to 1,000 gallons of solution.