

## **Addendum #1 – Replacement of 20 – Ton HVAC System**

- During a number of site visits, vendors have pointed out that units of this size do not have SEER ratings. Please quote units with an EER rating of 11.