

Addendum #1

Facilities – Repair Bleachers – NHS and SHS

6.3.1.4 Install chain link fence below railing in front of bleachers at both ends of seating. 36ft x 2ft on one side and 38ft x 2ft on other side.

SECTION 8.0

ADDITIVE/ALTERNATE

- 8.1 We are open to alternative methods to achieve code that are more cost effective. If your firm has identified ways to achieve code in a more cost effective way, please include those in your response under Additive/Alternate.