## **BID TABULATION FOR PUMP REPAIRS/WELL CLEANINGS**

## Engineer's Estimate = \$299,100.00

					OHIO DRILLING	
TECH. SPEC. SECTION	DESCRIPTION OF SERVICE	EST QTY	UNIT	UNIT PRICE	TOTAL PRICE	
PUMP REI	PAIRS					
3.4.A	Overhaul of the Discharge Head		1			
	- High Service Pump	2	EA	\$1,000.00	\$2,000.00	
	- Well Pump	9		\$850.00	\$7,650.00	
3.4.B	Clean and Straighten the Line Shaft					
	- 1-1/2" Shaft	60	EA	\$30.00	\$1,800.00	
	- 1-15/16" Shaft	70	EA	\$35.00	\$2,450.00	
	- 2-3/16" Shaft	30	EA	\$40.00	\$1,200.00	
3.4.C	Sandblast Bearing Retainer Assemblies and Replace the Line Shaft Bearing					
	- High Service Pump	10	EA	\$70.00	\$700.00	
	- Well Pump	90	EA	\$35.00	\$3,150.00	
3.4.D	Overhaul of the Pump					
	- High Service Pump	2	EA	\$2,500.00	\$5,000.00	
	- Well Pump	9	EA	\$1,500.00	\$13,500.00	
WATER W	ELL CLEANING					
4.0	Water Well Cleaning	9	EA	\$26,000.00	\$234,000.00	

TOTAL AMOUNT \$271,450.00