

Ojai Unified School District

414 East Ojai Avenue, P.O. Box 878, Ojai, CA 93024 (805) 640-4300 • Fax (805) 640-4419 • www.ojaiusd.org

June 3, 2020

Addendum #2

Project #2020-1508

RESPONSES TO REQUESTS FOR INFORMATION:

1) Do we need to raise the utility boxes?

OUSD Response: Utility boxes should match the new asphalt to avoid any trip hazards.

2) Do the utility box lids need to be replaced?

OUSD Response: Yes.

3) New asphalt should receive two (2) coats of traffic paint. What does OUSD require? OUSD Response: Two (2) coats on all new asphalt.

4) When does this project need to be completed?

OUSD Response: This needs to be completed no later than August 10, 2020.

5) There are four (4) cracked concrete panels near the west ball wall. Does OUSD want these removed?

OUSD Response: Yes