



Please Reply To:

AmeriSci Los Angeles

24416 S. Main Street, Ste 308

Carson, California 90745

TEL: (310) 834-4868 • FAX: (310) 834-4772

LABORATORY ELECTRONIC TRANSMITTAL

To: Yesenia Galeana
Executive Environmental Services Corporatio

From: Rosa E. Pena

Fax #:

AmeriSci Job #: 923011442

Subject: PLM 3 day Results

Client Project: 23-Z0172-0023; Building F MPR

Email: info@execenv.com, ygaleana@execenv.com

Date: Tuesday, January 31, 2023

Time: 11:45:02

Comments:

Number of Pages: _____
(including cover sheet)

NOTE: Attached report is to be considered preliminary until final review with accompanying analysis summary letter is issued.

CONFIDENTIALITY NOTICE: Unless otherwise indicated, the information contained in this communication is confidential information intended for use of the individual named above. If the reader of this communication is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is prohibited. If you have received this communication in error, please immediately notify the sender by telephone and return the original message to the above address via the US Postal Service at our expense. Samples are disposed of in 60 days or unless otherwise instructed by the protocol or special instructions in writing. Thank you.

Certified Analysis Service 24 Hours A Day • 7 Days A Week Competitive Prices
visit our web site - www.amerisci.com

Boston • Los Angeles • New York • Richmond



AmeriSci Los Angeles

24416 S. Main Street, Ste 308
Carson, California 90745
TEL: (310) 834-4868 • FAX: (310) 834-4772

PLM Bulk Asbestos Report

Executive Environmental Services Corpor **Date Received** 01/27/23 **AmeriSci Job #** 923011442
Attn: Yesenia Galeana **Date Examined** 01/29/23 **P.O. #**
310 East Foothill Blvd. **Page** 1 of 3
Suite 200 **RE: 23-Z0172-0023; Building F MPR**
Arcadia, CA 91006

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2301250023RK-01	923011442-01L1	No	NAD
Location: Dining Area, NE / 12x12 White Floor Tile And Mastic / Dining Area, Serving Area, Hallway			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: White, Homogeneous, Non-Fibrous, Floor Tile			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250023RK-01	923011442-01L2	No	NAD
Location: Dining Area, NE / 12x12 White Floor Tile And Mastic / Dining Area, Serving Area, Hallway			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Tan, Homogeneous, Non-Fibrous, Mastic			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250023RK-02	923011442-02L1	No	NAD
Location: Dining Area, West Near Custodial Closet / 12x12 White Floor Tile And Mastic / Dining Area, Serving Area, Hallway			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: White, Homogeneous, Non-Fibrous, Floor Tile			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250023RK-02	923011442-02L2	No	NAD
Location: Dining Area, West Near Custodial Closet / 12x12 White Floor Tile And Mastic / Dining Area, Serving Area, Hallway			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Tan / Black, Heterogeneous, Non-Fibrous, Mastic			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250023RK-03	923011442-03L1	No	NAD
Location: Serving Area, South / 12x12 White Floor Tile And Mastic / Dining Area, Serving Area, Hallway			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: White, Homogeneous, Non-Fibrous, Floor Tile			
Asbestos Types:			
Other Material: Non-fibrous 100%			

Client Name: Executive Environmental Services Corporation

PLM Bulk Asbestos Report

23-Z0172-0023; Building F MPR

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2301250023RK-03	923011442-03L2	No	NAD
Location: Serving Area, South / 12x12 White Floor Tile And Mastic / Dining Area, Serving Area, Hallway			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Tan, Homogeneous, Non-Fibrous, Mastic			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250023RK-04	923011442-04	No	NAD
Location: Dining Area, West Wall / Vinyl Baseboard Adhesive (Multiple Types) / Dining Area, Serving Area, Hallway Walls And Cabinets			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Dark Brown, Homogeneous, Non-Fibrous, Adhesive			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250023RK-05	923011442-05L1	No	NAD
Location: Dining Area, East Wall / Vinyl Baseboard Adhesive (Multiple Types) / Dining Area, Serving Area, Hallway Walls And Cabinets			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Baseboard			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250023RK-05	923011442-05L2	No	NAD
Location: Dining Area, East Wall / Vinyl Baseboard Adhesive (Multiple Types) / Dining Area, Serving Area, Hallway Walls And Cabinets			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Dark Brown, Homogeneous, Non-Fibrous, Adhesive			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250023RK-05	923011442-05L3	No	NAD
Location: Dining Area, East Wall / Vinyl Baseboard Adhesive (Multiple Types) / Dining Area, Serving Area, Hallway Walls And Cabinets			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: White, Homogeneous, Non-Fibrous, Compound			
Asbestos Types:			
Other Material: Non-fibrous 100%			
2301250023RK-06	923011442-06L1	No	NAD
Location: Hallway, West Wall / Vinyl Baseboard Adhesive (Multiple Types) / Dining Area, Serving Area, Hallway Walls And Cabinets			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Black, Homogeneous, Non-Fibrous, Baseboard			
Asbestos Types:			
Other Material: Non-fibrous 100%			

Client Name: Executive Environmental Services Corporation

PLM Bulk Asbestos Report

23-Z0172-0023; Building F MPR

Client No. / HGA	Lab No.	Asbestos Present	Total % Asbestos
2301250023RK-06	923011442-06L2	No	NAD
Location: Hallway, West Wall / Vinyl Baseboard Adhesive (Multiple Types) / Dining Area, Serving Area, Hallway Walls And Cabinets			(by CVES) by Rosa E. Pena on 01/29/23
Analyst Description: Off-White, Homogeneous, Non-Fibrous, Adhesive			
Asbestos Types:			
Other Material: Non-fibrous 100%			

Reporting Notes:

Analyzed by: Rosa E. Pena
 Date: 1/29/2023



Reviewed by: Patricia Weakley



*NAD = no asbestos detected; Detection Limit <1%; Reporting Limits: CVES = 1%, 400 Pt Ct = 0.25%, 1000 Pt Ct = 0.1%; NA = not analyzed; NA/PS = not analyzed / positive stop; NVA = No Visible Asbestos; PLM (polarized light microscopy) Bulk Asbestos Analysis by EPA 600/R-93/116, including requirements for EPA 600/M4-82-020 per 40 CFR 763 (NVLAP Lab #200346-0); Note: PLM is not consistently reliable in detecting asbestos in floor coverings and similar NOB materials. TEM is currently the only method that can be used to determine if this material can be considered or treated as non-asbestos-containing in New York State (also see EPA Advisory for floor tile, FR 59, 146, 38970, 8/1/94). NIST Accreditation requirements mandate that this report must not be reproduced except in full with the approval of the laboratory. This PLM report relates ONLY to the items tested.

923011442

ENVIRONMENTAL HEALTH & SAFETY SIMPLIFIED

Asbestos -- PLM

Project #: 23-Z0172-0023

Sampled by: Rhys Kuzmic

Site Zip Code: 91723

Sample Date: 01/25/2023

Page 1 of 2

Originating Office: [] 349 E. Foothill Blvd., Suite 200, Arcadia, CA 91006
 Phone: 626.441.7050 Fax: 626.441.0016

Lab Submitted to: [x] AmegSci
 [] EMLab (Glendale)
 [] LA Testing

The receiving Laboratory is required to complete the following:

- All invoices are to be sent to: 310 E. Foothill Blvd., Suite 200, Arcadia, CA 91006 with a copy of the lab report.
- Analyze all samples by PLM by EPA 600/R-93/116.
- Stop analysis of homogeneous groups at first positive that is greater than or equal to 1.0%.

Optional items to be completed by the laboratory (if check marked): [x] Email Report to: Info@execenv.com [x] Other: ygalearna@execenv.com;
 US Mail Report to: Originating office check marked above Other: Alternate billing address:

Building Name: Building F MPR

4. All lab reports and invoices are to contain the Project Number from above.

5. Unsigned and reports marked draft are unacceptable.

6. Report to the attention of: Yesenia Galeana, Phone: (562) 889-1327

Sample No.:	Sample Location - Include Room information where appropriate	Material Description	Homogeneous Location	No.	Quantity	Percent Damaged
-01	Dinms Area, NE	12x12 white floor tile and grout	Dinms Area, Scrubs Area, Hallway	1	4,800 sq ft	< 1
-02	Dinms Area, west near Custodial Closet	Mastic		↓	↓	↓
-03	Scrubs Area, south			↓	↓	↓
-04	Dinms Area, West wall	Vinyl baseboard adhesive (multiple types)	Dinms Area, Scrubs Area, Hallway walls and cabinets	2	300 LF	0
-05	Dinms Area, east wall			↓	↓	↓
-06	Hallway, west wall			↓	↓	↓

Prefix: 2301250023RK

Notes:

Released By, Date, & Time: [Signature] 01-27-2023 17:25

Received By, Date, & Time: [Signature] 01-27-2023 17:25

Released By, Date, & Time: [Signature] 01-27-2023 17:25

Form: AL-006PLM