



**ARLINGTON COUNTY, VIRGINIA
AGREEMENT NO. 22-DES-R-585
AMENDMENT NUMBER 2**

This Amendment Number 2 is made on the date of execution by the County and amends Agreement Number 22-DES-R-585 ("Main Agreement") dated July 29, 2021, between DPF Services LLC ("Contractor") and the County Board of Arlington County, Virginia ("County").


The County and the Contractor agree to amend the Main Agreement as follows:

- 1. PURSUANT TO PARAGRAPH 2. CONTRACT TERM, THIS AGREEMENT IS HEREBY RENEWED FROM JULY 1, 2024 TO JUNE 30, 2025.**


All other terms and conditions of the Main Agreement remain in effect.

WITNESS THESE SIGNATURES:

THE COUNTY BOARD OF ARLINGTON
COUNTY, VIRGINIA

SIGNATURE: 
PRINT: Meloni Hurley
TITTLE: Assistant Purchasing Agent
DATE: 5/3/2024

DPF SERVICES LLC

SIGNATURE: 
PRINT: Lindsay Rehebrg
TITTLE: Director of Operations
DATE: 5/2/2024

STAFFORD COUNTY PUBLIC SCHOOLS

31 Stafford Avenue
Stafford, Virginia 22554
Telephone (540) 658-6000
www.staffordschools.net



AMENDMENT # 4
CONTRACT RENEWAL

February 26, 2024

DPF Services, LLC
11812 Main St., Unit C-112
Fredericksburg, VA 22408

Reference: Contract # 22-SCPS-006B, Sublet Repair Services, Contract Renewal

Dear DPF Services, LLC:

Stafford County Public Schools (Stafford Schools) requests to extend the above referenced contract between Stafford Schools and DPF Services, LLC dated November 20th, 2021 for an additional one year term from July 1, 2024 through June 30, 2025. There are no remaining renewals. .

All other terms, conditions, specifications and pricing remain the same. Please sign below confirming your acceptance to extend this contract through June 30, 2025 per all terms and conditions of the above referenced contract

Best Regards,
Kadie Smith
Procurement Coordinator
Stafford County Public Schools

CONTRACTOR: DPF Services, LLC

Print Name: Lindsay Rehberg

Signature: Lindsay Rehberg

Date: 03/28/2024



County of Fairfax, Virginia

NOTICE OF AWARD

Date of Award: July 29, 2021

CONTRACT TITLE: OEM Parts and Repair Services for Heavy Duty Trucks & Freightliners

CONTRACT TYPE: Cooperative (CC)

CONTRACT NUMBER: 4400010479 (City of Fairfax Contract #17036)

NIGP CODE: 06066, 92815

CONTRACT PERIOD: Date of Award though June 30, 2022

RENEWALS: None

PAYMENT TERMS: Net 30 Days

FOB: Destination

PRICES: In accordance with the City of Fairfax Contract #17036. See attached Pricing Schedule.

CONTRACTOR:
DPF Services, LLC.
11812 Main St. Unit C-112
Fredericksburg, VA 22408

SUPPLIER CODE:
1000046356

Contact: Richard Rehberg
Telephone: (540)-412-5611 ext. 100
E-mail: richard@dpfservicesllc.com

DPMM CONTACT: Krystyna Watts, Contract Specialist I
Telephone: (703) 324-3279
Fax: (703) 324-3228
E-mail: krystyna.watts@fairfaxcounty.gov

ORDERING INSTRUCTIONS:

County Departments may enter into FOCUS (Fairfax County Unified Systems) a shopping cart indicating the item/service required, the quantity, the payment terms and the delivery date. The shopping cart must be annotated with the contract number. Requests exceeding the small purchase threshold (\$10k) will be routed to DPMM and a purchase order will be executed.

Krystyna Watts
Contract Specialist

DISTRIBUTION:

DOF – Accounts Payable/e
DVS – Steve Slaustas/e
DVS – Jaime Martinez/e

Contract Specialist – Krystyna Watts
ACS, Team 1 – Cynthia Parker
Supplier Diversity – Chris McGough/e

Notice of Award**4400010479****Page 2****Pricing Schedule**

MFG/OEM	OEM Part #	Type	DPF Services, LLC Part Number	NEW PRICING
CAT C13, C15	290-0045 / 301-7856 Or Re-man 10R-6088	DPF	CQ1702-K	\$3,523.50
CAT C13, C15	291-8519 / 294-8694 Or re-man 10R-6089	DPF	CQ1704-K	\$3,645.00
CAT C9	261-2318 / 264-1556 / 220-6054 / 250-0630	DPF	C0011-SA	N/A
CAT C9	272-2425 / 6351696	DPF	C0093-SA	N/A
CAT C9, C13, C15	304-7502 / 304-7519 Or Re-man 10R-7056	DPF	CQ1501-K	\$2,841.75
CAT C9, C13, C15	304-7502 / 304-7519, 10R-7056	DPF	DX46005	\$3,171.15
CAT C9, C7	291-8515 / 294-8692 Re-Man 10R-6087 Assembly # 309-6991	DPF	CN1505-K	\$2,798.55
CATERPILLAR OFF-ROAD Model Nos: 324E L, D7E, 120M2	20R-0696 / 20R-5620 / 358-3658 / 358-3659	DPF	D2003-SA	N/A
CATERPILLAR OFF-ROAD Model Nos: 735B, 740B, 349E, 980K	20R-0700 / 20R-5624 / 358-3668 / 358-3669	DPF	D2011-SA	N/A
CATERPILLAR OFF-ROAD Model Nos: 966K, 972K	20R-0698 / 20R-5622 / 358-3663 / 358-3664	DPF	D2001-SA	N/A
Caterpillar C7 (US07) (i.e. C7S)	305-4565, 305-6294, 10R-6084, 309-0000, 00116233	DPF	CH1110-K	\$1,403.88
Caterpillar C7 and C15 US07	304-7578, 304-7579, 10R-6082, 302-5204	DPF	CK1406-K	\$2,841.75
Caterpillar C7 US07	291-8513, 294-8690, 10R-6085, 290-7307, 0117438	DPF	CH1408-K	\$1,925.41
Caterpillar Off-Road	390-0673, 390-0675, 390-0637, D2016-SA	DPF	46011	\$2,968.65
Caterpillar: C13/15	10R-6088, 290-0045, 301-7856, C0013-SA, C17-0040	DPF	46002	\$3,503.25
Caterpillar: C13/15	10R-6089 / 173-3481, 291-8519, 293-9990, 291-8519, 294-8694	DPF	DX46003	\$3,549.15
CHEVROLET/GMC	15876232 - Chevy/GMC Silverado & Sierra C/K 2500HD 2007-2009 Duramax 6.6L Crew Cab Short Bed (6'6"); 153" WB Only	DPF	649004/RL46804	\$1,716.71

Notice of Award

4400010479

Page 3Pricing Schedule

CHEVROLET/GMC	25784982 - Chevy/GMC Express 3500- SAVANA 3500 Cutaway Van 139" WB only 2010 VIN #6 Duramax 6.6L 2008-2010	DPF	649006/RL46806	\$1,716.71
Cummins	2871571NX, 2871760NX, 2871467NX, C0180-ID, BG0412	DOC	58071	\$1,618.65
Cummins	5284269NX	DOC	58075	\$2,295.00
Cummins	5287473NX, BG0409	DOC	58076	\$2,025.00
Cummins	4353285NX, C0229-ID, XN0625	DOC	58080	\$2,428.65
Cummins	5287472NX, 2871485NX, BG0408	DOC	58084	\$1,620.00
Cummins	4965285NX / 5287480NX	DOC	BG0401-K	\$1,417.50
Cummins	Q617786 / Q617786A / 94106MD	DOC	C0085-ID	N/A
Cummins	3976606 Or Q617788 / 3103617 / Q619496 / Q619733 / Q617940A / Assembly #3978026 / 3999661 Or 3999662	DPF	CJ1202-K	\$1,944.00
Cummins ISB	2871571 / 2871571NX / 2871571RX	DOC	BG0412-K	\$1,687.77
Cummins ISB, PACCAR PX6	5287473 / 5287473NX / 2871535 / 2871535NX	DOC	BG0409-K	\$1,801.98
Cummins ISB, PACCAR PX6	5287476 / 5287476NX / 2871518 / 2871518NX	DOC	BG0410-K	\$1,795.64
Cummins ISB, PACCAR PX6	5287478 / 5287478NX / 5287478RX / 4965340 / 4965340NX	DOC	BG0411-K	\$1,713.15
Cummins ISC	2871753	DOC	CJ0419-K	\$2,111.17
Cummins ISC	2871569	DOC	CJ0422-K	\$2,095.78
Cummins ISC	2880153	DOC	CJ0424-K	\$2,106.77
Cummins ISC	5295365RX	DOC	XN0637-K	\$2,666.83
Cummins ISL/ISB	4353303	DOC	LJ0429-K	\$1,738.53
Cummins ISX	2880516	DOC	CJ0423-K	\$2,113.37
Cummins ISX	2880508, 2880508NX, 2880508RX	DOC	XN0616-K	\$2,760.33
Cummins ISX	2871583, 2871583NX, 2871583RX	DOC	XN0630-K	\$2,678.93
Cummins ISX	2880165, 2880165NX, 2880165RX	DOC	XN0636-K	\$2,660.24

Notice of Award4400010479Page 4Pricing Schedule

Cummins ISX	2880500, 2880500NX, 2880500RX	DOC	XN0638-K	\$2,671.23
Cummins ISX	2885912, 2885912NX, 2885912RX	DOC	XN0639-K	\$2,664.63
Cummins / Paccar	2871599NX, 4329017NX, C0132-SC	SCR	58074	\$2,158.65
Cummins / Paccar	4354211NX, 2880256NX, 2880222NX, A029F272, C0147-SC	SCR	58087	\$2,227.50
Cummins / Paccar	A029D872 or 2880167, 2880247NX, 4329093NX, C0168-SC	SCR	58091	\$2,698.65
Cummins / Paccar MX	2134929, 2134929NX, 2134929PE	DPF	58092	\$3,171.15
Cummins / Paccar(SiliconCarbide DPF)	4394577, 5579297, 4394979	DPF SIC	58081	\$3,442.50
Cummins / Paccar: MX	1906311PEX, C0159-SA. XN1107	DPF	58036	\$1,591.65
Cummins / Paccar: MX (RECON)	1906311PEX, C0159-SA, XN1107	DPF (Recon)	58036-RX	\$1,012.50
Cummins / Paccar: MX / International	2131533PE, 2516807C91	DPF	58069	\$3,105.00
Cummins ISB	4965285NX, 5287480NX, A035H236, C0103-ID, C20- 0001, BG0401	DOC	58022	\$1,414.80
Cummins ISB	4965338NX, 5287474NX, C0119-ID, BG0402	DOC	58053	\$2,023.65
Cummins ISB	Q621299, 5287477NX, 4965222NX, C20-002, C0121- ID, BG0403	DOC	58054	\$1,551.15
Cummins ISB	5302638NX, 4353352RX, A047V540, C0184-ID, BG0431	DOC	58072	\$2,058.75
Cummins ISB	4353326NX, 4353324NX, 5308480NX, C0226-ID, BG0430	DOC	58093	\$1,555.20
Cummins ISB	5287474NX / 4965338NX	DOC	BG0402-K	\$2,125.04
Cummins ISB	5287477NX / 4965222NX	DOC	BG0403-K	\$1,429.37
Cummins ISB	2871461NX / Q6293555 / 3618711	DPF	BG1104-K	\$1,424.25
Cummins ISB	5295603NX (EPN A040M135)	DPF	BGF006-K	\$1,201.50
Cummins ISB	5295607NX	DPF	BGF007-K	\$1,316.25
Cummins ISB	5295605NX	DPF	LJ1206-K	\$1,463.40

Notice of Award**4400010479****Page 5****Pricing Schedule**

Cummins ISB & Paccar PX6	5287475, 5287475NX, 4965339, 4965339NX	DOC	BG0404-K	\$1,607.38
Cummins ISB 6.7 & Paccar PX6	2880499NX, BG0407, C0200-ID	DOC	58083	\$1,618.65
Cummins ISB 6.7 & Paccar PX6	2880499, 2880499NX, 2880499RX	DOC	BG0407-K	\$1,694.76
Cummins ISB / ISX	5295605NX, C0153-SA, C17-0073, LJ1206	DPF	58035	\$1,466.10
Cummins ISB / ISX (RECON)	5295605NX, C0153-SA, C17-0073, LJ1206	DPF (Recon)	58035-RX	\$911.25
Cummins ISB 6.7	4353324 / 4353324NX / 4353324RX / 4353326 / 4353326NX / 4353326RX / 5308480 / 5308480NX	DOC	BG0430-K	\$1,992.33
Cummins ISB 6.7	4353352 / 4353352NX / 4353352RX / 5302638 / 5302638NX	DOC	BG0431-K	\$2,005.02
Cummins ISB 6.7L	4965227NX	DPF	BG1102-K	\$1,066.50
Cummins ISB(US10)&Paccar PX6(US10)	2880520 / 2880520NX / 2880520RX	DOC	BG0406-K	\$2,185.79
Cummins ISB, Paccar PX6	5287478NX, 4965340NX, BG0411	DOC	58200	\$1,483.65
Cummins ISB, Paccar PX6	2880520NX, BG0406	DOC	58202	\$1,414.80
Cummins ISB, Paccar PX6	5287472 / 5287472NX / 2871485 / 2871485NX	DOC	BG0408-K	\$1,649.70
Cummins ISB, PX6	2871462NX	DPF	BG1103-K	\$1,181.25
Cummins ISB/ISC	2885940NX, C0158-ID, CJ0407	DOC	58063	\$1,552.50
Cummins ISB/ISC	2885940 / 2885940NX / 2885940RX	DOC	CJ0407-K	\$1,768.50
Cummins ISB/ISC/ISX/ISL	2880512NX, 2871468NX, A029W349, C0224-ID, CJ0404	DOC	58098	\$1,726.65
Cummins ISB; PX6	4965287NX	DPF	BG1101-K	\$1,120.50
Cummins ISC	4965352NX, 5287491NX, C0117-ID, C20-0016, CJ0403	DOC	58052	\$1,591.65
Cummins ISC	5287491NX / 4965352NX	DOC	CJ0403-K	\$1,456.79
Cummins ISC / ISL	2871923NX, 2871923, CJ0405, A029B190, 281923, 26326120259, C20-0011, C0137-ID	DOC	58059	\$1,348.65
Cummins ISC / ISL	4353304	DOC	58095	\$1,549.80
Cummins ISC / ISL	2880498NX, CJ0421	DOC	58208	\$1,618.65

Notice of Award4400010479Page 6Pricing Schedule

Cummins ISC / ISL	2880589, A029S790, C0142-ID	DOC	58216	\$1,753.65
Cummins ISC / ISL	2880588RX / A029U287	DOC	58221	\$1,753.65
Cummins ISC / ISL / Paccar PX8	2871569NX, CJ0422	DOC	58209	\$1,888.65
Cummins ISC / ISL / Paccar PX8	2880516NX, CJ0423	DOC	58210	\$1,618.65
Cummins ISC / ISL / Paccar PX8	2880154RX, CJ0417	DOC	58220	\$1,888.65
Cummins ISC / ISL, PX8	4965284NX, 5287496NX, A035H295, C0005-ID, C20-0002, CJ0401	DOC	58023	\$1,618.65
Cummins ISC / Paccar PX8	4969838NX, Q621371, Q623316, Q623804, 4969839NX, 4965286NX, C0003-SA, C17-0042,	DPF	58003	\$1,537.65
Cummins ISC / Paccar PX8	4969838NX / 4965286NX	DPF	CJ1201-K	\$1,458.00
Cummins ISC / Paccar PX8	4969839 / 4969839NX	DPF	CJ1203-K	\$1,736.10
Cummins ISC / ISL / Paccar PX8	2880153NX, CJ0424	DOC	58211	\$1,551.15
Cummins ISC 8.3/ISL 9 & Paccar PX8	2871929 / 2871929NX / 2871929RX	DOC	CJ0420-K	\$1,658.31
Cummins ISC 8.3/ISL 9 & Paccar PX8	2880498 / 2880498NX / 2880498RX	DOC	CJ0421-K	\$1,658.31
Cummins ISC 8.3/ISL 9 and Paccar PX8	2880154 / 2880154NX	DOC	CJ0417-K	\$1,921.05
Cummins ISC, PX8	4965353NX, 5287489NX, C0092-ID, CJ0402	DOC	58044	\$1,753.65
Cummins ISC, PX8	4965284NX / 5287496NX	DOC	CJ0401-K	\$1,609.88
Cummins ISC, PX8	5287489NX / 4965353NX	DOC	CJ0402-K	\$1,606.23
Cummins ISC, PX8	2871459NX	DPF	CJ1205-K	\$1,397.25
Cummins ISC, PX8	5295606NX	DPF	LJ1207-K	\$1,606.50
Cummins ISC, PX8	5295606NX, C0136-SA, LJ1207	DPF	58030	\$1,524.15
Cummins ISC/ ISL, Paccar PX8	2880514NX, CJ0427	DOC	58097	\$1,684.80
Cummins ISC/ISL, Paccar PX8	2880497	DOC	CJ0418-K	\$2,252.61
Cummins ISC/ISL, Paccar PX9	2880514 / 2880514NX	DOC	CJ0427-K	\$1,985.99
Cummins ISL	2871929NX, C0186-ID, CJ0420	DOC	58073	\$1,549.80

Notice of Award**4400010479****Page 7****Pricing Schedule**

Cummins ISL	5287368NX, 4353289NX, 4387170, C0176-ID, LJ0426	DOC	58078	\$1,788.75
Cummins ISL	5272453 / 4354234 / A034C371 / 5272456	SCR	C0173-SC	N/A
Cummins ISL	2871923NX	DOC	CJ0405-K	\$1,403.33
Cummins ISL	2880589NX	DOC	CJ0406-K	\$1,600.16
Cummins ISL	5300556 / 4353289 / 5287368 (Assmby# 4353399)/ A041R626	DOC	LJ0426-K	\$1,942.84
Cummins ISL	2871463NX	DPF	LJ1204-K	\$1,458.00
Cummins ISL/ISB	4353303RX, 5302636NX, LJ0429, C0228-ID	DOC	58061	\$1,834.65
Cummins ISL-G	4969770NX, C0101-ID, 4969771NX (Two Calaysts per Truck)	DOC	58045	\$1,726.65
Cummins ISM	4965243NX, 5287191NX, A035G674, C20-0003, C0028- ID	DOC	58015	\$1,699.65
Cummins ISM	5287521NX, 4965223NX, A035H536, C20-0004, C0043- ID, MN0403	DOC	58024	\$1,518.75
Cummins ISM	4965217NX, 5287520NX, C0046-ID. MN0403	DOC	58043	\$1,370.25
Cummins ISM	4969668NX, 5287516NX, C0072-ID	DOC	58050	\$1,753.65
Cummins ISM	4969846NX, 5287522NX, MN0406, A68040903214, C0131-ID	DOC	58058	\$1,861.65
Cummins ISM	4969722NX, 5287515NX, 4965078NX, C0139-ID, MN0407	DOC	58060	\$1,416.15
Cummins ISM	4969719NX / 5287519NX / 2606987C91	DOC	MN0401-K	\$1,634.85
Cummins ISM	4965243NX / 5287191NX	DOC	MN0402-K	\$1,701.00
Cummins ISM	4965223, 4965223NX, 5287521, 5287521NX, 5287521RX, 5287520, 5287520NX, 5287520RX, 4965217, 4965217NX	DOC	MN0403-K	\$1,485.00
Cummins ISM	5287522NX / 4969846NX	DOC	MN0406-K	\$1,742.31
Cummins ISM	5287515 / 5287515NX / 4969722 / 4969722NX / 4965078 / 4965078NX	DOC	MN0407-K	\$1,935.23

Notice of Award**4400010479****Page 8****Pricing Schedule**

Cummins ISM	4965055 / 4965055NX / 4352920 / 4352920NX / 3817962C91 (Assembly#), 4352921, 4352921NX, 2880281, 2880281NX, 2606777c1	DPF	MN1001-K	\$1,518.75
Cummins ISM	4936737, 4936737NX, 4965244, 4965244NX, 4352923, 4352923NX, 2880169, 2880169NX, 3623370C93	DPF	MN1002-K	\$1,482.30
Cummins ISM	4965224NX / 4352989NX	DPF	MN1003-K	\$1,591.65
Cummins ISM	4965218NX / 4352922NX	DPF	MN1004-K	\$1,549.80
Cummins ISM / ISL / Paccar	4965244NX, 2880169NX, Q621378, 4352923NX, 4965055D, N8894071, 3623370C93, 4352920NX, C17-0031, C0004-SA, C0073- SA, MN1002	DPF	58004	\$1,348.65
Cummins ISM / ISL / Paccar	2606777C1, 2817962C91, 3817962C91, 4352920NX, 4936737NX, 4965055NX, C0018-SA, C17-0038, MN1001	DPF	65012	\$1,552.50
Cummins ISM/ISL	4936736NX, 2606987C91, 5287519NX, A035H544, 4969719NX, C20-0017, C0017-ID	DOC	58039	\$1,645.65
Cummins ISX	2871496NX, 2888250NX, A030W859, C20-0019, C0076-ID, XN0509	DOC	58016	\$1,667.25
Cummins ISX	2888262NX, 4969721NX, 2606971NX, 2880259NX, A030X734, Q62230, 4936734NX, 2607044C91, 4969721NX, 4965079NX, Q620939, C0083-ID, C20- 0020, C0016-ID, XN0506	DOC	58017	\$1,821.15
Cummins ISX	2880174NX, C0114-ID, XN0614	DOC	58018	\$1,983.15
Cummins ISX	2880505NX, C0106-ID, XN0612, 4353251RX, C0211- ID, XN0622	DOC	58019	\$2,361.15
Cummins ISX	2885941NX, 2888263NX, C0109-ID, C20-0028, XN0508	DOC	58020	\$1,915.65

Notice of Award**4400010479****Page 9****Pricing Schedule**

Cummins ISX	5309560NX, 4353264NX, C0152-ID, XN0618	DOC	58021	\$2,112.75
Cummins ISX	2888249NX, 4965317NX, A030W858, 4969542NX, C20- 0005, C0060-ID, XN0504	DOC	58025	\$1,659.15
Cummins ISX	2888248, 4965225NX, A030W857, C20-0006, C0038-ID, XN0501	DOC	58026	\$1,788.75
Cummins ISX	2888247NX, A035W856, 4695304NX, C20-0007, C0015-ID, XN0502	DOC	58027	\$1,956.15
Cummins ISX	2888231, 5289769, 5303922, C0145-SA, C17-0087	DPF	58034	\$1,856.25
Cummins ISX	2880506NX, C20-0015, C0112-ID, XN0615	DOC	58040	\$1,983.15
Cummins ISX	2880501NX, C0124-ID. XN0617	DOC	58055	\$1,788.75
Cummins ISX	4328760NX, C0126-ID. XN0621	DOC	58056	\$1,969.65
Cummins ISX	5274535RX	DOC	58066	\$2,308.50
Cummins ISX	5289745NX	DOC	58068	\$2,254.50
Cummins ISX	4353284NX, 4329542NX, XN0624, A047V484, 1978265PE, C0187-ID, C0163-ID	DOC	58079	\$2,631.15
Cummins ISX	4329453 (Assembly # A045R857)	SCR	58088	\$4,657.50
Cummins ISX	4353305, 4353305RX, C0227- ID	DOC	58094	\$1,686.15
Cummins ISX	4353323	DOC	58096	\$1,566.00
Cummins ISX	2888257NX, 2880502NX, XN0641	DOC	58099	\$2,428.65
Cummins ISX	5304054NX	DOC	58207	\$2,563.65
Cummins ISX	2880504, XN0635	DOC	58212	\$2,226.15
Cummins ISX	2880503, XN0634	DOC	58213	\$2,833.65
Cummins ISX	2871583NX, XN0630	DOC	58215	\$2,496.15
Cummins ISX	2885912NX, XN0639	DOC	58217	\$2,833.65
Cummins ISX	5295365NX, 5289224NX, XN0637	DOC	58218	\$2,563.65
Cummins ISX	2880165, XN0636	DOC	58219	\$2,011.50
Cummins ISX	4353219, A045R856, 4329452	SCR	58222	\$2,158.65
Cummins ISX	2888231NX / 5289769NX Or 5303922NX	DPF	58034	\$1,856.25

Notice of Award**4400010479****Page 10****Pricing Schedule**

Cummins ISX	2880246 / 4329094 / 5290105 / A029D871 (Assmby 2880166)	SCR	C0169-SC	N/A
Cummins ISX	2880163 / 4329092 / 5290070 (Assmby# 2880276)	SCR	C0171-SC	N/A
Cummins ISX	2880512NX / 2871468	DOC	CJ0404-K	\$2,211.30
Cummins ISX	4965225NX / 2888248NX	DOC	XN0501-K	\$1,701.00
Cummins ISX	4965304NX / 2888247NX	DOC	XN0502-K	\$1,822.50
Cummins ISX	2888249NX / 4969542NX Or 4965317NX	DOC	XN0504-K	\$1,633.50
Cummins ISX	2888261NX / 4969718NX, 4965053, 2596690C91	DOC	XN0505-K	\$1,761.75
Cummins ISX	2888262, 4969721, 4969721NX, 4965079, 4965079NX, 2880259, 2880259NX, 4936734, 4936734NX, Q620939	DOC	XN0506-K	\$1,721.25
Cummins ISX	2888263NX / 2885941NX / 2601509	DOC	XN0508-K	\$2,119.50
Cummins ISX	2888250NX / 2871496NX	DOC	XN0509-K	\$1,853.55
Cummins ISX	2888246, 2888246NX, 2888246RX, 4965215, 4965215NX	DOC	XN0525-K	\$1,902.15
Cummins ISX	2880505NX	DOC	XN0612-K	\$2,029.05
Cummins ISX	2880582, 2880582NX, 2880582RX, 4353249, 4353249NX, 4353249RX, 5298340, 5298340NX, 5286910, 5286910NX	DOC	XN0613-K	\$1,871.10
Cummins ISX	2880174NX	DOC	XN0614-K	\$1,962.23
Cummins ISX	2880506NX	DOC	XN0615-K	\$1,871.10
Cummins ISX	2880501NX	DOC	XN0617-K	\$1,965.87
Cummins ISX	5309560NX / 4353264NX	DOC	XN0618-K	\$2,127.47
Cummins ISX	5298349NX or RX / 4353221NX or RX / 5287321NX or RX	DOC	XN0620-K	\$2,193.89
Cummins ISX	4328760NX	DOC	XN0621-K	\$2,029.05
Cummins ISX	4353251 / 4353251NX / 4353251RX / 5300526 / 5300526NX/ 5289000 / 5289000NX	DOC	XN0622-K	\$2,595.11

Notice of Award**4400010479****Page 11****Pricing Schedule**

Cummins ISX	4353284 / 4353284NX / 4353284RX / 5298350 / 5298350NX / 5287100 / 5287100NX / 4329542 / 4329542NX	DOC	XN0624-K	\$2,671.25
Cummins ISX	4353285 / 4353285NX / 4353285RX / 5298345 / 5298345NX / 4329543 / 4329543NX	DOC	XN0625-K	\$2,664.90
Cummins ISX	2880507 / 2880507NX / 2880507RX	DOC	XN0633-K	\$2,609.58
Cummins ISX	2880503 / 2880503NX / 2880503RX	DOC	XN0634-K	\$2,449.36
Cummins ISX	2880504 / 2880504NX / 2880504RX	DOC	XN0635-K	\$2,449.36
Cummins ISX	2880502 / 2880502NX / 2880502RX	DOC	XN0641-K	\$2,563.38
Cummins ISX	4969700NX / 5283778NX / 5297990NX / 4969702NX / 5283669NX / 5297522NX / 4965226NX / 4965129NX	DPF	XN1101-K	\$1,458.00
Cummins ISX	4965129D / 5283799NX / 4965305NX / 5297989NX / 4969703NX or Assembly 20970295 / 4965322	DPF	XN1102-K	\$1,610.55
Cummins ISX	4969701NX / 2880168NX / 4965129 / 4965129NX	DPF	XN1105-K	\$1,458.00
Cummins ISX	5295604NX	DPF	XN1106-K	\$1,748.25
Cummins ISX	5295609, 5295609NX, 5295609RX, 5283286, 5283286NX, 5579295, 5579295NX, 5579295RX, 1906311, 1906311PE, 1906311PEX, 2510616C91, 2510795C91, 5011031R91	DPF	XN1107-K	\$1,822.50
Cummins ISX / International Maxxforce N13 / Paccar MX	5295609NX, 2510616C91, 2510795C91, C17-0079, C0107-SA, XN1107	DPF	58014	\$1,599.75
Cummins ISX / Maxxforce 13, 11	4969718NX, 2888261NX, C0010-ID, C20-0018, XN0505	DOC	58048	\$1,753.65
Cummins ISX / Navistar N13	4353274 / 5313770, 2510787C91, XN0632-K	DOC	58214	\$2,226.15

Notice of Award**4400010479****Page 12****Pricing Schedule**

Cummins ISX / Paccar	2880168NX, 4965129NX, 4965226NX, 4969702NX, 5283778NX, 5283669NX, 5297522NX, 4969700NX, 4969701NX, 5297990NX, 4388409RX, 4388410RX, C17-0032, C0001-SA, XN1105	DPF	58001	\$1,551.15
Cummins ISX / Paccar	5295604NX, XN1106, C0134-SA, C17-0084	DPF	58031	\$1,734.75
Cummins ISX / Paccar (RECON)	2880168NX, 4965129NX, 4965226NX, 4969702NX, 5283778NX, 5283669NX, 5297522NX, 4969700NX, 4969701NX, 5297990NX, 4388409RX, 4388410RX, C17-0032, C0001-SA, XN1105	DPF (Recon)	58001-RX	\$877.50
Cummins ISX / Paccar (RECON)	5295604NX, XN1106, C0134-SA, C17-0084	DPF (Recon)	58031-RX	\$1,046.25
Cummins ISX / Paccar MX	1827739PEX, 2871578NX, Q629458, C0066-SA, C0067-SA, C17-0037	DPF	58008	\$1,471.50
Cummins ISX / Paccar MX	2880582NX, 5298340NX, 4353249NX, 5286910NX, XN0613, C0111-ID, C0127-ID, C0303-ID, 1978266	DOC	58041	\$2,091.15
Cummins ISX / Paccar MX	5298349NX, 4353221NX, 2871577NX, 1837303PE, C0070-ID, 1978264PE, C0143-ID	DOC	58062	\$2,023.65
Cummins ISX / Paccar MX	2871577NX / 1837303PE	DOC	XN0610-K	\$2,064.29
Cummins ISX / Paccar MX	2871581NX, 1827310PEX	DPF	XN1103-K	\$1,714.50
Cummins ISX / Paccar MX	2871578NX, 1827739PEX	DPF	XN1104-K	\$1,671.30
Cummins ISX / Volvo / Mack: MP7	4388411, 4388411RX, 4965322, 4969703, 4969703NX, 5283799, 5297989, 5297989NX, 5579292, 4965129D, 4965305NX, 20970295, 85001366, 4388411NX, 4965305RX, 4965305,	DPF	82002	\$1,586.25

Notice of Award**4400010479****Page 13****Pricing Schedule**

	5297989RX, 4969703RX, C0021-SA, VN1203, C17-0044			
Cummins ISX / Volvo / Mack: MP7 (Recon)	4388411, 4388411RX, 4965322, 4969703, 4969703NX, 5283799, 5297989, 5297989NX, 5579292, 4965129D, 4965305NX, 20970295, 85001366, 4388411NX, 4965305RX, 4965305, 5297989RX, 4969703RX, C0021-SA, VN1203, C17-0044	DPF (Recon)	82002-RX	\$945.00
Cummins ISX/ International MaxxforceN13/ PaccarMX (Recon)	5295609NX, 2510616C91, 2510795C91, C17-0079, C0107-SA, XN1107	DPF (Recon)	58014-RX	\$945.00
Cummins: ISB	4965227NX, BG1102-K, Q621376, C0024-SA, C17- 0058	DPF	58005	\$1,100.25
Cummins: ISB	4965287NX, Q612386A, Q621386, BG1101, C0023-SA, C17-0029	DPF	58007	\$1,062.45
Cummins: ISB	2871461NX, BG1104, Q629355, 3618711, C17- 0081, C0128-SA	DPF	58028	\$1,281.15
Cummins: ISB	2871462NX, A040M135, C0098-SA, C17-0080, BG1103	DPF	58029	\$1,235.25
Cummins: ISB	5295603NX, C0161-SA, C17- 0091, BGF006	DPF	58067	\$1,208.25
Cummins: ISB (RECON)	4965227NX, BG1102-K, Q621376, C0024-SA, C17- 0058	DPF (Recon)	58005-RX	\$675.00
Cummins: ISB (RECON)	4965287NX, Q612386A, Q621386, BG1101, C0023-SA, C17-0029	DPF (Recon)	58007-RX	\$675.00
Cummins: ISB (RECON)	5295603NX, C0161-SA, C17- 0091, BGF006	DPF (Recon)	58067-RX	\$742.50
Cummins: ISB / Paccar PX6	5295607NX, C0164-SA, BGF007	DPF	58077	\$1,215.00

Notice of Award**4400010479****Page 14****Pricing Schedule**

Cummins: ISC	3103617, 3976606, 3978026, 3999662, Q617940, Q619496, Q619733, 619733, 619496, Q619495, Q619725, Q617940A, 3999661, Q617788, 061794A0A, C17-0054, C0026-SA, CJ1202	DPF	58009	\$1,456.65
Cummins: ISC / ISX	3103618, Q619723, Q619494, 3999660, C0034-ID	DOC	58042	\$2,698.65
Cummins: ISC / Paccar PX8 (RECON)	4969838NX, Q621371, Q623316, Q623804, 4969839NX, 4965286NX, C0003-SA, C17-0042, CJ1201	DPF (Recon)	58003-RX	\$877.50
Cummins: ISL	2871463NX, Q629362, LJ1204, C0062-SA, C17-0030	DPF	58006	\$1,248.75
Cummins: ISL	2871459, 2871459NX, Q629361, CJ1205-K, C0125-SA, C17-0074	DPF	58012	\$1,424.25
Cummins: ISL (RECON)	2871459, 2871459NX, Q629361, CJ1205-K, C0125-SA, C17-0074	DPF (Recon)	58012-RX	\$877.50
Cummins: ISL/ISM (RECON)	4965244NX, 2880169NX, Q621378, 4352923NX, 4965055D, N8894071, 3623370C93, 4352920NX, C17-0031, C0004-SA, C0073-SA, MN1002	DPF (Recon)	58004-RX	\$810.00
Cummins: ISM	4352989NX, 4965224NX, C0022-SA, C17-0043	DPF	58010	\$1,617.30
Cummins: ISM	5273093NX	DPF	DX58033	\$1,483.65
Cummins: ISX (RECON)	1827310PEX, 2871581NX, Q629477, C0033-SA, C0099-SA, C17-0068, XN1103	DPF (Recon)	58011-RX	\$877.50
Detroit DD 15/Mercedes MBE 4000	EA6804901714	DOC	DNT506-K	\$2,477.25
Detroit DD13	EA6804910894 / EA0014903492 * Two DPFs per Truck	DPF	DJ0806-K	\$1,032.72
Detroit DD13, DD15	EA6804910794 / EA00114907192	DPF	DQ1202-K	\$2,617.65
Detroit DD15	EA6804910494 / RA0004903692 * Two DPFs per Truck	DPF	DJ1005-K	\$1,093.50

Notice of Award**4400010479****Page 15****Pricing Schedule**

Detroit DD15	RA6804910294 Or 23537225 / RA6804908692 Or Assembly A6804910594	DPF	DN1501-K	\$1,660.50
Detroit Diesel	A0014907692 / RA0014907692	DPF	DJ0813-K	\$1,032.72
Detroit Diesel DD Series 60, DD13, DD15 & MBE4000	A6804901414	DOC	35018	\$3,003.75
Detroit Diesel DD15	RA6804901214 / A6804903014 Or Assembly A6804901592	DOC	DNT501-K	\$2,477.25
Detroit Diesel DD15	A6804901614	DOC	DNT503-K	\$2,477.25
Detroit Diesel DD15 US07	A6804910394 / RA6804908592	DPF	DQ1508-K	\$3,204.90
Detroit Diesel Series 60/DD13/DD15 and Mercedes-Benz MBE 4000	A6804901414	DOC	DNT505-K	\$2,741.04
Detroit Diesel Series 60/DD15 (US07)	A6804901914	DOC	DNT508-K	\$2,477.25
Detroit Diesel Series 60/DD15 US07	A6804901314	DOC	DNT502-K	\$2,477.25
Detroit Diesel: DD13/15	A0004903492, EA6804910794, RA0014907192, RA6804910794, A6804910794, EA0014907192, C0029-SA, C17-0067	DPF	35008	\$2,328.75
Detroit Diesel: DD15	A0014903592, A6804910894, A0004903792, A6804914194, DJ0806, DJ1005, C17-0076, C0080-SA	DPF	35007	\$938.25
Detroit Diesel: DD15 (RECON)	A0014903592, A6804910894, A0004903792, A6804914194, DJ0806, DJ1005, C17-0076, C0080-SA	DPF (Recon)	35007-RX	\$607.50
Detroit Diesel: MB OM926	A6804904392, A6804905792, A6804906192, A6804910094, R23537521, RA6804908792, RA6804910097, DG1204 C0054-SA, C17-0039	DPF	35006	\$1,667.25
Detroit Diesel: MP7	A0004903692, A6804910494, EA6804910494, C0088-SA	DPF	35011	\$1,065.15

Notice of Award**4400010479****Page 16****Pricing Schedule**

Detroit Diesel: S60	A6804908692, A6804910294, A6804910594, EA6804910594, EA6804910294, 23537225, DN1501, C0002-SA, C17-0036	DPF	35002	\$1,956.15
Detroit Diesel: S60 (RECON)	A6804908692, A6804910294, A6804910594, EA6804910594, EA6804910294, 23537225, DN1501, C0002-SA, C17-0036	DPF (Recon)	35002-RX	\$1,080.00
Detroit Series 50	23535827	DPF	DJ1207-K	\$2,673.00
Detroit/Mercedes MBE 4000/OM460	A6804903214	DOC	C0129-ID	N/A
Detroit/Mercedes MBE 4000/OM460	A6804910094 / A6804906192 R23537521 / RA6804908792 Or A6804904392 Assembly# A6804905792	DPF	DG1204-K	\$1,518.75
DODGE	68035060AA / 68035060AC - Dodge RAM 2500 6.7L Cummins ALL 2007-2012 or RAM 3500 6.7L Cummins 2007-2008 No Cab & Chassis	DPF	649002/RL46802	\$1,488.71
DODGE	68035061AA / 68035061AB - Dodge RAM 3500 6.7L Cummins 2009-2012 No Cab or Chassis	DPF	649003/RL46803	\$1,274.11
FORD	9C3Z5H221B - Ford F-250,350,450,550 SD's 6.4L Pwr Stroke 2008-2010 No Cab or Chassis	DPF	649001/RL46801	\$1,247.29
FORD	9C3Z5H221A - Ford F-250,350,450,550 SD's 6.4L Pwr Stroke 2008-2010 INCLUDING Cab & Chassis	DPF	649007/RL46807	\$1,247.29
FORD	9C3Z5H267B / F-250/350/450/550 SD's 2008-2010 - No Cab & Chassis	DOC	649051/RL49251	\$543.18
FORD	9C3Z5H267A / F-250/350/450/550 SD's CAB & CHASSIS 2008-2010	DOC	649057/RL49257	\$543.18
Freightliner One Box	A0004900736 / A6804903556, A6804905556 (No DPFs)	One Box	DX35017	\$6,480.00

Notice of Award**4400010479****Page 17****Pricing Schedule**

Freightliner One Box	A0004900736 / A6804903556, A6804905556 (DPFs INCLUDED)	One Box	DX35035	\$7,965.00
HINO 6-Cyl. J08E	S1807E0011	DOC	C0151-ID	N/A
HINO 6-Cyl. J08E	S1805E0270 / S1850E0281	DPF+D OC	JG1002-K	\$2,398.41
HINO 6-Cyl. J08E	S1850E0B00 / S1850E0580 / S1805E0B5	DPF	JJB703-K	\$1,224.59
Hino DPF + DOC Combo	S1805E0270, S1805E0281, C0027-HF	DPF + DOC	34603	\$2,767.50
Hino: J08E	S1805C0B5, S1805E0B5, S1850E0580, S1850E0B00, C0149-SA	DPF	34602	\$982.80
International / Maxxforce	2609066C91 / 5010910R91 (REPLACES C0148-HF)	DOC + DPF	MJ0831-K	\$1,721.25
Isuzu 6HK1	897608057 / 8-97608-057-3 Assembly # 8-97608057-0	DPF	SG0801-K	\$1,174.50
Isuzu: 4HK1-TC 5.2L	898155142 Assembly # 898155142-0, C0077-SA	DPF	39001	\$1,011.15
Isuzu: 6HKL	897608057, 897608057, 8976080573, SG0801, C0053-SA, C17-0072	DPF	39000	\$876.15
Maxxdorce 7, DT	2594363C91 / 2514351C91 Reman 5010838R91	DPF - MOD	MN1025-K	\$1,800.90
Maxxforce 11 or 13	2596665C91, 5010851R1, 3817990C91 (assembly #), 3817989C91 (assembly #), 3817964C91 (assembly #)	DPF	1N1202-K	\$1,975.05
Maxxforce 11, 13	2604828C91 (BOX) / 2604043C91 / 5010849R1	DPF	1N1207-K	\$2,250.45
Maxxforce 11, 13	2603456C91	DOC	1N0508-K	\$2,659.64
Maxxforce 13	2603960C91 Or Re-man 5010812R91	DOC	1M0402-K	\$1,883.25
Maxxforce 13	2604039C91 Or Re-man 5010811R91	DOC	1M0403-K	\$1,914.30
Maxxforce 13	2604830C91 Or 2604046C91 / 5010845R1 / 3859691C94	DPF	1N1204-K	\$1,822.50
Maxxforce 13	2603961C91, 2604823C91, 5010844R1, 3886127C91 (assembly #), 3859549C93 (assembly #), CP232717 (check assembly #, multiple Skyline options), 2606157C91	DPF	1N1205-K	\$1,822.50
Maxxforce 13	2596666C91	DOC	1N0505-K	\$1,763.91

Notice of Award**4400010479****Page 18****Pricing Schedule**

Maxxforce 13, 11	2601229C91 / 5010848R1	DPF	1N1210-K	\$1,822.50
Maxxforce 15	2608438C91, 3936996C91, 2606157C9, 4166543, C0156- SA	DPF	65035	\$1,821.15
Navistar / Maxxforce 7 DT	2597007C91	DOC	MC0505-K	\$1,863.00
Maxxforce 7	2594200C91	DOC	MC0506-K	\$1,547.91
Maxxforce 7, DT	2594454C91	DOC	C0102-ID	N/A
Maxxforce 7, DT	2594140C91 / 2594146C91	DOC	MC0501-K	\$1,369.25
Maxxforce 7, DT	2595714C91	DOC	MC0504-K	\$1,548.18
Maxxforce 7, DT	2604873C91 / 2605123C1 / 5010847R1 / SERVICABLE	DPF- CONES	MJ0804-K	\$1,701.00
Maxxforce 7, DT	2605837C1 / 2605124C1 Or Re-man 5010850R1	DPF	MJ0820-K	\$1,675.35
Maxxforce 7, DT	2604873C91 / 2605123C1 / 5010847R1	DPF- ONLY+	MJ0824-K	\$1,518.75
Maxxforce 7, DT	2593981C91 Re-man 5010836R91 *C039-SA for Vertical Install / SERVICABLE	DPF- MOD+	MJ1206-K	\$1,761.75
Maxxforce 7, DT	2594131C91 Re-man 5010832R91	DPF	MJ1222-K	\$1,755.00
Maxxforce 7, DT	2593981C91 Re-man 5010836R91 *C039-SA for Vertical Install	DPF- ONLY+	MJ1226-K	\$1,721.25
Maxxforce 7, DT	2594356C91 *C042-SA for Vertical Install / SERVICABLE	DPF- MOD+	MK1208-K	\$1,946.70
Maxxforce 7, DT	2594165C91 Re-man 5010830R91	DPF	MK1223-K	\$1,525.50
Maxxforce 7, DT	2594356C91 *C058-SA - Horizontal Install	DPF- ONLY+	MK1228-K	\$1,854.90
Maxxforce 9, DT	2604870C91 2605796C91 / 2611630C91 Or Re-man 5010852R1 5010846R1/ SERVICABLE	DPF- MOD+	MN1009-K	\$1,829.25
Maxxforce 9, DT	2604870C91 2605796C91 / 2611630C91 Or Re-man 5010852R1	DPF- ONLY+	MN1029-K	\$1,761.75
Maxxforce 9/10	2594369C91	DPF	MK1221-K	\$1,822.50
Maxxforce DT	2605332C91 / Assembly # 2605039C91 w/Bolt on Flange	DOC	MC0502-K	\$1,395.90
Maxxforce DT	2596407C92 / 2595007C91 w/ Slip on Clamp	DOC	MC0503-K	\$1,408.59

Notice of Award**4400010479****Page 19****Pricing Schedule**

Maxxforce DT	3712647C91 / 2604430C91 2612521C91 / Asbly 2605039C91 Or Re-man 5010853R1	DPF	MN1027-K	\$1,640.25
Mercedes-Benz MBE 4000 US07	A6804901814	DOC	DNT504-K	\$2,477.25
Navistar / Maxxforce 7, DT	2597007C91, 5011121R91	DOC	MC0405-K	\$1,863.00
Navistar MaxxForce 11/13	2596690C91, C0071-ID, XN0505	DOC	65029	\$2,266.65
Navistar MaxxForce 13	2604039C91, 3865483C93, 3869133C93, IP23265, C20- 0023, C0105-ID, 1M0403	DOC	65020	\$1,510.65
Navistar MaxxForce 13	2603960C91, 5010812R91, C20-0024, C0104-ID, 1M0402	DOC	65021	\$1,483.65
Navistar MaxxForce 7	2605332C91, C0051-ID, 5011047R91, MC0502	DOC	65027	\$1,159.65
Navistar MaxxForce DT/11/13	2604828C91, 5010849R1, 2604043C91, 1N1207-K	DPF	65039	\$2,295.00
Navistar N13	2510787C91	DOC	XN0632-K	\$2,606.80
Navistar/International	2605127C1	DOC	65034	\$1,294.65
Navistar: Maxxforce	2601229C91, 2601229C92, 2601229C93, Q621944, 5010848R1, C17-0063, C0063-SA, 1N1210	DPF	65015	\$1,653.75
Navistar: MaxxForce	2594165C91, 2594165R91, 5010830R91, MK1223, C0047-SA, C17-0053	DPF	65018	\$1,551.15
Navistar: Maxxforce	2605802C1, 5011044R1, 2605126C1, 2605128C1, C0138-ID	DOC	65022	\$978.75
Navistar: MaxxForce	2594140C91, 2594179C91, C0019-ID, MC0501	DOC	65026	\$1,281.15
Navistar: Maxxforce	2596407C92, 5011122R91, C0069-ID, MC0503	DOC	65028	\$1,348.65
Navistar: Maxxforce	2595714C91, 5011120R91, C0081-ID, MC0504	DOC	65030	\$1,591.65
Navistar: Maxxforce	2608438C91, 3936996C91, 2606157C9, 4166543, C0156- SA	DPF	65035	\$1,821.15
Navistar: MaxxForce 11/13	Q622369, 2596665C91, 5010851R1, 2596665R91, 3817990C91, 3817989C91, 3817964C91, Q621936, C17- 0055, C0030-SA, 1N1202	DPF	65016	\$1,748.25

Notice of Award4400010479Page 20Pricing Schedule

Navistar: MaxxForce 13	2604046C91, 2604830C91, 2604830R91, 3859691C94, 5010845R1, CP232717, C0079-SA, C17-0056, 1N1204	DPF	65011	\$1,753.65
Navistar: MaxxForce 13	2603961C91, 2604823C91, 2604823R91, 3859549C93, 3886127C91, 5010844R1, 3930745C91, C0091-SA, C17-0059, 1N1205	DPF	65014	\$1,680.75
Navistar: MaxxForce 13	2596666C91, C0122-ID, 1N0505	DOC	65025	\$1,456.65
Navistar: MaxxForce 13 (RECON)	2604046C91, 2604830C91, 2604830R91, 3859691C94, 5010845R1, CP232717, C0079-SA, C17-0056, 1N1204	DPF (Recon)	65011-RX	\$1,046.25
Navistar: MaxxForce 13 (RECON)	2603961C91, 2604823C91, 2604823R91, 3859549C93, 3886127C91, 5010844R1, 3930745C91, C0091-SA, C17-0059, 1N1205	DPF (Recon)	65014-RX	\$1,046.25
Navistar: MaxxForce 7/DT	2593981R91, 2594022C91, 2604873C91, 2605123C91, 5010836R91, 5010847R91, A00383921, 82003341, MJ0824, MJ1206, MJ1226, C0057-SA, C0113-SA, C17-0060, 2517331C91	DPF	65005	\$1,572.75
Navistar: MaxxForce 7/DT	2594356C91, 2594356R91, 5010834R91, MK1208, MK1228, C17-0061, C0058-SA	DPF	65013	\$1,464.75
Navistar: MaxxForce 7/DT	2605124C1, 2605837C1, 5010850R1, C17-0082, C0144-SA, MJ0820	DPF	65023	\$1,753.65
Navistar: MaxxForce 7/DT	2514351C91, 2594363C91, 5010838R1, C0146-SA, MN1025	DPF	65024	\$1,390.50
Navistar: MaxxForce 7/DT	2594200C91, C0118-ID, MC0506	DOC	65032	\$1,416.15
Navistar: MaxxForce 7/DT (RECON)	2593981R91, 2594022C91, 2604873C91, 2605123C91, 5010836R91, 5010847R91, A00383921, 82003341, MJ0824, MJ1206, MJ1226, C0057-SA, C0113-SA, C17-0060, 2517331C91	DPF (Recon)	65005-RX	\$810.00

Notice of Award**4400010479****Page 21****Pricing Schedule**

Navistar: MaxxForce 9	2604870C91, 2604870R91, 2605796C91, 2611630C91, 5010846R1, 5010852R1, 82002756, A00317258, MN1009, MN1029, C0078-SA, C17-0062	DPF	65009	\$1,834.65
Navistar: MaxxForce 9 (RECON)	2604870C91, 2604870R91, 2605796C91, 2611630C91, 5010846R1, 5010852R1, A00317258, MN1009, MN1029, C0078-SA, C17-0062	DPF (Recon)	65009-RX	\$985.50
Navistar: Maxxforce DPF + DOC Combo	2609066C91, C0148-HF, MJ0831	DPF + DOC	65033	\$1,674.00
Navistar: MaxxForce DT/9/10	2594131C91, 2604430C91, 2605039C91, 2612512C91, 2612521C91, 2613113C91, 3712647C91, 5010832R91, 5010843R1, 5010853R1, A00420195, A00574039, 82002806, C17-0064, C0048-SA, MJ1222	DPF	65010	\$1,640.25
Navistar: MaxxForce DT/9/10 (RECON)	2594131C91, 2604430C91, 2605039C91, 2612512C91, 2612521C91, 2613113C91, 3712647C91, 5010832R91, 5010843R1, 5010853R1, A00420195, A00574039, 82002806, C17-0064, C0048-SA, MJ1222	DPF (Recon)	65010-RX	\$985.50
Paccar	1909949PE, 205857A, 205670A, 1821898PE, 1894310PE, C0166-SC	SCR	58089	\$2,698.65
Paccar	A041C815, 1934705PE, A041C814, 1893740PE, C0167-SC	SCR	58090	\$2,563.65
Paccar MX	1900626PE, C0155-SA, MN1104	DPF	58065	\$1,551.15
Paccar MX	1900626PE	DPF	MN1104-K	\$1,586.25
Paccar MX	1837300PE	DOC	XN0631-K	\$1,748.39
SPRINTER (Van)	68011959AA / A9064901592 - ALL DODGE & FREIGHTLINER 2007-2009 3.0L 2500 & 3500 / MERCEDES 2010-2013	DPF	649005/RL46805	\$1,200.35

Notice of Award4400010479Page 22Pricing Schedule

Sprinter Van Mercedes 3.0L	A9064901592 Dodge Part# 68011959AA	DPF-MOD	C0055-SA	N/A
Sprinter/Mercedes 30L	9064900792, 490-0792 W/WB3665, 4285623	DPF	56346	\$1,370.25
Volvo - VNM / VNL	21794709	DPF	8AI001	\$1,686.15
Volvo / Mack	21716414, 21716416, 22936980, 23108407, 23108408, 7421716414	DPF	8AI002	\$1,753.65
Volvo / Mack D13	21850645, 85001355, 20864129, C20-0009, C0009-ID, VNB402	DOC	82012	\$2,023.65
Volvo / Mack: D11 / D13 /16	Q621328, 20864127, 21850658, 85000726, VQ1202, C0006-SA, C17-0045	DPF	82006	\$1,687.50
Volvo / Mack: D13	21212405, 21756505, C0097-ID, VNB407	DOC	82017	\$1,599.75
Volvo / Mack: MP7	20869859, 20992181, 21048577, 21246955, 21804785, 21817835, 85001366, 85125682, OTR0151035, C0049-SA, C17-0035, VN1201	DPF	82008	\$1,613.25
Volvo / Mack: MP7	21395825, 85124613, VN1207, C0095-SA	DPF	82014	\$1,842.75
Volvo / Mack: MP7	20863840, 85001356, 21850643, 85000777, C0008-ID, C20-0008, VN0401	DOC	82016	\$1,782.00
Volvo / Mack: MP7	20863859, 21850651, 86000761, 85001352, 85000751, C0007-SA, VN1203, C17-0044	DPF	82020	\$1,551.15
Volvo / Mack: MP7 (RECON)	20869859, 20992181, 21048577, 21246955, 21804785, 21817835, 85001366, 85125682, OTR0151035, C0049-SA, C17-0035, VN1201	DPF (Recon)	82008-RX	\$978.75
Volvo / Mack: MP7/8	20864558, 21905492, 85001367, C0050-SA, C17-0046	DPF	82009	\$1,618.65
Volvo / Mack: MP8	20864316, 21851879, VQ1204, 21905428, 85000725, C0044-SA, C17-0048	DPF	82011	\$1,753.65

Notice of Award4400010479Page 23Pricing Schedule

Volvo / Mack: MP8	21756506, 21212407, C0075-ID, VNB406	DOC	82018	\$1,726.65
Volvo D11/D13, Mack MP7-8	22342601, 22761989, 21471269, 21393279, 85124653, 21395827, C0165-SA, C17-0089, VN1209	DPF	82013	\$1,821.15
Volvo D13 / Mack MP8	20864132, 85000779, 85001354, 21850647, C0116-ID, VN0603	DOC	82019	\$1,903.50
Volvo D13, Mack MP8	21212429 / 21212431 Or 21415912 / 21212428 / 21212426 / 22810502 / 22413832 / 22810503	DPF	VN1206-K	\$1,640.25
Volvo D13/Mack MP8	20864132 / 85001354 / 85000779 or 21850647	DOC	VN0603 -K	\$2,227.50
Volvo/Mack D13	28064129 / 85001355 / 20864129 / 21850645	DOC	VNB402-K	\$2,092.50
Volvo/Mack D13	20864127 / 85000726 Or 21850658	DPF	VQ1202-K	\$1,695.60
Volvo/Mack D13 / MP8	21311953	SCR	C0179-SC	N/A
Volvo/Mack D13/11	21212405 / 21756505	DOC	VNB407-K	\$1,756.30
Volvo/Mack MP7	20863840 / 85001356 / 85000777 / 21850643	DOC	VN0401-K	\$1,822.50
Volvo/Mack MP7	21817835 / 21804785 / 85125682 / 21048577 / 20231111 / 85000899 / 20992181 / 85003793 / " 21395825 - 2007-2009 ONLY"	DPF	VN1201-K	\$1,567.35
Volvo/Mack MP7	20863859 / 85001366 Or 21850651	DPF	VN1203-K	\$1,610.55
Volvo/Mack MP7	" 21395825 - 2010-2012 ONLY " / 85124613	DPF	VN1207-K	\$1,761.75
Volvo/Mack MP7, MP8	20864558 / 85001367 / 21905492	DPF	VN1205-K	\$1,721.25
Volvo/Mack MP8	21212407 / 21756506	DOC	VNB406-K	\$1,756.30
Volvo/Mack MP8	20864316 / 85000725 Or 21851879	DPF	VQ1204-K	\$1,761.75
Volvo/Mack, MP7-8 D11/D13	22342601 / 22761989 / 21471269 / 21395827 / 85124653 / 21393279 / " 21395825 - 2013++ "	DPF	VN1209-K	\$1,890.00
Volvo: D11 / D13/ D16 / Mack (RECON)	Q621328, 20864127, 21850658, 85000726, VQ1202, C0006-SA, C17-0045)	DPF (Recon)	82006-RX	\$1,012.50

Notice of Award**4400010479****Page 24****Pricing Schedule**

Volvo: D11/13 Mack: MP7 / MP8 (RECON)	22342601, 22761989, 21471269, 21393279, 85124653, 21395827, C0165- SA, C17-0089, VN1209	DPF (Recon)	82013-RX	\$1,080.00
Volvo: D13 / Mack: MP8	21212431, 21212426, 21212428, 21212429, 21212431, 21415912, 22413830, 22810502, 22810503, VN1206, C0061- SA, C0064-SA, C17-0057, 21756428, 21756429	DPF	82010	\$1,456.65
Volvo: D13 / Mack: MP8	21212431, 21212426, 21212428, 21212429, 21415912, 22413830, 22810502, 22810503, VN1206, C0061-SA, C0064- SA, C17-0057, 21756428, 21756429	DPF (Recon)	82010-RX	\$877.50
Caterpillar	278-5711	Gasket	DG5711G	\$35.86
Caterpillar	279-2123	Gasket	DG2123G	\$31.27
Caterpillar	296-7780	Gasket	DG7780G	\$6.99
Caterpillar	247-1899	Gasket	DG1899G	\$29.12
Caterpillar	279-3259	Gasket	DG3259G	\$25.44
Cummins	2871453	Gasket	DG1453G	\$17.85
Cummins	2871452	Gasket	DG1452G	\$14.85
Cummins	2871451	Gasket	DG1451G	\$13.53
Cummins	2871566	Gasket	DG1566G	\$33.08
Cummins	2871772	Gasket	DG1772G	\$33.83
Cummins	2871827	Gasket	DG1827G	\$19.33
Cummins	2866636 / 3846392c1	Gasket	DG6636G	\$3.99
Cummins	2866337 (Paccar 1844253PE)	Gasket	DG6337G	\$5.31
Cummins	2880214	Gasket	DG0214G	\$9.71
Cummins	2880215	Gasket	DG0215G	\$14.16
Cummins	4966441	Gasket	DG6441G	\$22.19
Cummins	3684355	Gasket	DG4355G	\$19.69
Cummins	5304868	Gasket	DG4868G	\$34.40
Cummins ISX Outlet	3684359	Gasket	DG4359G	\$8.72
Cummins ISX Flange	4966447	Gasket	DG6447G	\$13.61
Detroit Diesel	A6804910480	Gasket	DG0480G	\$21.95
Detroit Diesel	A6804910180	Gasket	DG0180G	\$20.82
Detroit Diesel	A4709971245	Gasket	DG1245G	\$9.35
Detroit Diesel	A4709971145	Gasket	DG1145G	\$20.82
Dodge / Cummins	68065844AA Pipe Flange Gasket 4 Hole	Gasket	DG44AAG	\$14.25

Notice of Award**4400010479****Page 25****Pricing Schedule**

Dodge / Cummins	68065844AB Flange Gasket 4 Hole	Filter	Gasket	DG44ABG	\$14.25
Doosan	400602-00242 Muffler Gasket	DPF	Gasket	DG0242G	\$51.51
Duramax	15126137		Gasket	DG6137G	\$14.25
Ford	7C3Z 5H247 B		Gasket	DG247BG	\$14.25
Hino	17173-E0090		Gasket	DG0090G	\$18.89
Hino	17451-E0060		Gasket	DG0060G	\$29.73
Hino	S1710-41930 Hole Gasket	DPF 8-	Gasket	DG1930G	\$41.17
International	2593986C1		Gasket	DG3986G	\$12.46
International	2593998C1		Gasket	DG3998G	\$12.46
International	2594129c1		Gasket	DG4129G	\$17.82
International	3853371C1		Gasket	DG3371G	\$12.49
International / Navistar	3846392C1 Gasket	Exhaust Pipe	Gasket	DG6392G	\$8.72
International	2604051C91		Tape	DG4051G	\$15.73
Isuzu	897628257-0		Gasket	DG2570G	\$19.28
Isuzu	897611080-0		Gasket	DG0800G	\$30.03
Isuzu	8-98159745-0		Gasket	DG7450G	\$25.27
Isuzu	8-98077194-0		Gasket	DG1940G	\$23.60
Isuzu	1221160400		Gasket	DG0400i	\$17.82
Isuzu	8-97611092-0 Filter Gasket 9.80 ID	10-Hole	Gasket	DG0920G	\$38.58
Isuzu	1221160430		Gasket	DG0430i	\$64.49
Isuzu - Nut/Bolt Assembly	DB5780M		Nut/Bo lt	DB5781F	\$19.25
John Deere	R530552 Flat Graphite		Gasket	DG0552G	\$24.20
John Deere	R532139 Conical Graphite		Gasket	DG2139G	\$14.80
John Deere	R537859 Spiral Wound		Gasket	DG7859G	\$10.70
John Deere	MIU802749 Hole Metal Gasket	3032E DPF 8-	Gasket	DG2749G	\$14.08
John Deere	MIU802868 DPF 10-Hole Metal Gasket	PC11739	Gasket	DG2868G	\$16.06
Kubota	1J500-18412 Steel Filter		Gasket	DG8412G	\$31.27
Paccar	1827320PE (Cummins 2880215)		Gasket	DG0215G	\$14.16
Volvo/Mack	21048511 (Detroit Diesel A4709970045)		Gasket	DG8511G	\$22.30
Volvo/Mack	85111358		Gasket	DG1358M	\$27.50
Volvo/Mack	21371339		Gasket	DG1339G	\$21.40
Volvo	21212522		Gasket	DG2522D/G	\$22.85
Volvo/Mack	21095726		Gasket	DG5726G	\$6.88

Notice of Award**4400010479****Page 26****Pricing Schedule**

Volvo/Mack	21021846 Inlet Gasket 4 (21095721)	Gasket	DG1846G	\$5.28
Volvo/Mack	21095726P Inlet Gasket 5 w/PSA	Gasket	DG726PG	\$9.79
Volvo/Mack	23075959 Inlet Gasket 6 w/PSA	Gasket	DG5959G	\$23.65
Volvo	21570880 Filter Gasket Stamped Metal	Gasket	DG0880G	\$24.78
Volvo	21774509 OR 160g/md6h Gasket	Gasket	DG4509G	\$29.54
Volvo	21894822 OR 160g/md6h Gasket	Gasket	DG4822G	\$23.02
Detroit Diesel / Speed Nut Assbly.	DDEA0049941645 (Speed Clip)	Bolt & Nut	DB1000DD	\$12.93
Hino	17451-E0060 10 Hole DPF Gasket	Gasket	DG0600G	\$29.73
Navistar / Maxxforce	Gasket for Roadwarrior C0057-SA PN: X1900-C0057- 11	Gasket	DG0057G	\$30.25
Navistar / Maxxforce	Gasket for Roadwarrior C0078-SA PN: X1900-C0078- 11	Gasket	DG0078G	\$33.00
Detroit Diesel / Mack / Volvo (OD Ø13.62") (2 per order)	A4709970045, 21424458, 21048511 Gasket for Dinex Part # 35002; 35008; 82013; 82014	Gasket	DG8511D	\$63.25
Detroit Diesel (OD Ø14.25") (2 per order)	A4709971145, G03003 Gasket for Dinex Part # 35008	Gasket	DG1145D	\$99.00
Cummins (OD Ø4.5") (2 per order)	2866636, Q312526 Gasket for Dinex Part # 58507; 58511; 58512; 58536; 58537; 58540; 65509; 65510; 65525; 65526; 65527; 65528	Gasket	DG6636D	\$93.50
Cummins / Paccar (OD Ø5.75") (2 per order)	2866337, 1844253PE Gasket for Dinex Part # 35525; 35562; 58508; 58509	Gasket	DG6337D	\$44.00
Detroit Diesel (OD Ø11.25") (2 per order)	A6804910180 Gasket for Dinex Part # 35006	Gasket	DG0180D	\$63.25
Detroit Diesel DD15 (OD Ø10") (2 per order)	A6804910480 Gasket for Dinex Part # 35007; 35011	Gasket	DG0480D	\$79.75

Notice of Award**4400010479****Page 27****Pricing Schedule**

Navistar / International (2 per order)	2604051C1 Gasket for Dinex Part # 65011; 65014	Gasket	DX35823	\$68.75
Hino Gasket	S171041930	Gasket	DG1930D	\$162.25
Caterpillar C13/15 (OD Ø13") (2 per order)	2792123 Gasket for Dinex Part # 46002	Gasket	DG2123D	\$104.50
Caterpillar C13/15 (OD Ø14") (2 per order)	2785711 Gasket for Dinex Part # 46003; 58001; 58004; 58008; 58010; 58011; 58014; 58015; 58024; 58025; 58026; 58027; 58031; 58033; 58036; 58043; 65012; 65016; 82002; 82008; 82009	Gasket	DG5711D	\$77.00
Cummins / Paccar / Mack / Volvo (OD Ø14.45") (2 per order)	21371338, 1818631PE, 2871453 Gasket for Dinex Part # 58001	Gasket	DG1453D	\$44.00
Cummins / Paccar / Mack / Volvo (OD Ø15.32") (2 per order)	2188190, 5304868, 5417859	Gasket	DG4868D	\$99.00
Kenworth / Peterbilt Bellow Gasket (OD Ø3") (2 per order)	020P/ 78-0245 Gasket for Dinex Part # 58510	Gasket	DX58823	\$104.50
Cummins (OD Ø13.25") (2 per order)	2871827	Gasket	DG1827D	\$88.00
Cummins (OD Ø6.25") (2 per order)	2880215, 1827320PE, A029E744	Gasket	DG0215D	\$33.00
Cummins / Paccar / Mack / Volvo (OD Ø5.04") (2 per order)	2880214	Gasket	DG0214D	\$44.00
Cummins (OD Ø12.62") (2 per order)	5417860, 2871722	Gasket	DX58836	\$44.00
Detroit Diesel (Single per order)	TCX AMS013	Gasket	DX58840	\$16.50
Gasket for Dinex Part # 39001	8976282570	Gasket	DX58841	\$33.00
Cummins / Paccar (OD Ø11.6") (2 per order)	4965072, 2871452CUM Gasket for Dinex Part # 58003; 58006; 58009; 58012; 58023; 58030; 58035	Gasket	DG1452D	\$38.50
Navistar: Maxxforce (comes as pair w/ 65830)	2593998C1 Gasket for Dinex Part # 65005; 65009; 65013	Gasket	DG3998D	\$44.00

Notice of Award**4400010479****Page 28****Pricing Schedule**

Navistar: Maxxforce (comes as pair w/ 65829)	2593986C1 Gasket for Dinex Part # 65005; 65009; 65013	Gasket	DG3986D	\$44.00
Cummins / Paccar (OD Ø10.25") (2 per order)	2871451 Gasket for Dinex Part # 58005; 58007; 58022; 58028; 58029; 58054	Gasket	DG1451D	\$35.75
Navistar / International (OD Ø9.25") (2 per order)	2594129C1 Gasket for Dinex Part # 65010; 65018; 65023; 65024	Gasket	DG4129D	\$60.50
Volvo / Mack (OD Ø14.37") (2 per order)	21371339 Gasket for Dinex Part # 82006; 82011; 82012	Gasket	DG1339D	\$52.25
Volvo / Mack (OD Ø5.75") (2 per order)	21095726 Gasket for Dinex Part # 82509; 82511; 82530; 82531; 82532; 82533	Gasket	DG5726D	\$49.50
Volvo / Mack (OD Ø14") (2 per order)	21212522 Gasket for Dinex Part # 82010	Gasket	DG2522D	\$68.75
Volvo Gasket	23075959	Gasket	DG5959D	\$68.75
Volvo Gaskets (OD Ø13.875") (2 per order)	21570880, 7421570880	Gasket	DG0880D	\$104.50
Volvo (2 per order)	21664918 (2 Per Order)	Gasket	DG4918D	\$181.50
Cummins	2880482 4.00 DOC V-Band Clamp	Clamp	DC0482G	\$35.80
Cummins	4965075 Sensor Strap I/D 12.75"	Clamp	DC5075G	\$29.34
Cummins	5290116 V-Band Clamp	Clamp	DC0116G	\$72.60
Cummins	5294271 Filter Strap I/D 13.25"	Clamp	DC4271G	\$26.06
Cummins	5304849 14.5 V-Band Clamp	Clamp	DC4849G	\$75.34
Cummins/Volvo	21060426 4.75 V-Band Clamp	Clamp	DC0426G	\$41.66
Cummins	2871861	Clamp	DC1861N	\$36.66
Cummins	2871862	Clamp	DC1862N	\$37.82
Cummins	2871863	Clamp	DC1863N	\$39.76
Cummins	2880212	Clamp	DC0212C	\$33.92
Cummins	3896337 / 21048521	Clamp	DC6337N	\$25.54
Cummins	5290118	Clamp	DC0118N	\$17.94
Cummins	5304600	Clamp	DC4600C	\$25.60
Cummins	4965329	Clamp	DC5329N	\$27.58
Cummins	A034R984	Clamp	DCR984N	\$28.68
Detroit Diesel	A4709950002	Clamp	DC0002G	\$43.90
Detroit Diesel	A6809950202	Clamp	DC0202N	\$26.18

Notice of Award**4400010479****Page 29****Pricing Schedule**

Detroit Diesel	A6809950302	Clamp	DC0302N	\$65.50
Detroit Diesel/Mercedes	A6809950102 10.50 V-Band Clamp	Clamp	DC0102G	\$37.92
Detroit Diesel	T130158342AB2P One Box Inlet V-Band Clamp	Clamp	DCAB2PG	\$32.58
International	2604049C91	Clamp	DC4049R	\$32.24
International/Navistar	2594128C1 9.35 V-Band Clamp	Clamp	DC4128G	\$29.32
John Deere	RE537767	Clamp	DC7767G	\$59.34
John Deere	RE545865	Clamp	DC5865G	\$56.26
John Deere	RE554363	Clamp	DC4363G	\$60.38
Volvo	21021850 (Cummins 5290118)	Clamp	DC0118N	\$25.48
Volvo/Mack	21212520	Clamp	DC2520G	\$35.70
Volvo/Mack	21445458	Clamp	DC5458N	\$42.66
International	2594128C1	Clamp	DC4128N	\$38.26
Cummins	2880213 (Replaces 5304600)	Clamp	DC0213G	\$25.60
BREEZE	4001 (Make-A-Clamp Kit)	Clamp Kit	DC4001N	\$84.82
All MFG/OEM [BREEZE]	4007 (Universal Filter/Electrical Strap Kit)	Strap Kit	DC4007N	\$25.20
Cummins	21445458 Clamp, 14.38" nominal diameter 1.8LBS	Clamp	DC5458G	\$41.82
Cummins	2871861	Clamp	DC1861G	\$35.96
Cummins	2871862	Clamp	DC1862G	\$33.26
Cummins	2871863	Clamp	DC1863G	\$41.58
Cummins ISX	Cummins: 3896337 / Mack: 21048521 4" V-Band Clamp	Clamp	DC6337G	\$29.94
Cummins	2880212 V-Band Clamp M3A5	Clamp	DC0212G	\$33.92
Detroit Diesel	A68099502020 V-Band Clamp	Clamp	DC0202G	\$38.56
Detroit Diesel DD13, DD15	A6809950302 (One Box Wrap Clamp)	Clamp	DC0302G	\$82.74
Volvo / Mack	21212520 14.35 V-Band DPF Clamp	Clamp	DC2520G	\$43.54
Norma [Torca]	L35AA-G Lap style joint w/gasket ID 3.75" reduced to 3.5"	Clamp	DC0228N	\$9.64
Cummins / Breeze	Cummins Part #: A034R984 / Breeze Part #: B9225-1327-PE00 B	Clamp	DCA034R984	\$28.68

Notice of Award4400010479Page 30Pricing Schedule

Caterpillar	375-0949 12 inches in diameter	Clamp	DC0949N	\$100.00
Caterpillar	375-0931 13 inches in diameter	Clamp	DC0931N	\$102.00
Caterpillar	371-1871 14 inches in diameter	Clamp	DC1871N	\$106.00
Norma [R.G. Ray]	002549-129 T-Bolt clamp ID 8" (Strap Clamp)	Clamp	DC2549N	\$12.96
Cummins / Paccar V-Band Clamp (5.9")	RAY/001010-001, 2880483, 5290118 Clamp for Dinex Part # 58508; 58509; 35562; 35525	Clamp	DX35803	\$15.06
Volvo / Mack V-Band Clamp (14.26")	X12C0-01418-VB, 21048521, A4709950002, 2023037 Clamp for Dinex Part # 35002; 82008; 82013; 82014	Clamp	DC0002D	\$34.90
Detroit Diesel V-Band Clamp (4")	TCX-AMS014AM Clamp for Dinex Part # 35502	Clamp	DX35809	\$18.98
Detroit Diesel V-Band Clamp (5")	TCX-AMS015AM Clamp for Dinex Part # 35563; 35564	Clamp	DX35810	\$21.16
Detroit Diesel V-Band Clamp (10.25")	A6809950102 Clamp for Dinex Part # 35006	Clamp	DC0102D	\$35.06
Navistar: Maxxforce V-Band Clamp (13.25")	X12C0-01338-VB, 2604049C91 Clamp for Dinex Part # 65011; 65014	Clamp	DC4049D	\$37.52
Detroit Diesel V-Band Clamp	998YM-1452, EA0014907192 Clamp for Dinex Part # 35008	Clamp	DX35821	\$38.94
Detroit Diesel V-Band Clamp (10.25")	A6809950202, 100289, X12C0-0150-VB Clamp for Dinex Part # 35007; 35011	Clamp	DC0202D	\$27.16
Detroit Diesel V-Band Clamp (10.5")	E27-0088, A6809950302, A0004902241 Clamp for Dinex Part # 35824 System	Clamp	DC0302D	\$85.78
Detroit Diesel 1-Box Clamp/Gaskets KIT	DJ0806, DJ1005, C17-0076, A6804910894, A0004903792, A6804913494, A0014903492, A6804913594, A0014903592, C0080-SA, C0088-SA, A6804910494, RA0004903692,	Clamp	DX35827	\$268.58

Notice of Award**4400010479****Page 31****Pricing Schedule**

	A0004903692, EA6804910494			
Cummins V-Band Clamp	5272750	Clamp	DX38843	\$60.00
Caterpillar V-Band Clamp (13.78")	279-2124 Clamp for Dinex DPF Part # 46002	Clamp	DX46804	\$36.48
Caterpillar V-Band Clamp (14.81")	2785712, 278-5712 Clamp for Dinex Part # 46003	Clamp	DX46805	\$39.10
Cummins / Paccar V-Band Clamp (4.8")	10028-6, 115774, P222018, 89520K, 893945R92, 2880482, A029T534 Clamp for Dinex Part # 58507; 58511; 58512; 58536; 58537; 58540; 65020; 65021; 65509; 65510; 65525; 65526; 65527; 65528	Clamp	DC0482D	\$13.46
Kenworth / Paccar V-Band Clamp (2.5")	90-0011TCP, 3683144 Clamp for Dinex Part # 58510	Clamp	DX58813	\$21.60
Cummins / Paccar V-Band Clamp (10.25")	Q187680, X12C0-01040, 2871861 Clamp for Dinex Part # 58028; 58029; 58054; 58022; 58005; 58007; 58006; 58023; 58030; 58035; 58003	Clamp	DC1861D	\$27.92
Cummins / Paccar V-Band Clamp (11.75")	2871862, Q187681, 2871862, 287186CUM Clamp for Dinex Part # 58006, 58009; 58012	Clamp	DC1862D	\$43.28
Cummins V-Band Clamp	5290116	Clamp	DC0116D	\$60.00
Cummins / Detroit / Volvo / Navistar V-Band Clamp (6.38")	2880213, 90-0013, A029E742, 5304600; 2511519C1; Clamp for Dinex Part # 58066; 58068; 58019; 58021	Clamp	DC0213D	\$20.00
Cummins V-Band Clamp (5.18")	2880212 / A029E741	Clamp	DC0212D	\$28.00
Cummins / Paccar / Volvo V-Band Clamp (15.38")	2011939, 5304849, 5304898	Clamp	DC4849D	\$50.00
Detroit Diesel	TCX 130158342AC2	Clamp	DCAB2PD	\$22.00
Cummins / Detroit / Volvo / Navistar V-Band Clamp (12.5")	2607045C1, 2871859, 2871863CUM, 2871863, 21445458, 1912710PE, X12C0-01342-VB, Q187682, P238310; 4965096 Clamp	Clamp	DC1863D	\$30.80

Notice of Award4400010479Page 32Pricing Schedule

	for Dinex Part # 58027; 58031; 58033; 58036; 58043; 58065; 65012; 65016; 82006; 58024; 58025; 58026; 58001; 58004; 58008; 58010; 58011; 58014; 58015			
Navistar: Maxxforce V-Band Clamp	2594128C1 Clamp for Dinex Part # 65010; 65018; 65023; 65024	Clamp	DC4128D	\$30.80
Cummins / Paccar / Volvo V-Band Clamp (14.43")	Q187683, 21445458, 21445458, P23831, 278- 5712, X12C0-01443-VB Clamp for Dinex Part # 82002; 82011; 82012	Clamp	DC5458D	\$30.94
Cummins / Paccar / Volvo V-Band Clamp (5")	21021850, 5290118, 2880483, A029T535 Clamp for Dinex Part # 82509; 82511; 82530; 82531; 82532; 82533	Clamp	DC0118D	\$15.10
Volvo / Mack V-Band Clamp (4")	21021852 Clamp for Dinex Part # 82509; 82530	Clamp	DX82816	\$12.72
Volvo / Mack V-Band Clamp	2121520 Clamp for Dinex Part # 82009; 82010	Clamp	DC2520D	\$31.06
Volvo Clamp	22778066	Clamp	DC8066D	\$50.00
Freightliner V-Band Clamp for bellow	No OE Crosses Clamp for Dinex Part # 35525; 35562	Clamp	DX99811	\$12.44
Volvo V-Band Clamp	21445539, 22778070, 7421445539	Clamp	DX8AL006	\$40.00
Volvo / Mack	22778066 Inlet/Outlet Clamp(6.4")for One Box "DPF is w/Handles"	Clamp	DC8066G	\$28.26
Volvo / Mack	22778070 Large Clamp for One Box "DPF is w/Handles"	Clamp	DC8070G	\$54.32
Volvo/Mack	22778066 Inlet/Outlet Clamp(6.4")for One Box "DPF is w/Handles"	Clamp	DC8066N	\$17.80
Volvo/Mack	22778070 Large Clamp for One Box "DPF is w/Handles"	Clamp	DC8070N	\$22.50
Cummins Kit 1	2871863 (2) / 2871453 (2) / 2880213 [replaces 5304600] (1) and 2880215 (1)	C & G Kit	Kit 1	\$155.12
Cummins Kit 2	2871863 (2) / 2871453 (2) / 5290118 (1) and 2866337 (1)	C & G Kit	Kit 2	\$141.28

Notice of Award**4400010479****Page 33****Pricing Schedule**

Cummins Kit 3	2871862 (2) / 2871452 (2) / 3896337 / 2104851 (1) and 2866636 / 3846392c1 (1)	C & G Kit	Kit 3	\$139.82
Cummins Kit 4	2871861 (2) / 2871451 (2) / 3896337 / 2104851 (1) and 2866636 / 3846392c1 (1)	C & G Kit	Kit 4	\$138.26
Cummins Kit 5	2871861 (2) / 2871451 (2) / 2880212 (1) and 2880214 (1)	C & G Kit	Kit 5	\$148.16
Detroit Diesel Kit 6	A6809950202 (2) / A6809950302 (2) / A6804910480 (2) / DDE-A0049941645 (10) / DDE-N910105006002 (10)	C & G Kit	Kit 6	\$206.46
Volvo/Mack Kit 7	A4709950002 (2) / 21048511 (2) / 5290118 (1) and 21095726 (1)	C & G Kit	Kit 7	\$153.11
Volvo/Mack Kit 8	21212520 (2) / 2122522 (2) / 5290118 (1) and 21095726 (1)	C & G Kit	Kit 8	\$141.10
Cummins Kit 1.10	2871863 (2) / 2871453 (2) / 2880213 [replaces 5304600] (1) and 2880215 (1) 10 or more ORDERED	C & G Kit	Kit 1.10	\$103.41
Cummins Kit 2.10	2871863 (2) / 2871453 (2) / 5290118 (1) and 2866337 (1) 10 or more ORDERED	C & G Kit	Kit 2.10	\$94.19
Cummins Kit 3.10	2871862 (2) / 2871452 (2) / 3896337 / 2104851 (1) and 2866636 / 3846392c1 (1) 10 or more ORDERED	C & G Kit	Kit 3.10	\$93.21
Cummins Kit 4.10	2871861 (2) / 2871451 (2) / 3896337 / 2104851 (1) and 2866636 / 3846392c1 (1) 10 or more ORDERED	C & G Kit	Kit 4.10	\$92.18
Cummins Kit 5.10	2871861 (2) / 2871451 (2) / 2880212 (1) and 2880214 (1) 10 or more ORDERED	C & G Kit	Kit 5.10	\$98.78
Detroit Diesel Kit 6.10	A6809950202 (2) / A6809950302 (2) / A6804910480 (2) / DDE-A0049941645 (10) / DDE-N910105006002 (10) 10 or more ORDERED	C & G Kit	Kit 6.10	\$137.64
Volvo/Mack Kit 7.10	A4709950002 (2) / 21048511 (2) / 5290118 (1)	C & G Kit	Kit 7.10	\$102.08

Notice of Award**4400010479****Page 34****Pricing Schedule**

	and 21095726 (1) 10 or more ORDERED			
Volvo/Mack Kit 8.10	21212520 (2) / 2122522 (2) / 5290118 (1) and 21095726 (1) 10 or more ORDERED	C & G Kit	Kit 8.10	\$94.07
Volvo Kit: Includes 82829 - Gasket (1) / 8AL005 - Gasket (2) / 82830 - Clamp (1) / 8AL006 - Clamp (1)	231088406	C & G Kit	DX82831	\$250.00
Detroit Diesel Kit: Includes 35809 - Clamp (1) / 35811 - Gasket (1) / 17200005 - Ring insert (1)	TCX-AMS014AM (KIT)	C & G Kit	DX35809KIT	\$56.00
Detroit Diesel Kit: Includes 35810 - Clamp (1) / 35812 - Gasket (1) / 17200006 - Ring insert (1)	TCX-AMS015AM (KIT)	C & G Kit	DX35810KIT	\$64.00
Detroit Diesel Onebox DEF Awning Kit	A0004921911 (DEF Awning Kit)	C & G Kit	DX58844	\$116.00
O. G. Supply	16mm x 1.00 Bung w/ Normal Flare	BUNG	BTF16100	\$21.19
O. G. Supply	12mm x 1.50 Bung w/ Flat Flare	BUNG	BFF12150	\$21.19
O. G. Supply	14mm x 1.50 Bung w/ Flat Flare	BUNG	BFF14150DD	\$21.19
O. G. Supply	16mm x 1.50 Bung w/ Flat Flare	BUNG	BFF16150	\$21.19
O. G. Supply	20mm x 1.50 Flat Bung	BUNG	BFF20150	\$21.19
O. G. Supply	12mm x 1.25-3/4 Bung w/ Flat Flare	BUNG	BFF12125	\$21.19
O. G. Supply	14mm x 1.50 Flat Bung Male	BUNG	BMF14150	\$21.19
O. G. Supply	14mm x 1.50 Flat Bung Female	BUNG	BFF14150CT	\$21.19
O. G. Supply	14mm x 1.50-7/8 Bung w/ Flat Flare	BUNG	BFF1415087	\$21.19
O. G. Supply	18mm x 1.50 Flat Bung	BUNG	BFF18150	\$21.19
O. G. Supply	20mm x 1.50 Flat Bung Stepped	BUNG	BFF20150	\$21.19
O. G. Supply	20mm x 1.50 Bung No Step	BUNG	BFF20150	\$21.19
O. G. Supply	12mm x 1.00-3/4 Bung w/ Normal Flare	BUNG	BNF1210075	\$21.19

Notice of Award4400010479Page 35Pricing Schedule

O. G. Supply	12mm x 1.25- $\frac{3}{4}$ Bung w/ Normal Flare	BUNG	BTf12125IT	\$21.19
O. G. Supply	14mm x 1.25- $\frac{7}{8}$ Bung w/ Normal Flare	BUNG	BTf14125	\$21.19
O. G. Supply	12mm x 1.00- $\frac{3}{4}$ Bung w/ Reversed Flare	BUNG	BRF1210075	\$21.19
O. G. Supply	12mm x 1.25- $\frac{3}{4}$ Bung w/ Reversed Flare	BUNG	BTf12125CM	\$21.19
O. G. Supply	12mm x 1.50- $\frac{3}{4}$ Bung w/ Reversed Flare	BUNG	BRF12150	\$21.19
O. G. Supply	14mm x 1.50- $\frac{7}{8}$ Bung w/ Reversed Flare	BUNG	BRF14150	\$21.19
O. G. Supply	16mm x 1.50- $\frac{7}{8}$ Bung w/ Reversed Flare	BUNG	BRF16150	\$21.19
O. G. Supply	Master Box - Consisting of 2 Pieces of Each Bung Offered	Bung Kit	B-KIT	\$537.95
O. G. Supply	12mm x 1.25 - 3/4" Temp. Sensor BUNG w/ a tapered flare	BUNG	BTf12125	\$21.19
Excel Truck Group	BDDE23539605 22MM X 1.50 Soot Level Sensor Bung w/Flat Flare	BUNG	BFF22150	\$43.82
O. G. Supply	22 x 1.50 soot level sensor	BUNG	BDDE23539925	\$28.20
O. G. Supply	22mm x 1.50 Bung w/ Flat Flare	BUNG	BDDE23539926	\$28.20
O. G. Supply	18mm x 1.50 Flat Bung w/KEY SLOT	BUNG	BFF18150key	\$28.20
Caterpillar C13 2004- 2007	286-1157	EGR- COOLR	Tx286- 1157XDRMc200	\$977.34
Cummins ISX Engines	2881783NX /4956008NX / 4089436NX w/gaskets 2002-2006	EGR- COOLR	GA100c200	\$1,030.93
Cummins ISX Engines	4955422RX w/gaskets 2002-2006	EGR- VALVE	GA101N	\$771.58
Cummins ISX Engines	2881747NX / 2881784NX /4309398NX or RX w/gaskets 2007-2009	EGR- COOLR	GA102c200	\$1,030.93
Cummins ISX Engines	4955969NX w/gaskets 2008-2010	EGR- VALVE	GA110N	\$933.72
Cummins ISX Gen 1	4309434	EGR- COOLR	Tx783XDRMc200	\$868.14
Cummins ISX Gen 1	4309434	EGR- COOLR	Tx783RMc200	\$737.10
Cummins ISX Gen 2	4309398	EGR- COOLR	Tx784XDc200	\$977.34

Notice of Award4400010479Page 36Pricing Schedule

Cummins ISX Gen 2	4309398	EGR-COOLR	Tx784RMc200	\$737.10
Cummins ISX15 Gen 3	4352360	EGR-COOLR	Tx360RMc200	\$1,195.74
Cummins ISX 12	4309498	EGR-COOLR	Tx498RMc200	\$1,304.94
Cummins ISBE (2003-2006)	4089256	EGR-COOLR	Tx256RMc200	\$540.54
Cummins ISBE (2007-2010)	4946088	EGR-COOLR	Tx088XDRMc200	\$682.50
Cummins ISX 1ST GEN (2003-2006)	????	EGR-VALVE	TxEGR422	\$544.91
Cummins ISX 2ND GEN (2007-2010)	????	EGR-VALVE	TxEGR784V	\$818.95
Cummins ISX 3rd GEN (2011-2012)	5406049RX	EGR-VALVE	Tx5406049RX	\$1,304.94
Cummins ISB 2007-2010	4309085RX	EGR-VALVE	Tx4309085RX	\$682.50
Cummins ISB 2011-2014	2881693RX	EGR-VALVE	Tx2881693RX	\$758.94
Detroit 60 Series 2002-2007	23535288	EGR-COOLR	Tx835XDRMc200	\$977.34
Detroit 60 series DDEC-IV,DDEC-V	23535288	EGR-COOLR	Tx835RMc200	\$758.94
Detroit 60 Series DDEC-VI	23537387	EGR-COOLR	Tx387RMc200	\$1,304.94
Detroit 60 Series DDEC-15, DDEC-16	A4721400175	EGR-COOLR	Tx475RMc200	\$1,414.14
DDEC-IV, V (HYD) (2003-2007)	????	EGR-VALVE	TxEGR301c300	\$868.14
DDEC-IV, V (AIR) (2003-2007)	????	EGR-VALVE	TxEGR705Vc300	\$649.74
DETROIT 60 SERIES DD15 (2010-2014) VALVE ACTUATOR	????	EGR-VALVE	TxEGR475VA	\$758.94
Mercedes MBE906	906142179	EGR-COOLR	TxEGR906XD	\$977.34
Mercedes MBE904	??	EGR-COOLR	TxEGR904XD	\$758.94
Mercedes MBE904	????	EGR-COOLR	TxEGR904RMc100	\$649.74
Mercedes MBE926	A9261420379	EGR-COOLR	TxEGR926RMc200	\$1,086.54
Mercedes MBE4000 2002-2006	A46011420679	EGR-COOLR	TxEGR679RMc200	\$868.14

Notice of Award**4400010479****Page 37****Pricing Schedule**

Mercedes MBE4000 2007-2010	A46011421079	EGR- COOLR	TxEGR079RMc200	\$977.34
Navistar VT365	1845145C99	EGR- COOLR	TxEGR500XD	\$300.30
Navistar DT 17 Inch	1832540C94	EGR- COOLR	TxEGR540XD	\$1,304.94
Navistar DT 21 Inch	1832542C94	EGR- COOLR	TxEGR542XD	\$1,632.54
Navistar DT466	1871733C95	EGR- COOLR	TxEGR733XD	\$758.94
Navistar Maxxforce 7 (2008-2011)	1876723C94	EGR- COOLR	TxEGR723RMc200	\$977.34
Navistar Maxxforce 7 (2011-2014)	1899244C94	EGR- COOLR	TxEGR244c500	\$2,574.00
Navistar Maxxforce DT,9,10 Exhaust side 2008-2010	7090595C91	EGR- COOLR	TxEGR595-261XD	\$1,036.31
Navistar Maxxforce DT,9,10 Intake 2008- 2010	43073262R91	EGR- COOLR	TxEGR874-262XD	\$686.87
Navistar Maxxforce DT, 9, 10 (2011-2014)	2513976C92	EGR- COOLR	Tx2513976C92c5 00	\$2,191.80
Navistar Maxxforce 11.13 (2008-2010)	5010587R95	EGR- COOLR	Tx5010587R95c3 00	\$2,724.54
Navistar Maxxforce 11.13 (2011-2014) Low Temp Core Kit	2513209C91	EGR- COOLR	Tx2513209C91c5 00	\$1,131.00
Navistar Maxxforce 11.13 (2011-2014) High Temp Core Kit	2513445C91	EGR- COOLR	TxEGR445XDc200	\$1,068.60
Navistar Maxxforce 11.13 (2011-2014) High Temp Assembly	3014254C96	EGR- COOLR	Tx3014254C96c5 00	\$1,414.14
Navistar Maxxforce 11.13 (2011-2014) Low Temp Assembly	3015862C96	EGR- COOLR	Tx3015862C94c5 00	\$1,414.14
Navistar Maxxforce 15 2012-2014 Assembly	3008056C95	EGR- COOLR	Tx3008056C95c5 00	\$2,396.94
Navistar DT466 (2004- 2008)	???	EGR- VALVE	TxEGR593V	\$431.34
MAXXFORCE DT, 9, 10 (2008-2010)	???	EGR- VALVE	TxEGR188V	\$533.99
MAXXFORCE DT, 9, 10 (2011-2014)	???	EGR- VALVE	TxEGR997c200	\$435.71

Notice of Award4400010479Page 38Pricing Schedule

MAXXFORCE 7 (2011-2014)	1881385C94	EGR-VALVE	Tx1881385C94	\$600.55
MAXXFORCE 11,13 (2008-2010)	3005113C97	EGR-VALVE	Tx3005113C97c175	\$2,178.54
MAXXFORCE 11,13 (2011-2014)	5010696R94	EGR-VALVE	Tx5010696R94c175	\$1,610.70
MAXXFORCE 11,13 (2014-2016)	5010918R92	EGR-VALVE	Tx5010918R92c175	\$1,801.80
Maxxforce 15 2012-2014	30166004C92	EGR-VALVE	Tx30166004C92	\$2,724.54
Navistar DT466E ENGINES	1832542C91 / 1832542C94 w/gaskets 2004-2009	EGR-COOLR	GA602FXN	\$1,030.93
Navistar DT466E ENGINES	1871733C95 / 1848258C92 w/gaskets 2006-2008	EGR-COOLR	GA603N	\$1,030.93
Navistar MAXFORCE DT/9/10 ENGINE	1876261C98 / 7090595C91 w/gaskets 2008 +	EGR-COOLR	GA604N	\$1,419.96
Navistar MAXFORCE DT/9/10 ENGINE	1876262C95 / 4307362R91 w/gaskets 2008 +	EGR-COOLR	GA605N	\$901.26
Navistar ENGINES 2003-06	1842593C91 w/gaskets 2003-2006	EGR-VALVE	GA610N	\$430.81
Navistar ENGINES 2007-11	1873842C92 / 1875808C1 / 1878918C1 or C2 w/gaskets 2007-2011	EGR-VALVE	GA611N	\$637.45
Navistar ENGINES 2011-14	5010696R94 / 7092735C93 or C94 w/gaskets 2011-2014	EGR-VALVE	GA612N	\$2,177.93
Navistar MAXFORCE DT/9/10 ENGINE	1890997C92 w/gaskets 2011-2014	EGR-VALVE	GA613N	\$291.14
Paccar MX13 #1933207	1933207	EGR-COOLR	TxEGR207RMc200	\$1,741.74
Paccar MX13 1922163	1922163	EGR-COOLR	TxEGR133RMc500	\$2,724.54
Volvo D12 W/ Reed assembly	85110346	EGR-COOLR	TxEGR340XDRMc200	\$1,304.94
Volvo D12 W/ Reed assembly	85110346	EGR-COOLR	TxEGR340RMc200	\$977.34
Volvo D12 W/o Reed assembly	85110346	EGR-COOLR	TxEGR341XDc200	\$977.34
Volvo D12 W/o Reed assembly	85110346	EGR-COOLR	TxEGR341RMc200	\$868.14

Notice of Award**4400010479****Page 39****Pricing Schedule**

Volvo D11, Mack MP7 2008-2016	85136427	EGR- COOLR	TxEGR427RMc200	\$1,195.74
Volvo D13, Mack MP8 2008-2016	85136428	EGR- COOLR	TxEGR428RMc200	\$1,195.74
Volvo Mack D16 (2008- 2016)	???	EGR- COOLR	TxEGR646RMc500	\$1,741.74
Mack AC380	21301444	EGR- COOLR	TxEGR444RMc200	\$1,632.54
Volvo D12 2003-2007	???	EGR- VALVE	TxEGR399V	\$544.91
VOLVO D13 ENGINES	85136258 / 85134017 / 35132028 / 85124969 / 8511060 / 22134241 / 85136428 inc. V-Band&Hose Clamp/Seal Ring/Gasket 2008-2016	EGR- COOLR	GA702c200	\$887.36
VOLVO Engines	20506894 / 20704284 / 20764334 / 20865398 / 21001173 / 85000785 / 85000816 / 85000908 / VPT21001173RM w/gaskets 2003-2009	EGR- VALVE	GA202N	\$716.10
Cummins ISM (2002- 2006)	4309506NX	EGR- COOLR	TxEGR380c150	\$977.34
Cummins ISM (2002- 2006)	4955421RX	EGR- VALVE	TxEGR421RX	\$544.91
Cummins (Kenworth/ Peterbilt/ International)	4326864, 1710806, A045S158, A2C95992900	NOx Sensor	DX22028	\$442.50
Cummins (Kenworth/ Peterbilt)	4326769, A045S162,1928760, 1953530, 1862931,2139930, 4326476, 4326868, 2872779,2897311	NOx Sensor	DX22035	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	2894943, 2871974, 1861423PRX, 1869930PRX, 1869930PE, 4984912	NOx Sensor	DX5EL001	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	2894939, 2871978, 4984053, 2872236, 2894944, 4984576	NOx Sensor	DX5EL002	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	2872297, 5293295, 5293295RX, 5293295NX	NOx Sensor	DX5EL003	\$442.50

Notice of Award**4400010479****Page 40****Pricing Schedule**

Cummins (Kenworth/ Peterbilt/ International)	2872948,2872948NX, 4326873, 4326873RX, 326873RX	NOx Sensor	DX5EL004	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	4326874, 28729846	NOx Sensor	DX5EL005	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	4326872, 4326872RX, 2872942, 2872942NX, 1954664PRX	NOx Sensor	DX5EL006	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	2872236, 2894944, 2872236RX, 2894944RX	NOx Sensor	DX5EL007	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	3687334, 2894941	NOx Sensor	DX5EL009	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	4326867	NOx Sensor	DX5EL010	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	2894940, 2894940RX	NOx Sensor	DX5EL011	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	3687930, 4326870	NOx Sensor	DX5EL012	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	4326869, 4326869RX, 1954666PRX, 2872947, 2872947NX, 1954665PRX	NOx Sensor	DX5EL013	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	1889126PEX	NOx Sensor	DX5EL015	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	7099784C1, 7099783C1	NOx Sensor	DX5EL017	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	2894946	NOx Sensor	DX5EL039	\$442.50
Cummins (Kenworth/ Peterbilt/ International)	4326861, 4307494, 4326469	NOx Sensor	DX5EL040	\$442.50
Detroit Diesel	A0101532228	NOx Sensor	DX3FL001	\$442.50
Detroit Diesel	A0101532328	NOx Sensor	DX3FL002	\$442.50
Detroit Diesel	A0101531928	NOx Sensor	DX3FL008	\$442.50

Notice of Award**4400010479****Page 41****Pricing Schedule**

Detroit Diesel	A0101538128	NOx Sensor	DX3FL009	\$442.50
Isuzu	8982313912	NOx Sensor	DX6IL001	\$442.50
Paccar (Kenworth/ Peterbilt)	1705520, 1705572, 2894940, 1702178, 1703687	NOx Sensor	DX22033	\$442.50
Paccar (Kenworth/ Peterbilt)	2897309, 2872945, 1971946, 1952565, 4326862, 4326470	NOx Sensor	DX22038	\$442.50
Paccar (Kenworth/ Peterbilt)	2006426PE	NOx Sensor	DX5EL008	\$442.50
Volvo/Mack	22303390	NOx Sensor	DX8CL001	\$442.50
Volvo/Mack	22303391	NOx Sensor	DX8CL002	\$442.50
Detroit Diesel	Detroit Diesel	Temp Sensor	DX3FL003	\$53.10
Detroit Diesel	Detroit Diesel	Temp Sensor	DX3FL004	\$53.10
Cummins / Paccar	Cummins / Paccar	Temp Sensor	DX5EL019	\$79.65
Cummins	Cummins	Temp Sensor	DX5EL020	\$79.65
Volvo/ Mack	Volvo/ Mack	Temp Sensor	DX5EL021	\$74.34
Volvo/ Mack	Volvo/ Mack	Temp Sensor	DX5EL022	\$74.34
Volvo/ Mack	Volvo/ Mack	Temp Sensor	DX5EL023	\$74.34
Paccar	Paccar	Temp Sensor	DX5EL024	\$123.90
Cummins	Cummins	Temp Sensor	DX5EL025	\$212.40
Cummins	Cummins	Temp Sensor	DX5EL026	\$70.80
Cummins	Cummins	Temp Sensor	DX5EL027	\$88.50
Caterpillar (Bellow Kit)	207-1364	Bellow	DX4CE001	\$272.70
Freightliner (Bellow Kit)	EBFL11875, 04-28578-000, A04-26193-018, A04-28578- 000	Bellow	DX35502	\$259.20
Freightliner (Bellow Kit)	A04-27334-018, A04-26200- 018	Bellow	DX35525	\$295.31
Freightliner (Bellow Kit)	04-28522-000, A04-28522- 000	Bellow	DX35563	\$379.89

Notice of Award4400010479Page 42Pricing Schedule

Freightliner (Bellow Kit)	A04-030008-000	Bellow	DX3FA003	\$472.50
Freightliner (Bellow Kit)	04-27254-000	Bellow	DX3FE007	\$309.15
Freightliner (Bellow Kit)	04-28675-000	Bellow	DX3FE008	\$268.65
Freightliner (Bellow Kit)	04-28907-000	Bellow	DX3FE009	\$268.65
Freightliner (Bellow Kit)	A04-25023-016	Bellow	DX3FE010	\$162.00
Freightliner (Bellow Kit)	A04-25922-018	Bellow	DX3FE011	\$297.00
Freightliner (Bellow Kit)	A04-26374-016	Bellow	DX3FE012	\$290.25
Freightliner (Bellow Kit)	ABPN49KW3541	Bellow	DX3FE014	\$364.50
Freightliner (Bellow Kit)	A04-25022-018	Bellow	DX3FE016	\$243.00
Freightliner (Bellow Kit)	04-31271-000	Bellow	DX3FE019	\$216.00
Freightliner (Bellow Kit)	A04-27252-000	Bellow	DX3FE020	\$268.65
Freightliner (Bellow Kit)	M66-7671-302	Bellow	DX3FE021	\$324.00
Freightliner (Bellow Kit)	A04-25023-018	Bellow	DX3FE022	\$324.00
Freightliner (Bellow Kit)	3FE040	Bellow	DX3FE040	\$418.50
Peterbilt / Kenworth	M66-6542-0320, KW-6542-0320	Bellow	DX58545	\$418.50
Peterbilt / Kenworth	M66-6542-0335, KW6542-0335	Bellow	DX58546	\$432.00
International (Bellow Kit)	3826294C2	Bellow	DX65509	\$322.45
International (Bellow Kit)	3628113C5,3625113C5	Bellow	DX65510	\$373.34
International (Bellow Kit)	3820024C3	Bellow	DX65527	\$352.35
Freighliner (Bellow Kit)	04-29405-000	Bellow	DX3FE044	\$506.25
International (Bellow Kit)	3989136C93	Bellow	DX6IA001	\$741.15
International (Bellow Kit)	3811755C4	Bellow	DX6IA002	\$471.15
International (Bellow Kit)	3859149C91, 4042712C91, 2512967C91, 3854061C1	Bellow	DX6IA005	\$471.15

Notice of Award**4400010479****Page 43****Pricing Schedule**

International (Bellow Kit)	3859154C1	Bellow	DX6IA006	\$673.65
International (Bellow Kit)	4037288C92	Bellow	DX6IA008	\$268.65
International (Bellow Kit)	M66-7064-0330	Bellow	DX6IA009	\$403.65
International (Bellow Kit)	4037286C3	Bellow	DX6IE001	\$538.65
International (Bellow Kit)	4042712C91	Bellow	DX6IE003	\$403.65
Kenworth / Peterbilt (Bellow Kit)	EBKW11866	Bellow	DX46517	\$202.50
Peterbilt (Bellow Kit)	M66-7091-0405, M66-6541-0405	Bellow	DX58507	\$209.25
Peterbilt (Bellow Kit)	M66-6559, KW-6559	Bellow	DX58510	\$131.22
Peterbilt (Bellow Kit)	M66-7091-0320, M66-3541	Bellow	DX58511	\$210.60
Peterbilt (Bellow Kit)	M66-7091-0335, M66-6541-0335	Bellow	DX58512	\$189.00
Peterbilt (Bellow Kit)	M66-4111	Bellow	DX58544	\$256.50
Volvo (Bellow Kit)	21428534, 21959393, 22307701	Bellow	DX82509	\$189.00
Volvo (Bellow Kit)	21959389, 22307697	Bellow	DX82511	\$316.78
Volvo (Bellow Kit)	21051403	Bellow	DX82532	\$368.75
Volvo (Bellow Kit)	22307703	Bellow	DX8CA007	\$322.65
Volvo (Bellow Kit)	21478686	Bellow	DX8CA010	\$303.75
Volvo (Bellow Kit)	21533396	Bellow	DX8CE004	\$309.15
Volvo (Bellow Kit)	2,230,769,923,089,930	Bellow	DX8CE012	\$346.95
Volvo (Bellow Kit)	21533406	Bellow	DX8CE017	\$861.30
Volvo Flex	3199065	Flex	DX82140	\$44.25
Freightliner (3S Flex Kit)	04-28578-000	Flex	DX35561	\$197.44
Freightliner (3S Flex Kit)	A04-27334-018,EBFL11879	Flex	DX35562	\$338.34
Freightliner (3S Flex Kit)	04-28522-000	Flex	DX35564	\$239.66
Freightliner (DS3 Flex Kit)	04-19105-017	Flex	DX3FE002	\$70.80
Freightliner (3S Flex Kit) 5" Pipe	04-17131-009	Flex	DX3FE003	\$175.23
Freightliner (DS3 Flex Kit)	04-19105-015	Flex	DX3FE004	\$69.03
Freightliner (3S Flex Kit)	GAFP117693	Flex	DX3FE013	\$88.50

Notice of Award4400010479Page 44Pricing Schedule

Freightliner (3S Flex Kit)	04-19105-014	Flex	DX3FE033	\$69.03
Freightliner Flex Pipe	04-23721-12	Flex	DX3FE050	\$79.65
International (3S Flex Kit)	3826294C2	Flex	DX65525	\$219.04
International (3S Flex Kit)	3628113C5	Flex	DX65526	\$286.74
International (3S Flex Kit)	3820024C3	Flex	DX65528	\$287.09
International (3S Flex Kit)	3849014C1	Flex	DX61A013	\$529.23
International (Flex Kit)	4023642C1	Flex	DX61A030	\$352.23
Kenworth (3S Flex Kit)	KW-6542-0320, M66-6542-0320	Flex	DX58508	\$130.98
Kenworth (3S Flex Kit)	KW-6542-0335, M66-6542-0335	Flex	DX58509	\$146.20
Peterbilt (3S Flex Kit)	M66-3541, M66-7091-0320,EBKW11865,EBPB11861	Flex	DX58536	\$113.28
Peterbilt (3S Flex Kit)	M66-7091-0335,EBPB11862	Flex	DX58537	\$138.06
Peterbilt (3S Flex Kit)	M66-7091-0405, EBPB11863	Flex	DX58540	\$120.36
Kenworth/Peterbilt (3S Flex Kit)	M66-6116	Flex	DX5EA002	\$318.60
Volvo (Flex Pipe)	20442244	Flex	DX81728	\$26.55
Volvo (3S Flex Kit)	21428534,EBVL11867	Flex	DX82530	\$138.06
Volvo (3S Flex Kit)	21959389	Flex	DX82531	\$150.36
Volvo (3S Flex Kit)	21051403	Flex	DX82533	\$141.16
Volvo (DS3 Flex Kit)	3186814	Flex	DX8CA002	\$35.40
Volvo (DS3 Flex Kit)	21142254	Flex	DX8CE005	\$53.10
Volvo (DS3 Flex Kit)	21497416	Flex	DX8CE006	\$86.73
Volvo VE-D13 (3S Flex Kit)	3179766	Flex	DX8CE014	\$104.43
Kenworth/ Peterbilt Pipe	M66-9043-001, M669043001	Pipe	DX46516	\$354.00
Volvo Pipe	211322002	Pipe	DX82525	\$283.20
Volvo Outlet can repair kit collar	53205131	Pipe	DX53205131	\$97.35
Volvo Insulation Jacket (for 8CE004 clamp)	22983867, 21533402	Insulation Jacket	DX71200121	\$161.07
Freightliner Pipe	04-21166000	Pipe	DX3FA001	\$136.29
Freightliner Pipe	04-27746-000	Pipe	DX3FA004	\$123.90
Freightliner Pipe	04-31321-000	Pipe	DX3FA005	\$192.93
Freightliner Pipe	04-18054-023	Pipe	DX3FA006	\$88.50

Notice of Award4400010479Page 45Pricing Schedule

Freightliner Pipe	04-24955-000	Pipe	DX3FA008	\$139.83
Freightliner Pipe	GAFP116403	Pipe	DX3FA009	\$115.05
Freightliner Pipe	A04-17476-001	Pipe	DX3FE005	\$139.83
Freightliner Pipe	04-27252-000	Pipe	DX3FE006	\$352.23
Freightliner/New Star	GAFP117603	Pipe	DX3FE015	\$159.30
Freightliner Pipe	04-26838-005	Pipe	DX3FE018	\$212.40
Freightliner Pipe	01-29031-000	Pipe	DX3FE024	\$175.23
Freightliner Pipe	04-29824-000	Pipe	DX3FE025	\$70.80
Freightliner Pipe	04-26247-014	Pipe	DX3FE030	\$194.70
Freightliner Pipe	04-25396-002	Pipe	DX3FE031	\$246.03
Freightliner Pipe	04-15653-001	Pipe	DX3FE032	\$132.75
Freightliner Pipe	04-17094-013	Pipe	DX3FE034	\$247.80
Freightliner Pipe	04-17094-014	Pipe	DX3FE035	\$247.80
Freightliner Pipe	3564821C3	Pipe	DX3FE036	\$265.50
Freightliner Pipe	04-16460-009	Pipe	DX3FE037	\$132.75
Freightliner Pipe	A04-19297-001	Pipe	DX3FE038	\$212.40
Freightliner Pipe / DD13 , DD15, DD16	04-28712-000	Pipe	DX3FE042	\$354.00
Freightliner Pipe / DD13 , DD15, DD17	04-29406-000	Pipe	DX3FE043	\$371.70
Freightliner Pipe / DD13 , DD15, DD18	04-27745-000, 04-30676-000	Pipe	DX3FE045	\$230.10
Freightliner Pipe	04-27744-002	Pipe	DX3FE046	\$238.95
Detroit Cascadia (One- box outlet)	04-32486-000, 04-27721-000	Pipe	DX3FE047	\$139.83
Freightliner One-Box Tail Pipe	04-26838-000	Pipe	DX3FE053	\$221.25
Bluebird Pipe	Q716131, EBBB11882	Pipe	DX5EA001	\$309.75
Kenworth/ Peterbilt Pipe	M66-6026	Pipe	DX5EA003	\$210.63
Kenworth/ Peterbilt Pipe	M66-3365-001	Pipe	DX5EA004	\$263.73
Peterbilt Pipe	M66-7465-004	Insulat ed Pipe	DX5EE001	\$352.23
Kenworth/ Peterbilt Pipe	M66-7504-001	Pipe	DX5EE002	\$352.23
International Turbo Pipe	3007671C96	Turbo Pipe	DX6IA010	\$265.50
International/Navistar Pipe	3503200C1	Pipe	DX6IA011	\$265.50
International/Navistar Pipe	3533076C1	Pipe	DX6IA012	\$316.83
International/Navistar Pipe	350230C1	Pipe	DX6IA014	\$246.03

Notice of Award4400010479Page 46Pricing Schedule

International Pipe	3596939C1	Pipe	DX6IA015	\$706.23
International/Navistar Pipe	3564822C2	Pipe	DX6IA016	\$352.23
Volvo Pipe	20554781-0917	Pipe	DX8CA001	\$210.63
Volvo Insulated Pipe	214786981	Insulated Pipe	DX8CA003	\$309.75
Volvo Intermediate Pipe	20554781-1017,20446745	Intermediate Pipe	DX8CA006	\$175.23
Volvo Pipe VE-D13	20457109	Pipe	DX8CA008	\$120.36
Volvo Pipe VE-D14	21131576	Pipe	DX8CA009	\$159.30
Volvo D16 Outlet pipe (SCR)	21660574	Pipe	DX8CA014	\$177.00
Volvo Z-Pipe (SCR)	21687287	Pipe	DX8CA018	\$177.00
Volvo Turbo D11	21478679	Turbo Pipe	DX8CA019	\$354.00
Mack Pipe (Post SCR)	21574250	Pipe	DX8CA026	\$168.15
Volvo Intermediate Pipe	23202231, 21274193	Intermediate Pipe	DX8CE002	\$228.33
Volvo Pipe	21131573	Pipe	DX8CE008	\$175.23
Volvo Pipe	21625281/23200556	Pipe	DX8CE009	\$352.23
Volvo Pipe	22415337	Pipe	DX8CE010	\$177.00
Volvo Pipe	21142286	Pipe	DX8CE013	\$263.73
Volvo Pipe	23154798	Pipe	DX8CG002	\$175.23
Volvo Pipe	21660573	Pipe	DX8CG003	\$228.33
Volvo Pipe	21131584	Pipe	DX8CG006	\$157.53
Volvo Pipe	23200555	Pipe	DX8CG008	\$352.23

Notice of Award**4400010479****Page 47****Pricing Schedule**

CLEANING/SERVICE ELEMENTS	NEW PRICING
Pneumatic DPF Cleaning	\$100.00
Pneumatic DOC Cleaning	\$75.00
Thermal DPF Cleaning	\$200.00
Thermal DOC Cleaning	\$125.00
Thermal DPF & DOC Combo (P/U @ Same Time)	\$300.00
Bad Filter Fee (BFF)*	\$150.00
BFF (\$75.00 w/Recycled CORE and buying a new Filter)	\$75.00
Ultra-Sonic DPF & DOC Cleaning**	\$400.00
Ultra-Sonic SCR Cleaning	\$200.00
Ultra-Sonic EGR Cooler Cleaning	\$300.00
OIL Soaked DPF or DOC <u>Each Piece</u>	\$800.00
De-Grease DPF/DOC (prior to Thermal)	\$35.00
Weld DPF/DOC (Ea. Weld)	\$75.00
Special Weld or Repair (Shop Determined)	\$150.00
Bung Replacement (Each)	\$75.00
Bung Repair (Each)	\$40.00
Disassemble/Reassemble DPF/DOC***	\$100.00
Bent Flange Repair	\$25.00
Sensor/Probe Removal (Each)	\$15.00
Painting of DPF or DOC (Each)	\$10.00
<u>Weekday</u> Pick-Up and Delivery	\$0.00
<u>Weekend/Holiday</u> Pick-Up and/or Delivery	\$550.00
Ground Shipping Costs inc. purchasing a new Filter	\$0.00
Bad Filter Fee: <u>Oil Soaked</u>	\$450.00
Bad Filter Fee: <u>Ultra-Sonic</u>	\$200.00
Bad Filter Fee: if Ultra-Sonic's recycled	\$100.00
Ultra-Sonic recommened post Thermal	\$100.00
Disassemble Fee: <u>ISUZU</u>	\$100.00
Disassemble Fee: <u>Detroit One Box</u>	\$150.00
Reassemble Fee: <u>ISUZU</u>	\$50.00
Reassemble Fee : <u>Detroit One Box</u>	\$100.00