
SERVICE & REPAIR QUOTE





OMNIA Certified Quote #: R200401-FL-275957

OCBOCC – Crestview Courthouse Chiller 1 and 2 Leak Repairs

OKALOOSA COUNTY CRESTVIEW COURTHOUSE 100 E James Lee Blvd Crestview, FL 32536

Quote #: Q-17024

Prepared for: Randy Overly

Randy Overly Mechanical Supervisor OKALOOSA COUNTY BOARD OF COMISSIONERS Quote Document Date: 05/17/23

Prepared by:

Anthony 'Spence' Corrao SSR Phone: (850)-420-8592 Mobile: E-mail: spence.corrao@daikinapplied.com Daikin Applied Americas, Inc. CONTRACT: C19-2824-FM DAIKIN APPLIED CHILLER mAINTENANCE EXPIRES: 07/30/2024

Scope of Services

Daikin Applied Americas, Inc. is pleased to offer the following Service & Repair Quote for your consideration. Thank you for selecting Daikin Applied Service Group to care for your building's system. Our service personnel have the knowledge and experience to deliver the best support available. Daikin is pleased to offer this Quote for your consideration.

Daikin Applied agrees to provide the following service as described in the scope of work below. <u>OCBOCC – Crestview Courthouse Chiller 1 and 2 Leak Repairs</u>

Model: RTWD 100F 2F02

Serial: U17G08571

- Lock out and tag out circuit #1 per the Daikin safety protocol.
- Recover refrigerant and weigh the refrigerant charge.
- · Remove failed / leaking liquid level sensor and dispose of.
- Provide and install new liquid level sensor.
- Remove failed electronic expansion valve.
- Provide and install (1) new electronic expansion valve.
- Pressure test with nitrogen and check for leaks.
- Evacuate to 500 microns and charge with recovered refrigerant.
- Provide and install new leaving water temperature sensor.

Model: RTWD 100F 2F02

Serial: U17G08570

- Lock out and tag out circuit #2 per the Daikin safety protocol.
- Recover refrigerant and weigh the refrigerant charge.
- · Remove failed / leaking oil return solenoid and dispose of.
- · Provide and install new oil return solenoid and coil.
- Pressure test with nitrogen and check for leaks.
- · Evacuate to 500 microns and charge with recovered refrigerant.

*Additional refrigerant needed to be supplied by the customer.

ltem	Item/Description	List, Cost, or Labor Rate \$	Qty.	Discount Multiplier	Net Price
1	CAT 1 Labor	\$136.00	36	0.90	\$4,406.40
2	Oil return solenoid	\$203.02	1	0.85	\$172.56
3	Oil return solenoid coil	\$121.62	1	0.85	\$103.37
4	Liquid level sensor	\$798.75	1	0.85	\$678.93
5	Electronic expansion valve	\$1,643.18	1	0.85	\$1,396.70
6	Leaving water temp sensor	\$157.91	1	0.85	\$134.22
7	Nitro / recovery	\$727.27	1	0.85	\$618.17



8	Shipping	\$181.82	1 1	\$181.82
Total	\$7,692.17			

Emergency Service Response

Emergency service is available on a 7-day, 24 hour basis. For scheduled service and repairs covered under this agreement and performed at the Customer's request outside of normal working hours, the Customer agrees to pay the difference between the prevailing standard billing rate and the prevailing overtime rate.

Equipment Repair

Daikin will perform all services during its regular working hours unless otherwise specified. Any services requested or agreed to by Customer that are outside the Scope of Work will be performed by Company at an additional cost. Company will invoice such services at a special service and repair billing rate at Company's published labor rate for the service area.

Standard Inclusions:

The agreement includes travel to and from the site, planned maintenance materials, and any trips to supply depots to procure materials. The Owner will receive a written report for the inspection or services provided. For specific activities associated with the equipment covered under the agreement, reference the planned maintenance activities section.

Standard Exclusions:

- Customer to have chiller secured and condenser bundle drained prior to arrival
- All work to be performed during 'normal working hours'
- Any and all recommended/required repairs to be quoted separately
- Asbestos identification, abatement, and pipe insulation are not included
- · Chemical (acid) cleaning of tubes, if required, is not included
- Vibration analysis testing is not included
- Refrigerant is not included
- Compressor overhaul/internal inspection is excluded
- . This Quote is only valid if check valve holds, otherwise we will need to revise the quote to cover refrigerant



OMNIA Pricing and Acceptance

Feel free to contact me if you have any questions or concerns regarding the information contained in this Service & Repair Quote. If you would like us to proceed with the solution presented above, sign the acceptance line below (including PO# if applicable) and return a copy so that we can begin to mobilize our efforts to complete services as quickly as possible. We appreciate the opportunity to provide you with this solution and look forward to working with you on this and servicing your needs in the future.

Investment Amount and Billing Terms:

Investment required to implement the proposed solution

\$7,692.17 (Seven Thousand, Six Hundred Ninety Two dollars and Seventeen cents) *Price does not include applicable sales tax Quote, inclusive of the pricing, is provided in accordance with Region 4 ESC Contract # R200401, available via OMNIA Partners, including the terms and conditions contained therein (https://public.omniapartners.com/suppliers/daikin-applied/contract-documentation#c38611) shall govern this

(https://public.omnlapartners.com/suppliers/daikin-applied/contract-documentation#c38611) shall govern this Quote and the corresponding scope of work as described herein which are hereby incorporated by this reference. Pricing and acceptance are subject to Daikin Applied's final credit approval.

Billing/Payment Terms*: Billed in full upon completion *All billings are due immediately upon Receipt

This Quote will be honored by Daikin Applied for 30 days from the date on the front of the Quote. After 30 days, Daikin Applied reserves the right to evaluate cost changes (both increases and decreases) from the Quote.

Randy Overly OKALOOSA COUNTY BOARD OF COMISSIONERS FACILITY MAINTENANCE5489 OLD BETHEL RD Crestview, Florida 32536 Site Address: OKALOOSA COUNTY CRESTVIEW COURTHOUSE 100 E James Lee Blvd Crestview, FL 32536

Accepted by:

Kyle Hubbel

(Print Full Legal Name of Customer)

Kyle Hubbel

(Signature)

District Manager

(Title) May 25, 2023

Date:

Approved by: DeRita Mason Digitally signed by DeRita Mason Date: 2023.05.25 15:41:59 -05'00'

(Print Full Legal Name of Daikin Applied Representative)

(Signature)

(Title)

Date:

Note: This Agreement is subject to final credit approval by Daikin Applied.

