


Gold Hill MS

300 Hall = 30 each windows
 200 Hall = 5 each windows
 total = 35 each windows


* No Band Room Window Replacements



Workrooms
 - hinged to place
 for stationary

GHES

Gold Hill Elementary School



C hall = 34 each
 D hall = 36 each
 A hall = 12 each
 total = 82 each

no blinds needed for these windows
 all stationary

GHES