



THE CITY OF DAYTONA BEACH OFFICE OF THE PURCHASING AGENT

Post Office Box 2451
Daytona Beach, Florida 32115-2451

Phone (386) 671-8080
Fax (386) 671-8085

ADDENDUM NO. 4

DATE: 5/30/2019

PROJECT: ITB 19401
FIRE ALARM MONITORING, TESTING, AND INSPECTION; FIRE SUPPRESSION SYSTEM INSPECTION AND MAINTENANCE; BACKFLOW PREVENTER CERTIFICATION; SECURITY SYSTEM INSTALLATION AND MONITORING

OPENING DATE: 6/12/2019 at 2:00 PM

This addendum is hereby incorporated into the Bid Documents for the project referenced above. The following items are clarifications, corrections, additions, deletions and/or revisions to and shall take precedence over the original documents. Additions are indicated by underlining, deletions are indicated by ~~striketrough~~.

1. Answers to Bidders' written questions:

Q1: Can you provide us with the most recent Fire Alarm and Sprinkler System Inspection Reports and what you are you currently paying for each?

A1: Most are in addendum #3, Police Department attached.

Q2: How are the current Burglar and Fire Alarm System being monitored (Phone Line or Cellular Communicator) and what are you currently paying for each?

A2: Most have phone line. Only the Archives location has a cellular connection. Current fees are in attachment.

Q3: Manufacturer and/or Part Numbers for the current Burglar Alarm Control Panels?

A3: ADT and CES

Q4: On current systems that are being monitored through cellular communicators, will the current provider be deactivating or releasing the serial numbers for each unit, to be utilized for new vendor?

A4: ADT or CES. We can do either one, what ever the awarded Contractor prefers.

Q5: Section 16 SI 2 "AWARD will be made to a single Contractor with the lowest responsive and responsible bid"; does this mean a sprinkler system installation & service sub-contractor would not be allowed as well?

A5: Award will be made to a single Contractor. Subcontractors may be utilized with approval of the City (page 40, 3.09 a) Any subcontractors or sub-consultants whom the Bidder proposes to use to perform work under

this solicitation must also hold the required licensure at the time of bid submittal. (page 7, item 27 last paragraph)

2. All other terms and conditions remain the same.

The Bidder shall acknowledge receipt of this addendum on the Bid Proposal Form.

The City of Daytona Beach

Kirk Zimmerman, CPPB
Buyer

CURRENT RATES FOR SERVICES

Location	SF	# Sprinklers	System Manuf.	Company	Service	Service2	Service3	Service4	Service5	Service6	Date of Service/contract	Cost
Midtown					Fire Alarm test & inspection	Fire Alarm monitoring	Phone line monitoring	Fire Sprinkler Inspection	Backflow Preventer Certification	Security System	Annual 10-01-18	\$480.00
Midtown						Fire Alarm monitoring					annual 10-01-17 - 9-30-18	\$480.00
Midtown		yes			Fire Alarm test & inspection						annual 5-01-18	\$420.00
IS 2					Dynafire	Dynafire					annual 5-01-18	\$180.00
IS 5					Dynafire	Dynafire					annual 5-01-18	\$180.00
IS 6					Fire Alarm test & inspection	Fire Alarm test & inspection					annual 5-01-18	\$180.00
IS 7					Dynafire	Dynafire					annual 5-01-18	\$250.00
Dickerson					Fire Alarm test & inspection	Fire Alarm test & inspection					annual 5-01-18	\$300.00
Dickerson					APS					security System APS		
VS6					Dynafire	Fire Alarm test & inspection	Fire Alarm monitoring				annual 8-01-18	\$300.00
IS 7					Certified Electronic Systems		Fire Alarm monitoring				annual 10-01-18	\$359.40
Halifax Plaza					Certified Electronic Systems		Fire Alarm monitoring				annual 10-01-18	\$362.45
Halifax Plaza					Honeywell - Notifier RP		Fire Alarm monitoring					
City Hall					2001	Certified Electronic Systems		Fire Alarm test & inspection			annual	\$345.00
City Hall					Honeywell - Notifier RP	Certified Electronic Systems		Fire Alarm monitoring			annual 12-01-18	\$423.00
Jose Rogers House					2001	Certified Electronic Systems		Fire Alarm test & inspection			annual 1-24-19	\$423.00
Archives		3752			Secura MR2615	Certified Electronic Systems		Fire Alarm test & inspection			annual 7-23-18	\$164.00
Archives					43 Silent Knight	Certified Electronic Systems		Fire Alarm test & inspection			annual 11-15-18	\$400.00
Archives					Honeywell - Notifier RP		Fire system monitoring					
Archives					2001	Wiginton		Fire Alarm test & inspection			annual 11-15-18	\$400.00
Archives					Wiginton			Fire Sprinkler Inspector			annual 11-15-18	\$900.00
Halifax Plaza		32 Whole bldg			Wiginton			Fire Sprinkler Inspector			annual 11-15-18	\$425.00
City Hall IT Room					Wiginton			Fire Sprinkler Inspector			annual 11-15-18	\$275.00
Peabody					Wiginton			Fire Sprinkler Inspector			annual 11-15-18	\$450.00
Peabody					MS3200	Johnson Controls/Tyco		Fire Alarm test & inspection			annual	\$3,770.45
PI Vidor					Wiginton			Fire Sprinkler Inspector			annual 11-15-18	\$745.00
Midtown					Mastercraft			Fire Sprinkler Inspector			annual 4-06-18	\$198.00
Midtown					Mastercraft				Backflow Preventer Certification		4/23/2018	\$320.00
VS6					Mastercraft				Backflow Preventer Certification		5/25/2018	\$350.00
VS6					Mastercraft			Fire Sprinkler Inspector			Quarterly 7-31-18	\$430.00
DUPD Vidor						Fire Suppression System						
Batteries												

FIRE ALARM INSPECTION FOR
POLICE DEPARTMENT



FIRE ALARM SYSTEM RECORD OF INSPECTION AND TESTING (NFPA 72, 2013)

LICENSE: FL EF20000358; GA LVA205662; SC FAC 13524; NC 29222-SP-FA/LV; AL A-0576; LA E18680; TX APS-1956566

Inspection/Test Start Date/Time: 04/03/2019 0730 Inspection/Test Completion Date/Time: 04/03/2019 16:30
Supplemental Form(s) Attached: Yes (yes/no)

1. PROPERTY INFORMATION

Name of property: City of Daytona Beach Police Department
Address: 129 Valor Blvd Daytona Beach FL 32114
Description of property: Police Department
Name of property representative: Nick Fiore
Address: 129 Valor Blvd Daytona Beach FL 32114
Phone: 386-299-5406 Fax: _____ E-mail: fiorenicholas@dbpd.us

2. TESTING AND MONITORING INFORMATION

Testing organization: Wiginton Fire Systems
Address: 482 Fentress Suite H Daytona Beach FL 32114
Phone: 386-527-4300 Fax: _____ E-mail: Bms@wiginton.net
Monitoring organization: Dynafire
Address: 501 mason ave Daytona Beach FL 32117
Phone: 888-996-3962 Fax: _____ E-mail: _____
Account number: K240337 Phone line 1: _____ Phone line 2: _____
Entity to which alarms are retransmitted: _____ Phone: _____

3. DOCUMENTATION

Onsite location of the required record documents and site-specific software: None

4. DESCRIPTION OF SYSTEM OR SERVICE

4.1 Control Unit

Manufacturer: Notifier Model number: NFS-320/ FCPS-24S6

4.2 Software Firmware

Firmware revision number: 23.00

4.3 System Power

4.3.1 Primary (Main) Power

Nominal voltage: 120 Amps: 6.0 Location: 1st floor electric room
Overcurrent protection type: Breaker Amps: 20 Disconnecting means location: Electric panel 12 Breaker 4

SYSTEM RECORD OF INSPECTION AND TESTING (continued)

4. DESCRIPTION OF SYSTEM OR SERVICE (continued)

4.3.2 Secondary Power

Type: Battery Location: Panel

Battery type (if applicable): SLA 12v 26ah

Calculated capacity of batteries to drive the system:

In standby mode (hours): 24 In alarm mode (minutes): 5

5. NOTIFICATIONS MADE PRIOR TO TESTING

Monitoring organization	Contact: <u>Dynafire</u>	Time: <u>0730</u>
Building management	Contact: <u>Nick</u>	Time: <u>0730</u>
Building occupants	Contact: <u>Staff</u>	Time: <u>0730</u>
Authority having jurisdiction	Contact: _____	Time: _____
Other, if required	Contact: _____	Time: _____

6. TESTING RESULTS

6.1 Control Unit and Related Equipment

Description	Visual Inspection	Functional Test	Comments
Control unit	X	X	
Lamps/LEDs/LCDs	X	X	
Fuses			
Trouble signals	X	X	
Disconnect switches			
Ground-fault monitoring	X	X	
Supervision	X	X	
Local annunciator	X	X	
Remote annunciators	X	X	
Remote power panels	X	X	12V 12AH Both floors

6.2 Secondary Power

Description	Visual Inspection	Functional Test	Comments
Battery condition	X	X	
Load voltage	X	X	
Discharge test	X	X	
Charger test	X	X	
Remote panel batteries	X	X	2 nd floor room 2037A / 3 rd floor room 3054A

SYSTEM RECORD OF INSPECTION AND TESTING *(continued)*

6. TESTING RESULTS *(continued)*

6.3 Alarm and Supervisory Alarm Initiating Device

Attach supplementary device test sheets for all initiating devices.

6.4 Notification Appliances

Attach supplementary appliance test sheets for all notification appliances.

6.5 Interface Equipment

Attach supplementary interface component test sheets for all interface components.

Circuit Interface / Signaling Line Circuit Interface / Fire Alarm Control Interface

6.6 SUPERVISING STATION MONITORING

Description	Yes	No	Time	Comments
Alarm signal	X		1436	
Alarm restoration	X		1438	
Trouble signal	X		0802	
Trouble restoration	X		1510	
Supervisory signal	X		0906	
Supervisory restoration	X		0906	

6.7 Public Emergency Alarm Reporting System

Description	Yes	No	Time	Comments
Alarm signal				
Alarm restoration				
Trouble signal				
Trouble restoration				
Supervisory signal				
Supervisory restoration				

SYSTEM RECORD OF INSPECTION AND TESTING (continued)

7. NOTIFICATIONS TESTING IS COMPLETE


Monitoring organization	Contact: <u>Dynafire</u>	Time: <u>16:30</u>
Building management	Contact: <u>Nick</u>	Time: <u>16:30</u>
Building occupants	Contact: <u>Staff</u>	Time: <u>16:30</u>
Authority having jurisdiction	Contact: _____	Time: _____
Other, if required	Contact: _____	Time: _____

8. SYSTEM RESTORED TO NORMAL OPERATION

Date: 04/03/2019 Time: 16:30

9. CERTIFICATION

This system as specified herein has been inspected and tested according to NFPA 72, 2013 edition, Chapter 14.

Signed:  Printed name: Brandon Schweickert Date: 04/03/2019
Organization: Wiginton Fire Systems Title: Inspector Phone: 386-451-7795
Qualifications (refer to 10.5.3): FASA/BASA

10. DEFECTS OR MALFUNCTIONS NOT CORRECTED AT CONCLUSION OF SYSTEM INSPECTION, TESTING, OR MAINTENANCE


All third floor strobes and horn strobes do not work

Batteries in 3rd floor expander are bad 12v 12 ah x2

Batteries in main panel 12v 26ah are bad

10.1 Acceptance by Owner or Owner's Representative:

The undersigned accepted the test report for the system as specified herein:

Signed:  Printed name: Warren Lewis Date: 04/03/2019
Organization: D.B.P.D. Title: Maintenance Phone: 386-366-2735

INITIATING DEVICE

SUPPLEMENTARY RECORD OF INSPECTION AND TESTING

This form is a supplement to the System Record of Inspection and Testing.

It includes an initiating device test record.

This form is to be completed by the system inspection and testing contractor at the time of the inspection and/or test. It shall be permitted to modify this form as needed to provide a more complete and/or clear record.

Insert N/A in all unused lines.

Inspection/Test Start Date/Time: 04/03/2019 0730 Inspection/Test Completion Date/Time: 04/03/2019 16:30

Number of Supplemental Pages Attached: 3

1. PROPERTY INFORMATION

Name of property: City of Daytona Beach Police Department

Address: 129 Valor Blvd Daytona Beach FL 32114

2. INITIATING DEVICE TEST RESULTS

Device Type	Address	Location	Test Results
Pull Station	001	Corridor 1135 S.E. exit	Pass
Pull Station	002	Corridor 1022 East exit	Pass
Pull Station	003	Lobby 1001 east	Pass
Pull Station	004	Lobby 1001 north	Pass
Pull Station	005	Corridor 1121 south	Pass
Pull Station	006	Corridor 1099 by 1107	Pass
Pull Station	007	Corridor South by dui	Pass
Pull Station	008	Staff vest 1085 west	Pass
Pull Station	009	Corridor 1026 west	Pass
Pull Station	010	Evidence 1058 west	Pass
Pull Station	011	Stairs #3 west exit	Pass
Tamper	014	Stair #2	Pass
Tamper	015	Stair #1	Pass
Waterflow	016	Stair #1	Pass
Tamper	017	Stair #1	Pass
Tamper	041	Pump room	Pass
Tamper	042	Pump room	Pass
Tamper	043	Pump room	Pass
Tamper	044	Pump room	Pass
Tamper	045	Dry system	Pass
Tamper	046	Dry system	Pass
Monitor	047	Pump run	Pass

INITIATING DEVICE

SUPPLEMENTARY RECORD OF INSPECTION AND TESTING *(continued)*

2. INITIATING DEVICE TEST RESULTS *(continued)*

Device Type	Address	Location	Test Results
Monitor	048	Pump phase reversal	Pass
Monitor	049	Pump fail	Pass
Monitor	051	Fire suppression (alarm)	Pass
Monitor	052	Fire suppression (trouble)	Pass
Monitor	053	Fire suppression (supervisory)	Pass
Monitor	088	Telephone room alarm	DNT
Monitor	089	Telephone room trouble	DNT
Monitor	090	Telephone room supervisory	DNT
Monitor	091	Preaction(alarm)	Pass
Monitor	092	Preaction(Trouble)	Pass
Monitor	093	Preaction(supervisory)	Pass
Tamper	101	Dry system hi low air	Pass
Waterflow	102	Dry system	Pass
Pull station	021	Stair #1 2012 east	Pass
Pull station	022	Stair #2 2027 east	Pass
Pull station	023	Stair #3 2095 west	Pass
Pull station	024	Stair #4 2062 center	Pass
Pull station	031	Stair #1 3012 east	Pass
Pull station	032	Stair#2 3017 east	Pass
Pull station	033	Stair# 3 3068 west	Pass
Tamper	027	Stair#1	Pass
Waterflow	026	Stair#1	Pass
Waterflow	036	Stair#1	Pass
Tamper	037	Stair#1	Pass
Heat detector	001	Garage 1139	Pass
Heat detector	002	Garage 1139	Pass
Heat detector	003	Garage 1139	Pass
Heat detector	004	Vehicle process 1132	Pass
Heat detector	005	Process lab 1145	Pass
Smoke detector	006	Elevator lobby 1003	Pass
Smoke detector	007	Stair #1	Pass
Smoke detector	008	2 nd floor refudge area	Pass
Smoke detector	009	East elevator equip 1013	Pass

See main System Record of Inspection and Testing for additional information, certifications, and approvals.

NOTIFICATION APPLIANCE

SUPPLEMENTARY RECORD OF INSPECTION AND TESTING

This form is a supplement to the System Record of Inspection and Testing.

It includes a notification appliance test record.

This form is to be completed by the system inspection and testing contractor at the time of the inspection and/or test. It shall be permitted to modify this form as needed to provide a more complete and/or clear record.

Insert N/A in all unused lines.

Inspection/Test Start Date/Time: 04/03/2019 0730 Inspection/Test Completion Date/Time: 04/03/2019 16:30

Number of Supplemental Pages Attached: _____

1. PROPERTY INFORMATION

Name of property: City of Daytona Beach Police Department

Address: 129 Valor Blvd Daytona Beach FL 32114

2. NOTIFICATION APPLIANCE TEST RESULTS

Appliance Type	Location/Identifier	Test Results
Horn strobe	Room 1132A	Pass
Horn strobe	Room 1139A	Pass
Horn strobe	Room 1139A	Pass
Horn strobe	Hall @ 1139A	Pass
Horn strobe	Hall @ 1018A	Pass
Horn strobe	Room 1145A	Pass
Horn strobe	Room 1142A	Pass
Horn strobe	Room 1142A	Pass
Horn strobe	Room 1142A breakroom	Pass
Horn strobe	Room 1021A	Pass
Horn strobe	1018A stairs	Pass
Horn strobe	Hall @ 1131A	Pass
Horn strobe	Room 1131A	Pass
Horn strobe	Room 1108A	Pass
Horn strobe	Hall @ 1119A	Pass
Horn strobe	Room 1119A hall	Pass
Horn strobe	Room 1119A hall	Pass
Horn strobe	Room 1124A	Pass
Horn strobe	Hall @ 1116A	Pass
Horn strobe	Booking garage	Pass
Horn strobe	@ womens booking	Pass
Horn strobe	Hall @ 1111A	Pass

NOTIFICATION APPLIANCE

SUPPLEMENTARY RECORD OF INSPECTION AND TESTING *(continued)*

2. NOTIFICATION APPLIANCE TEST RESULTS *(continued)*

Appliance Type	Location/Identifier	Test Results
Horn strobe	Room 1103B	Pass
Horn strobe	Hall @ 1103B	Pass
Horn strobe	Room 1081A	Pass
Horn strobe	Room 1081A	Pass
Horn strobe	Room 1025A	Pass
Horn strobe	Room 1025A	Pass
Horn strobe	Room 1033	Pass
Horn strobe	Room 1033	Pass
Horn strobe	Hall @ SUI	Pass
Horn strobe	Maint shop	Pass
Horn strobe	Hall @ 1107	Pass
Horn strobe	Room 1107	Pass
Horn strobe	Hall @1101	Pass
Horn strobe	Outside west entrance	Pass
Horn strobe	Outside west entrance	Pass
Horn strobe	West entrance	Pass
Horn strobe	Room 1075	Pass
Horn strobe	Hall @ 1075	Pass
Horn strobe	Room 1056A	Pass
Horn strobe	Outside 1058A	Pass
Horn strobe	Evidence Pros	Pass
Horn strobe	Room 1059A	Pass
Horn strobe	Room 1072A	Pass
Horn strobe	Hall@ 1049	Pass
Horn strobe	Hall @ 1045A	Pass
Horn strobe	Hall @ 1038A	Pass
Horn strobe	Hall @ 1033A	Pass
Horn strobe	Room 1013A	Pass
Horn strobe	Outside lobby	Pass
Horn strobe	Lobby	Pass
Horn strobe	Lobby	Pass
Horn strobe	Hall @ 1011A	Pass

See main System Record of Inspection and Testing for additional information, certifications, and approvals.

INTERFACE COMPONENT

SUPPLEMENTARY RECORD OF INSPECTION AND TESTING

This form is a supplement to the System Record of Inspection and Testing.

It includes an interface component test record for circuit interfaces, signaling line circuit interfaces, and fire alarm control interfaces.

This form is to be completed by the system inspection and testing contractor at the time of the inspection and/or test. It shall be permitted to modify this form as needed to provide a more complete and/or clear record.

Insert N/A in all unused lines.

Inspection/Test Start Date/Time: 04/03/2019 0730 Inspection/Test Completion Date/Time: 04/03/2019 16:30

Number of Supplemental Pages Attached: _____

1. PROPERTY INFORMATION

Name of property: City of Daytona Beach Police Department

Address: 129 Valor Blvd Daytona Beach FL 32114

2. NOTIFICATION APPLIANCE TEST RESULTS

Interface Component Type	Location/Identifier	Test Results
Relay	Evedence door release	Pass
Relay	Door holders	Pass
Control	Nac trip	Pass
Relay	Elevator shunt	Pass
Relay	Elevator recall	Pass
Relay	Elevator alt	Pass
Relay	Roll down door	Pass
Relay	Security door override	Pass
Relay	AHU shutdown	Pass

See main System Record of Inspection and Testing for additional information, certifications, and approvals.

INITIATING DEVICE

SUPPLEMENTARY RECORD OF INSPECTION AND TESTING *(continued)*

2. INITIATING DEVICE TEST RESULTS *(continued)*

Device Type	Address	Location	Test Results
Heat detector	010	East elevator equip 1013	Pass
Heat detector	011	CSI files 1017	Pass
Smoke detector	012	Corridor by room 1159	Pass
Smoke detector	013	Corridor by stair #2	Pass
Heat detector	014	Breakroom 1131	Pass
Smoke detector	015	General supply 1161	Pass
Heat detector	016	Chemical Storge 1137	Pass
Heat detector	017	Maintenance shop 1132	Pass
Heat detector	018	Maintenance shop 1132	Pass
Heat detector	019	Equipment storage 1133	Pass
Heat detector	020	Pumproom 1140	Pass
Smoke detector	021	FACP 1134	Pass
Heat detector	022	Holding cell 1117	Pass
Heat detector	023	Holding cell 1118	Pass
Heat detector	024	Holding cell 1111	Pass
Heat detector	025	Holding cell 1112	Pass
Heat detector	026	Holding cell 1113	Pass
Heat detector	027	Holding cell 1114	Pass
Heat detector	028	Tactical garage 1107	Pass
Heat detector	029	Tactical garage 1107	Pass
Smoke detector	030	Bike shop 1106	Pass
Heat detector	031	Armory 1098	Pass
Heat detector	032	Arsenal 1097	Pass
Smoke detector	033	Uniforms 1101	Pass
Smoke detector	034	Uniforms 1101	Pass
Heat detector	035	File server 1108	Pass
Heat detector	036	File server 1108	Pass
Heat detector	037	File server 1108	Pass
Heat detector	038	Holding cell 1128	Pass
Heat detector	039	Holding cell 1127	Pass
Heat detector	040	Holding cell 1126	Pass
Heat detector	041	General storage 1072	Pass
Heat detector	042	Large storage 1059	Pass

See main System Record of Inspection and Testing for additional information, certifications, and approvals.

INITIATING DEVICE

SUPPLEMENTARY RECORD OF INSPECTION AND TESTING *(continued)*

2. INITIATING DEVICE TEST RESULTS *(continued)*

Device Type	Address	Location	Test Results
Heat detector	043	Large storage 1059	Pass
Heat detector	044	Large storage 1059	Pass
Heat detector	045	Fire arm storage 1071	Pass
Heat detector	046	General storage 1072	Pass
Heat detector	047	Large storage 1072	Pass
Heat detector	048	Bio hazard storage 1067	Pass
Heat detector	049	Narcadic storage 1066	Pass
Heat detector	050	Evidence disposal 1058	Pass
Smoke detector	051	Elevator mech 1077 west	Pass
Heat detector	052	Elevator mech 1077 west	Pass
Smoke detector	054	Elevator lobby 1077 west	Pass
Heat detector	055	Storage 1054	Pass
Heat detector	056	Breakroom 1042	Pass
Smoke detector	057	Records 1041	Pass
Heat detector	058	Personnel files 2015	Pass
Smoke detector	059	Elevator lobby 2088 east	Pass
Heat detector	060	Comp stat 2001	Pass
Heat detector	061	Comp stat 2001	Pass
Heat detector	062	Gally 2044	Pass
Smoke detector	063	Storage 2047	Pass
Heat detector	064	Gally 2048	Pass
Smoke detector	065	West elevator lobby 2061	Pass
Smoke detector	066	Electric room 2069	Pass
Heat detector	067	Data closet 2038	Pass
Smoke detector	068	Storage 2047	Pass
Duct detector	071	AHU mech 2036	Pass
Duct detector	072	AHU mech 2036	Pass
Duct detector	073	AHU mech 2036	Pass
Duct detector	074	AHU mech 2036	Pass
Duct detector	075	AHU mech 2036	Pass
Duct detector	076	AHU mech 2036	Pass
Duct detector	077	AHU mech 2036	Pass
Duct detector	078	AHU mech 2036	Pass

See main System Record of Inspection and Testing for additional information, certifications, and approvals.

INITIATING DEVICE

SUPPLEMENTARY RECORD OF INSPECTION AND TESTING *(continued)*

2. INITIATING DEVICE TEST RESULTS (continued)

[illegible]

See main System Record of Inspection and Testing for additional information, certifications, and approvals.

INITIATING DEVICE

SUPPLEMENTARY RECORD OF INSPECTION AND TESTING *(continued)*

2. INITIATING DEVICE TEST RESULTS *(continued)*

Device Type	Address	Location	Test Results
Horn strobe		Hall @1134	Pass
Horn strobe		2027A Stairs	Pass
Horn strobe		Hall @ 2027A	Pass
Horn strobe		Room 2018A hall	Pass
Horn strobe		Room 2018A hall	Pass
Horn strobe		Hall @ 2001A	Pass
Horn strobe		Room 2001A	Pass
Horn strobe		Room 2046A	Pass
Horn strobe		Room 2036A	Pass
Horn strobe		Room 2036A	Pass
Horn strobe		Room 2044A	Pass
Horn strobe		Room 2044A	Pass
Horn strobe		Hall @ 2053A	Pass
Horn strobe		Hall @ 2038A	Pass
Horn strobe		Hall @ 2 nd floor elevator	Pass
Horn strobe		2062A stairs	Pass
Horn strobe		Hall @ 2056A	Pass
Horn strobe		Room 2067B	Pass
Horn strobe		Hall @ 2075A	Pass
Horn strobe		Room 2087A	Pass
Horn strobe		Hall @ 2077	Pass
Horn strobe		Hall @ 2084	Pass
Horn strobe		Hall @ 2091	Pass
Horn strobe		2094 Stairs	Pass
Horn strobe		2094 stairs	Pass
Horn strobe		Hall @ 3068	Fail
Horn strobe		Room 3072	Fail
Horn strobe		Room 3075	Fail
Horn strobe		Hall @3054	Fail
Horn strobe		Hall @ 3043	Fail
Horn strobe		Hall @ 3034	Fail
Horn strobe		Hall @ 3017	Fail
Horn strobe		Hall @ 3002	Fail

See main System Record of Inspection and Testing for additional information, certifications, and approvals.

INITIATING DEVICE

SUPPLEMENTARY RECORD OF INSPECTION AND TESTING *(continued)*

2. INITIATING DEVICE TEST RESULTS *(continued)*

Device Type	Address	Location	Test Results
Horn strobe		Hall @ 3061	Fail
Horn strobe		Hall @ 3012	Fail
Strobe		Room 1159	Pass
Strobe		Room 1017	Pass
Strobe		Room 1081	Pass
Strobe		Room 1081	Pass
Strobe		Room 1025	Pass
Strobe		Room 1025	Pass
Strobe		Room 1025	Pass
Strobe		Room 1092	Pass
Strobe		Room 1090	Pass
Strobe		Room 1075	Pass
Strobe		Room 1074	Pass
Strobe		Room 1053	Pass
Strobe		Room 1058	Pass
Strobe		Hall @ 1052	Pass
Strobe		Room 1051	Pass
Strobe		Room 1048	Pass
Strobe		Room 1047	Pass
Strobe		Room 1038	Pass
Strobe		Room 1036	Pass
Strobe		Room 1035	Pass
Strobe		Room 1015	Pass
Strobe		Room 1014	Pass
Strobe		Room 1002	Pass
Strobe		Room 1007	Pass
Strobe		Room 1006	Pass
Strobe		Room 2018	Pass
Strobe		Room 2028	Pass
Strobe		Room 2033	Pass
Strobe		Room 2034	Pass
Strobe		Room 2004	Pass
Strobe		Room 2007	Pass

See main System Record of Inspection and Testing for additional information, certifications, and approvals.

INITIATING DEVICE

SUPPLEMENTARY RECORD OF INSPECTION AND TESTING *(continued)*

2. INITIATING DEVICE TEST RESULTS (continued)

[illegible]

See main System Record of Inspection and Testing for additional information, certifications, and approvals.