
S PARK DR TEST HOLES







Project: M-0618-0201-S44D ADD (Sparrow Pond)	Prepared By: Bryson Ricks		Date: 2021-09-27	
City: Arlington	State: VA		Test Hole: 1 of	
General Location: S. Park Dr.				
	UTILITY IN	IFORMATION		
Utility Size: 12" Per Record	Material: Ductile Iron		Good Condition: YES	
Utility Type: Water Line			Utility Owner: Arlington County	
	ADDITIONAL UTI	LITY INFORMATION		
Utility Size:	Material:		See Test Hole No.:	
Utility Type: None			Utility Owner:	
	SITE CC	ONDITIONS		
Field Condition: Grass Area		Pavement thickness: NA		
Ground Condition: Brown Soil		•		
FIRST & SECOND BENCHMARK INFORMATION				
1st Elevation:	1st Benchmark Description:			
BM Check:				
2nd Elevation:	2nd Benchmark Description:			
Elevation Datum:				
FIELD MARKER INFORMATION				
Type set: Chiseled "X"	Elevation: 189.64'			
Offset/Direction: Chiseled "X" is set C/L of the Utility	<i>.</i>			
	PROFI			
		ield measurement: <u>5.32'</u> ity field measurement: <u>No</u> r	Elevation: <u>184.32'</u> ne Elevation: <u>None</u>	
Facing: West Utility Width/Spacin	ng:			
PLAN VIEW			COORDINATES	
		Northing: 7000528.8813	Easting: 11876517.5045 COMMENTS/NOTES	





Project: M-0618-0201-S44D ADD (Sparrow Pond)	Prepared By: Bryson Ricks		Date: 2021-09-27	
City: Arlington	State: VA		Test Hole: 2 of	
General Location: S. Park Dr.				
	UTILITY IN	FORMATION		
Utility Size: 12" Per Record	Material: Ductile Iron		Good Condition: YES	
Utility Type: Water Line			Utility Owner: Arlington County	
	ADDITIONAL UTI	LITY INFORMATION		
Utility Size:	Material:		See Test Hole No.:	
Utility Type: None			Utility Owner:	
	SITE CC	NDITIONS		
Field Condition: Grass Area		Pavement thickness: NA		
Ground Condition: Brown Soil				
FIRST & SECOND BENCHMARK INFORMATION				
1st Elevation:	1st Benchmark Description:			
BM Check:				
2nd Elevation:	2nd Benchmark Description:			
Elevation Datum:				
FIELD MARKER INFORMATION				
Type set: Wooden Hub	Elevation: 184.58'			
Offset/Direction: Hub is set C/L of the Utility.				
	PROFI	LE VIEW		
Top of utility field measurement: 4.98' Elevation: 179.60' Bottom of utility field measurement: None Elevation: None				
Facing: West		ny neiù measurement. <u>No</u>		
Facing: West Utility Width/Spacing: PLAN VIEW COORDINATES			COORDINATES	
FLAN VILW		Northing: 7000540.8474	Easting: 11876470.3272	
		Northing. 7000340.6474	COMMENTS/NOTES	





Project: M-0618-0201-S44D ADD (Sparrow Pond)	Prepared By: Bryson Ricks		Date: 2021-09-27
City: Arlington	State: VA		Test Hole: 3 of
General Location: S. Park Dr.			
	UTILITY IN	FORMATION	
Utility Size: 12" Per Record	Material: Ductile Iron		Good Condition: YES
Utility Type: Water Line			Utility Owner: Arlington County
	ADDITIONAL UTI	LITY INFORMATION	
Utility Size:	Material:		See Test Hole No.:
Utility Type: None			Utility Owner:
	SITE CC	ONDITIONS	
Field Condition: Asphalt		Pavement thickness: 6"	
Ground Condition: Brown Soil	Ground Condition: Brown Soil		
FIRST & SECOND BENCHMARK INFORMATION			
1st Elevation:	1st Benchmark Description:		
BM Check:			
2nd Elevation:	2nd Benchmark Description:		
Elevation Datum:			
	FIELD MARKE	R INFORMATION	
Type set: Mag Nail	Elevation: 181.27'		
Offset/Direction: Nail is set C/L of the Utility.			
PROFILE VIEW			
Top of utility field measurement: 4.79' Elevation: 176.48' Bottom of utility field measurement: None Elevation: None			
Facing: West Hillin: Width Pracis		ity neid measurement: <u>NO</u>	
Facing: West Utility Width/Spacing: DLAN VIEW COORDINATES			
PLAN VIEW		Northing 7000552 0405	
		Northing: 7000553.0165	Easting: 11876443.1561
			<u>COMMENTS/NOTES</u>





Project: M-0618-0201-S44D ADD (Sparrow Pond)	Prepared By: Bryson Ricks		Date: 2021-09-27
City: Arlington	State: VA		Test Hole: 4 of
General Location: S. Park Dr.			
	UTILITY IN	FORMATION	
Utility Size: 12" Per Record	Material: Ductile Iron		Good Condition: YES
Utility Type: Water Line			Utility Owner: Arlington County
	ADDITIONAL UTI	LITY INFORMATION	
Utility Size:	Material:		See Test Hole No.:
Utility Type: None			Utility Owner:
	SITE CO	NDITIONS	
Field Condition: Asphalt		Pavement thickness: 6"	
Ground Condition: Brown Soil	Ground Condition: Brown Soil		
FIRST & SECOND BENCHMARK INFORMATION			
1st Elevation:	1st Benchmark Description:		
BM Check:			
2nd Elevation:	2nd Benchmark Description:		
Elevation Datum:			
	FIELD MARKE	R INFORMATION	
Type set: Mag Nail	Elevation: 173.00'		
Offset/Direction: Nail is set C/L of the Utility.			
	PROFI	LE VIEW	
Top of utility field measurement: 6.02' Elevation: 166.98' Bottom of utility field measurement: None Elevation: None			
Facing: West Utility Width/Spacing:			
PLAN VIEW COORDINATES			
		Northing: 7000564.8628	Easting: 11876378.2606 COMMENTS/NOTES





Project: M-0618-0201-S44D ADD (Sparrow Pond)	Prepared By: Bryson Ricks		Date: 2021-09-27
City: Arlington	State: VA		Test Hole: 5 of
General Location: S. Park Dr.			
	UTILITY IN	IFORMATION	
Utility Size: 12" Per Record	Material: Ductile Iron		Good Condition: YES
Utility Type: Water Line			Utility Owner: Arlington County
Utility Size:	Material:		See Test Hole No.:
Utility Type: None			Utility Owner:
	SITE CO	ONDITIONS	
Field Condition: Asphalt		Pavement thickness: 7"	
Ground Condition: Brown Soil			
FIRST & SECOND BENCHMARK INFORMATION			
1st Elevation:	1st Benchmark Description:		
BM Check:			
2nd Elevation:	2nd Benchmark Description:		
Elevation Datum:			
FIELD MARKER INFORMATION			
Type set: Mag Nail	Elevation: 171.81'		
Offset/Direction: Nail is set C/L of the Utility.			
PROFILE VIEW			
Top of utility field measurement: 5.83' Elevation: 165.98' Bottom of utility field measurement: None Elevation: None			
Facing: West Utility Width/Spacin	ıg:		
PLAN VIEW COORDINATES			COORDINATES
		Northing: 7000559.6193	Easting: 11876371.7306 COMMENTS/NOTES





Project: M-0618-0201-S44D ADD (Sparrow Pond)	Prepared By: Bryson Ricks		Date: 2021-09-27	
City: Arlington	State: VA		Test Hole: 6 of	
General Location: S. Park Dr.				
	UTILITY IN	FORMATION		
Utility Size: 12" Per Record	Material: Ductile Iron		Good Condition: YES	
Utility Type: Water Line			Utility Owner: Arlington County	
	ADDITIONAL UTI	LITY INFORMATION		
Utility Size:	Material:		See Test Hole No.:	
Utility Type: None			Utility Owner:	
	SITE CC	ONDITIONS		
Field Condition: Grass Area		Pavement thickness: NA		
Ground Condition: Brown Soil		-		
FIRST & SECOND BENCHMARK INFORMATION				
1st Elevation:	1st Benchmark Description:			
BM Check:				
2nd Elevation:	2nd Benchmark Description:			
Elevation Datum:				
FIELD MARKER INFORMATION				
Type set: Wooden Hub	Elevation: 168.54'			
Offset/Direction: Hub is set C/L of the Utility.				
	PROFI			
Top of utility field measurement: 6.20' Elevation: 162.34' Bottom of utility field measurement: None Elevation: None				
Facing: West Utility Width/Spacin	ng:			
PLAN VIEW COORDINATES			COORDINATES	
		Northing: 7000544.2830	Easting: 11876351.8870 COMMENTS/NOTES	