



ADDENDUM # 3

ITB REBID 2023-818, SENIOR CENTER KITCHEN RENOVATION

ADDENDUM DATE: February 23, 2023

BID DUE DATE/ TIME: **March 16, 2023, 3:00 PM**

This addendum includes the following:

1. Asbestos Report

For further information contact:
Joni Gay, Procurement Manager, CPO
Phone: 505-334-7656
Fax: 505-334-7649
email: jgay@aztecnm.gov



February 03, 2023

Project No. 93132-0032

Mr. Charles Dobey
 City OF Aztec
 201 W. Chaco St.
 Aztec, NM 87410

Email: cdobey@aztecnm.org

RE: ASBESTOS SAMPLING REPORT FOR SENIOR CENTER AT 101 S PARK AVE, LOCATED IN AZTEC NEW MEXICO

Dear Mr. Dobey,

On January 23, 2023, Ten (10) samples of suspect Asbestos Containing Material (ACM) were collected from the Aztec Senior Community Center, located in Aztec, New Mexico. These samples were shipped priority overnight under Chain-of-Custody No. 0285997 to EMC LABS, Inc. Phoenix, Arizona; EMC Laboratory is a NVLAP Accredited Asbestos Analytical Laboratory, Accreditation No.101926-0.

The following table shows a breakdown of the analysis:


Sample ID	Sample Location	Layer	Description	Asbestos
O-15561	Sample 1	Layer 1	Drywall, Off White / Brown	None Detected
		Layer 2	Texture/ Paint, Tan/ White / Lt. Green	None Detected
O-15562	Sample 2	Layer 1	Texture, Tan/ White/ Lt. Green	None Detected
O-15563	Sample 3	Layer 1	Vinyl Flooring, Red Square Pattern	18% Chrysotile
		Layer 2	Mastic, Brown	3% Chrysotile
O-15564	Sample 4	Layer 1	Vinyl, Blue / White	None Detected
		Layer 2	Mastic, Yellow	None Detected
O-15565	Sample 5	Layer 1	Vinyl, Pink	None Detected
		Layer 2	Mastic, Yellow	None Detected
O-15566	Sample 6	Layer 1	Floor Tile, White	None Detected
		Layer 2	Mastic, Yellow	None Detected
O-15567	Sample 7	Layer 1	Drywall, Off White/ Brown	None Detected
		Layer 2	Paint, gray / White	None Detected
O-15568	Sample 8	Layer 1	Ceiling Tile, Beige	None Detected
O-15569	Sample 9	Layer 1	Cove Base, Brown	None Detected
		Layer 2	Mastic, Brown	None Detected
O-15570	Sample 10	Layer 1	Ceiling Tile, White/ Beige	None Detected

As per the attached analytical results Sample 3 Vinyl Flooring, Red Square Pattern and Brown Mastic are positive for Asbestos. A total of Seventeen (17) separate layers were analyzed. Anything over 1% Asbestos is a regulated material per USEPA regulations. USEPA Trained and Certified Asbestos Workers must perform any disturbance or removal of the ACM. We appreciate the opportunity to be of service and look forward to working with you in the future. If you should require additional information or have any questions, please contact our office at (505) 632-0615.

Sincerely,
 ENVIROTECH, INC.

John A. De Anda
 Haz Department
jdeanda@envirotech-inc.com

Attachment: Laboratory Report



EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0285997

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIROTECH	Job# / P.O. #:	93132-0032	146550
Address:	5796 HIGHWAY 64-3014	Date Received:	01/26/2023	
	FARMINGTON NM 87401	Date Analyzed:	02/02/2023	
Collected:	01/23/2023	Date Reported:	02/02/2023	
Project Name:	AZTEC SENIOR CENTER-101 PARK AVE	EPA Method:	EPA 600/R-93/118	
Address:	AZTEC, NM 87410	Submitted By:	JOHN ALFONSO DE ANDA	
		Collected By:		

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0285997-001 0-15561	ASC-DW1-01	LAYER 1 Drywall, Off White/ Brown	No	None Detected	Cellulose Fiber Gypsum Carbonates Quartz Mica	12% 88%
		LAYER 2 Texture/ Paint, Tan/ White / Lt. Green	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler	<1% 99%
0285997-002 0-15562	ASC-DW1-02	Texture, Tan/ White / Lt. Green Note: No Drywall Present	No	None Detected	Carbonates Mica Quartz Perlite Binder/Filler	 100%
0285997-003 0-15563	ASC-VF1-01	LAYER 1 Vinyl Flooring, Red Square Patterns	Yes	Chrysotile 18%	Cellulose Fiber Carbonates Quartz Binder/Filler	2% 80%
		LAYER 2 Mastic, Brown	Yes	Chrysotile 3%	Cellulose Fiber Carbonates Gypsum Quartz Binder/Filler	2% 95%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0285997

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIROTECH	Job# / P.O. #:	93132-0032	146550
Address:	5796 HIGHWAY 64-3014	Date Received:	01/26/2023	
	FARMINGTON NM 87401	Date Analyzed:	02/02/2023	
Collected:	01/23/2023	Date Reported:	02/02/2023	
Project Name:	AZTEC SENIOR CENTER-101 PARK AVE	EPA Method:	EPA 800/R-93/116	
Address:	AZTEC, NM 87410	Submitted By:	JOHN ALFONSO DE ANDA	
		Collected By:		

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0285997-004 0-15564	ASC-VF2-01	LAYER 1 Vinyl, Blue / White	No	None Detected	Fibrous Glass Carbonates Gypsum Quartz Binder/Filler	10% 90%
		LAYER 2 Mastic, Yellow	No	None Detected	Cellulose Fiber Gypsum Quartz Carbonates Mica Binder/Filler	<1% 99%
0285997-005 0-15565	ASC-VF3-01	LAYER 1 Vinyl, Pink	No	None Detected	Carbonates Quartz Binder/Filler	100%
		LAYER 2 Mastic, Yellow	No	None Detected	Cellulose Fiber Synthetic Fiber Carbonates Quartz Binder/Filler	1% <1% 98%
0285997-006 0-15566	ASC-FT1-01	LAYER 1 Floor Tile, White	No	None Detected	Carbonates Quartz Binder/Filler	100%
		LAYER 2 Mastic, Yellow	No	None Detected	Carbonates Quartz Binder/Filler	100%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0285997

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client: ENVIROTECH Job# / P.O. #: 93132-0032 146550
Address: 5796 HIGHWAY 64-3014 Date Received: 01/26/2023
FARMINGTON NM 87401 Date Analyzed: 02/02/2023
Collected: 01/23/2023 Date Reported: 02/02/2023
Project Name: AZTEC SENIOR CENTER-101 PARK AVE EPA Method: EPA 600/R-93/116
Address: AZTEC, NM 87410 Submitted By: JOHN ALFONSO DE ANDA
Collected By:

Lab ID Client ID	Sample Location	Layer Name / Sample Description	Asbestos Detected	Asbestos Type (%)	Non-Asbestos Constituents	
0285997-007 0-15567	ASC-DW2-01	LAYER 1 Drywall, Off White/ Brown	No	None Detected	Cellulose Fiber Gypsum Carbonates Quartz Mica	12% 88%
		LAYER 2 Paint, Gray / White	No	None Detected	Cellulose Fiber Carbonates Quartz Binder/Filler	<1% 99%
0285997-008 0-15568	ASC-CT1-01	Ceiling Tile, Beige	No	None Detected	Cellulose Fiber Mineral Wool Carbonates Quartz Perlite Binder/Filler	40% 40% 20%
0285997-009 0-15569	ASC-CB1-01	LAYER 1 Cove Base, Brown	No	None Detected	Carbonates Quartz Binder/Filler	 100%
		LAYER 2 Mastic, Brown	No	None Detected	Gypsum Quartz Carbonates Binder/Filler	 100%
0285997-010 0-15570	ASC-CT2-01	Ceiling Tile, White/ Beige	No	None Detected	Cellulose Fiber Mineral Wool Carbonates Quartz Perlite Binder/Filler	45% 35% 20%

EMC LABS, INC.

9830 S. 51st Street, Suite B109, Phoenix, AZ 85044
Phone: 800-362-3373 or 480-940-5294 - Fax: (480) 893-1726

Laboratory Report
0285997

Bulk Asbestos Analysis by Polarized Light Microscopy

NVLAP#101926-0

Client:	ENVIROTECH	Job# / P.O. #:	93132-0032	146550
Address:	5796 HIGHWAY 64-3014	Date Received:	01/26/2023	
	FARMINGTON NM 87401	Date Analyzed:	02/02/2023	
Collected:	01/23/2023	Date Reported:	02/02/2023	
Project Name:	AZTEC SENIOR CENTER-101 PARK AVE	EPA Method:	EPA 800/R-93/116	
Address:	AZTEC, NM 87410	Submitted By:	JOHN ALFONSO DE ANDA	
		Collected By:		

Lab ID	Sample	Layer Name /	Asbestos	Asbestos Type	Non-Asbestos
Client ID	Location	Sample Description	Detected	(%)	Constituents



Analyst - Mark Steiner



Signatory - Lab Director - Kurt Kettler

Distinctly stratified, easily separable layers of samples are analyzed as subsamples of the whole and are reported separately for each discernible layer. All analyses are derived from calibrated visual estimate and measured in area percent unless otherwise noted. The report applies to the standards or procedures identified and to the sample(s) tested. The test results are not necessarily indicative or representative of the quality of the lot from which the sample was taken or of apparently identical or similar products, nor do they represent an ongoing quality assurance program unless so noted. These reports are for the exclusive use of the addressed client and that they will not be reproduced wholly or in part for advertising or other purposes over our signature or in connection with our name without special written permission. The report shall not be reproduced except in full, without written approval by our laboratory. The samples not destroyed in testing are retained a maximum of thirty days. The laboratory measurement of uncertainty for the test method is approximately less than 1 by area percent. Accredited by the National Institute of Standards and Technology, Voluntary Laboratory Accreditation Program for selected test method for asbestos. The accreditation or any reports generated by this laboratory in no way constitutes or implies product certification, approval, or endorsement by the National Institute of Standards and Technology. The report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the Federal Government. Polarized Light Microscopy may not be consistently reliable in detecting asbestos in floor coverings and similar non-flable organically bound materials.

CHAIN OF CUSTODY

EMC Laboratories
 9830 S. 51ST St., Ste B-109
 Phoenix, AZ 85044
 (800) 362-3373 Fax (480) 893-1726

LAB#: 285997
 TAT: 3-5 Day
 Rec'd: JAN 26 AM

COMPANY NAME: **ENVIROTECH**
 5796 Highway 64-3014
 Farmington, NM 87401
 CONTACT: Donald Ortiz
 Phone/Fax: (505) 632-0615 / 505-632-1865
 Email: enviroadmin@envirotech-inc.com; dortiz@envirotech-inc.com

BILL TO: (If Different Location)
 Scan COC
 jdeanda@envirotech-inc.com

Now Accepting: **VISA - MASTERCARD** Price Quoted: \$ _____ / Sample \$ _____ / Layers

COMPLETE ITEMS 1-4: (Failure to complete any items may cause a delay in processing or analyzing your samples)

1. **TURNAROUND TIME:** [Same Day RUSH] [1-Day] [2-Day] [3-Day] [5-Day] [6-10 Day]

****Prior confirmation of turnaround time is required
 ****Additional charges for rush analysis (please call marketing department for pricing details)
 ****Laboratory analysis may be subject to delay if credit terms are not met

2. **TYPE OF ANALYSIS:** [Bulk-PLM] [Air-PCM] [Lead] [Point Count] [Fungi: AOC, W-C, Bulk, Swab, Tape]

3. **DISPOSAL INSTRUCTIONS:** [Dispose of samples at EMC] / [Return samples to me at my expense]
 (If you do not indicate preference, EMC will dispose of samples 30 days from analysis.)

4. Project Name: Aztec Senior Center / 101 Park Ave, Aztec NM 87410
 P.O. Number: 146550 Project Number: 93132-0032

EMC SAMPLE #	CLIENT SAMPLE #	DATE & TIME SAMPLED	LOCATION/MATERIAL TYPE	Samples Accepted Yes / No	AIR SAMPLE INFO / COMMENTS		
					ON	OFF	FLOW RATE
1	0-15561	1/23/2023	ASC-DW1-01 / Tan Drywall	Y N			
2	0-15562	1/23/2023	ASC-DW1-02 / Tan Drywall	Y N			
3	0-15563	1/23/2023	ASC-VF1-01 / Red Square Pattern	Y N			
4	0-15564	1/23/2023	ASC-VF2-01 / Blue Vinyl	Y N			
5	0-15565	1/23/2023	ASC-VF3-01 / Pink Vinyl	Y N			
6	0-15566	1/23/2023	ASC-FT1-01 / White Floor Tile	Y N			
7	0-15567	1/23/2023	ASC-DW2-01 / Gray Drywall	Y N			
8	0-15568	1/23/2023	ASC-CT1-01 / Ceiling Tile Dark	Y N			
9	0-15569	1/23/2023	ASC-CB1-01 / Brown Cove Base	Y N			
10	0-15570	1/23/2023	ASC-CT2-01 / Ceiling Tile Tight	Y N			

SPECIAL INSTRUCTIONS:

Sample Collector: (Print) John De Anda (Signature) John De Anda
 Relinquished by: John De Anda Date/Time: 01/23/23 16:11 pm Received by: Diana Federico Date/Time: 1/26/23
 Relinquished by: Diana Federico Date/Time: 1/26/23 Received by: [Signature] Date/Time: 1/26/23
 Relinquished by: _____ Date/Time: _____ Received by: _____ Date/Time: _____