



Photo No. 1

Description: View of Constitution Park sidewalk looking South. Arrow points to bulkhead sheet piling to be replaced.



Photo No. 2

Description: View of Constitution Park sidewalk looking West. Arrow points to caved-in soil.



Photo No. 3

Description: View of Constitution Park sidewalk looking West. Arrow points to handrails to be replaced.



Photo No. 4

Description: View of Constitution Park sidewalk looking East. Arrow points to damaged sidewalk to be replaced.