



Tank Column Foundation



Erosion Under Column Base Plate



Erosion Under Column Base Plate




Corroded Ladder Standoff



Corroded Ladder Standoff



Severe Corrosion of Ladder Bolts



Float for Level Indicator (Sunk)



Broken Level Indicator



Roof Vent



Riser Foundation Bolt



Riser Foundation Bolt



Safety Climb Bar



Top of Tank Bowl



Tank Interior



Tank Interior



Interior Ladder



Tank Photo



Tank Information Plate

The photos shown below are **not** of the Port tank. These photos have been included as supplemental information to show an example of the fall protection grate to be installed over the riser opening of the Port tank.



Example of Fall Protection Grate



Example of Fall Protection Grate