



1

IMG_2161.JPG

Occupied camp to the South



2

IMG_2162.JPG

Occupied camp to the South



3
Occupied camp to the South

IMG_2163.JPG



4
Pipe protruding from camp floor believed to be former sewer drop

IMG_2164.JPG



5

IMG_2167.JPG

Segment of PVC pipe associated with former treatment system



6

IMG_2170.JPG

Pipe protruding from camp floor believed to be former sewer drop



7
Battery in water beneath camp

IMG_2173.JPG



8
View of camp in reference to Apache property marker (Looking South)

IMG_2174.JPG



9

IMG_2176.JPG

Side view of occupied camp



10

IMG_2178.JPG

Apache property marker



11

IMG_2181.JPG

View of two camps from Apache property marker (looking North)



12

IMG_2183.JPG

General view of camp from across bayou



13
General view of camp from across bayou

IMG_2184.JPG