

Income-Based Roof Program Scope of Work

Property Owner Name: Robert Laster &
Melissa Hale

Contractor: _____

Address: 2202 West Blount Street

Contractor PH#: _____

PH#: 850-791-2886

Total SF: 1,817

Pre-Bid Meeting (Date & Time): 4/15/2020-9am

Bid Close (Date & Time): 4/22/2020-5pm

Description:

- Remove all existing shingles, underlayment and drip-edge to expose decking, inspect vent boots
- Repair degraded and damaged decking, replace underlayment, new drip edge and install architectural shingles
- Replace soffit around entire house; and paint
- Install ridge vent

Note: Six squares of roof structure at 9/12 pitch

Cost of Labor: \$ _____

Cost of Materials: \$ _____

Total Cost: \$ _____

Property Owner Signature _____

Property Owner Signature _____

Contractor Signature _____

Income-Based Roof Program Scope of Work

Property Owner Name: Annie Causey

Contractor: _____

Address: 3400 W. Bobe Street

Contractor PH#: _____

PH#: 850-434-0381 or 850-450-6691

Total SF: 1,540

Pre-Bid Meeting (Date & Time): 4/15/2020-9am

Bid Close (Date & Time): 4/22/2020-5pm

Description: Roof Replacement

- Remove all existing shingles, underlayment and drip-edge to expose decking, inspect vent boots
- Repair degraded and damaged decking, replace underlayment, new drip edge and install architectural shingles
- Replace soffit & fascia around entire structure; and paint

Cost of Labor: \$_____

Cost of Materials: \$_____

Total Cost: \$_____

Property Owner Signature _____

Contractor Signature _____

Income-Based Roof Program Scope of Work

Property Owner Name: Ella Mae Walker

Contractor: _____

Address: 1127 W. Maxwell Street

Contractor PH#: _____

PH#: 850-438-2633 or 850-723-8423

Total SF: 1,501

Pre-Bid Meeting (Date & Time): 4/15/2020-9am

Bid Close (Date & Time): 4/22/2020-5pm

Description: Roof Replacement

- Remove all existing shingles, underlayment and drip-edge to expose decking, inspect vent boots
- Repair degraded and damaged decking, replace underlayment, new drip edge and install architectural shingles
- Replace leaf vents at rear of the house

Cost of Labor: \$ _____

Cost of Materials: \$ _____

Total Cost: \$ _____

Property Owner Signature _____

Contractor Signature _____

Income-Based Roof Program Scope of Work

Property Owner Name: Stephanie Neal

Contractor: _____

Address: 707 Loire Way

Contractor PH#: _____

PH#: 850-287-1277

Total SF: 1,593

Pre-Bid Meeting (Date & Time): 4/15/2020-9am

Bid Close (Date & Time): 4/22/2020-5pm

Description: Roof Replacement

- Remove all existing shingles, underlayment and drip-edge to expose decking, inspect vent boots
- Repair degraded and damaged decking, replace underlayment, new drip edge and install architectural shingles
- Repair soffit and fascia around structure; and paint
- Replace 10ft. of wood soffit and fascia on back patio (10x12); and paint
- Replace 10ft. of vinyl soffit and fascia on back patio (10x12)
- Flashing over patio top

Cost of Labor: \$ _____

Cost of Materials: \$ _____

Total Cost: \$ _____

Property Owner Signature _____

Contractor Signature _____

Income-Based Roof Program Scope of Work

Property Owner Name: Minnie Berry

Contractor: _____

Address: 4517 Deauville Way

Contractor PH#: _____

PH#: 850-490-1776

Total SF: 1,626

Pre-Bid Meeting (Date & Time): 4/15/2020-9am

Bid Close (Date & Time): 4/22/2020-5pm

Description: Roof Replacement

- Remove all existing shingles, underlayment and drip-edge to expose decking, inspect vent boots
- Repair degraded and damaged decking, replace underlayment, new drip edge and install modified shingles
- Coat Florida Room/Sunroom
- Rebuild carport structure to allow drainage

Cost of Labor: \$ _____

Cost of Materials: \$ _____

Total Cost: \$ _____

Property Owner Signature _____

Contractor Signature _____

Income-Based Roof Program Scope of Work

Property Owner Name: Jessie White

Contractor: _____

Address: 4521 Havre Way

Contractor PH#: _____

PH#: 850-485-6350

Total SF: 1,463

Pre-Bid Meeting (Date & Time): 4/15/2020-9am

Bid Close (Date & Time): 4/22/2020-5pm

Description:

- Remove all existing shingles, underlayment and drip-edge to expose decking, inspect vent boots
- Repair degraded and damaged decking, replace underlayment, new drip edge and install architectural shingles
- Replace soffit and fascia at right side and rear of the structure; and paint
- Replace siding at rear of the structure (on the side with the back door)
- Cut in ridge vent
- Replace three (3) sheets of soffit and fascia across front porch; and paint
- Replace missing vinyl on rear addition

Cost of Labor: \$ _____

Cost of Materials: \$ _____

Total Cost: \$ _____

Property Owner Signature _____

Contractor Signature _____