

As required by NFPA 1911 22.3:

Report of Inspection

SAFETY INSPECTION
FOR

Aerial Ladder

In accordance with
NFPA 1911 Chapter 22
Performance Testing of Aerial Devices

Customer Escambia County Fire Recue

Location Pensacola, FL


Manufacturer E-ONE

Date of Manufacture 2010 **Date of Inspection** 03/22/18

Category # 4

Unit Number
Ladder 19

Type of Unit
Aerial Ladder



Serial Number
135824

Model Number
HP 100

Heat Sensors Replaced 16

Inspected By _____

Job # 2018JM0067