CONTRACT: C23-3322-WS Sheppard Services, LLC. Electric Motor, Pump, and Rotating Equipment Repai EXPIRES:05/01/2026 W/2 (1) YR RENEWALS

DeRita Mason

From: Darren L. Alford

Sent: Monday, December 11, 2023 10:15 AM

To: Mike Sims

Cc: Chris McNeil; Nick Enders; DeRita Mason; WSInvoice; Joe Jones

Subject: FW: 17722 GEARMOTOR

Attachments: image001.jpg; Quote Detail RQ3550 2023128152057.pdf; 17722 Snip Repair.PNG; IMG

6828.jpeg; IMG_6830.jpeg

Mike,

Please consider this Okaloosa County's Notice to Proceed (NTP) for the repair to the gear box, ID# M3553. This particular gearbox is located on the Russel Stephenson WRF sludge thickener. We are opting for repair over replacement due to the cost difference. Per your attached quote and the further quote details document, the total price will be \$1,672.99, which is the cost of the shop labor(\$1,305.00), plus Material (\$367.99) with appropriate % markup.

When work is completed, to ensure that the County makes payment as quickly as possible, please send invoices w/backup (i.e. documentation on the catalog price or what you paid for the material/equipment) to wsinvoice@myokaloosa.com

Thank you,

Darren Alford Wastewater Operations Manager Okaloosa County Water & Sewer (850)651-7133

Please note: Due to Florida's very broad public records laws, most written communications to or from County employees regarding County business are public records, available to the public and media upon request. Therefore, this written e-mail communication, including your e-mail address, may be subject to public disclosure.

From: Mike Sims <msims@sheppardsvs.com> Sent: Monday, December 11, 2023 9:58 AM

To: Darren L. Alford <dlalford@myokaloosa.com>; Nick Enders <nenders@myokaloosa.com>

Subject: Fwd: 17722 GEARMOTOR

This is the quote for repair vs replacement. Thank you, Michael Sims Sheppard Services 251-751-3592

Begin forwarded message:

From: Fallon Goodwin < Fgoodwin@sheppardsvs.com >

Date: December 11, 2023 at 9:07:34 AM CST **To:** Mike Sims <<u>msims@sheppardsvs.com</u>>

Subject: 17722 GEARMOTOR



3460 Hurricane Bay Drive Theodore, AL 36582 Phone: (251) 443-0700

Website: www.sheppardsvs.com

Customer ID Quote Date 10522

12/8/2023 CC

Quote Number

Quote

1/2

RQ3550

Job Number R17722

Fallon Goodwin

Ship To Information Customer Information

Okaloosa County 1250 North Eglin Parkway SHALIMAR, FL 32579

Okaloosa county 1250 Miracle Strip Pkwy SE FORT WALTON BEACH, FL 32548

Attn

PO #: RFQ#:

Quote By:

Salesperson: Michael Sims

> Phone: Fax:

Terms: Net 30

Nameplate Information

ID M3553

Quote Information

Reason Sent For Repair: TDI. Tear down and inspect for failure.

Cause of Failure: Gearbox and motor bad.

Required Work: Photograph motor & gearbox perform visual inspection of unit.

Remove gearbox & inspect spline and shaft extension for wear.

Disassemble motor.and gearbox.

Clean & inspect all individual components.

Measure & record the following mechanical fits:

- · Shaft journals, seal fits, keyway, bearing housings and seals, etc.
- Measure keyway width at the top and bottom
- Inspect motor feet for flatness and record

Check & record all critical TIR'S areas Visually inspect stator windings.

Test, measure & record the following:

Perform rotor growl test.

Perform incoming electrical tests per specifications.

Burn out stator in a temperature-controlled oven with chart recordings.

Remove winding from stator core and record data.

Perform post burn core loss test

Rewind stator using Class H materials.

Properly block & tie winding.

VPI stator & bake in controlled oven using Solid Epoxy resin.

Perform the following Electrical tests:

- Meg and PI stator windings
- Surge comparison test each phase of the winding

Perform all Baker AWA IV tests or PDMA as required

Furnish and install new lip seals in both motor and gearbox.

Furnish and install new DE and ODE bearing Assemble motor per customer specification.

Attach motor onto gearbox.

Test run motor per specifications including the following:

- Phase voltage, current balance, rpm & rotation.
- Record horizontal, vertical & axial vibration readings.

	Subtotal:	1,672.99
Lead Time	Tax:	
	Total for Quote RQ3550 :	
SIGNATURE:	DATE:	
PO# (IF NOT ALREADY ISSUED):	Ship Via: Bestway	



3460 Hurricane Bay Drive Theodore, AL 36582 Phone: (251) 443-0700

Website: www.sheppardsvs.com

		Quote	
Customer ID	Quote Date	Quote Num	
10522	12/8/2023	RQ3550	
Attn	CC	Job Numi	

Customer ID	Quote Date	Quote Number
10522	12/8/2023	RQ3550
Attn	cc	Job Number
		R17722
To Information		Quote By: Fallon Goodwin

Customer Information	Ship To Information	Quote By: Fallon Goodwin
Okaloosa County	Okaloosa county	PO #:
1250 North Eglin Parkway		RFQ#:
SHALIMAR, FL 32579		Salesperson: Michael Sims
		Phone:
		Fax:
		Terms: Net 30
• Record bearing	g temperature & run time to stabilize.	

Labor		Unit Price	Ext Price
12	Labor Hours for Repair	72.50	870.00
6 -	Machine Work	72.50	435.00
_		Total for Labor :	1,305.00
Material		Unit Price	Ext Price
1	Repair kit	367.99	367.99
		Total for Material :	367.99

Quotes Do Not Include Sales Tax or Freight, Unless Otherwise Noted.

We Are not Responsible For Items Left Over 60 Days.

QUOTE IS

VALID FOR 30 DAYS, unless otherwise noted.

Lead Time	Subtotal : Tax : Total for Quote RQ3550 :	1,672.99
SIGNATURE:	DATE:	